

LUL Doc No: 4RS/LUL/RPT/0097

Report No. 4RS-SAH-034790-R41651

Revision: 1

**TYPE 2 ASBESTOS SURVEY OF WESTMINSTER STATION,
PROPOSED CABLE ROUTE, LUL CONNECT PROJECT**

Prepared for: **Mr Steve Fleet
London Underground Limited
Connect Project**



Issue Date: 27th May 2004


Prepared by: 
Technologist

Signature:



Certified by: 
Senior Consultant

Signature:



*Controlled Copy No. 1
Private - Not for Publication
©L.R.T. - 27th May 2004*

CONDITIONS OF ISSUE OF REPORTS.

THIS REPORT IS ISSUED IN CONFIDENCE AND SHALL NOT BE REPRODUCED, EXCEPT IN FULL, WITHOUT WRITTEN APPROVAL FROM 4-RAIL SERVICES.

FURTHER INFORMATION.

REQUESTS FOR ADDITIONAL INFORMATION ON THE SUBJECT OF THIS REPORT OR OTHER QUERIES SHOULD BE ADDRESSED TO THE AUTHOR.

CONTENTS	Page
CONTENTS PAGE.....	3
1. INTRODUCTION	4
1.1 LEGAL REQUIREMENTS.....	4
2. SAMPLING STRATEGY	4
3. LIMITATIONS OF SURVEYING	5
4. ANALYSIS OF SAMPLES	5
5. MATERIAL ASSESSMENT	5
6. RISK ASSESSMENT	5
7. PRIORITY ASSESSMENT	5
8. RESULTS	5
9. RECOMMENDATIONS	6
APPENDIX 1: OTHER AREAS OF POTENTIAL ASBESTOS	
APPENDIX 2: MATERIAL ASSESSMENT VARIABLES	
APPENDIX 3: RISK ASSESSMENT	
APPENDIX 4: PRIORITY ASSESSMENT	
APPENDIX 5: SURVEY SITE SHEETS	

1. Introduction

4-RAIL Services Ltd were requested by Mr Steve Fleet, London Underground Limited, Connect Project, to survey Westminster Station along a proposed cable route, design package supplied by Fluor, Document No FGS/EBW/CMS/9694 Revision B for materials suspected of containing asbestos.

A Type 2 survey of selected areas was undertaken on the 9th & 13th February 2004 by [REDACTED], and [REDACTED].

1.1 Legal Requirements

The Control of Asbestos at Work Regulations, 2002 (CAWR) apply to the vast majority of work involving asbestos. Three Approved Codes of Practice (ACOP's) offer practical guidance.

Undertaking an asbestos survey of a building partly satisfies Regulation 4 which stipulates that prior to commencing work, materials should be identified as containing asbestos, presumed to contain asbestos, or proved otherwise. Recent changes in legislation have put the onus on landlords to implement and maintain asbestos registers as a means of preventing unnecessary exposure to asbestos. The requirement comes into force on 21st May 2004.

2. Sampling Strategy

- 2.1 Sampling for asbestos containing materials was carried out in accordance with the procedures described in HSE Document MDHS 100 *Surveying, Sampling & Assessment of Asbestos Containing Materials* and 4-Rail Services Ltd in-house procedure 4R-E200 Issue 4.
- 2.2 When surveying rooms, walls were numbered using the following system: wall1 was the first wall to the left of the main entrance door, wall 2 was the next wall in a clockwise direction, and wall 3 was the next wall in a clockwise direction and so on, finishing with the wall where the main entrance door was.
- 2.3 Each material suspected of containing asbestos was sampled and returned to the laboratory for analysis.
- 2.4 Electrical equipment was not surveyed since it was considered live. However, assumptions may have been made as to possible asbestos containing materials within electrical units based on the experience of the surveyor. There is always the possibility that further asbestos containing materials may be present within live electrical equipment.
- 2.5 When materials are sampled as asbestos, no further attempt is made to identify materials below those sampled since investigation would lead to unnecessary disturbance of the hazardous material.

3. Limitations of Surveying

Although assigned surveyors have extensive experience in locating and sampling asbestos containing materials, there may be occasions whereby asbestos is not identified due to its location within a building. For example, some asbestos containing materials may have been used in the construction of a building that has been sealed in with concrete. Hence, they will only be located during demolition or refurbishment of the premises. (Appendix 1)

4. Analysis of Samples

Samples taken were analysed in accordance with HSE Document MDHS 77 *Asbestos in Bulk Materials: Sampling & Identification by Polarised Light Microscopy*.

5. Material Assessment

Each sample identified as containing asbestos was awarded a material assessment score based on the following variables:

- Product Type;
- Current Condition;
- Surface Treatment; and
- Asbestos Type.

Appendix 2 classifies the material assessment variables.

6. Risk Assessment

Each sample identified as containing asbestos was awarded a risk assessment score based on the potential for disturbance as perceived by the surveyor (Appendix 3). This value is provided *for information only* since different uses of the areas may significantly alter this value.

7. Priority Assessment

The priority assessment takes into account the material assessment score and the risk assessment score: the material assessment score is multiplied by the risk assessment score to give a priority score of between 2 and 48.

Appendix 4 classifies the priority assessment variables.

8. Results

Appendix 5 contains the site survey sheets detailing all areas surveyed and results of analysis of all samples taken.

9. Recommendations

The following recommendations are made in order of priority as calculated in Section 7. Priority Assessment.

As discussed in Section 6. Risk Assessment, the Client is advised to review the risk assessment and thus amend the priority assessment as required prior to the inclusion of actions within a management plan.

All areas requested by the client in accordance with document, FGS/EBW/CMS/9694 Revision B were surveyed.

No hazards were found during the survey. 4-Rail Services Ltd believe this to conform to LUL Connects definition of an Asbestos free route. Therefore the construction of the proposed cable management system at Westminster station can commence.

An asbestos register should be kept in an accessible location on site.

Type 2 Asbestos Survey of Westminster Station, Proposed Cable Route, LUL Connect Project

Node Point Summary Tables

Table 1 – Direct Impact

Node	Figure	Location	Hazard
N/A	N/A	N/A	N/A

Table 2 – Hazards to Be Aware Of

Node	Figure	Location	Hazard
N/A	N/A	N/A	N/A

Table 3 – Hazards Noted For Information Only

Node	Figure	Location	Hazard
N/A	N/A	N/A	N/A

Table 4 – Node Points Where No Asbestos Is Present

Node	Figure	Location	Hazard
1 to 115	N/A	As Per Node Schedule	N/A

Table 5 – Other Asbestos or Possible Asbestos that is Present in Areas External To the Proposed Route

Node	Figure	Location	Hazard
N/A	N/A	N/A	N/A

Appendix 1: Other Areas of Potential Asbestos

Every possible effort is made by all surveyors to ensure the contents of each survey report are as comprehensive as possible. However, there may be occasions when asbestos containing materials are overlooked due to their location within the building structure or due to restricted access.

1. Beneath Non Asbestos Lagging

Where non-asbestos lagging has been identified, but the pipework was previously lagged in asbestos containing insulation material, there may be residual asbestos located underneath the replacement lagging, especially around gaskets and by valves.

2. Electrical Boxes

Visual assessments will be made if possible, but a full survey inclusive of sampling can only be undertaken if electrical equipment is isolated.

3. Trunking Gaskets

Generally, gaskets located in trunking are not visible unless the trunking is dismantled.

4. External Areas

Unless specifically requested as part of a survey, inaccessible external areas are not surveyed due to safe access being required.

5. Fire Breaks

While every effort is made to identify the full depth of materials used to construct fire breaks, there may, on occasion, be layers of asbestos containing materials beneath non-asbestos materials that remain undetected.

6. Ductwork

Ductwork that passes through the structure of buildings is not fully surveyed. This would require specialist equipment to access such small areas, and would then only maybe result in materials being identified as suspected asbestos, due to limitations of sampling.

7. Debris

There is a possibility that asbestos debris may have been left after previous asbestos removal works. The debris will generally be very small in size and therefore go unnoticed.

8. Encapsulated Debris

If for example, during asbestos removal, small amounts of asbestos containing material could not be removed from some areas due to insufficient access, the residual asbestos would have been encapsulated. It therefore would be very difficult to locate.

9. Machinery

Type 2 Asbestos Survey of Westminster Station, Proposed Cable Route, LUL Connect Project

For safety reasons, mechanical machinery can only be surveyed if isolated.

10. Columns

Asbestos located within columns may not become evident until refurbishment or demolition. Location would require a full intrusive survey which would result in severe damage to the columns.

11. Flange Gaskets

Flange gaskets generally remain obscured from view until pipework is taken apart.

12. Confined Spaces

Confined spaces will not normally be surveyed due to specialist equipment required in accordance with Confined Space Regulations. Such areas include floor voids or any inverts.

13. Fire Doors

Some fire doors have asbestos containing materials within their structure. Investigation into this would reduce the fire rating of the doors, and hence they are not fully surveyed.

14. Security Areas

Any areas where security clearance is required are not surveyed, unless arrangements have been made by the Client.

15. Asbestos Materials Behind Known Asbestos

When a material is suspected of containing asbestos, and sampled accordingly, further investigation is not undertaken to identify what is behind it. It is only as part of the removal works under controlled conditions, that any such occurrences will become apparent.

16. Within the Building Structure

Asbestos containing materials may have been used as part of the structure of a building and since encapsulated. For example, there may asbestos within wall cavities or above plaster ceilings or it may have been used as shuttering. The presence of such materials may not become apparent until the area is undergoing refurbishment or demolition.

17. Representative Sampling

When considering large areas, a representative number of samples are taken. There is always a possibility that a material that may resemble all other materials which have not been found to contain asbestos, may contain asbestos

Type 2 Asbestos Survey of Westminster Station, Proposed Cable Route, LUL Connect Project

Appendix 2: Material Assessment Variables

PARAMETER	DESCRIPTION	RATING	EXAMPLES
Product Type	Asbestos reinforced composites	1	Plastics, resins, mastics, roofing felt, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement.
	Medium density insulating materials	2	Asbestos insulating boards, mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes or woven textiles, asbestos paper and felt.
	Highly friable insulating materials	3	Thermal insulation e.g. pipe and boiler lagging, sprayed asbestos, loose asbestos, asbestos mattresses and packing.
Current Condition	Good condition	0	No visible damage.
	Slight damage	1	A few scratches or surface marks, broken edges on boards, tiles, etc.
	Moderate damage	2	Significant breakage or several small areas of damage revealing loose fibres.
	Extensive damage	3	High levels of damage. Visible asbestos debris.
Surface Treatment	Asbestos reinforced composites	0	Plastics, resins, mastics, roofing felt, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, bituminous Cellactite.
	Encapsulated medium density materials	1	Encapsulated asbestos insulation board (AIB).
	Unencapsulated medium density or encapsulated highly friable materials	2	Untreated AIB, encapsulated lagging/spray.
	Unencapsulated highly friable materials	3	Untreated lagging/spray.
Asbestos Type	Chrysotile	1	Cable insulation, fuse backing material
	Amphibole excluding crocidolite	2	Ceiling Tiles, Soffits
	Containing Crocidolite *	3	Cable Insulation

* Presumed or strongly presumed asbestos containing materials are recorded as Crocidolite unless there is reasoned argument to suggest otherwise.

Type 1 & 2 surveys yield four parameters (product type, current condition, surface treatment & asbestos type) that are **added** to arrive at an overall **material assessment score** between 2 and 12.

Material Assessment Score	10+	High potential for release fibre
	7-9	Medium potential for fibre release
	5-6	Low potential for fibre release
	<4	Very low potential for fibre release

Type 2 Asbestos Survey of Westminster Station, Proposed Cable Route, LUL Connect Project

Appendix 3: Risk Assessment

The one element of the risk assessment assessed by the surveyors is potential for disturbance. The value allocated by the surveyors is included in the report *for information only* since it may be different from the value considered by the Client due to an intended use of the surveyed area.

PARAMETER	DESCRIPTION	RATING	EXAMPLES
Potential for disturbance	Very Low	1	Roofs, Cellactite sheets
	Low	2	Ceiling tiles, soffits
	Medium	3	Cable insulation
	High	4	Public areas, intentional disturbance

It is recommended that the Client undertakes a more detailed risk assessment taking into consideration other specific risks such as:

- The use to which the location is put
- The occupancy of the area
- The activities carried out in the area
- The likelihood/frequency with which the maintenance activities are likely to take place.

Type 2 Asbestos Survey of Westminster Station, Proposed Cable Route, LUL Connect Project

Appendix 4: Priority Assessment

A **priority assessment score** of between 2 and 48 is arrived at by **multiplying** the material assessment score with the potential for disturbance rating.

Priority Assessment Score	28+	High risk
	21-27	Medium risk
	5-20	Low risk
	<5	Very low risk

High risk: Urgent attention required. Until action can be taken, the area should be sealed.

Medium risk: Consideration should be given to removal, or as an absolute minimum, remedial work may be appropriate. Until action can be taken, the area should be sealed.

Low risk: A limited amount of remedial work may be required. The material should be protected from further damage occurring. If necessary, the area should be sealed off.

Very low risk: No action is required. As with all asbestos containing materials present on a site, records must be kept in an accessible location at the site, and regular checks implemented of the condition of the material to detect any deterioration.

On the basis of the priority assessment score, remedial action may be scheduled and/or a maintenance or inspection programme planned.

The priority assessment score contained within this report refers to the combination of the material assessment score and the potential for disturbance rating. Clients are advised to review the provided information taking into consideration other specific risks such as:

- The use to which the location is put
- The occupancy of the area
- The activities carried out in the area
- The likelihood/frequency with which the maintenance activities are likely to take place.

**Type 2 Asbestos Survey of Westminster Station, Proposed Cable Route,
LUL Connect Project**

Appendix 5: Survey Site Sheets

Type 2 Asbestos Survey of Westminster Station, Proposed Cable Route, LUL Connect Project

AREA: Westminster	CLIENT: LUL Connect	DATE OF SURVEY: 09/02/04	SURVEYOR (S): [REDACTED]
-------------------	---------------------	--------------------------	--------------------------

Sample No.	Node Point	Area Surveyed		Material Description	Quantity /m ²	Product Type	Current Condition	Surface Treatment	Potential for Disturbance	Asbestos Type	Comments and Recommendations	Photo
		Location	Room/ Plant No									
	N1-6	Vent plant	5/788	All walls, ceiling and floor							Solid with durasteel panels. No asbestos detected	
		Vent plant		Cable at high level on new containment							No Hazards	
	N6-8	Fan Room	5/785	All walls, ceiling and floor							Solid with durasteel panels	
		Fan Room		Cable at high level on new containment through existing hole							No Hazards	
	N8-10	Fan Room	5/776	All walls, ceiling and floor							Solid	
		Fan Room		Cable at high level to existing core							No Hazards	
	n-10	Lobby	5/083	All walls, ceiling and floor							Solid	
		Lobby		New containment and new cored hole at high level							No Hazards	
	N+10	Lobby	5/082	All walls, ceiling and floor							Solid	
		Lobby		New containment and cored holes							No Hazards	

Material Description	Product Type	Current Condition	Surface Treatment	Potential for Disturbance	Asbestos Type
W Wall PW Partition wall C Ceiling F Floor FC False ceiling AFC Above false ceiling CA Cable	1.Composite 2.Medium density 3.High friable	0.Good condition 1.Slight damage 2.Moderate damage 3.Extensive damage	0.Composite 1.Encapsulated medium density 2.Unencapsulated medium density or treated highly friable 3.Untreated highly friable	1.Very Low 2.Low 3.Medium 4.High	P presumed SP strongly presumed 0.Non-asbestos 1.Chrysotile 2.Amphibole excluding Crocidolite 3.Crocidolite

Lead Surveyor: [REDACTED]

Signed:pp..... [REDACTED]

Analyst:

Signed:....No Samples Taken.....

Type 2 Asbestos Survey of Westminster Station, Proposed Cable Route, LUL Connect Project

AREA: Westminster	CLIENT: LUL Connect	DATE OF SURVEY: 09/02/04	SURVEYOR (S): [REDACTED]
-------------------	---------------------	--------------------------	--------------------------

Sample No.	Node Point	Area Surveyed		Material Description	Quantity /m ²	Product Type	Current Condition	Surface Treatment	Potential for Disturbance	Asbestos Type	Comments and Recommendations	Photo
		Location	Room/Plant No									
	N13-25	Stairs	5/631	All walls, ceiling and floor							Solid	
		Stairs		Cable at high containment using new containment and core holes							No Hazards	
	N25-30	Disused	5/901	All walls, ceiling and floor							Solid	
		Disused		Cable at high level down wall 3 into isolators on wall new cored holes and existing containment							No Hazards	
	N42-N20	Platform 1		Cable to run whole length of platform at high level using new containment on existing RSJ's on to solid wall at either end							No Hazards	
	N33-36	Relay Room	3/773	New cored hole onto durasteel panels with new containment							No Hazards	
	N38-45	OTX		Cable at high level on new on new containment attached to RSJ							No Hazards	
	N40	Platform 1		Cable at high level onto brick wall using containment							No Hazards	
	N19-N22	Platform 1		Cable attached to wall on new containment							No Hazards	

Material Description	Product Type	Current Condition	Surface Treatment	Potential for Disturbance	Asbestos Type
W Wall PW Partition wall C Ceiling F Floor FC False ceiling AFC Above false ceiling CA Cable	1.Composite 2.Medium density 3.High friable	0.Good condition 1.Slight damage 2.Moderate damage 3.Extensive damage	0.Composite 1.Encapsulated medium density 2.Unencapsulated medium density or treated highly friable 3.Untreated highly friable	1.Very Low 2.Low 3.Medium 4.High	P presumed SP strongly presumed 0.Non-asbestos 1.Chrysotile 2.Amphibole excluding Crocidolite 3.Crocidolite

Lead Surveyor : [REDACTED]

Signed:pp..... [REDACTED]

Analyst :

Signed: ...No Samples Taken...

Type 2 Asbestos Survey of Westminster Station, Proposed Cable Route, LUL Connect Project

AREA: Westminster	CLIENT: LUL Connect	DATE OF SURVEY: 09/02/04	SURVEYOR (S): [REDACTED]
-------------------	---------------------	--------------------------	--------------------------

Sample No.	Node Point	Area Surveyed		Material Description	Quantity /m ²	Product Type	Current Condition	Surface Treatment	Potential for Disturbance	Asbestos Type	Comments and Recommendations	Photo
		Location	Room/ Plant No									
	N23	Stairs	3/086	Cable on existing containment on solid wall up stairs							No Hazards	
	N17-N18	OTX Platform 1		Cable on new containment attached to RSJ to Platform 2							No Hazards	
	N55-N58	Platform 2		All cables PVC utilise any J hanger							No Hazards	
	N46	Platform 2		Cable in existing containment through false ceiling on new containment to 3/788							No Hazards	
	N61-N77	Platform 2		All walls, ceiling and floor							No Hazards	
		Platform 2		Cable using new containment and cored holes attached to solid walls							No Hazards	
		Platform 2		All wall, ceiling and floor							solid	
		Platform 2		All cables							PVC	
		Platform 2		Any J hangers can be utilised for route							No Hazards	
	N82-83		5/631	All walls, ceiling and floor							New containment new cored holes. Solid with durasteel panels	

Material Description	Product Type	Current Condition	Surface Treatment	Potential for Disturbance	Asbestos Type
W Wall PW Partition wall C Ceiling F Floor FC False ceiling AFC Above false ceiling CA Cable	1.Composite 2.Medium density 3.High friable	0.Good condition 1.Slight damage 2.Moderate damage 3.Extensive damage	0.Composite 1.Encapsulated medium density 2.Unencapsulated medium density or treated highly friable 3.Untreated highly friable	1.Very Low 2.Low 3.Medium 4.High	P presumed SP strongly presumed 0.Non-asbestos 1.Chrysotile 2.Amphibole excluding Crocidolite 3.Crocidolite

Lead Surveyor : [REDACTED]

Signed:pp..... [REDACTED]

Analyst : Signed:No Samples Taken.....

Type 2 Asbestos Survey of Westminster Station, Proposed Cable Route, LUL Connect Project

AREA: Westminster	CLIENT: LUL Connect	DATE OF SURVEY: 13/02/04	SURVEYOR (S): [REDACTED]
-------------------	---------------------	--------------------------	--------------------------

Sample No.	Node Point	Area Surveyed		Material Description	Quantity /m ²	Product Type	Current Condition	Surface Treatment	Potential for Disturbance	Asbestos Type	Comments and Recommendations	Photo
		Location	Room/ Plant No									
	N115-N97	Platform 3		All walls, ceiling and floor							Solid	
		Platform 3		All cables							PVC	
		Platform 3		Existing cable through to station areas							No Hazards	
	N94	Cable route	8/781	All walls, ceiling and floor							Solid	
		Cable route		Cable to use new and existing containment at high level with new cored holes							No Hazards	
	N112-N111	Switch Room	8/663	All walls, ceiling and floor							Solid	
		Switch Room		New cored hole from wall cable to run at high level using new containment							No Hazards	
	N92	Corridor	8/236	All walls, ceiling and floor							Solid	
		Corridor		Cable run at high level on new and existing containment with new cored holes							No Hazards	
	N88	Service Area	8/773	All walls, ceiling and floor							Solid	

Material Description	Product Type	Current Condition	Surface Treatment	Potential for Disturbance	Asbestos Type
W Wall PW Partition wall C Ceiling F Floor FC False ceiling AFC Above false ceiling CA Cable	1.Composite 2.Medium density 3.High friable	0.Good condition 1.Slight damage 2.Moderate damage 3.Extensive damage	0.Composite 1.Encapsulated medium density 2.Unencapsulated medium density or treated highly friable 3.Untreated highly friable	1.Very Low 2.Low 3.Medium 4.High	P - presumed SP - strongly presumed 0.Non-asbestos 1.Chrysotile 2.Amphibole excluding Crocidolite 3.Crocidolite

Lead Surveyor : [REDACTED]

Signed:pp..... [REDACTED]

Analyst : Signed:No Samples Taken.....

Type 2 Asbestos Survey of Westminster Station, Proposed Cable Route, LUL Connect Project

AREA: Westminster	CLIENT: LUL Connect	DATE OF SURVEY: 13/02/04	SURVEYOR (S): [REDACTED]
-------------------	---------------------	--------------------------	--------------------------

Sample No.	Node Point	Area Surveyed		Material Description	Quantity /m ²	Product Type	Current Condition	Surface Treatment	Potential for Disturbance	Asbestos Type	Comments and Recommendations	Photo
		Location	Room/ Plant No									
		Service Area		Cable at high level using new containment and new cored holes							No Hazards	
	N84-N83	Access Shaft	9/482	All walls, ceiling and floor							Solid	
		Access Shaft		Cable to use new and existing containment with new cored holes							No Hazards	
	N99-N101	CER	8/731	All walls, ceiling and floor							Solid	
		CER		Cable to use new and existing containment with new cored holes							No Hazards	
	N109	Scada	7/481	All walls, ceiling and floor							Solid	
		Scada		Cable to use new and existing containment with new cored holes							No Hazards	
	N27-N31	CER	2/731	All walls, ceiling and floor							Solid	
		CER		Cable to use new and existing containment with new cored holes							All cables PVC	
	N25	Corridor	2/236	All walls, ceiling and floor							Solid	

Material Description	Product Type	Current Condition	Surface Treatment	Potential for Disturbance	Asbestos Type
W Wall PW Partition wall C Ceiling F Floor FC False ceiling AFC Above false ceiling CA Cable	1.Composite 2.Medium density 3.High friable	0.Good condition All walls, ceiling and floor 1.Slight damage 2.Moderate damage 3.Extensive damage	0.Composite 1.Encapsulated medium density 2.Unencapsulated medium density or treated highly friable 3.Untreated highly friable	1.Very Low 2.Low 3.Medium 4.High	P - presumed SP - strongly presumed 0.Non-asbestos 1.Chrysotile 2.Amphibole excluding Crocidolite 3. Crocidolite

Lead Surveyor [REDACTED]

Signed:pp..... [REDACTED]

..... Analyst :

Signed:No Samples Taken.....

Type 2 Asbestos Survey of Westminster Station, Proposed Cable Route, LUL Connect Project

AREA: Westminster	CLIENT: LUL Connect	DATE OF SURVEY: 13/02/04	SURVEYOR (S): [REDACTED]
-------------------	---------------------	--------------------------	--------------------------

Sample No.	Node Point	Area Surveyed		Material Description	Quantity /m ²	Product Type	Current Condition	Surface Treatment	Potential for Disturbance	Asbestos Type	Comments and Recommendations	Photo
		Location	Room/ Plant No									
		Corridor		False ceiling							No Hazards	
		Corridor		Cable to run at high level new cored hole and containment							No Hazards	
	N25-N24	Stairs	3/631	All walls, ceiling and floor							Solid	
		Stairs		Cable to run at high level using new containment							No Hazards	
	N71-N73	Stairs	3/633	All walls, ceiling and floor							Solid	
		Stairs		Cable to run at high level using new containment							No Hazards	
		Passage	2/201	All walls, ceiling and floor							Solid	
	N16-18	Fan Room	4/776	All walls, ceiling and floor							Solid	
		Fan Room		Cable using new containment							No Hazards	
	N22	DIR Shaft	4/792	All walls, ceiling and floor							Solid	

Material Description	Product Type	Current Condition	Surface Treatment	Potential for Disturbance	Asbestos Type
W Wall PW Partition wall C Ceiling F Floor FC False ceiling AFC Above false ceiling CA Cable	1.Composite 2.Medium density 3.High friable	0.Good condition 1.Slight damage 2.Moderate damage 3.Extensive damage	0.Composite 1.Encapsulated medium density 2.Unencapsulated medium density or treated highly friable 3.Untreated highly friable	1.Very Low 2.Low 3.Medium 4.High	P presumed SP strongly presumed 0.Non-asbestos 1.Chrysotile 2.Amphibole excluding Crocidolite 3.Crocidolite

Lead Surveyor: [REDACTED]

Signed: ..pp..... [REDACTED]

Analyst : Signed:No Samples Taken.....

Type 2 Asbestos Survey of Westminster Station, Proposed Cable Route, LUL Connect Project

AREA: Westminster	CLIENT: LUL Connect	DATE OF SURVEY: 13/02/04	SURVEYOR (S): [REDACTED]
-------------------	---------------------	--------------------------	--------------------------

Sample No.	Node Point	Area Surveyed		Material Description	Quantity /m ²	Product Type	Current Condition	Surface Treatment	Potential for Disturbance	Asbestos Type	Comments and Recommendations	Photo
		Location	Room/Plant No									
		DIR Shaft		Existing containment new cored holes								

Material Description	Product Type	Current Condition	Surface Treatment	Potential for Disturbance	Asbestos Type
W Wall PW Partition wall C Ceiling F Floor FC False ceiling AFC Above false ceiling CA Cable	1.Composite 2.Medium density 3.High friable	0.Good condition 1.Slight damage 2.Moderate damage 3.Extensive damage	0.Composite 1.Encapsulated medium density 2.Unencapsulated medium density or treated highly friable 3.Untreated highly friable	1.Very Low 2.Low 3.Medium 4.High	P. presumed SP. strongly presumed 0.Non-asbestos 1.Chrysotile 2.Amphibole excluding Crocidolite 3. Crocidolite

Lead Surveyor : [REDACTED]

Signed:pp..... [REDACTED]

Analyst :

Signed:No Samples Taken.....