

Sample Reference Number	School Name	Location	Product Type	Condition	MATERIAL ASSESSMENT			PRIORITY ASSESSMENT					Monitor Condition			
	Surface Treatment				Asbestos Type	OVERALL RISK SCORE	Normal Occupant Activity	Likelihood of disturbance	Human Exposure Potential	Maintenance Activity	FINAL RISK	What	When	Who	Outcomes i.e. Amended Risk or Removed	
CO6925/SO2	Lumbertubs Primary School	17 WC Cistern to wall	1- Plastics	1- Low	0- Reinforced Composite Materials	Amosite	Very Low	0	1	3	0	6	Monitor Condition	Annually	ARP	Removed from during toilet refurbishment 03/17
CO6925/SO1	Lumbertubs Primary School	16 & 17 WC Cement cladding to beams	1- Cement	0- No Visible	2- Unsealed Board	1- Chrysotile	Very Low	0	1	1	1	7	Monitor Condition	Annually	ARP	Monitor condition of ACM
1609295/0014	Lumbertubs Primary School	075 - Quiet Room, Under carpet to floor	1- Vinyl	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
1609295/0015	Lumbertubs Primary School	21 Corridor; Under carpet and latex	1- Bitumen	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
1609295/0016	Lumbertubs Primary School	21 Corridor; Pipework within ceiling void	2- Gasket	1- Low	2- Encapsulated Textile/Paper	3- Presumed Asbestos	Low	0	0	1	2	11	Monitor Condition	Annually	ARP	No maintenance works to be carried out without prior permission from ARP
1609295/0018	Lumbertubs Primary School	59 Store Room; Floor	1- Vinyl	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
1609295/0028	Lumbertubs Primary School	23 Classroom; Under carpet to floor	1- Bitumen	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
1609295/0031	Lumbertubs Primary School	28 Resource Room; To floor, under carpet and under latex	1- Bitumen	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
1609295/0036	Lumbertubs Primary School	29 Classroom; Under carpet	1- Bitumen	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
1609295/0037	Lumbertubs Primary School	30 Classroom; Under carpet to floor	1- Bitumen	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
1609295/0039	Lumbertubs Primary School	32 Classroom; Under carpet to floor	1- Bitumen	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
1609295/0048	Lumbertubs Primary School	45 Practical areas; Redundant pipework within ceiling void	1- Bitumen	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
1609295/0049	Lumbertubs Primary School	40 Classroom Inc. 62 Store; Under Carpet	1- Bitumen	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
1609295/0051	Lumbertubs Primary School	43 Classroom incl 61 Store; Under carpet	1- Bitumen	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
1609295/0052	Lumbertubs Primary School	44 Resource Area; Under Carpet to floor	1- Bitumen	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
1609295/0057	Lumbertubs Primary School	49 Nursery; Under carpet and modern lino to floor	1- Bitumen	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
1609295/0058	Lumbertubs Primary School	52 Store; Under carpet	1- Bitumen	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
1609295/0059	Lumbertubs Primary School	54 Store; Under Carpet	1- Bitumen	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
1609295/0060	Lumbertubs Primary School	53 Nursery and 55 Library; Under carpet	1- Bitumen	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
1609295/0068	Lumbertubs Primary School	17 WC and 16 WC; Cistern to wall	1- Plastics	1- Low	0- Reinforced Composite Materials	2- Amosite	Very Low	0	1	3	0	6	Monitor Condition	Annually	ARP	Removed from during toilet refurbishment 03/17
1609295/0070	Lumbertubs Primary School	900 Plant; Ceiling	2- Insulating Board	0- No Visible	2- Unsealed Board	2- Amosite	Low	0	1	1	1	7	Monitor Condition	Annually	ARP	Monitor condition of ACM
1609295/0071	Lumbertubs Primary School	900 Plant; Cement Flu Pipe	2- Insulating Board	0- No Visible	2- Sealed Cement	2- Amosite	Low	0	1	1	1	7	Monitor Condition	Annually	ARP	ENCAPULATION COMPLETED 29/11/14 Continue to Monitor condition of ACM,
1609295/0073	Lumbertubs Primary School	Caretaker Office; Ceiling Void	2- Insulating Board	0- No Visible	2- Unsealed Board	2- Amosite	Low	0	1	1	1	7	Monitor Condition	Annually	ARP	Monitor condition of ACM
ARMAC 02	Lumbertubs Primary School	Boiler Room - Pipe Flue	1- Cement	1- Low	1-Unsealed Cement	2- Amosite	Low	0	1	3	1	8	Monitor Condition	Annually	ARP	Monitor condition of ACM
ARMAC 03	Lumbertubs Primary School	Room 23 -Floor Tiles	1- Vinyl	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
ARMAC 04	Lumbertubs Primary School	Room 29 - Floor Tiles	1- Vinyl	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
ARMAC 05	Lumbertubs Primary School	Room 32 - Floor Tiles	1- Vinyl	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
ARMAC 06	Lumbertubs Primary School	Room 36 - Floor Tiles	1- Vinyl	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
ARMAC 07	Lumbertubs Primary School	Room 39 - Floor Tiles	1- Vinyl	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
ARMAC 08	Lumbertubs Primary School	Room 43 - Floor Tiles	1- Vinyl	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
ARMAC 09	Lumbertubs Primary School	Room 49 - Floor Tiles	1- Vinyl	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
ARMAC 10	Lumbertubs Primary School	Room (Corridor) 02 - Floor Tiles	1- Vinyl	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
ARMAC 11	Lumbertubs Primary School	Room (Corridor) 65 - Floor Tiles	1- Vinyl	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
ARMAC 12	Lumbertubs Primary School	Room (Corridor) 21 - Floor Tiles	1- Vinyl	1- Low	0- Reinforced Composite Materials	1- Chrysotile	Very Low	1	0	3	0	6	Monitor Condition	Annually	ARP	Monitor condition of ACM
14-17				Medium Risk												
This category indicates that deterioration in any of the contributory factors may result in asbestos fibre release																
9-13				Low Risk												
This category indicates the need for regular monitoring as although the current risk of fibre release is low, this risk may rapidly alter should any number of factors contribute to the materials deterioration																
1-8				Very Low Risk												
This category indicates low priority. Visual inspections should be made on an annual basis to ascertain any change in condition																
0				No Risk												
No action necessary																