

Site Asbestos Compendium Summary

This compendium report is based on Site id: **171126**, Client Site Ref: **Airport**, Client Ref: **Airport**, Account Ref No: **3074**

Airport, Nexus Metro Station Newcastle International Airport, Ponteland, Newcastle, NE13 8BZ

This Site Asbestos Compendium Summary report has been produced at the request of Tyne and Wear Metro T/a Nexus it is a summary of asbestos survey findings. Not all of this buildings or items within may have been surveyed for asbestos containing materials - check for exceptions below. Information in this report should not be regarded as an exhaustive inventory of all asbestos containing materials on these premises. Any proposed work of an intrusive nature in the vicinity of asbestos containing material as identified in this summary MUST in the first instance be referred to Tyne and Wear Metro T/a Nexus building and civil section.

This Compendium Asbestos report aims to be concise, yet comprehensive compilation of asbestos records relating to *Airport, Nexus Metro Station Newcastle International Airport, Ponteland, Newcastle, NE13 8BZ*. This compendium will summarize larger work shown in individual reports undertaken for jobs carried out on this site.

The full Site Asbestos Compendium report can be found at:

<https://web.lucion.co.uk/print/compendium/171126?s=143f7d3b59c5b0ee7d8d2bdcca9f5f70>


Cover Photo



Overview of Jobs carried out at this Site

Job ID	Job-Type	Start Date	Due Date
187875	Survey, Management		

Breakdown of Asbestos findings

⊖ Asbestos should be presumed to be present within Locations and Items not accessed until further assessment. 
Additional surveyor comments.

Head Office

E:
T:

Issuing Office:




↓ Previous Asbestos Records

Most Recent Asbestos Records ↓

Building: Airport Metro Station **Level: 0** **Location: 001/North walkway**

No reportable Items and Materials recorded at this Location

Building: Airport Metro Station **Level: 0** **Location: 002/Ticket concourse**

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Panel within fire indicator panel	No Asbestos Identified	NAD	--	--		 NAD
	💬 (inspected during Survey, Survey, Management)						
	VE panels	Asbestos Insulating Board	--	--	--	--	 PRESUME
	💬 (inspected during Survey, Survey, Management)						
	Panel to fire extinguisher dry riser	No Asbestos Identified	NAD	--	--		 NAD
	💬 (inspected during Survey, Survey, Management)						


Building: Airport Metro Station **Level: 0** **Location: 002/Ticket concourse-ceiling void**

No reportable Items and Materials recorded at this Location



Building: Airport Metro Station **Level: 0** **Location: 003/Staff toilet**

No reportable Items and Materials recorded at this Location



Building: Airport Metro Station **Level: 0** **Location: 004/Cleaners store**

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Partition wall	No Asbestos Identified	NAD	--	--		 NAD
	💬 (inspected during Survey, Survey, Management)						

Building: Airport Metro Station **Level: 0** **Location: 005/Staff / Security room**

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Sink pad	No Asbestos Identified	NAD	--	--		 NAD
	💬 (inspected during Survey, Survey, Management)						
	Partition wall	No Asbestos Identified	NAD	--	--		 NAD
	💬 (inspected during Survey, Survey, Management)						



Building: Airport Metro Station Level: 0 Location: 006/Plant room corridor

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Panel to wall service penetration point	No Asbestos Identified	NAD	--	--		
<p> (inspected during Survey, Survey, Management)</p>							NAD











Building: Airport Metro Station Level: 0 Location: 007/Store room

No reportable Items and Materials recorded at this Location

Building: Airport Metro Station Level: 0 Location: 008/LV room



First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Debris within penetration panel	No Asbestos Identified	NAD	--	--		
<p> (inspected during Survey, Survey, Management)</p>							NAD

Building: Airport Metro Station Level: 0 Location: 009/C & S room

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Textured coating to wall	No Asbestos Identified	NAD	--	--		
<p> (inspected during Survey, Survey, Management)</p>							NAD
	Penetration Panels to wall	No Asbestos Identified	NAD	--	--		
<p> (inspected during Survey, Survey, Management)</p>							NAD
	Redundant panel within service duct	No Asbestos Identified	NAD	--	--		
<p> (inspected during Survey, Survey, Management)</p>							NAD
	Dust within service duct	No Asbestos Identified	NAD	--	--		
<p> (inspected during Survey, Survey, Management)</p>							NAD
	Debris within service duct	No Asbestos Identified	NAD	--	--		
<p> (inspected during Survey, Survey, Management)</p>							NAD

Building: Airport Metro Station Level: 0 Location: 010/South walkway

No reportable Items and Materials recorded at this Location

Building: Airport Metro Station							Level: 0	Location: 011/Station platform 1 & 2
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record	
	VE panels	Asbestos Insulating Board	--	--	--	--		
	(inspected during Survey, Survey, Management)							
Building: Airport Metro Station							Level: 0	Location: 011/Station platform 1 & 2 - Manhole covers
No reportable Items and Materials recorded at this Location								
Building: Airport Metro Station							Level: 0	Location: 011/Station platform 1 & 2 - Turning chambers
No reportable Items and Materials recorded at this Location								
Building: Airport Metro Station							Level: 0	Location: 012/Station platform toilet
No reportable Items and Materials recorded at this Location								
Building: Airport Metro Station							Level: 0	Location: 013/Relay room
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record	
	Debris to floor void	No Asbestos Identified	NAD	--	--			
	(inspected during Survey, Survey, Management)							