# Asbestos Material & Priority Assessment Report

at

## CAMHS/Lodge Road TAJ51



Survey Conducted by: Riverside Environmental Services Ltd

**Date:** 8/12/2016

**Survey Report Number J099844** 

**Sandwell New Code** 

CAMHS/Lodge Road TAJ51
Sample Record Number: J054909PS69
Building External Element
Position Location (Cachet

Inspection Date	14/9/2016		
Component:	Gaskets	Sample No.	J054909PS69
Survey Type	Type 2	Surveyor	Richard Farmer
Asbestos type	·	Chrysotile	
Quantity of Material		10N°	

## **Material Assessment**

Material	2	Extent of Damage 0
Surface Treatment	1	Asbestos Type 1
Material Assessment Total:	4	C



## **Comments:**

This material requires no immediate attention.

Total Score:	6 Sound	
Frequency of maintenance activity	1 Risk Assessment Total:	2
Frequency of use	$oxed{0}$ Average time is in use	0
Accessibility	0 Number of Occupants	0
Maintenance Activity	0 Location	2
Main Type of Activity	$\left 0\right $ Extent of Material	0

Actions Arising	<b>Due Date</b>	Est. Cost
Label & Manage	9-11-2016	£0

Re-Inspection Schedule:	Status	<b>Due Date</b>	
	Due after six Months	14-9-2017	

Sample Record Number: FU000410 Basement -1, Plant Room 007-03-(-1)-001

Position Location :Flash Guard

Inspection Date	14/9/2016		
Component:	Flash Guard	Sample No.	FU000410
Survey Type	Type 2	Surveyor	Richard Farmer
Asbestos type	·	Chrysotile	
Quantity of Material		2N°	

## **Material Assessment**

Material	2	Extent of Damage	2
Surface Treatment	2	Asbestos Type	1
Material Assessment Total:		В	



#### Comments:

Restrict access and remove the material as soon as is practicable.

Main Type of Activity	0 Extent of Material	0
Maintenance Activity	0 Location	2
Accessibility	0 Number of Occupants	0
Frequency of use	0 Average time is in use	0
Frequency of maintenance activity	0 Risk Assessment Total:	1
Total Score:	8 Slight Risk	

Actions Arising	<b>Due Date</b>	Est. Cost

Re-Inspection Schedule:	Status	<b>Due Date</b>	
	Due after six Months	14-9-2017	

Sample Record Number: FU000411 Basement -1, Plant Room 007-03-(-1)-001

**Position Location :**Walls

Inspection Date	14/9/2016		
Component:	Residue	Sample No.	FU000411
Survey Type	Type 2	Surveyor	Richard Farmer
Asbestos type	·	Chrysotile	
Quantity of Material		10m <sup>2</sup>	

## **Material Assessment**

Material	3	Extent of Damage	3
Surface Treatment	3	Asbestos Type	1
Material Assessment Total:		A	



#### Comments:

Restrict access and remove the material as soon as possible.

Main Type of Activity	0	Extent of Material
Maintenance Activity	0	Location
Accessibility	0	Number of Occupants
Frequency of use	0	Average time is in use
Frequency of maintenance activity	1	Risk Assessment Total:
Total Score:	12	Slight Risk

Actions Arising	<b>Due Date</b>	Est. Cost
Remove under Controlled Conditions by Approved	9-11-2016	f0
Contractor.	7 11 2010	~~

Re-Inspection Schedule:	Status	<b>Due Date</b>
	Due after six Months	14-9-2017

Sample Record Number: FU000412

Basement -1, Plant Room 007-03-(-1)-001

**Position Location :**Behind Pipework

Inspection Date	14/9/2016		
Component:	Residue	Sample No.	FU000412
Survey Type	Type 2	Surveyor	Richard Farmer
Asbestos type		Chrysotile	
Quantity of Material		8lm	

## **Material Assessment**

Material	3	Extent of Damage	3
Surface Treatment	2	Asbestos Type	1
Material Assessment Total:	9	В	



#### Comments:

Restrict access and remove material as soon as possible.

Main Type of Activity	0	Extent of Material	1
Maintenance Activity	0	Location	2
Accessibility	0	Number of Occupants	0
Frequency of use	0	Average time is in use	0
Frequency of maintenance activity	1	Risk Assessment Total:	2
Total Score:	11	Slight Risk	

Actions Arising	<b>Due Date</b>	Est. Cost
Remove under Controlled Conditions by Approved	9-11-2016	f0
Contractor.	7 11 2010	~~

Re-Inspection Schedule:	Status	<b>Due Date</b>
	Due after six Months	14-9-2017

Sample Record Number: FU000413 Basement -1, Plant Room 007-03-(-1)-001

**Position Location :**Wall

Inspection Date	14/9/2016		
Component:	Residue	Sample No.	FU000413
Survey Type	Type 2	Surveyor	Richard Farmer
Asbestos type		Chrysotile	
Quantity of Material		10m <sup>2</sup>	

## **Material Assessment**

Material	3	Extent of Damage	3
Surface Treatment	2	Asbestos Type	1
Material Assessment Total:	9	В	



#### Comments:

Restrict access and remove material as soon as possible.

Main Type of Activity	0	Extent of Material	1
Maintenance Activity	0	Location	2
Accessibility	0	Number of Occupants	0
Frequency of use	0	Average time is in use	0
Frequency of maintenance activity	1	Risk Assessment Total:	2
Total Score:	11	Slight Risk	

Actions Arising	<b>Due Date</b>	Est. Cost
Remove under Controlled Conditions by Approved Contractor.	9-11-2016	£0

Re-Inspection Schedule:	Status	<b>Due Date</b>
	Due after six Months	14-9-2017

Sample Record Number: FU000414

Basement -1, Plant Room 007-03-(-1)-001

**Position Location :**Floor

Inspection Date	14/9/2016		
Component:	Dust Debris	Sample No.	FU000414
Survey Type	Type 2	Surveyor	Richard Farmer
Asbestos type	·	Chrysotile	
Quantity of Material		15m <sup>2</sup>	

## **Material Assessment**

Material	3	Extent of Damage	3
Surface Treatment	2	Asbestos Type	1
Material Assessment Total:	9	В	



#### Comments:

Restrict access and remove material as soon as possible.

Main Type of Activity	0	Extent of Material	2
Maintenance Activity	0	Location	2
Accessibility	0	Number of Occupants	0
Frequency of use	0	Average time is in use	0
Frequency of maintenance activity	1	Risk Assessment Total:	2
Total Score:	11	Slight Risk	

Actions Arising	<b>Due Date</b>	Est. Cost
Remove under Controlled Conditions by Approved Contractor.	9-11-2016	£0

Re-Inspection Schedule:	Status	<b>Due Date</b>
	Due after six Months	14-9-2017

Sample Record Number: FU000415

Basement -1, Plant Room 007-03-(-1)-001

**Position Location :**Ceiling

Inspection Date	14/9/2016		
Component:	Residue	Sample No.	FU000415
Survey Type	Type 2	Surveyor	Richard Farmer
Asbestos type		Chrysotile	·
Quantity of Material		1m <sup>2</sup>	

## **Material Assessment**

Material	3	Extent of Damage	3
Surface Treatment	2	Asbestos Type	1
Material Assessment Total:	9	В	



#### Comments:

Restrict access and remove material as soon as possible.

Main Type of Activity	0	Extent of Material	1
Maintenance Activity	0	Location	2
Accessibility	0	Number of Occupants	0
Frequency of use	0	Average time is in use	0
Frequency of maintenance activity	1	Risk Assessment Total:	2
Total Score:	11	Slight Risk	

Actions Arising	<b>Due Date</b>	Est. Cost
Remove under Controlled Conditions by Approved Contractor.	9-11-2016	£0

Re-Inspection Schedule:	Status	<b>Due Date</b>
	Due after six Months	14-9-2017

## **Bulk Analysis Report**

**Client: Sandwell New Code** 

Address: CAMHS/Lodge Road TAJ51

**Date:** 08/12/2016

**Survey Report Number J099844** 

Sample Ref. No.	Sample Location	Sample Description	Asbestos Types
J054909PS69	CAMHS/Lodge Road TAJ51	Gaskets	Chrysotile
FU000410	Plant Room 007-03-(-1)-001	Flash Guard	Chrysotile
FU000411	Plant Room 007-03-(-1)-001	Residue	Chrysotile
FU000412	Plant Room 007-03-(-1)-001	Residue	Chrysotile
FU000413	Plant Room 007-03-(-1)-001	Residue	Chrysotile
FU000414	Plant Room 007-03-(-1)-001	Dust Debris	Chrysotile
FU000415	Plant Room 007-03-(-1)-001	Residue	Chrysotile

Sample analysis was conducted in accordance with in house procedures and the methodology contained in MDSHS77 (Asbestos in bulk materials. Sampling and identification by polarised light microscopy. June 1994). The information provided concerning sample locations is as provided by the client no liability can be accepted for the accuracy of this information Comments, Opinions, Recommendations are outside the scope of our UKAS accreditation. Determination of concentration is outside the scope of laboratory accreditaion

Key = Chysotile: White Asbetsos Amosite: Brown Asbestos Crocidolite: Blue Asbestos NAD: No Asbestos Detected

## Areas With No Suspect Materials Within the Definition of this type of Survey

CAMHS/Lodge Road	TAJ51	
Basement	-1	
Ground Floor	00	
Entrance	007-03-00-001	
Waiting Area	007-03-00-002	
Consult/Exam Room	007-03-00-003	
Circulation - Lobby	007-03-00-004	
Office	007-03-00-005	
Circulation - Corridor	007-03-00-006	
Consult/Exam Room	007-03-00-007	
Kitchenette	007-03-00-008	
Sluice	007-03-00-009	
W.C. – Assisted	007-03-00-010	
W.C.	007-03-00-011	
W.C.	007-03-00-012	
Consult/Exam Room	007-03-00-013	
Circulation - Corridor	007-03-00-014	
Circulation - Lift	007-03-00-015	
Circulation - Corridor	007-03-00-017	
Store - Medical Records	007-03-00-018	
Consult/Exam Room	007-03-00-019	
Store - Cleaners	007-03-00-020	
Server Room	007-03-00-021	
First Floor	01	
Circulation - Lobby	007-03-01-001	
Consult/Exam Room	007-03-01-002	
Consult/Exam Room	007-03-01-003	
Consult/Exam Room	007-03-01-004	
Consult/Exam Room	007-03-01-005	
Consult/Exam Room	007-03-01-006	
-		

CAMHS/Lodge Road	TAJ51
First Floor	01
Office	007-03-01-007
Consult/Exam Room	007-03-01-008
Consult/Exam Room	007-03-01-009
Consult/Exam Room	007-03-01-010
Consult/Exam Room	007-03-01-011
Consult/Exam Room	007-03-01-012
Consult/Exam Room	007-03-01-013
Circulation – Lobby	007-03-01-014
W.C.	007-03-01-015
Kitchenette	007-03-01-016
Group Room	007-03-01-017
Circulation – Lobby	007-03-01-018
W.C.	007-03-01-019
W.C.	007-03-01-020
Consult/Exam Room	007-03-01-021
Consult/Exam Room	007-03-01-022
Circulation – Stairs	007-03-01-023
Circulation - Corridor	007-03-01-024
Circulation - Corridor	007-03-01-025
Circulation – Lift	007-03-01-026
Circulation - Corridor	007-03-01-027
Group Room	007-03-01-028
Circulation - Corridor	007-03-01-029
Second Floor	02
Staff Room	007-03-02-001
W.C.	007-03-02-002
W.C.	007-03-02-003
W.C.	007-03-02-004
W.C.	007-03-02-005
Office	007-03-02-006

CAMHS/Lodge Road	TAJ51
Second Floor	02
Office	007-03-02-007
Office	007-03-02-008
Office	007-03-02-009
Office	007-03-02-011
Office	007-03-02-012
Office	007-03-02-013
Quiet Room	007-03-02-014
Quiet Room	007-03-02-015
Circulation - Stairs	007-03-02-016
Circulation - Corridor	007-03-02-017
Circulation - Corridor	007-03-02-018
Circulation - Corridor	007-03-02-019
Circulation – Lobby	007-03-02-020
Circulation – Lift	007-03-02-021
Staff Room	007-03-02-022


# Asbestos Re-Inspection Schedule Date: 8/12/2016


Date: 8/12/2016
Survey Report Number J099844
In Chronological Order

#### **Due after six Months**

Sa	mple Location	Description	Comments	<b>Due Date</b>	Status
e	CAMHS/Lodge Road	Gaskets		14/9/2017	Due after six Months
e	CAMHS/Lodge Road,Basement,Plant Room,007-03-(-1)- 001	Flash Guard		14/9/2017	Due after six Months
e	CAMHS/Lodge Road,Basement,Plant Room,007-03-(-1)- 001	Residue		14/9/2017	Due after six Months
e	CAMHS/Lodge Road,Basement,Plant Room,007-03-(-1)- 001	Residue		14/9/2017	Due after six Months
e	CAMHS/Lodge Road,Basement,Plant Room,007-03-(-1)- 001	Residue		14/9/2017	Due after six Months
e	CAMHS/Lodge Road,Basement,Plant Room,007-03-(-1)- 001	Dust Debris		14/9/2017	Due after six Months
e	CAMHS/Lodge Road,Basement,Plant Room,007-03-(-1)- 001	Residue		14/9/2017	Due after six Months

**No Historical Events Pending** 





Type of Survey

This is a Management Survey (Standard Sampling, Identification and Assesment Survey).

For major refurbishments / Pre demolition a Refurbishment/ Demolition survey must be undertaken.

See Report for Details

DRAWING KEY

ASBESTOS PRESENT

PRESUMED TO CONTAIN ASBESTOS


NO ASBESTOS DETECTED

**OUTSIDE SCOPE OF SURVEY** 

**NOT ACCESSED AREAS** 

Rev Date Report by DWN CHK





Black Country Partnership NHS Foundation Trust Headquarters, Delta House Greets Green Road West Bromwich, West Midlands B70 9PL

AJK

Black Country Partnership NHS


NHS Foundation Trus

48 Lodge Road - Ground Floor Building Layout

18/11/2012

1:125

No: TAJ07-CAMHS-G



Type of Survey

This is a Management Survey (Standard Sampling, Identification and Assesment Survey).


For major refurbishments / Pre demolition a Refurbishment/ Demolition survey must be undertaken.

See Report for Details

ASBESTOS PRESENT
PRESUMED TO CONTAIN ASBESTOS
NO ASBESTOS DETECTED
OUTSIDE SCOPE OF SURVEY
NOT ACCESSED AREAS

Rev Date Report by DWN CHK





Black Country Partnership NHS Foundation Trust Headquarters, Delta House Greets Green Road West Bromwich, West Midlands B70 9PL


Black Country Partnership

NHS Foundation Trust


48 Lodge Road - First Floor Building Layout

Rev A


awn: AJK Date: Scale: DWG No: TAJ07-CAMHS-1



SECOND FLOOR







48 Lodge Road - Second Floor Building Layout

18/11/2012

AJK

DWG No: 1:60 TAJ07-CAMHS-2

