

Site Asbestos Compendium Summary

This compendium report is based on Site id: **95664**, Client Ref: , Account Ref No: **3074**

Monument Metro Station, Lisle Street, Newcastle upon Tyne, NE1 7AL


This Site Asbestos Compendium Summary report has been produced at the request of Tyne and Wear Metro T/a Nexus it is a summary of asbestos survey findings. Not all of this buildings or items within may have been surveyed for asbestos containing materials - check for exceptions below. Information in this report should not be regarded as an exhaustive inventory of all asbestos containing materials on these premises. Any proposed work of an intrusive nature in the vicinity of asbestos containing material as identified in this summary MUST in the first instance be referred to Tyne and Wear Metro T/a Nexus building and civil section.

This Compendium Asbestos report aims to be concise, yet comprehensive compilation of asbestos records relating to *Monument Metro Station, Lisle Street, Newcastle upon Tyne, NE1 7AL*. This compendium will summarize larger work shown in individual reports undertaken for jobs carried out on this site.

The full Site Asbestos Compendium report can be found at:

<https://web.lucion.co.uk/print/compendium/95664?s=b191bb621e5698c0f355f3dd4b3b411b>

Cover Photo




Most Recent Site Photo

Overview of Jobs carried out at this Site

Job ID	Job-Type	Start Date	Due Date
187918	Survey, Management		
376521	Air Test, Reassurance		
130404	Air Test, Management	Wednesday, 24th August, 2016	Friday, 26th August, 2016
144885	Bulk ID	Wednesday, 30th November, 2016	Friday, 9th December, 2016
224256	Air Test, Reassurance	Thursday, 12th October, 2017	Thursday, 19th October, 2017

Breakdown of Asbestos findings

⊖ Asbestos should be presumed to be present within Locations and Items not accessed until further assessment. 
Additional surveyor comments.

Head Office

E:

T:

Issuing Office:

[↓ Previous Asbestos Records](#)
[Most Recent Asbestos Records ↓](#)

Building: Chichester Metro Station				Level: -1	Location: 001/Main Sub		
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	FHC Breaker	insulating board	NAD	--	2 No.		 NAD
	FSC Breaker	insulating board	NAD	--	2 No.		 NAD
	FCH Breaker	insulating board	NAD	--	2 No.		 NAD
	FCS Breaker	insulating board	NAD	--	--		 NAD
	Breaker unit	debris	NAD	--	4 Sqm.		 NAD
	💬 Sampled at the request of the client						



Building: Moment Metro Station				Level: 0	Location: 001/Main Sub		
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	FMS Breaker	insulating board	NAD	--	2 No.		 NAD
	FMG Breaker	insulating board	NAD	--	2 No.		 NAD
	Breaker unit	debris	NAD	--	4 Sqm.		 NAD
	💬 Sample taken at the request of the client						
	Loose Board	insulating board	NAD	--	1 No.		 NAD
	💬 Not part of scope but sampled as was unknown to client.						









Building: Monument Metro Station (underground) Level: -3 Location: 001/Platform 1 Station Void							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Debris within void	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Debris within void	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Debris within void	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Debris to floor	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Debris to pipework	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Debris to cable tray	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Debris to cable trough	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
Building: Monument Metro Station (underground) Level: -3 Location: 002/Platform 2 Station Void							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Debris to floor	Loose Insulation	Chrysotile	10	--	--	 R1
	 (inspected during Survey, Survey, Management)						
	Debris to cable tray	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Pipe gasket	Paper, Felt & Cardboard	Chrysotile	3	--	--	R3

table continued from previous page...

Building: Monument Metro Station (underground) Level: -3 Location: 002/Platform 2 Station Void							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	 (inspected during Survey, Survey, Management)						
	Debris to pipework	No Asbestos Identified	NAD	--	--		
	 (inspected during Survey, Survey, Management)						NAD
	Debris within void	No Asbestos Identified	NAD	--	--		
	 (inspected during Survey, Survey, Management)						NAD
	Debris within void	No Asbestos Identified	NAD	--	--		
	 (inspected during Survey, Survey, Management)						NAD
	Debris within void	Loose Insulation	Amosite	11	--	--	
	 (inspected during Survey, Survey, Management)						R1

Building: Monument Metro Station (underground) Level: -3 Location: 003/Platform 3 Station Void							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Debris to cable tray	Loose Insulation	Amosite	11	--	--	
	 (inspected during Survey, Survey, Management)						R1
	Debris to floor	Loose Insulation	Amosite	11	--	--	
	 (inspected during Survey, Survey, Management)						R1
	Debris to cable tray	Loose Insulation	Amosite	11	--	--	
	 (inspected during Survey, Survey, Management)						R1
	Debris to cable tray	No Asbestos Identified	NAD	--	--		
	 (inspected during Survey, Survey, Management)						NAD
	Debris to pipework	Loose Insulation	Amosite	11	--	--	
	 (inspected during Survey, Survey, Management)						R1

Building: Monument Metro Station (underground)				Level: -2.5	Location: 001/Concourse ceiling void			
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record	
	Wetshield	Bitumen Products	Chrysotile	3	--	--	 R3	
	 (inspected during Survey, Survey, Management)							

Building: Monument Metro Station (underground)				Level: -2.5	Location: 002/Platform 1 canopy			
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record	
	Debris to canopy	No Asbestos Identified	NAD	--	--		 NAD	
	 (inspected during Survey, Survey, Management)							
	Debris to canopy	No Asbestos Identified	NAD	--	--		 NAD	
	 (inspected during Survey, Survey, Management)							
	Debris to canopy	No Asbestos Identified	NAD	--	--		 NAD	
	 (inspected during Survey, Survey, Management)							
	Wetshield	Bitumen Products	Chrysotile	3	--	--	 R3	
	 (inspected during Survey, Survey, Management)							








Building: Monument Metro Station (underground)				Level: -2.5	Location: 003/Platform 2 canopy			
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record	
	Debris to canopy	No Asbestos Identified	NAD	--	--		 NAD	
	 (inspected during Survey, Survey, Management)							
	Debris to canopy	No Asbestos Identified	NAD	--	--		 NAD	
	 (inspected during Survey, Survey, Management)							
	Debris to canopy	No Asbestos Identified	NAD	--	--		 NAD	
	 (inspected during Survey, Survey, Management)							

table continued from previous page...

Building: Monument Metro Station (underground)				Level: -2.5	Location: 003/Platform 2 canopy			
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record	
	Wetshield	Bitumen Products	Chrysotile	3	--	--	 R3	
	(inspected during Survey, Survey, Management)							


















Building: Monument Metro Station (underground)				Level: -2	Location: 001/Station platform 1 & 2			
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record	
	Panels to Fire extinguisher dry riser platform 1	No Asbestos Identified	NAD	--	--		 NAD	
	(inspected during Survey, Survey, Management)							
	Caulking to tunnel section (ENCAPSULATED)	Loose Insulation	Chrysotile, Amosite	6	--	--	 R3	
	(inspected during Survey, Survey, Management)							
	Debris to Fire extinguisher dry riser platform 2 (NOW REMOVED)	Loose Insulation	Amosite	2	--	--	 R3	
	(inspected during Survey, Survey, Management)							
	Panels to Fire extinguisher dry riser	No Asbestos Identified	NAD	--	--		 NAD	
	(inspected during Survey, Survey, Management)							
	Panels to Fire extinguisher dry riser platform 2	No Asbestos Identified	NAD	--	--		 NAD	
	(inspected during Survey, Survey, Management)							
	Debris to Fire extinguisher dry riser platform 2 (NOW REMOVED)	Loose Insulation	Amosite	2	--	--	 R3	
	(inspected during Survey, Survey, Management)							
	Caulking to tunnel section (ENCAPSULATED)	Loose Insulation	Chrysotile, Amosite	6	--	--	 R3	
	(inspected during Survey, Survey, Management)							
	Panels to Fire extinguisher dry riser platform 2	No Asbestos Identified	NAD	--	--		 NAD	
	(inspected during Survey, Survey, Management)							

table continued from previous page...

Building: Monument Metro Station (underground) Level: -2 Location: 001/Station platform 1 & 2							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Debris to Fire extinguisher dry riser platform 2 (NOW REMOVED)	Loose Insulation	Amosite	2	--	--	 R3
	(inspected during Survey, Survey, Management)						
	Caulking to tunnel section (ENCAPSULATED)	Loose Insulation	Chrysotile, Amosite	6	--	--	 R3
	(inspected during Survey, Survey, Management)						
	VE panels	Asbestos Insulating Board	--	--	--	--	 PRESUME
	(inspected during Survey, Survey, Management)						
	Panels to Fire extinguisher dry riser platform 1	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Debris to Fire extinguisher dry riser platform 1 (NOW REMOVED)	Loose Insulation	Amosite	2	--	--	 R3
	(inspected during Survey, Survey, Management)						
	Caulking to tunnel section (ENCAPSULATED)	Loose Insulation	Chrysotile, Amosite	6	--	--	 R3
	(inspected during Survey, Survey, Management)						
	Caulking to tunnel section (ENCAPSULATED)	Loose Insulation	Chrysotile, Amosite	6	--	--	 R3
	(inspected during Survey, Survey, Management)						
	Debris to Fire extinguisher dry riser platform 1(NOW REMOVED)	Loose Insulation	Amosite	2	--	--	 R3
	(inspected during Survey, Survey, Management)						
	Panels to Fire extinguisher dry riser platform 1	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
Building: Monument Metro Station (underground) Level: -2 Location: 002/Comms & Siggs room platform 2							
No reportable Items and Materials recorded at this Location							

Building: Monument Metro Station (underground) Level: -2 Location: 002/Comms & Siggs room platform 2 - within penetration panels							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Caulking to tunnel ring sections within penetration panel	Loose Insulation	Chrysotile	10	--	--	 R1
	(inspected during Survey, Survey, Management)						

Building: Monument Metro Station (underground) Level: -2 Location: 003/HV room							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Doorheader	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						

Building: Monument Metro Station (underground) Level: -2 Location: 004/Relay room							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Debris to floor	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Penetration panel	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						

Building: Monument Metro Station (underground) Level: -2 Location: 005/Lift machine room							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Panel to door	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						

Building: Monument Metro Station (underground) Level: -2 Location: 006/Comms & Siggs room platform 1							
No reportable Items and Materials recorded at this Location							


Building: Monument Metro Station (underground) Level: -2 Location: 006/Comms & Siggs room platform 1 - within penetration panels							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Caulking to tunnel ring sections within penetration panel	Loose Insulation	Chrysotile	10	--	--	 R1
	(inspected during Survey, Survey, Management)						


Building: Monument Metro Station (underground) Level: -2 Location: 007/Headwall beyond public platform							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Tunnel ring sections	Loose Insulation	Chrysotile	10	--	--	 R1
	 (inspected during Survey, Survey, Management)						





Building: Monument Metro Station (underground) Level: -1.5 Location: 001/Platform 3 canopy							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Wetshield	Bitumen Products	Chrysotile	3	--	--	 R3
	 (inspected during Survey, Survey, Management)						
	Debris to canopy	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Debris to canopy	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Debris to canopy	Loose Insulation	Chrysotile	10	--	--	 R1
	 (inspected during Survey, Survey, Management)						


Building: Monument Metro Station (underground) Level: -1.5 Location: 002/Platform 4 canopy							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Wetshield	Bitumen Products	Chrysotile	3	--	--	 R3
	 (inspected during Survey, Survey, Management)						
	Debris to canopy	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Debris to canopy	Loose Insulation	Chrysotile	10	--	--	 R1
	 (inspected during Survey, Survey, Management)						



table continued from previous page...



Building: Monument Metro Station (underground)				Level: -1.5	Location: 002/Platform 4 canopy			
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record	
	Debris to canopy	No Asbestos Identified	NAD	--	--		 NAD	
	💬 (inspected during Survey, Survey, Management)							

Building: Monument Metro Station (underground)				Level: -1	Location: 001/Escalator 1&2 maintenance corridor			
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record	
	Door surround	No Asbestos Identified	NAD	--	--		 NAD	
	💬 (inspected during Survey, Survey, Management)							

Building: Monument Metro Station (underground)				Level: -1	Location: 002/Escalator 1&2 maintenance tunnel			
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record	
	Caulking to tunnel section	Loose Insulation	Chrysotile, Amosite	10	--	--	 R1	
	💬 (inspected during Survey, Survey, Management)							
	Debris to top of stairs	No Asbestos Identified	NAD	--	--		 NAD	
	💬 (inspected during Survey, Survey, Management)							
	Debris to floor (NOW REMOVED)	Loose Insulation	Amosite	2	--	--	 R3	
	💬 (inspected during Survey, Survey, Management)							
	Debris to base of stairs (NOW REMOVED)	Loose Insulation	Chrysotile, Amosite	2	--	--	 R3	
	💬 (inspected during Survey, Survey, Management)							

Building: Monument Metro Station (underground)				Level: -1	Location: 003/Station undercroft			
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record	
	Whole location	No Access Gained	--	--	--			
	🚫 Limited Access: 💬 (inspected during Survey, Survey, Management)							

Building: Monument Metro Station (underground) Level: -1 Location: 004/Escalator 1&2 maintenance void							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Debris to floor	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						

Building: Monument Metro Station (underground) Level: -1 Location: 005/Escalator 1&2 maintenance void							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Debris to floor	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						















Building: Monument Metro Station (underground) Level: -1 Location: 006/Main relay room							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Debris to flat surfaces	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Debris to floor	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Debris to cable tray	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Debris to floor	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Penetration panels	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Debris within wall void	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						

table continued from previous page...

Building: Monument Metro Station (underground) Level: -1 Location: 006/Main relay room

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Debris to penetration panel void	No Asbestos Identified	NAD	--	--		
	(inspected during Survey, Survey, Management)						NAD
	Protective cover to cables	No Asbestos Identified	NAD	--	--		
	(inspected during Survey, Survey, Management)						NAD


Building: Monument Metro Station (underground) Level: -1 Location: 006/Main relay room - Penetration panels

No reportable Items and Materials recorded at this Location



Building: Monument Metro Station (underground) Level: -1 Location: 007/Cable tunnel entrance

No reportable Items and Materials recorded at this Location

Building: Monument Metro Station (underground) Level: -1 Location: 008/Escalator 3&4 maintenance area

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Wall panels	No Asbestos Identified	NAD	--	--		
	(inspected during Survey, Survey, Management)						NAD

Building: Monument Metro Station (underground) Level: -1 Location: 009/Monument track parallelling room

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Debris to floor	No Asbestos Identified	NAD	--	--		
	(inspected during Survey, Survey, Management)						NAD
	Penetration panels	No Asbestos Identified	NAD	--	--		
	(inspected during Survey, Survey, Management)						NAD

Building: Monument Metro Station (underground) Level: -1 Location: 010/Station platform 3 & 4


First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Tunnel caulking to tunnel ring section behind penetration panel platform 3	Loose Insulation	Chrysotile	10	--	--	
	(inspected during Survey, Survey, Management)						R1

table continued from previous page...










Building: Monument Metro Station (underground) Level: -1 Location: 010/Station platform 3 & 4							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Panels to Fire extinguisher dry riser	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Panels to Fire extinguisher dry riser platform 4	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Debris to Fire extinguisher dry riser platform 4	Loose Insulation	Amosite	11	--	--	 R1
	(inspected during Survey, Survey, Management)						
	VE panels	Asbestos Insulating Board	--	--	--	--	 PRESUME
	(inspected during Survey, Survey, Management)						
	Panels to Fire extinguisher dry riser	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Debris to Fire extinguisher dry riser platform 3	Loose Insulation	Amosite	11	--	--	 R1
	(inspected during Survey, Survey, Management)						
	Caulking to tunnel section	Loose Insulation	Chrysotile, Amosite	11	--	--	 R1
	(inspected during Survey, Survey, Management)						
	Caulking to tunnel section	Loose Insulation	Chrysotile, Amosite	11	--	--	 R1
	(inspected during Survey, Survey, Management)						
	Debris to Fire extinguisher dry riser platform 3	Loose Insulation	Amosite	11	--	--	 R1
	(inspected during Survey, Survey, Management)						

table continued from previous page...

Building: Monument Metro Station (underground) Level: -1 Location: 010/Station platform 3 & 4							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Panels to Fire extinguisher dry riser platform 3	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Caulking to tunnel section	Loose Insulation	Chrysotile, Amosite	11	--	--	 R1
	(inspected during Survey, Survey, Management)						

Building: Monument Metro Station (underground) Level: -1 Location: 011/Comms & Siggs room platform 4							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Caulking to tunnel ring sections behind penetration panel	Loose Insulation	Chrysotile	10	--	--	 R1
	(inspected during Survey, Survey, Management)						

Building: Monument Metro Station (underground) Level: -1 Location: 012/Comms & Siggs room platform 3							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Caulking to tunnel ring sections behind penetration panel	Loose Insulation	Chrysotile	10	--	--	 R1
	(inspected during Survey, Survey, Management)						




Building: Monument Metro Station (underground) Level: -1 Location: 013/Switch room							
No reportable Items and Materials recorded at this Location							

Building: Monument Metro Station (underground) Level: -1 Location: 014/Duct							
No reportable Items and Materials recorded at this Location							

Building: Monument Metro Station (underground) Level: 0 Location: 001/Ticket concourse							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Panel to fire extinguisher dry riser	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	VE panels	Asbestos Insulating Board	--	--	--	--	 PRESUME
	(inspected during Survey, Survey, Management)						

table continued from previous page...



Building: Monument Metro Station (underground) Level: 0 Location: 001/Ticket concourse

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Panel to fire extinguisher dry riser	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Panel within Fire indicator panel	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Panels to Fire extinguisher dry riser	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						


Building: Monument Metro Station (underground) Level: 0 Location: 002/Eldon square lift

No reportable Items and Materials recorded at this Location

Building: Monument Metro Station (underground) Level: 0 Location: 003/Travel centre

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Sink pad	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	VE panels	Asbestos Insulating Board	--	--	--	--	 PRESUME
	(inspected during Survey, Survey, Management)						

Building: Monument Metro Station (underground) Level: 0 Location: 004/Cleaners store

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Redundant VE panels	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						

Building: Monument Metro Station (underground) Level: 0 Location: 005/Staff corridor






First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Brown floor tiles	Composites	Chrysotile	3	--	--	 R3
	(inspected during Survey, Survey, Management)						

table continued from previous page...





Building: Monument Metro Station (underground) Level: 0 Location: 005/Staff corridor

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Wall panel	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						

Building: Monument Metro Station (underground) Level: 0 Location: 006/Cleaners cupboard

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Wall panels	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						



Building: Monument Metro Station (underground) Level: 0 Location: 007/Plant room stairwell

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Wall panels	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Penetration panel	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						

Building: Monument Metro Station (underground) Level: 0 Location: 008/Staff room

No reportable Items and Materials recorded at this Location

Building: Monument Metro Station (underground) Level: 0 Location: 009/Fan room

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Penetration panels	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						

Building: Monument Metro Station (underground) Level: 0 Location: 010/HV room









First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Floor Debris	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Floor Debris	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						

table continued from previous page...



Building: Monument Metro Station (underground) Level: 0 Location: 010/HV room

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Floor Debris	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Penetration Panels	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						






Building: Monument Metro Station (underground) Level: 0 Location: 011/Ops department

No reportable Items and Materials recorded at this Location

Building: Monument Metro Station (underground) Level: 0 Location: 012/Maintenance stairwell

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Wall panel	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						


Building: Monument Metro Station (underground) Level: 0 Location: 013/Relay room

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Wall egress panel	No Asbestos Identified	NAD	--	--		NAD
	 (inspected during Survey, Survey, Management)						
	Debris to distribution board	No Asbestos Identified	NAD	--	--		NAD
	 (inspected during Survey, Survey, Management)						
	Panel to riser	No Asbestos Identified	NAD	--	--		NAD
	 (inspected during Survey, Survey, Management)						
	Dust and Debris to floor	No Asbestos Identified	NAD	--	--		NAD
	 (inspected during Survey, Survey, Management)						
	Penetration panel to floor	No Asbestos Identified	NAD	--	--		NAD
	 (inspected during Survey, Survey, Management)						

Building: Monument Metro Station (underground) Level: 0 Location: 014/Relay room stairwell

No reportable Items and Materials recorded at this Location

Building: Monument Metro Station (underground) Level: 0 Location: 015/Male staff toilet

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Penetration panel	No Asbestos Identified	NAD	--	--		NAD
	 (inspected during Survey, Survey, Management)						









































Building: Monument Metro Station (underground) Level: 0 Location: 016/Female staff toilet							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Penetration panel	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
Building: Monument Metro Station (underground) Level: 0 Location: 017/Battery room							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Penetration Panel	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Debris to flat surfaces	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Boxing Penetration panel	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
Building: Monument Metro Station (underground) Level: 0 Location: 018/Maintenance stairwell							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Wall panel	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
Building: Monument Metro Station (underground) Level: 0 Location: 019/Female travel staff toilet							
No reportable Items and Materials recorded at this Location							
Building: Monument Metro Station (underground) Level: 0.5 Location: 001/Concourse ceiling void							
No reportable Items and Materials recorded at this Location							
Building: Monument Station (underground) Ventilation survey				Level: -1 Location: 006/Main relay room			
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Residue to ventilation grill	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Residue to ventilation ductwork	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						

table continued from previous page...


Building: Monument Station (underground) Level: -1 Location: 006/Main relay room Ventilation survey							
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Residue to ventilation ductwork	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Residue to fire dampner	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Residue to ventilation ductwork	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Residue to ventilation grill	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Residue to ventilation grill	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Residue to ventilation ductwork	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Residue to ventilation ductwork	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Residue to ventilation ductwork	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Residue to ventilation ductwork	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						

Building: Monument Station (underground) Ventilation survey				Level: 0	Location: 005/Staff corridor		
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Bitumen to concrete deckhead	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Residue to ventilation duct FD01	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Residue to ventilation duct FD02	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Composite residue sample to flat surfaces	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Residue to ventilation duct FD04	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Residue to ceiling below penetration FD04	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Residue to ventilation duct FD06	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Penetration panel to wall	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						

Building: Monument Station (underground)
Ventilation survey

Level: 0





Location: 006/Cleaners cupboard

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Residue to ventilation duct FD08	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						

Building: Monument Station (underground)
Ventilation survey

Level: 0




Location: 008/Staff room

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Penetration panel to wall	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Gasket to duct hanger	Paper, Felt & Cardboard	Chrysotile	4	--	--	 R3
	(inspected during Survey, Survey, Management)						
	Residue to ventilation grill	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Residue to ventilation duct	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						


Building: Monument Station (underground)
Ventilation survey


Level: 0





Location: 009/Fan room

First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Penetration panel to floor	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Residue to ventilation ductwork	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						
	Residue to fire dampner	No Asbestos Identified	NAD	--	--		 NAD
	(inspected during Survey, Survey, Management)						

Building: Monument Station (underground)				Level: 0	Location: 010/HV room			
Ventilation survey								
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record	
	Residue to ventilation grill	No Asbestos Identified	NAD	--	--			
	 (inspected during Survey, Survey, Management)						NAD	
	Debris to fire dampner	No Asbestos Identified	NAD	--	--			
	 (inspected during Survey, Survey, Management)						NAD	
	Residue to ventilation ductwork	No Asbestos Identified	NAD	--	--			
	 (inspected during Survey, Survey, Management)						NAD	
	Penetration panel to wall	No Asbestos Identified	NAD	--	--			
	 (inspected during Survey, Survey, Management)						NAD	

Building: Monument Station (underground)				Level: 0	Location: 013/LV room			
Ventilation survey								
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record	
	Residue to ventilation duct FD01	No Asbestos Identified	NAD	--	--			
	 (inspected during Survey, Survey, Management)						NAD	
	Residue to ventilation duct FD02	No Asbestos Identified	NAD	--	--			
	 (inspected during Survey, Survey, Management)						NAD	
	Residue to ventilation grill FD02	No Asbestos Identified	NAD	--	--			
	 (inspected during Survey, Survey, Management)						NAD	

Building: Monument Station (underground)				Level: 0	Location: 019/Female travel staff toilet			
Ventilation survey								
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record	
	Residue to ventilation grill	No Asbestos Identified	NAD	--	--			
	 (inspected during Survey, Survey, Management)						NAD	

Building: Monument Station (underground) Ventilation survey							
Level: 0				Location: 020/Draft relief room			
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Debris to floor	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						
	Residue to ventilation duct	No Asbestos Identified	NAD	--	--		 NAD
	 (inspected during Survey, Survey, Management)						