



**ENVIRONMENTAL CONSULTANTS LTD**

---

**Report No: AR/04/1677 (Update 06)**

**Page 1 of 21**

**CRAMLINGTON HILLCREST SCHOOL,  
EAST VIEW AVENUE  
CRAMLINGTON, NE23 9DY**



**UPDATED ASBESTOS REGISTER FROM VEGA REPORT  
AR/04/1677  
UPDATED BY ASBESTOS MANAGER – RON BROWN  
UPDATE NUMBER 06**

---

***Registered Office:* Church Buildings, Station Road, Seaton Delaval,  
Whitley Bay, TYNE & WEAR, NE25 0PT  
Tel: (0191) 298 0198 Fax: (0191) 298 0199**

Visit our Web-site at: <http://www.vegaec.co.uk>

## Contents

	<i>Page No</i>
Introduction	3
Asbestos Register	4-9
Report Summary	10-21
Appendices	
Appendix A – Survey Report Data Record Sheets	
Appendix B – Material Algorithm	
Appendix C – Bulk analysis and sample locations.	
Appendix D – Asbestos Management Plan	

**CONFIDENTIAL**

**ASBESTOS SURVEY REPORT**

Page 3 of 21

**INTRODUCTION**

**Report No:** AR/04/1677 (Update 06)

**Date of Issue:** 08/03/18

**Client:** Mr R Brown  
Northumberland County Council  
County Hall  
Morpeth  
Northumberland  
NE61 2EF

**Clients Order No:** -

**Date(s) of Survey:** 15/10/04

**Establishment Surveyed:** Cramlington  
Hillcrest School, East View Avenue,  
Cramlington, NE63 9DY

**Area(s) Surveyed:** All accessible areas.

**Type of Survey:** Type 2 - Standard Sampling, Identification and Assessment, (see Additional Information section for definition)

**Purpose, Aims and Objectives**

This survey was undertaken to establish the presence and nature of asbestos based materials in the area(s) surveyed. Surveying, sampling and assessment of asbestos-containing materials was carried out in accordance with MDHS 100: July 2001.

Representative bulk and - if applicable - air samples were taken from the locations detailed in the following pages of this report. The bulk samples were subject to a careful cleaning procedure involving disintegration of the sample, acid washing, solvent washing, filtration etc., in order to expose fibres in a form suitable for microscopic analysis. Analysis was carried out in accordance with MDHS 77: June 1994 by documented in-house procedures.

Vega Environmental Consultants Ltd cannot accept responsibility for any errors or misinterpretations introduced into a survey, or any resulting conclusions, as a result of a reduced sampling frequency specified by a client.








This survey attempts to identify all asbestos materials within the agreed scope of work. However, as asbestos materials can be completely hidden/buried within a structure, VEGA cannot accept responsibility for additional materials that may be identified at a later date.

**Checked by: Mr. R. Brown**  
*Asbestos Manager*

## ASBESTOS REGISTER – MATERIAL ASSESSMENT

Report No AR/04/1677 (Update 06)










Page 4 of 21

Area Id	Location of sample point/ Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Action
Ground Floor, Entrance Lobby	Columns – metal – no access	P	-	
Ground Floor, Corridor 2	Wall mounted heater – bitumen coating to heater	ID	BS/02	REMOVED FEB 2015
Ground Floor, Corridor 2	Columns – metal – no access	P	-	
Ground Floor, Void Above Corridor 2	Skylight – to ceiling tiles AIB debris	ID	BS/15	REMOVED 2005
Ground Floor, Headmasters' Office	Columns – metal – no access	P	-	
Ground Floor, Store Cupboard 1	Column – metal – no access	P	-	
Ground Floor, Office 1	Columns – metal – no access	P	-	
Ground Floor, Male Staff Toilet	Skylight – panel	ID	BS/04	REMOVED 2005
Ground Floor, Male Staff Toilet	Column – metal – no access	P	-	
Ground Floor, Male Staff Toilet	Toilet Cistern	ID	BS/05	REMOVED MAR 2005
Ground Floor, Void Above Male Staff Toilet	Debris from broken skylight panels to back of ceiling	SP	As BS/04	REMOVED 2005
Ground Floor, Female Staff Toilet	Skylight – panel	SP	As BS/04	REMOVED 2005
Ground Floor, Female Staff Toilet	Column – metal – no access	P	-	
Ground Floor, Female Staff Toilet	Toilet Cistern	SP	As BS/05	REMOVED MAR 2005

## ASBESTOS REGISTER – MATERIAL ASSESSMENT

Report No AR/04/1677 (Update 06)

Page 5 of 21

Area Id	Location of sample point/ Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Action
Ground Floor, Void Above, Female Staff Toilet	Debris from broken skylight panel to back of ceiling	SP	As BS/04	REMOVED 2005
Ground Floor, Staff Room	Columns – metal – no access	P	-	
Ground Floor, Foyer	Columns – metal – no access	P	-	
Ground Floor, Foyer	Wall mounted heaters	SP	As BS/02	REMOVED FEB 2015
Ground Floor, Void Above Foyer	Debris from broken skylight panels to back of ceiling	SP	As BS/04	REMOVED 2005
Ground Floor, Hall	Columns – metal – no access	P	-	
Ground Floor, Hall	Wall mounted heaters	SP	As BS/02	REMOVED FEB 2015
Ground Floor, Classroom 18	Columns – metal – no access	P	-	
Ground Floor, Store Room 19	Columns – metal – no access	P	-	
Ground Floor, Store Room 20	Columns – metal – no access	P	-	
Ground Floor, Hall Store	Columns – metal – no access	P	-	
Ground Floor, Changing Room	Columns – metal – no access	P	-	
Ground Floor, Changing Room	Wall mounted heater	SP	As BS/02	

## ASBESTOS REGISTER – MATERIAL ASSESSMENT

Report No AR/04/1677 (Update 06)





Page 6 of 21

Area Id	Location of sample point/ Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Action
Ground Floor, Changing Room Toilet	Skylight – panel	SP	As BS/04	REMOVED 2005
Ground Floor, Changing Room Toilet	Columns – metal – no access	P	-	G
Ground Floor, Void Above Changing Room	Debris from broken skylight panel to back of ceiling	SP	As BS/04	REMOVED 2005
Ground Floor, Shower Room2	Columns – metal – no access	P	-	G
Ground Floor, Photocopier Room	Columns – metal – no access	P	-	G
Ground Floor, Classroom 22	Columns – metal – no access	P	-	G
Ground Floor, Void Above Classroom 22	Debris from broken skylight panel to back of ceiling	SP	As BS/04	REMOVED 2005
Ground Floor, Classroom 23	Columns – metal – no access	P	-	G
Ground Floor, Void Above Classroom 23	Tiles – debris on top	SP	As BS/04	REMOVED 2005
Ground Floor, Store Room 24	Column – metal – no access	P	-	G
Ground Floor, Quite Room	Column – metal – no access	P	-	G
Ground Floor, Classroom 25	Columns – metal – no access	P	-	G
Ground Floor, Void Above Classroom 25	Debris from broken skylight panel to back of ceiling	SP	As BS/04	REMOVED 2005

## ASBESTOS REGISTER – MATERIAL ASSESSMENT

Report No AR/04/1677 (Update 06)









Page 7 of 21

Area Id	Location of sample point/ Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Action
Ground Floor, Store Room 26	Columns – metal – no access	P	-	
Ground Floor, Library	Skylight – panel	SP	As BS/04	REMOVED 2005
Ground Floor, Library	Columns – metal – no access	P	-	
Ground Floor, Corridor 1	Columns – metal – no access	P	-	
Ground Floor, Corridor 1	Wall mounted heaters	SP	As BS/02	REMOVED FEB 2015
Ground Floor, Girls' Toilet	Skylights – panels	SP	As BS/04	REMOVED 2005
Ground Floor, Void Above Girls' Toilet	Debris from broken skylight to back of ceiling	SP	As BS/04	REMOVED 2005
Ground Floor, Void Above Girls' Changing Room	Debris from broken skylight to back	SP	As BS/04	REMOVED 2005
Ground Floor, Classroom 29	Column – metal – no access	P	-	
Ground Floor, Void Above Classroom 29	Debris from broken skylight panel to back of ceiling	SP	As BS/04	REMOVED 2005
Ground Floor, Classroom 35	Columns – metal – no access	P	-	
Ground Floor, Void Above Classroom 35	Debris from broken skylight panel to back of ceiling	SP	As BS/04	REMOVED 2005
Ground Floor, Store Room 34	Column – metal – no access	P	-	

## ASBESTOS REGISTER – MATERIAL ASSESSMENT

Report No AR/04/1677 (Update 06)

Page 8 of 21







Area Id	Location of sample point/ Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Action
Ground Floor, Classroom 34	Skylights – panels	SP	As BS/04	REMOVED 2005
Ground Floor, Store Room 33	Columns – metal – no access	P	-	
Ground Floor, Classroom 36	Columns – metal – no access	P	-	
Ground Floor, Void Above, Classroom 36	Debris from broken skylight panel to back of ceiling	SP	As BS/04	REMOVED 2005
Ground Floor, Store Room 38	Columns – metal – no access	P	-	
Ground Floor, Boys' Toilet	Skylights – panels	SP	As BS/04	REMOVED 2005
Ground Floor, Void Above Boys' Toilet	Debris from broken skylight panel to back of ceiling	SP	As BS/04	REMOVED 2005
Ground Floor, Classroom 39	Columns – metal – no access	P	-	
Ground Floor, Void Above Classroom 39	Tiles – debris on top	SP	As BS/04	REMOVED 2005
Ground Floor, Store Room 37	Column – metal – no access	P	-	
Ground Floor, Store Room 40	Column – metal – no access	P	-	
Ground Floor, Kitchen	Skylights – panels	SP	As BS/04	REMOVED 2005
Ground Floor, Kitchen	Column – metal – no access	P	-	
Ground Floor, Kitchen	Kitchen, Deep Fat Fryer - Panel	ID	BS/01 Appendix B Report No. AR/05/0713	



## ASBESTOS REGISTER – MATERIAL ASSESSMENT

Report No AR/04/1677 (Update 06)



Page 9 of 21




Area Id	Location of sample point/ Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Action
Ground Floor, Kitchen	Heaters	P	-	
Ground Floor, Kitchen	Steam heated oven – rope gasket	ID	BS/14	REMOVED AUG 2006
Ground Floor, Vegetable Store	Skylight – panel	SP	As BS/04	REMOVED 2005
Ground Floor, Vegetable Store	Column – metal – no access	P	-	
Ground Floor, Staff Office	Skylight – panels	SP	As BS/04	REMOVED 2005
Ground Floor, Staff Office	Column – metal – no access	P	-	
Ground Floor, Void Above Staff Office	Debris from broken skylight panel to back of ceiling	SP	As BS/04	REMOVED 2005
Ground Floor, Staff Room	Entrance to Tank Room – panels	SP	As BS/04	REMOVED 2005
Ground Floor, Staff Toilet	Toilet cistern	SP	As BS/05	
Ground Floor, Larder	Skylight – panels	SP	As BS/04	REMOVED 2005
Ground Floor, Larder	Column – metal – no access	P	-	
Ground Floor, Larder	Pipe riser – panel	SP	As BS/04	REMOVED 2005
Ground Floor, Exit Lobby	Columns – metal – no access	P	-	

## ASBESTOS REGISTER – MATERIAL ASSESSMENT

Report No AR/04/1677 (update 04)

Page 10 of 21

Area Id	Location of sample point/ Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Action
Ground Floor, Room 11	Columns – metal – no access	P	-	
Ground Floor, Boiler Room	Ceiling – tiles	ID	BS/18	REMOVED 2005
Ground Floor, Boiler Room	Burner gasket	ID	BS/19	REMOVED 2010
Ground Floor, Boiler Room	Boiler front – rope gasket	ID	BS/20	REMOVED 2010
Ground Floor, Boiler Room	Boiler – internal segments – no access	P	-	REMOVED 2010
Ground Floor, Boiler Room	Flue Pipe penetration – rope gasket	SP	As BS/20	REMOVED 2010
Ground Floor, Boiler Room	Adjacent doorway – redundant panel	SP	As BS/18	REMOVED 2005
Ground Floor, Void Above Boiler Room	Ceiling – asbestos tiles – no access	P	-	REMOVED 2005
Ground Floor, Caretakers Office	Insulation board panel to wall	SP	As BS/04	

CODE	ACTION
	Remove ASAP
	Repair/Encapsulate ASAP
	Leave Undisturbed and Monitor Situation

## **REPORT SUMMARY**

**Report No:** AR/04/1677 (Update 06)

**Survey Specification:**


**Type 2 Survey:**

**Definition:** **Type 2 Survey (Standard Sampling, Identification and Assessment):** The analyst will do a general walk around the whole area and look at all readily accessible areas. From his experience the analyst will attempt to identify any asbestos and/or asbestos products without the need for sampling. The areas will be assessed and where appropriate will be **presumed** to contain asbestos. Where it appears highly likely that materials will contain asbestos, there should be a **strong presumption** that it does. All materials, which are presumed to contain asbestos, must be assessed using the Material Assessment Algorithm. Where practicable representative samples will be taken from all materials in accordance with full sampling frequency recommendations and analysed. Sample points will be made safe but redecoration will not be carried out. (see Appendix A)

On 15 October 2004, a type 2 survey was carried out at Cramlington Hillcrest School, East View Avenue, Cramlington, Northumberland. The premises surveyed were erected in the 1970's, of a one storey construction with a flat roof and pebbledash over brick walls.

The purpose of the survey was to identify and report on the presence and condition of asbestos based materials.

### **GROUND FLOOR**



**Entrance Lobby** – metal columns were inaccessible, therefore, we must presume they contain asbestos. It is recommended a closer inspection be undertaken prior to invasive maintenance works. Surveying experience of similar building constructions has identified AIB material inside these metal columns. Often this material cannot easily be found until demolition or major refurbishment works.

Similar metal columns can be found in Corridors 1 and 2, Head Masters' Office, Store Cupboard 1, Office 1, Male and Female Staff Toilets, Staff Room, Foyer, Hall, Classrooms 18, 22, 23, 25, 29, 35, 36 and 39, Store Rooms 19, 20, 24, 26, 33, 34, 37, 38 and 40, Hall Store, Changing Room, Changing Room Toilet, Shower Rooms 1 and 2, Photocopier Room, Quiet Room, Library, Kitchen, Vegetable Store, Staff Office, Larder, Exit Lobby and Room 11.

Level of ID	Sample ID	Extent (m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
P	-	<1m <sup>2</sup>	2	0	0	2	4	IA	A3

**ADDITIONAL INFORMATION: Report No: AR/04/1677 (Update 06)****GROUND FLOOR**

Corridor 2 – wall mounted heater, bitumen coating to motor is an asbestos containing material (ACM sample BS/02). It is in good condition and recommended it be left undisturbed and monitored. Similar wall mounted heaters can be found in the Hall, Foyer and Corridor 1.

**ALL ABOVE REMOVED FEB 2015**

Still 1 heater in changing room

Level of ID	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
ID	BS/02	<0.25m <sup>2</sup>	1	0	0	1	2	OA	A3



Void Above Corridor 2 – Skylight AIB debris. Removal is recommended as soon as possible.

**REMOVED 2005**

Level of ID	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
ID	BS/15	80 m <sup>2</sup>	2	3	2	2	9	IA	REMOVED 2005

**ADDITIONAL INFORMATION: Report No: AR/04/1677 (update 04)****GROUND FLOOR**

Male Staff Toilet – Skylight panel is an ACM (sample BS/04). It is in good condition and recommended it be left undisturbed and monitored. Similar skylight panels can be found in the Female Staff Toilet, Changing Room, Library, Boys' and Girls' Toilets, Classroom 34, Kitchen, Vegetable Store, Staff Office, Larder and Entrance to Tank Room. Similar panels can also be found to the pipe riser in Larder.

**REMOVED 2005**

Level of ID	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
ID	BS/04	4m <sup>2</sup>	2	0	1	2	5	OA	REMOVED 2005



Staff Toilet– toilet cistern is an ACM (sample BS/05). It is in good condition and recommended it be left undisturbed and monitored.

Level of ID	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
ID	BS/05	<0.5m <sup>2</sup>	1	0	0	2	3	EA	A3

**ADDITIONAL INFORMATION: Report No: AR/04/1677 (Update 06)**

**GROUND FLOOR**



Void Above Male Staff Toilet – debris from broken skylight panels to back of ceiling is an ACM (sample As BS/04). Removal is recommended as soon as possible. Similar debris from broken skylight panels to back of ceiling can be found in the Voids Above Female Staff Toilet, Foyer, Changing Room Toilet, Classrooms 22, 25, 29, 36 and 39, Girls' and Boys' Toilet, Girls' Changing Room, and Staff Office.

**REMOVED 2005**



Void Above Classroom 22 – AIB debris on top of tiles.

**REMOVED 2005**

Level of ID	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
SP	As BS/04	<0.5m <sup>2</sup>	2	2	3	2	9	OA	REMOVED 2005



**ADDITIONAL INFORMATION: Report No: AR/04/1677 (update 04)**

**GROUND FLOOR**



Kitchen – heaters were inaccessible, therefore, we must presume they contains asbestos. It is recommended a closer inspection be undertaken prior to invasive maintenance works.

Level of ID	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<i>P</i>	-	<i>&lt;0.5m<sup>2</sup></i>	<i>2</i>	<i>0</i>	<i>2</i>	<i>2</i>	<i>6</i>	<i>IA</i>	<i>A3</i>



Kitchen – steam heated oven, rope gasket to door is and ACM (sample BS/14). Although the material assessment is low, consideration should be given to replacement with a non asbestos material.

**REMOVED AUGUST 2006**

Level of ID	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<i>ID</i>	<i>BS/14</i>	<i>1m</i>	<i>2</i>	<i>0</i>	<i>2</i>	<i>1</i>	<i>5</i>	<i>EA</i>	<i>A2</i>

**ADDITIONAL INFORMATION: Report No: AR/04/1677 (Update 06)****GROUND FLOOR**

Boiler Room – ceiling panels are an ACM (sample BS/18). They are in fair condition and recommended they be left undisturbed and monitored.

**REMOVED 2005**

Level of ID	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
ID	BS/18	22m <sup>2</sup>	2	2	1	2	4	OA	REMOVED 2005



Boiler Room – burner gasket is an ACM (sample BS/19). It is in good condition and recommended it be left undisturbed and monitored.

**REMOVED SUMMER 2010**

Level of ID	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
ID	BS/19	0.25m <sup>2</sup>	1	0	0	1	2	EA	A3



**ADDITIONAL INFORMATION: Report No: AR/04/1677 (Update 06)**

**GROUND FLOOR**



Boiler Room – boiler front rope gasket is an ACM (sample BS/20). This material should be paint sealed for it to remain in place. Similar rope gasket can be found in the, flue pipe penetration, through to boiler housing.

REMOVED SUMMER 2010

Level of ID	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
ID	BS/20	1m	2	1	2	1	6	EA	A2




Boiler Room - boiler internal segments were inaccessible, therefore, we must presume they contain asbestos. It is recommended a closer inspection be undertaken prior to invasive maintenance works.

REMOVED SUMMER 2010

Level of ID	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
P	-	<0.25m <sup>2</sup>	2	0	1	1	4	IA	A3

**ADDITIONAL INFORMATION: Report No: AR/04/1677 (Update 06)**

**GROUND FLOOR**



Boiler Room – redundant panel adjacent doorway is an ACM (as sample BS/18). Removal is recommended as soon as possible.

**REMOVED 2005**

Level of ID	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
SP	As BS/18	<0.5m <sup>2</sup>	2	1	2	2	7	EA	REMOVED 2005




Caretaker's Office – insulation board panel to wall is an ACM (as sample BS/04). It is in good condition and recommended it be left undisturbed and monitored.

Level of ID	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
ID	BS/04	1.5m <sup>2</sup>	2	0	1	2	5	OA	A3

**Report No:** AR/04/1677 (Update 06)

**DRAWING TO DEPICT ASBESTOS CONTAINING MATERIALS  
AND ASBESTOS SAMPLE POINT LOCATIONS**


**GROUND FLOOR**



**Report No:** AR/04/1677 (Update 06)

**DRAWING TO DEPICT ASBESTOS CONTAINING MATERIALS  
AND ASBESTOS SAMPLE POINT LOCATIONS**


**GROUND FLOOR, BOILER ROOM**




**Report No:** AR/04/1677 (Update 06)

**DRAWING TO DEPICT ASBESTOS CONTAINING MATERIALS  
AND ASBESTOS SAMPLE POINT LOCATIONS**

**GROUND FLOOR  
Diagram to depict metal columns**



**Key -**       Metal columns – no access, presumed to contain asbestos

# VEGA ENVIRONMENTAL CONSULTANTS LTD

## APPENDIX A

## ASBESTOS SURVEY - DATA RECORD SHEET

Page 1 of 54

**Report No:** AR/04/1677 (Update 06)

**Contact:** Mr R Brown

**Date of survey:** 15/10/04

**Client:** Northumberland County Council

**Survey Type:** 2

**Analyst:** M Peterson and C Johnston

**Site Location:** Cramlington Hillcrest School, East View Avenue, Cramlington, Northumberland

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR</b>												
Entrance Lobby	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plaster over brick and wood	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 4 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Floor – vinyl tiles over concrete	ID	BS/01	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 2 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Void Above	Yes	Roof – corrugated metal	SP	-	-	-	-	-	NA	-	-	-
		Pipe insulation – foam	SP	-	-	-	-	-	NA	-	-	-
		Walls – polystyrene foam over concrete	SP	-	-	-	-	-	NA	-	-	-
Corridor 2	Yes	Ceiling- MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		<i>Wall mounted heater – bitumen coating to motor</i>	<i>ID</i>	<i>BS/02</i>	<i>&lt;0.25m<sup>2</sup></i>	<i>1</i>	<i>0</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>OA</i>	<i>REMOVED FEB 2015</i>
		<i>Columns x 4 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Notice boards x 3	SP	As BS/01	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 3 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Void Above	Yes	Roof – corrugated metal	SP	-	-	-	-	-	NA	-	-	-
		Pipe insulation – foam	SP	-	-	-	-	-	NA	-	-	-
		Walls – polystyrene over concrete	SP	-	-	-	-	-	NA	-	-	-
		<i>Skylight – AIB debris to back of ceiling tiles</i>	<i>P</i>	<i>As BS/15</i>	<i>8m2</i>	<i>2</i>	<i>3</i>	<i>2</i>	<i>2</i>	<i>9</i>	<i>IA</i>	<b>REMOVED 2005</b>
		Skylights x 3 – wood panels	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation



**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 4 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Headmasters' Office	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		Notice boards x 2	SP	-	-	-	-	-	NA	-	-	-
		Window – panel below	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 4 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Floor – carpet over concrete	SP	-	-	-	-	-	NA	-	-	-
Void Above	Yes	Roof – corrugated metal	SP	-	-	-	-	-	NA	-	-	-
		Pipe insulation – foam	SP	-	-	-	-	-	NA	-	-	-
		Walls – polystyrene over concrete	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 5 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Store Cupboard 1	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		<i>Column – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		Door – wood panel above	SP	-	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	ID	BS/03	-	-	-	-	NA	-	-	-
Office 1	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 3 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Walls – plasterboard over brick	SP	-	-	-	-	-	NA	-	-	-
		Floor – carpet over concrete	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 6 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Male Staff Toilet	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		<i>Skylight – panel</i>	<i>ID</i>	<i>BS/04</i>	<i>4m<sup>2</sup></i>	<i>2</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>5</i>	<i>OA</i>	<b>REMOVED 2005</b>
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		<i>Column – metal – no access</i>	<i>P</i>	<i>-</i>	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<b>A3</b>
		<i>Toilet cistern</i>	<i>ID</i>	<i>BS/05</i>	<i>&lt;0.5m<sup>2</sup></i>	<i>1</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>3</i>	<i>EA</i>	<b>REMOVED MAR 2005</b>
		Floor – vinyl tiles over concrete	ID	BS/06	-	-	-	-	NA	-	-	-
Void Above	Yes	<i>Debris from broken skylight panels to back of ceiling tiles</i>	<i>SP</i>	<i>As BS/04</i>	<i>8m<sup>2</sup></i>	<i>2</i>	<i>3</i>	<i>2</i>	<i>2</i>	<i>9</i>	<i>OA</i>	<b>REMOVED 2005</b>

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 7 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Female Staff Toilet	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		<i>Skylight – panel</i>	<i>SP</i>	<i>As BS/04</i>	<i>4m<sup>2</sup></i>	<i>2</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>5</i>	<i>OA</i>	REMOVED 2005
		Wall – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		<i>Column – metal – no access</i>	<i>P</i>	<i>-</i>	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		<i>Toilet cistern</i>	<i>SP</i>	<i>As BS/05</i>	<i>&lt;0.5m<sup>2</sup></i>	<i>1</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>3</i>	<i>EA</i>	REMOVED MAR 2005
		Floor – vinyl tiles over concrete	SP	As BS/06	-	-	-	-	NA	-	-	-
Void Above	Yes	<i>Debris from broken skylight panels to back of ceiling tiles</i>	<i>SP</i>	<i>As BS/04</i>	<i>8m<sup>2</sup></i>	<i>2</i>	<i>3</i>	<i>2</i>	<i>2</i>	<i>9</i>	<i>OA</i>	REMOVED 2005

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 8 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Staff Room	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard and wood over brick	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 5 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Sink – vibration pad below	ID	BS/07	-	-	-	-	NA	-	-	-
		Water boiler	SP	-	-	-	-	-	NA	-	-	-
		Floor – wood over concrete	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 9 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Foyer	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 13 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Skylights x 6 – wood panels	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard and plastic	SP	-	-	-	-	-	NA	-	-	-
		Door – wood panel below	SP	-	-	-	-	-	NA	-	-	-
		Notice boards x 6	SP	-	-	-	-	-	NA	-	-	-
		<i>Wall mounted heaters</i>	<i>SP</i>	<i>As BS/02</i>	<i>&lt;0.25m<sup>2</sup></i>	<i>1</i>	<i>0</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>OA</i>	<i>REMOVED FEB 2015</i>
		Floor – vinyl tiles over concrete	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 10 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Void Above	Yes	<i>Debris from broken skylight panels to back of ceiling tiles</i>	<i>SP</i>	<i>As BS/04</i>	<i>8M<sup>2</sup></i>	<i>2</i>	<i>3</i>	<i>2</i>	<i>2</i>	<i>9</i>	<i>OA</i>	<b>REMOVED 2005</b>
Hall	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plaster over brick	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 19 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Notice boards x 3	SP	-	-	-	-	-	NA	-	-	-
		<i>Wall mounted heaters x 3</i>	<i>SP</i>	<i>As BS/02</i>	<i>&lt;0.25m<sup>2</sup></i>	<i>1</i>	<i>0</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>OA</i>	<b>REMOVED FEB 2015</b>
		Door – wood panels above	SP	-	-	-	-	-	NA	-	-	-
		Floor – wood over concrete	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 11 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Classroom 18	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Skylights x 3 – wood panels	SP	-	-	-	-	-	NA	-	-	-
		Walls – plaster over brick	SP	-	-	-	-	-	NA	-	-	-
		Notice board	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 3 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Floor – carpet over concrete	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation



**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 12 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Store Room 19	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 4 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Floor – vinyl tiles over concrete	SP	As BS/03	-	-	-	-	NA	-	-	-
Store Room 20	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 4 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Floor – carpet over vinyl tiles and concrete	SP	As BS/03	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 13 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUD FLOOR (cont)</b>												
Hall Store	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard over brick	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 8 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Windows – panels to side	SP	As BS/09	-	-	-	-	NA	-	-	-
		Columns – wood panels to side	SP	-	-	-	-	-	NA	-	-	-
		Door – wood panels above	SP	-	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	SP	As BS/03	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 14 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Changing Room	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard and plastic	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 6 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Window – panels to side	SP	As BS/09	-	-	-	-	NA	-	-	-
		Columns – wood panels to side	SP	-	-	-	-	-	NA	-	-	-
		<i>Wall mounted heater</i>	<i>SP</i>	<i>As BS/02</i>	<i>&lt;0.25m<sup>2</sup></i>	<i>1</i>	<i>0</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>OA</i>	<i>A3</i>
		Door – wood panel above	SP	-	-	-	-	-	NA	-	-	-
		Floor – rubber tiles over concrete	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 15 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Changing Room Toilet	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		<i>Skylight – panel</i>	<i>SP</i>	<i>As BS/04</i>	<i>4m<sup>2</sup></i>	<i>2</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>5</i>	<i>OA</i>	<b>REMOVED 2005</b>
		Walls – plasterboard and plastic	SP	-		-	-	-	NA	-	-	-
		Window – panels to side	ID	BS/09	-	-	-	-	NA	-	-	-
		<i>Column – metal – no access</i>	<i>P</i>	<i>-</i>	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Columns – wood panels to side	SP	-	-	-	-	-	NA	-	-	-
		Toilet cistern	SP	-	-	-	-	-	NA	-	-	-
		Floor – rubber tiles over concrete	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 16 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Void Above	Yes	<i>Debris from broken skylight panel to back of ceiling tiles</i>	<i>SP</i>	<i>As BS/04</i>	<i>8m<sup>2</sup></i>	<i>2</i>	<i>3</i>	<i>2</i>	<i>2</i>	<i>9</i>	<i>OA</i>	<b>REMOVED 2005</b>
Shower Room 1	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 4 – metal – no access</i>	<i>P</i>	<i>-</i>	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Walls – ceramic tiles over plasterboard	SP	-	-	-	-	-	NA	-	-	-
		Floor – rubber tiles over concrete	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 17 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Shower Room 2	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 4 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Walls – ceramic tiles over plasterboard and brick	SP	-	-	-	-	-	NA	-	-	-
		Floor – concrete	SP	-	-	-	-	-	NA	-	-	-
Photocopier Room	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 4 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Notice board	SP	-	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	ID	BS/10	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 18 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Classroom 22	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Skylights x 2 – wood panels	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard over brick	SP	-	-	-	-	-	NA	-	-	-
		Window - panels to sides	SP	As BS/09	-	-	-	-	NA	-	-	-
		Notice boards x 2	SP	-	-	-	-	-	NA	-	-	-
		<b><i>Columns x 5 – metal – no access</i></b>	<b><i>P</i></b>	-	<b><i>&lt;1m<sup>2</sup> per column</i></b>	<b><i>2</i></b>	<b><i>0</i></b>	<b><i>0</i></b>	<b><i>2</i></b>	<b><i>4</i></b>	<b><i>IA</i></b>	<b><i>A3</i></b>
		Wall mounted heaters	SP	-	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	SP	As BS/03	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 19 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Void Above	Yes	<i>Debris from broken skylight panel to back of ceiling tiles</i>	<i>SP</i>	<i>As BS/04</i>	<i>8m<sup>2</sup></i>	<i>2</i>	<i>3</i>	<i>2</i>	<i>2</i>	<i>9</i>	<i>OA</i>	<b>REMOVED 2005</b>
Store Room 17	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	SP	As BS/06	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation



**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 20 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Classroom 23	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Skylights x 2 – Wood panel	SP	-	-	-	-	-	NA	-	-	-
		Wall – plasterboard over brick	SP	-	-	-	-	-	NA	-	-	-
		Wall mounted heater	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 8 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Notice boards x 2	SP	-	-	-	-	-	NA	-	-	-
		Window – panels to side	SP	As BS/09	-	-	-	-	NA	-	-	-
		Sink – vibration pad below	ID	BS/11	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	SP	As BS/03	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 21 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Void Above	Yes	<i>Tiles – debris on top</i>	<i>SP</i>	<i>As BS/04</i>	<i>&lt;0.05m<sup>2</sup></i>	<i>2</i>	<i>2</i>	<i>3</i>	<i>2</i>	<i>9</i>	<i>OA</i>	<b>REMOVED 2005</b>
Store Room 24	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 2 – metal – no access</i>	<i>P</i>	<i>-</i>	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Door – wood panels above	SP	-	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	SP	As BS/03	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 22 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Quiet Room	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 3 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Notice board	SP	-	-	-	-	-	NA	-	-	-
		Door – wood panels above	SP	-	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	ID	BS/12	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 23 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Classroom 25	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Skylights x 2 – wood panels	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard and plastic	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 10 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Window – panels	SP	As BS/09	-	-	-	-	NA	-	-	-
		Wall mounted heater	SP	-	-	-	-	-	NA	-	-	-
		Notice board	SP	-	-	-	-	-	NA	-	-	-
		Sink – coating to bottom	SP	As BS/07	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	SP	As BS/12	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 24 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Void Above	Yes	<i>Debris from broken skylight panel to back of ceiling tiles</i>	<i>SP</i>	<i>As BS/04</i>	<i>8m<sup>2</sup></i>	<i>2</i>	<i>3</i>	<i>2</i>	<i>2</i>	<i>9</i>	<i>OA</i>	<b>REMOVED 2005</b>
Store Room 26	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		<i>Column – metal – no access</i>	<i>P</i>	<i>-</i>	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Floor – vinyl tiles over concrete	SP	As BS/03	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 25 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Library	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		<i>Skylights – panels x 4</i>	<i>SP</i>	<i>As BS/04</i>	<i>16m<sup>2</sup></i>	<i>2</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>5</i>	<i>OA</i>	<b>REMOVED 2005</b>
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 7 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Door – wood panels above	SP	-	-	-	-	-	NA	-	-	-
		Notice board	SP	-	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 26 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Corridor 1	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Skylights x 2 – wood panels	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard and plastic	SP	-	-	-	-	-	NA	-	-	-
		Door – wood panels above	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 5 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Notice boards	SP	-	-	-	-	-	NA	-	-	-
		<i>Wall mounted heaters</i>	<i>SP</i>	<i>As BS/02</i>	<i>&lt;0.25m<sup>2</sup></i>	<i>1</i>	<i>0</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>OA</i>	<i>REMOVED FEB 2015</i>
		Columns – wood panels to side	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 27 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Corridor 1 (cont)	Yes	Window – panels to side	SP	As BS/09	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	SP	As BS/08	-	-	-	-	NA	-	-	-
Girls' Toilet	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		<i>Skylights x 2 – panels</i>	<i>SP</i>	<i>As BS/04</i>	<i>8m<sup>2</sup></i>	<i>2</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>5</i>	<i>OA</i>	<b>REMOVED 2005</b>
		Walls – ceramic tiles over plasterboard	SP	-	-	-	-	-	NA	-	-	-
		Toilet cisterns x 3	SP	-	-	-	-	-	NA	-	-	-
		Door – wood panel above	SP	-	-	-	-	-	NA	-	-	-
		Floor – vinyl cover over concrete	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation



**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 28 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Void Above	Yes	<i>Debris from broken skylight panel to back of ceiling tiles</i>	<i>SP</i>	<i>As BS/04</i>	<i>8m<sup>2</sup></i>	<i>2</i>	<i>3</i>	<i>2</i>	<i>2</i>	<i>9</i>	<i>OA</i>	<b>REMOVED 2005</b>
Girls' Changing Room	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Skylight – wood panel	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	SP	As BS/08	-	-	-	-	NA	-	-	-
Void Above	Yes	<i>Debris from broken skylight panel to back of ceiling tiles</i>	<i>SP</i>	<i>As BS/04</i>	<i>8m<sup>2</sup></i>	<i>2</i>	<i>3</i>	<i>2</i>	<i>2</i>	<i>9</i>	<i>OA</i>	<b>REMOVED 2005</b>

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 29 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Classroom 29	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Skylights x 3 – wood panels	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 7 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Window – wood panels to side	SP	As BS/09	-	-	-	-	NA	-	-	-
		Notice boards	SP	-	-	-	-	-	NA	-	-	-
		Wall mounted heater	SP	-	-	-	-	-	NA	-	-	-
		Sink – coating to bottom	SP	As BS/07	-	-	-	-	NA	-	-	-
		Door – wood panels above	SP	-	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	SP	As BS/08	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 30 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Void Above	Yes	<i>Debris from broken skylight panel to back of ceiling tiles</i>	<i>SP</i>	<i>As BS/04</i>	<i>8m<sup>2</sup></i>	<i>2</i>	<i>3</i>	<i>2</i>	<i>2</i>	<i>9</i>	<i>OA</i>	<b>REMOVED 2005</b>
Store Room 31	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		Water heater	SP	-	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	SP	As BS/12	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 31 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Classroom 35	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Skylights x 5 – wood panels	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 9 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		Notice boards	SP	-	-	-	-	-	NA	-	-	-
		Windows – panels	SP	As BS/09	-	-	-	-	NA	-	-	-
		Wall mounted heaters	SP	-	-	-	-	-	NA	-	-	-
		Door – wood panel above	SP	-	-	-	-	-	NA	-	-	-
		Sink – coating to bottom	SP	As BS/07	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 32 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Classroom 35 (cont)	Yes	Floor – vinyl tiles over concrete	SP	As BS/03	-	-	-	-	NA	-	-	-
Void Above	Yes	<i>Debris from broken skylight panel to back of ceiling tiles</i>	<i>SP</i>	<i>As BS/04</i>	<i>8m<sup>2</sup></i>	<i>2</i>	<i>3</i>	<i>2</i>	<i>2</i>	<i>9</i>	<i>OA</i>	<b>REMOVED 2005</b>

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 33 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Store Room 34	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		<i>Skylight – panel</i>	<i>SP</i>	<i>As B/04</i>	<i>4m<sup>2</sup></i>	<i>2</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>5</i>	<i>OA</i>	<b>REMOVED 2005</b>
		<i>Column – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		Door – wood panel above	SP	-	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	ID	BS/13	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 34 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Store Room 33	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		<i>Column – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Windows – panels to side	SP	As BS/09	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	SP	As BS/03	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 35 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Classroom 36	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Skylights x 4 – wood panels	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 9 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Door – wood panel above	SP	-	-	-	-	-	NA	-	-	-
		Kiln	SP	-	-	-	-	-	NA	-	-	-
		Notice boards	SP	-	-	-	-	-	NA	-	-	-
		Wall mounted heaters	SP	-	-	-	-	-	NA	-	-	-
		Windows – panels to side	SP	As BS/09	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation



**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 36 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Classroom 36 (cont)	Yes	Walls – plasterboard and plastic	SP	-	-	-	-	-	NA	-	-	-
		Sink – coating to bottom	SP	As BS/07	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	SP	As BS/03	-	-	-	-	NA	-	-	-
Void Above	Yes	<i>Debris from broken skylight panel to back of ceiling tiles</i>	<i>SP</i>	<i>As BS/04</i>	<i>8m<sup>2</sup></i>	<i>2</i>	<i>3</i>	<i>2</i>	<i>2</i>	<i>9</i>	<i>OA</i>	<b>REMOVED 2005</b>

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 37 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Store Room 38	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		Windows – panels to side	SP	As BS/09	-	-	-	-	NA	-	-	-
		<i>Column – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Door – wood panel above	SP	-	-	-	-	-	NA	-	-	-
		Floor – rubber tiles over concrete	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 38 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Boys' Toilet	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		<i>Skylights x 2 – panels</i>	<i>SP</i>	<i>As BS/04</i>	<i>8m<sup>2</sup></i>	<i>2</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>5</i>	<i>OA</i>	<b>REMOVED 2005</b>
		Walls – ceramic tiles over plasterboard	SP	-	-	-	-	-	NA	-	-	-
		Toilet cisterns x 3	SP	-	-	-	-	-	NA	-	-	-
		Door – wood panels above	SP	-	-	-	-	-	NA	-	-	-
		Floor – vinyl over concrete	SP	-	-	-	-	-	NA	-	-	-
Void Above	Yes	<i>Debris from broken skylight to back of ceiling tiles</i>	<i>SP</i>	<i>As BS/04</i>	<i>8m<sup>2</sup></i>	<i>2</i>	<i>3</i>	<i>2</i>	<i>2</i>	<i>9</i>	<i>OA</i>	<b>REMOVED 2005</b>

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 39 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Classroom 39	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Skylight – wood panels	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 8 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Column – wood panels to side	SP	-	-	-	-	-	NA	-	-	-
		Window – panels to side	SP	As BS/09	-	-	-	-	NA	-	-	-
		Notice boards	SP	-	-	-	-	-	NA	-	-	-
		Door – wood panels above	SP	-	-	-	-	-	NA	-	-	-
		Wall mounted heaters	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 40 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Classroom 39 (cont)	Yes	Sink – coating to bottom	SP	As BS/07	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	SP	As BS/03	-	-	-	-	NA	-	-	-
Void Above	Yes	<i>Tiles – debris on top</i>	<i>SP</i>	<i>As BS/04</i>	<i>8m<sup>2</sup></i>	<i>2</i>	<i>3</i>	<i>2</i>	<i>2</i>	<i>9</i>	<i>OA</i>	REMOVED 2005
Store Room 41	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	SP	As BS/03	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 41 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Store Room 37	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 3 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Columns – wood panels to sides	SP	-	-	-	-	-	NA	-	-	-
		Windows – panels to sides	SP	As BS/09	-	-	-	-	NA	-	-	-
		Floor – vinyl tiles over concrete	SP	As BS/03	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 42 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Store Room 40	Yes	Ceiling – MMMF tiles	Sp	-	-	-	-	-	NA	-	-	-
		Water heater	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		<i>Column – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Floor – vinyl tiles over concrete	SP	As BS/03	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 43 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Kitchen	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		<i>Skylight – panels</i>	<i>SP</i>	<i>As BS/04</i>	<i>20m<sup>2</sup></i>	<i>2</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>5</i>	<i>OA</i>	<b>REMOVED 2005</b>
		Walls – ceramic tiles over plasterboard and plastic	SP	-	-	-	-	-	NA	-	-	-
		Windows – panels to side	SP	As BS/09	-	-	-	-	NA	-	-	-
		<i>Columns x 6 – metal – no access</i>	<i>P</i>	<i>-</i>	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		<i>Deep Fat Fryer - Panel</i>	<i>ID</i>	<i>BS/01 Report No. AR/05/07 13</i>	<i>&lt;0.5m<sup>2</sup></i>	<i>2</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>5</i>	<i>EA</i>	<i>A2</i>
		<i>Heaters x 2</i>	<i>P</i>	<i>-</i>	<i>&lt;0.5m<sup>2</sup></i>	<i>2</i>	<i>0</i>	<i>2</i>	<i>2</i>	<i>6</i>	<i>IA</i>	<i>A3</i>
		Fire blanket	SP	-	-	-	-	-	NA	-	-	-
		<i>Steam heated oven – rope gasket</i>	<i>ID</i>	<i>BS/14</i>	<i>1m</i>	<i>2</i>	<i>0</i>	<i>2</i>	<i>1</i>	<i>5</i>	<i>EA</i>	<b>REMOVED AUG 2006</b>

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation



**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 44 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Kitchen (cont)	Yes	Cooker door – insulation	ID	BS/15	-	-	-	-	NA	-	-	-
		Sink – coating to bottom	SP	As BS/07	-	-	-	-	NA	-	-	-
		Floor – vinyl over concrete	SP	-	-	-	-	-	NA	-	-	-
Vegetable Store	Yes	Ceiling – tiles	SP	-	-	-	-	-	NA	-	-	-
		<i>Skylight – panels</i>	<i>SP</i>	<i>As BS/04</i>	<i>4m<sup>2</sup></i>	<i>2</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>5</i>	<i>OA</i>	<b>REMOVED 2005</b>
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		<i>Column – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Floor – vinyl tiles over concrete	SP	As BS/03	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 45 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Staff Office	Yes	Ceiling – tiles	SP	-	-	-	-	-	NA	-	-	-
		<i>Skylight – panels</i>	<i>SP</i>	<i>As BS/04</i>	<i>4m<sup>2</sup></i>	<i>2</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>5</i>	<i>OA</i>	<b>REMOVED 2005</b>
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		<i>Column – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Notice board	SP	-	-	-	-	-	NA	-	-	-
		Floor – carpet over concrete	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 46 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Void Above	Yes	<i>Debris from broken skylight to back of ceiling tiles</i>	SP	<i>As BS/04</i>	<i>8m<sup>2</sup></i>	<i>2</i>	<i>3</i>	<i>2</i>	<i>2</i>	<i>9</i>	<i>OA</i>	REMOVED 2005
Staff Toilet	Yes	Ceiling – tiles	SP	-	-	-	-	-	NA	-	-	-
		<i>Entrance to Tank Room – panels</i>	SP	<i>As BS/04</i>	<i>4m<sup>2</sup></i>	<i>2</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>5</i>	<i>OA</i>	REMOVED 2005
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		<i>Toilet cistern</i>	SP	<i>As BS/05</i>	<i>&lt;0.5m<sup>2</sup></i>	<i>1</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>3</i>	<i>EA</i>	<i>A3</i>
		Floor – tiles over concrete	SP	As BS/03	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 47 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Larder	Yes	Ceiling – MMMF tiles	SP	-	-	-	-	-	NA	-	-	-
		<i>Skylight – panels</i>	<i>SP</i>	<i>As BS/04</i>	<i>4m<sup>2</sup></i>	<i>2</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>5</i>	<i>OA</i>	<b>REMOVED 2005</b>
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		<i>Column – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Right hand wall - column	SP	-	-	-	-	-	NA	-	-	-
		<i>Pipe riser - panel</i>	<i>SP</i>	<i>As BS/04</i>	<i>2m<sup>2</sup></i>	<i>2</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>5</i>	<i>EA</i>	<b>REMOVED 2005</b>
		Floor – vinyl tiles over concrete	SP	As BS/03	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 48 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Tank Room above Staff Toilet	Yes	Roof – wood	SP	-	-	-	-	-	NA	-	-	-
		Walls – brick, wood and polystyrene	SP	-	-	-	-	-	NA	-	-	-
		Water tanks x 3 – metal	SP	-	-	-	-	-	NA	-	-	-
		Water tank insulation – MMMF	SP	-	-	-	-	-	NA	-	-	-
		Pipe insulation – plastic covered foam	SP	-	-	-	-	-	NA	-	-	-
		Floor – coating	ID	BS/16	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 49 of 54**

**Report No:** AR/04/1677 (update 04)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Exit Lobby	Yes	Ceiling – tiles	SP	-	-	-	-	-	NA	-	-	-
		Walls – plasterboard	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 2 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Floor – vinyl over concrete	ID	BS/17	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 50 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Room 11	Yes	Roof – perforated metal	SP	-	-	-	-	-	NA	-	-	-
		Walls – brick	SP	-	-	-	-	-	NA	-	-	-
		<i>Columns x 2 – metal – no access</i>	<i>P</i>	-	<i>&lt;1m<sup>2</sup> per column</i>	<i>2</i>	<i>0</i>	<i>0</i>	<i>2</i>	<i>4</i>	<i>IA</i>	<i>A3</i>
		Insulation – MMMF	SP	-	-	-	-	-	NA	-	-	-
		Floor – concrete	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 51 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Boiler Room	Yes	<i>Ceiling – tiles</i>	<i>ID</i>	<i>BS/18</i>	<i>22m<sup>2</sup></i>	<i>1</i>	<i>2</i>	<i>1</i>	<i>2</i>	<i>4</i>	<i>OA</i>	<i>REMOVED 2005</i>
		Walls – brick	SP	-	-	-	-	-	NA	-	-	-
		Pipe insulation – foam	SP	-	-	-	-	-	NA	-	-	-
		Boiler – metal	SP	-	-	-	-	-	NA	-	-	-
		<i>Burner gasket</i>	<i>ID</i>	<i>BS/19</i>	<i>0.25m<sup>2</sup></i>	<i>1</i>	<i>0</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>EA</i>	<i>REMOVED 2010</i>
		<i>Boiler front – rope gasket</i>	<i>ID</i>	<i>BS/20</i>	<i>1m</i>	<i>2</i>	<i>1</i>	<i>2</i>	<i>1</i>	<i>6</i>	<i>EA</i>	<i>REMOVED 2010</i>
		Inspection hatches x 2 - panels	SP	-	-	-	-	-	NA	-	-	-
		Outlet pipes – gasket	ID	BS/21	-	-	-	-	NA	-	-	-
		<i>Boiler – internal segments – no access</i>	<i>P</i>	<i>-</i>	<i>&lt;0.25m<sup>2</sup></i>	<i>2</i>	<i>0</i>	<i>1</i>	<i>1</i>	<i>4</i>	<i>IA</i>	<i>REMOVED 2010</i>

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation





**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 52 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Boiler Room (cont)	Yes	Boiler – metal flue pipes	SP	-	-	-	-	-	NA	-	-	-
		<i>Flue pipe penetration to boiler housing – rope gasket</i>	<i>SP</i>	<i>As BS/20</i>	<i>0.5m</i>	<i>2</i>	<i>0</i>	<i>2</i>	<i>1</i>	<i>5</i>	<i>OA</i>	<i>REMOVED 2010</i>
		Calorifier tank and internal insulation	SP	-	-	-	-	-	NA	-	-	-
		Calorifier flue pipe	SP	-	-	--	-	-	NA	-	-	-
		Air vents x 4 – panels	ID	BS/23	-	-	-	-	NA	-	-	-
		Electrical equipment	SP	-	-	-	-	-	NA	-	-	-
		<i>Adjacent doorway – redundant panel</i>	<i>SP</i>	<i>As BS/18</i>	<i>&lt;0.5m<sup>2</sup></i>	<i>2</i>	<i>1</i>	<i>2</i>	<i>2</i>	<i>7</i>	<i>EA</i>	<i>REMOVED 2005</i>
		Floor – concrete	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 53 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>GROUND FLOOR (cont)</b>												
Void Above	No	<i>Ceiling – asbestos tiles – no access</i>	<i>P</i>	-	-	-	-	-	-	-	<i>IA</i>	REMOVED 2005
Caretakers Office	Yes	Ceiling – corrugated metal	-	-	-	-	-	-	NA	-	-	-
		Walls - brick	-	-	-	-	-	-	NA	-	-	-
		<i>Wall panel – insulation board</i>	<i>SP</i>	<i>As BS/04</i>	<i>1.5m</i>	<i>2</i>	<i>0</i>	<i>1</i>	<i>2</i>	<i>5</i>	<i>MA</i>	<i>A3</i>
		Floor – cement	-	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

**VEGA ENVIRONMENTAL CONSULTANTS LTD**

**APPENDIX A**

**ASBESTOS SURVEY - DATA RECORD SHEET - continued**

**Page 54 of 54**

**Report No:** AR/04/1677 (Update 06)

**Date of survey:** 15/10/04

Area ID	Surveyed Yes/No	Location of sample point / Description of suspect material	Level of ID (P/SP/ID)	Sample ID	Extent (m/m <sup>2</sup> /m <sup>3</sup> )	Product Type (1,2,3)	Condition (0,1,2,3)	Surface Treatment (0,1,2,3)	Asbestos Type (1,2,3)	Score	Access (IA,OA,EA)	Action (A1,A2,A3)
<b>EXTERIORS</b>												
Exterior	Yes	Roof – felt	ID	BS/22	-	-	-	-	NA	-	-	-
		Walls - pebble dashed concrete and PVC	SP	-	-	-	-	-	NA	-	-	-
		Windows – PVC panels below	SP	-	-	-	-	-	NA	-	-	-
		Walls to tank room – wood	SP	-	-	-	-	-	NA	-	-	-

**Level of ID:** P – Presumed, SP – Strongly Presumed, ID – Identified. **Access:** IA – Inaccessible, OA – Occasionally Accessed, EA – Easily/Regularly Accessed

**Asbestos Type:** NA – Non-Asbestos **Action:** A1 – Remove ASAP, A2 – Repair/Encapsulate ASAP, A3 – Leave Undisturbed and Monitor Situation

## APPENDIX B

### VEGA ENVIRONMENTAL CONSULTANTS LTD

MATERIAL ASSESSMENT ALGORITHM – FOR TYPE 1/TYPE 2 SURVEY		
Sample Variable	Score	Main Examples
Product Type	1	Asbestos reinforced composites (plastic, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.)
	2	Asbestos insulating board, mill boards, other low-density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt.
	3	Thermal insulation (e.g. pipe and boiler lagging), sprayed asbestos, loose asbestos, asbestos mattresses and packing.
Condition	0	Good condition: no visible damage
	1	Low damage: a few scratches or surface marks; broken edges on boards, tiles etc.
	2	Medium damage: significant breakage of materials or several small areas where material has been damaged revealing loose asbestos fibres.
	3	High damage or delamination of materials, sprays and thermal insulation. Visible asbestos debris.
Surface Treatment	0	Composite materials containing asbestos: reinforced plastics, resins, vinyl tiles, painted or asbestos cement (with exposed face painted or encapsulated)
	1	Enclosed sprays and lagging, AIB (with exposed face painted or encapsulated), asbestos cement sheets etc.
	2	Unsealed AIB, or encapsulated lagging and sprays.
	3	Unsealed lagging and sprays.
Asbestos Type	1	Chrysotile.
	2	Amphibole asbestos excluding crocidolite.
	3	Crocidolite.

INITIAL ACTION PLAN			
MATERIAL ASSESSMENT SCORE	ACCESS		
	Inaccessible	Occasionally Accessed	Easily/Regularly Accessed
Very Low Risk: < 5	A3	A3	A3
Low Risk: 5-6	A3	A3	A2
Medium Risk: 7-9	A3	A2	A1
High Risk: 10-12	A2	A1	A1

## APPENDIX B

### CONFIDENTIAL

#### ADDITIONAL INFORMATION: Report No: AR/05/0713

#### ASBESTOS ANALYSIS REPORT

**Report No:** AR/05/0713 (Update 06) **Date of Issue:** 08/03/18

**Client:** Mr R Brown  
Northumberland County Council

**Date Sample Received:** 16/06/05

County Hall

Morpeth

Northumberland

NE61 2EF

**Date Analysed:** 17/06/05

**Laboratory:** Permanent

**Order/Contract No.** -

**Origin of bulk sample:** Cramlington Hillcrest School, East View Avenue, East View, Northumberland.

**Samples taken by:** J. Warwick **Company:** Vega Ltd

**Samples analysed by** H. J. Curry

Sample ID	Location of Sample Point	Analysis
BS/01	Kitchen, Deep Fat Fryer - Panel	Amosite – (brown asbestos)

*Analysis was carried out in accordance with MDHS 77: June 1994 by documented in-house procedure Number ASB/3.*

*VEGA cannot accept responsibility for the information on, or condition of, bulk samples taken/supplied by non-Vega personnel or the effect such information or condition may have on the analysis of fibrous content.*

**Checked by: Mr. R. Brown**  
*Asbestos Manager*

**CONFIDENTIAL**

**APPENDIX C**

**ASBESTOS ANALYSIS REPORT**

Page 1 of 3

**Report No:** AR/04/1677 (Update 06)      **Date of Issue:** 08/03/18

**Client:** Mr R Brown  
Northumberland County Council      **Date Sample Received:** 15/10/04

**Date Analysed:** 26/10/04

**Laboratory:** Permanent

**Order/Contract No.** -

**Origin of bulk sample:** Cramlington Hillcrest School, East View Avenue,  
Cramlington, Northumberland

**Samples taken by:** M Peterson      **Company:** Vega Ltd

**Samples analysed by** H J Curry

Sample ID	Location of Sample Point	Analysis
BS/01	Ground Floor, Entrance Lobby, Floor – tiles	No asbestos detected
BS/02	Ground Floor, Corridor 2, Wall Mounted Heater – bitumen coating to motor	<b><u>Chrysotile</u></b> – (white asbestos) <b><i>REMOVED FEB 2015</i></b>
BS/03	Ground Floor, Store Cupboard 1, Floor – vinyl tiles	No asbestos detected

*Analysis was carried out in accordance with MDHS 77: June 1994 by documented in-house procedure Number ASB/3.*

*VEGA cannot accept responsibility for the information on, or condition of, bulk samples taken/supplied by non-Vega personnel or the effect such information or condition may have on the analysis of fibrous content.*

**CONFIDENTIAL**

**APPENDIX C**

**ASBESTOS ANALYSIS REPORT - CONTINUED**

Page 2 of 3

Report No. AR/04/1677 (Update 06)

Sample ID	Location of Sample Point	Analysis
BS/04	Ground Floor, Male Staff Toilet, Skylight – panel	<b><u>Amosite</u></b> – (brown asbestos) <b>REMOVED 2005</b>
BS/05	Ground Floor, Male Staff Toilet – toilet cistern	Amosite <b>REMOVED MARCH 2005</b>
BS/06	Ground Floor, Male Staff Toilet, Floor – vinyl tiles	No asbestos detected
BS/07	Ground Floor, Staff Room, Below Sink – vibration pad	No asbestos detected
BS/08	Ground Floor, Foyer, Floor – vinyl tiles	No asbestos detected
BS/09	Ground Floor, Changing Room Toilet, Window – panel to side	No asbestos detected
BS/10	Ground Floor, Photocopier Room, Floor – vinyl covering	No asbestos detected
BS/11	Ground Floor, Classroom 22, Below Sink – vibration pad	No asbestos detected
BS/12	Ground Floor, Quite Room, Floor – vinyl tiles	No asbestos detected
BS/13	Ground Floor, Store Room 34, Floor – vinyl tiles	No asbestos detected
BS/14	Ground Floor, Kitchen, Steam heated ovens – rope gaskets	Chrysotile <b>REMOVED AUGUST 2006</b>
BS/15	Ground Floor, Kitchen, Cooker Door – insulation	No asbestos detected

*Analysis was carried out in accordance with MDHS 77: June 1994 by documented in-house procedure Number ASB/3.*

*VEGA cannot accept responsibility for the information on, or condition of, bulk samples taken/supplied by non-Vega personnel or the effect such information or condition may have on the analysis of fibrous content.*



**CONFIDENTIAL**

**APPENDIX C**

**ASBESTOS ANALYSIS REPORT - CONTINUED**

Page 3 of 3

**Report No.** AR/04/1677 (Update 06)

<b>Sample ID</b>	<b>Location of Sample Point</b>	<b>Analysis</b>
BS/16	Ground Floor, Kitchen, Tank Room above Staff Toilet, Floor - coating	No asbestos detected
BS/17	Ground Floor, Exit Lobby, Floor – vinyl tiles	No asbestos detected
BS/18	Ground Floor, Boiler Room, Ceiling – panel	Amosite <b>REMOVED 2005</b>
BS/19	Ground Floor, Boiler Room, Boiler Burner – gasket	Chrysotile <b>REMOVED 2010</b>
BS/20	Ground Floor, Boiler Room, Boiler Front – rope gasket	Chrysotile <b>REMOVED 2010</b>
BS/21	Ground Floor, Boiler Room, Outlet Pipes – gaskets	No asbestos detected <b>REMOVED 2010</b>
BS/22	Exteriors, Roof – felt	No asbestos detected
BS/24	Ground Floor, Boiler Room, Air Vents – panels	No asbestos detected
Report No. AR/05/0713 BS/01 See Appendix B	Ground Floor, Kitchen, Deep Fat Fryer - Panel	Amosite – (brown asbestos)

*Analysis was carried out in accordance with MDHS 77: June 1994 by documented in-house procedure Number ASB/3.*

*VEGA cannot accept responsibility for the information on, or condition of, bulk samples taken/supplied by non-Vega personnel or the effect such information or condition may have on the analysis of fibrous content.*