HSE

Health and Safety Executive: RIDDOR Report

Report Number: DCBEB802E8 Date Submitted: 05/07/2017 Current Authority: East and South East - 08

Lutor

About you and your organisation:

Phone Number:

Organisation:

Address:

Town:

County:

Post Code: Fax Number:

E-Mail:

Did the incident happen at the above address?

Which authority is responsible for monitoring H & S

where the incident happened?

Park & Ride / Guided Busway Team Leader .

Cambridgeshire County Council

ET1026 Trumpington Park & Ride

43 Hauxton Road CAMBRIDGE

Cambridgeshire CB2 9FT

01223945791

@cambridgeshire.gov.uk

HSE

About where the incident happened:

Where did Incident happen:

The incident happened elsewhere in my organisation

Organisation:

Address:

Cambridgeshire Guided Busway

Town:

County:

CAMBRIDGE

Cambridgeshire UNKNOWN

Post Code: Details of where (address unknown):

Access road adjacent to Hills Road bridge, Cambridge, Cambridgeshire

About the incident

Incident date:

Incident time:

21/06/2017

15:47

Which LA did incident occur in?

Country:

Geographic Area:

Local Authority:

England

Cambridgeshire

Cambridge

In which department or where on premises did incident happen?

Cambridgeshire Guided Busway section adjacent to Hills Road bridge, C

What type of work was being carried out?

Main Industry:

Transportation and Storage Land, pipeline transport

Main Activity: Sub Activity:

Other passenger land transport

About the kind of accident

Kind of accident that described incident:

Another kind of accident

How high was fall?

0 metres

Work process involved:

Movement, including aboard transport

Main factor involved:

Loss of control of machinery, transport or equipment

Describe what happened:

A guided bus, in service and operated by Whippet Coaches on their Universal service,, was travelling along a roadway towards the guided sections of the Busway for the purposes of joining the guideway to continue its journey between Cambridge Rail Station and Addenbrooke's Hospital in Cambridge. As the bus entered the guideway, the front offside wheel struck part of the track infrastructure, causing the bus's travel to be deflected in such a way that the bus did not engage correctly with the guideway. A subsequent collision (involving the nearside front wheel and the track infrastructure) caused a deflection to the bus's travel which resulted in the bus exiting the guideway, and crossing the adjacent parallel guideway and surfaced maintenance track. The bus struck an adjacent wall, a metal staircase, a lighting column and a section of fencing, the combined effect of which served to bring the bus to a halt. The second deflection led to the bus driver being thrown from his seat by the force of the impact, such that he was unable to control the movement of the bus beyond that point.

About the injured person

Name:

.

Address:

Town: County:

Post Code: Phone Number:

Gender:

Age:

Injured person's employment status

What was the person's occupation or job title?

What was the person's work status?

Details if on training scheme / employed by

someone else

About the injured person's injuries

Injured person's injuries: Part of body affected:

What was the severity of the injury?

c/c Whippet Coaches Ltd.

2 Rowles Way, Buckingway Bus. Park

Swavesey CAMBRIDGE

Cambridgeshire CB24 4UG

01954230011

Male

Bus driver

The injured person was employed by someone else

Full time employee of bus operator

Other known injuries Several locations

Injury preventing the injured person from working for more than 7 days