













		
Fire originated to front left hand side wall, corner area.	View of smoke damage to right hand side entrance wall.	Fire doors from main lobby area to ground floor flats, 1-12.
		
L 15.05 x W 5.5. View of front entrance doors taken from rear of lobby.	Ceiling height 2.3m. Damage to ceiling.	L 1.6 x W 3.7. Fire doors from main lobby area to rear left hand side ground floor flats. Possible damage to pipe cladding tbc. And quoted for by Stonegrove Ltd. Currently on site.

		
Smoke damage to ceiling.	Smoke damage to ceiling.	Smoke damage to central concrete column.
		
Damage to floors, possibly caused during clean up process.	Damage to floors, possibly caused during clean-up process.	Smoke damage to walls.

		
L 1.6 x W 2.6. Smoke damage to walls rear right hand side.	Smoke damage to walls front right-hand side. Fire doors to flats 1-12 leading to Lower Ground – 1A to 4A.	Closer view of wall damage.
		
Still taken from tenants' phone of damage pre-clean-up operation and prior to surveyors visit.	Still taken from tenants' phone of damage pre-clean-up operation and prior to surveyors visit.	Still taken from tenants' phone of damage pre-clean-up operation and prior to surveyors visit.