

Site History Report

Page 1 of 6

Effective: 01/01/2015 to 22/06/2020
Display Action Officer: No

Asset Number: 10001.00 to 10039.00
Site: HOUTING (39400164)

Site: HOUTING (39400164)

Locality: TAMWORTH, STAFFORDSHIRE

Area: Tamworth - Watling South

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|------------|---|----------------|----------|---------------|------------------------------|--------------|--------------------------------|------------|
| Asset: | 10,001.00 | Asset - Locn.: | 115883 | Feature Type: | Drainage Asset - Gully | | Area: Tamworth - Watling South | |
| Batch: | 30004973 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,002.00 | Asset - Locn.: | 115885 | Feature Type: | Drainage Asset - Gully | | Area: Tamworth - Watling South | |
| Batch: | 30004974 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,003.00 | Asset - Locn.: | 115888 | Feature Type: | Drainage Asset - Gully | | Area: Tamworth - Watling South | |
| Batch: | 30004975 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,004.00 | Asset - Locn.: | 115890 | Feature Type: | Drainage Asset - Gully | | Area: Tamworth - Watling South | |
| Batch: | 30004976 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,005.00 | Asset - Locn.: | 115893 | Feature Type: | Drainage Asset - Gully | | Area: Tamworth - Watling South | |
| Batch: | 30004977 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,006.00 | Asset - Locn.: | 115896 | Feature Type: | Drainage Asset - Gully | | Area: Tamworth - Watling South | |
| Batch: | 30005038 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,007.00 | Asset - Locn.: | 115898 | Feature Type: | Drainage Asset - Gully | | Area: Tamworth - Watling South | |
| Batch: | 30005037 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |

Site History Report

Page 2 of 6

Effective: 01/01/2015 to 22/06/2020
Display Action Officer: No

Asset Number: 10001.00 to 10039.00
Site: HOUTING (39400164)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|---|-----------------------|----------|----------------------|------------------------------|--------------|--------------------------|-------------------------|
| Asset: | 10,008.00 | Asset - Locn.: | 115899 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004978 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | | Date: 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | | Date: 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,009.00 | Asset - Locn.: | 115903 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004979 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | | Date: 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | | Date: 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,010.00 | Asset - Locn.: | 115904 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004980 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | | Date: 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | | Date: 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,011.00 | Asset - Locn.: | 115906 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30005036 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | | Date: 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | | Date: 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,012.00 | Asset - Locn.: | 115908 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30005035 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | | Date: 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | | Date: 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,013.00 | Asset - Locn.: | 115909 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30005034 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | | Date: 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | | Date: 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,014.00 | Asset - Locn.: | 115910 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30005033 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | | Date: 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | | Date: 27/08/2015 |
| | No actionable defects found | | | | | | | |

Site History Report

Effective: 01/01/2015 to 22/06/2020
Display Action Officer: No

Asset Number: 10001.00 to 10039.00
Site: HOUTING (39400164)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|---|-----------------------|----------|----------------------|------------------------------|--------------|--------------------------|------------|
| Asset: | 10,015.00 | Asset - Locn.: | 115912 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004981 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,016.00 | Asset - Locn.: | 115914 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004982 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,017.00 | Asset - Locn.: | 115915 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30005027 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,018.00 | Asset - Locn.: | 115918 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30005028 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,019.00 | Asset - Locn.: | 115924 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30005030 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,020.00 | Asset - Locn.: | 115926 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30005031 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,021.00 | Asset - Locn.: | 115928 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30005032 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |

Site History Report

Page 4 of 6

Effective: 01/01/2015 to 22/06/2020
Display Action Officer: No

Asset Number: 10001.00 to 10039.00
Site: HOUTING (39400164)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|---|-----------------------|----------|----------------------|------------------------------|--------------|--------------------------|------------|
| Asset: | 10,022.00 | Asset - Locn.: | 115932 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004983 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,023.00 | Asset - Locn.: | 115935 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004984 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,024.00 | Asset - Locn.: | 115938 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004985 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,025.00 | Asset - Locn.: | 115995 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004957 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,026.00 | Asset - Locn.: | 115996 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004958 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,027.00 | Asset - Locn.: | 115999 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004959 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,028.00 | Asset - Locn.: | 116000 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004960 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |

Site History Report

Page 5 of 6

Effective: 01/01/2015 to 22/06/2020
Display Action Officer: No

Asset Number: 10001.00 to 10039.00
Site: HOUTING (39400164)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|---|-----------------------|----------|----------------------|------------------------------|--------------|--------------------------|------------|
| Asset: | 10,029.00 | Asset - Locn.: | 116001 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004961 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,030.00 | Asset - Locn.: | 116002 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004962 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,031.00 | Asset - Locn.: | 116003 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004964 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,032.00 | Asset - Locn.: | 116004 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004965 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,033.00 | Asset - Locn.: | 116006 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004967 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,034.00 | Asset - Locn.: | 116007 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004968 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,035.00 | Asset - Locn.: | 116011 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004969 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 Historic Inspection | | | Route: | Gully Historic Import | | Date: | 27/08/2015 |
| | No actionable defects found | | | | | | | |
| Asset: | 10,036.00 | Asset - Locn.: | 116013 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30005040 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | | Date: | 10/07/2018 |
| | No actionable defects found | | | | | | | |

Site History Report

Page 6 of 6

Effective: 01/01/2015 to 22/06/2020
Display Action Officer: No

Asset Number: 10001.00 to 10039.00
Site: HOUTING (39400164)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|------------|-----------------------------|---------------------|----------|-----------------------------|------------------------------|--------------------|--------------------------|---------|
| Asset: | 10,036.00 | Asset - Locn.: | 116013 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30001277 - 27/08/2015 | Historic Inspection | | Route: | Gully Historic Import | Date: | 27/08/2015 | |
| | No actionable defects found | | | | | | | |
| Asset: | 10,037.00 | Asset - Locn.: | 116016 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30005039 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | Date: | 10/07/2018 | |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 | Historic Inspection | | Route: | Gully Historic Import | Date: | 27/08/2015 | |
| 30005223 | | 27/08/2015 | | Brickwork/Frame/Replacement | Internal | No Action Required | | |
| Asset: | 10,038.00 | Asset - Locn.: | 116019 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004972 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | Date: | 10/07/2018 | |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 | Historic Inspection | | Route: | Gully Historic Import | Date: | 27/08/2015 | |
| | No actionable defects found | | | | | | | |
| Asset: | 10,039.00 | Asset - Locn.: | 116020 | Feature Type: | Drainage Asset - Gully | Area: | Tamworth - Watling South | |
| Batch: | 30004971 - Inspection Batch | | | Route: | Gully 6 - Triennial Pack 003 | Date: | 10/07/2018 | |
| | No actionable defects found | | | | | | | |
| Batch: | 30001277 - 27/08/2015 | Historic Inspection | | Route: | Gully Historic Import | Date: | 27/08/2015 | |
| | No actionable defects found | | | | | | | |