Site: CRANFORD ROAD (7601827)

Service: Roads Display Action Officer: No

Site: CRAN	IFORD ROAD (7601827)		Locality: N	IANNOFIELD, ABERDEEN, ABERD	EEN CITY	Area: Aberdee	n South
ondition Su	rvey						
efect No: Desc	ription	Log Date	Location	Defect Type	Class. Organisation	Status	Job No.
Asset:	1,000.00 Asset - Locn.:	S/31/0686 - C	RANFORD ROAD	Feature Typ	e: RDS Road Section	Area: Aberde	en South
Batch: 54	5201 - Inspection Batch			Route: Adhoc Inspection			Date: 28/02/2018
ROA Site (Loca Loca First First wear near Seco whole surfa Addit areas	ional Information : This refers to s down the whole of Cranford Road	28/02/2018	Cranford Road	Pot Hole	Internal	Committed	721251
	uiry 733755) 3903 - Inspection Batch			Route: Adhoc Inspection			Date: 23/01/2018
467399 Block DRA Site (Loca Loca First First block Seco Seco gully Nam Telep Emai	ked Gully - Reference No: INAGE16364 (Street/Park/etc): Cranford Road (tion: 11 Cranford Road (tional Details: In front of house Type of Fault: Blocked Gully Fault Details: Gully appears to be (tional Details: Gully appears to be (tional Details: Gully appears to be (tional Details: When it rains the (tional Street Fault)	23/01/2018	Cranford Road, Aberdeen	Blocked Gully	Internal	Committed	720307
	2536 - Inspection Batch ctionable defects found			Route: Week: 36 - Area: 24			Date: 20/12/2017
Batch: 53	8417 - Inspection Batch			Route: Week: 24 - Area: 24			Date: 07/09/2017
	ctionable defects found			B 4 All 1 2			B 4 00/00/05:=
	8240 - Inspection Batch air 2 potholes, both approx' 300 x 300	28/08/2017	Outside numbers 74 and 1	Route: Adhoc Inspection 04. Pot Hole	Internal	Committed	Date: 28/08/2017 717855
	5569 - Inspection Batch			Route: Adhoc Inspection			Date: 11/07/2017
	air pothole approx' 300 x 200 x 50.	11/07/2017	Lampost number 14.	Pot Hole	Internal	Committed	716856

Site: CRANFORD ROAD (7601827)

Service: Roads Display Action Officer: No

Condition Survey

efect No: Description	Log Date	Location	Defect Type	Class. Org	anisation Status	Job No
Asset: 1,000.00 Asset - Locn.:	S/31/0686 - C	RANFORD ROAD	Feature Type	e: RDS Road Section	Area: Aberde	en South
Batch: 535567 - Inspection Batch		Route	Adhoc Inspection			Date: 11/07/2017
465635 Repair pothole approx' 500 x 300 x 50.	11/07/2017	Adjacent to junction with CRANFC TERRACE.	RD Pot Hole	Internal	Committed	71685
Batch: 533976 - Inspection Batch		Route	Week: 12 - Area: 24			Date: 13/06/2017
No actionable defects found						
Batch: 531880 - Inspection Batch		Route	Adhoc Inspection			Date: 15/05/2017
464687 Clean and jet blocked gulley.	15/05/2017	Cranford Road outside Mr Chips opposite lampost number 1.	Blocked Gully	Internal	Committed	71529
Batch: 527754 - Inspection Batch		Route	Week: 48 - Area: 24			Date: 16/03/2017
No actionable defects found						
Batch: 525086 - Inspection Batch		Route	Adhoc Inspection			Date: 06/02/2017
462511 Repair 3 potholes, all approx' 300 x 300 x 50.	06/02/2017	Between number 88 and junction v BROOMHILL ROAD.	with Pot Hole	Internal	Committed	71200
Batch: 522282 - Inspection Batch		Route	Adhoc Inspection			Date: 19/12/2016
461868 Repair approx' 8 square metres of damaged carriageway surface.	19/12/2016	Between junctions with HUTCHISO TERRACE and BROOMHILL ROA		Internal	Committed	71068
Batch: 522063 - Inspection Batch		Route	Week: 36 - Area: 24			Date: 15/12/2016
No actionable defects found						
Batch: 516169 - Inspection Batch		Route	Week: 24 - Area: 24			Date: 01/10/2016
No actionable defects found						
Batch: 508651 - Inspection Batch		Route	Adhoc Inspection			Date: 05/08/2016
460059 Repair 2 areas of damaged carriageway surface, total area approx' 1 square metre	05/08/2016	At edge of carriageway outside numbers 15 and 17.	Pot Hole	Internal	Archived	70753
Batch: 505548 - Inspection Batch		Route	Week: 12 - Area: 24			Date: 12/07/2016
459509 Approx 400 x 300 x 50.	12/07/2016	At speed bump opposite number 5	9. Pot Hole	Internal	Archived	70669
Batch: 501299 - Inspection Batch		Route	Adhoc Inspection			Date: 24/05/2016
458641 Repair 2 potholes, both approx' 450 x 300 x 50.	24/05/2016	Outside 78 - 80.	Pot Hole	Internal	Archived	70526
Batch: 497569 - Inspection Batch		Route	Week: 48 - Area: 24			Date: 12/04/2016
457319 Repair pothole approx' 300 x 200 x 50.		TERRACE.	Pot Hole	Internal	Archived	70355
457318 Repair 3 potholes, all approx' 300 x 300 x 50.	12/04/2016	Opposite numbers 75 - 77.	Pot Hole	Internal	Archived	70355
Batch: 497198 - Inspection Batch		Route	Adhoc Inspection			Date: 05/04/2016
457124 Repair 14 potholes, all approx' 400 x 400 50.	x 05/04/2016	Between junctions with CRANFOR TERRACE and BROOMHILL ROA		Internal	Archived	70332
Batch: 497197 - Inspection Batch	<u> </u>	Route	Adhoc Inspection			Date: 05/04/2016
457123 Repair 6 potholes, all approx' 400 x 400 x 50.	05/04/2016	Between number 47 and junction v CRANFORD TERRACE.	vith Pot Hole	Internal	Archived	70332

Contract: Roads Contract (General Maint) (RD01)

Site: CRANFORD ROAD (7601827)

Service: Roads Display Action Officer: No

Condition Survey

Defect No: Desc	ription		Log Date	Location	Defect Type	Class. Organisation	n Status	Job No.
Asset:	1,000.00	Asset - Locn.:	S/31/0686 - C	RANFORD ROAD	Feature Type	: RDS Road Section	Area: Aberde	en South
Batch: 49	7196 - Inspectio	on Batch		Ro	ute: Adhoc Inspection			Date: 05/04/2016
457122 Repa 50.	ir 3 potholes, all	approx' 200 x 200 x	05/04/2016	Outside numbers 47 to 53.	Pot Hole	Internal	Archived	703322
Batch: 49	7195 - Inspectio	on Batch		Ro	ute: Adhoc Inspection			Date: 05/04/2016
457121 Repa 50.	ir 4 potholes, all	approx' 200 x 200 x	05/04/2016	Outside numbers 33 - 37.	Pot Hole	Internal	Archived	703321
Batch: 49	4737 - Inspectio	on Batch		Ro	ute: Adhoc Inspection			Date: 03/03/2016
456216 Repa	air pothole approx	x' 450 x 450 x 60.	03/03/2016	Outside number 37.	Pot Hole	Internal	Archived	702135
Asset:	1,002.00	Asset - Locn.:	1 - Footway		Feature Type	: RDS Footway	Area: Aberde	en South
Batch: 54	3920 - Inspectio	on Batch		Ro	ute: Adhoc Inspection			Date: 23/01/2018
467407 Gene	eral Enquiry - Re	ference No :	23/01/2018	Cranford Road, Aberdeen	Sunken Footway	Internal	Committed	720320

467407 General Enquiry - Reference No :

PATHS18424 Site (Street/Park/etc): Cranford Road

Location: 11 Cranford Road

Locational Details : In front of house First Type of Fault: Rocking/Low Manhole

or Toby Cover

First Fault Details: The concrete around the toby cover is not level with the footpath Additional Information: The issue may seem minor, however the gap between the toby cover and our footpath into 11 Cranford Road is just the right size to trap a pram wheel making it very difficult to get our pram in and out of the house

Name: Telephone Number : Email Address: (Enquiry 731436)

Site: CRANFORD ROAD (7601827)

Service: Roads Display Action Officer: No

Condition Survey

fect No: Des	cription		Log Date	Location	Defect Type	Class.	Organisation	Status	Job No
Asset:	1,002.00	Asset - Locn.: 1	I - Footway		Feature Type	: RDS Footway		Area: Aberdeen S	South
Batch: 5	43919 - Inspection	Batch			Route: Adhoc Inspection				Date: 23/01/2018
PAT Site Loca Loca First or T First the t Addi seer toby Crar a pra our Nam Tele	bby Cover Fault Details: The oby cover is not letional Information in minor, however to cover and our food Road is just tham wheel making foram in and out of	Cranford Road Road ront of house cking/Low Manhole e concrete around wel with the footpath The issue may he gap between the path into 11 ne right size to trap t very difficult to get		Cranford Road, Aberdeen	Sunken Footway	Internal		Uncommitted	720319
(End	uiry 731436) 43918 - Inspection	Potoh			Route: Adhoc Inspection				Date: 23/01/2018
	eral Enquiry - Refe		00/04/0040	Cranford Road, Aberdeen	Sunken Footway	Internal		Uncommitted	720318
PAT Site Loca Loca First or To First the t Addi seer toby Crar a pro	HS18424 (Street/Park/etc): ation: 11 Cranford ational Details: In f Type of Fault: Roby Cover Fault Details: The oby cover is not letional Information minor, however t cover and our fool offord Road is just the	Cranford Road Road ront of house cking/Low Manhole e concrete around wel with the footpath The issue may he gap between the path into 11 ne right size to trap t very difficult to get		C. G. HOLDER TO THE STATE OF TH	Current Footway	поли		Chommitted	120316
Ema (End	phone Number : iil Address : juiry 731436)								
Batch: 5	42537 - Inspection	Batch			Route: Week: 36 - Area: 24				Date: 20/12/2017
No a	actionable defects f	ound							

Contract: Roads Contract (General Maint) (RD01) Site: CRANFORD ROAD (7601827) Display Action Officer: No

Service: Roads

Condition Survey

efect No: Desc	cription		Log Date	Location	Defect Type	Class.	Organisation	Status	Job No
Asset:	1,002.00	Asset - Locn.: 1	I - Footway		Feature Typ	e: RDS Footway		Area: Aberdee	en South
Batch: 54	10590 - Inspection	Batch		Route:	Adhoc Inspection				Date: 24/10/2017
Site 11 C Loca Loca First Slab First dang Secc Secc manl Addi 17th our h The am p using my h diffic bugg manl	ranford Road Ition: Aberdeen Itional Details: In Type of Fault: Br (s) Fault Details: Ro per to pedestrians. Ind Type of Fault Ind Fault Details: Ro Ind Type of Fault Ind Fault Details: Inde covers outsic Itional Information Informati	Pavement outside footpath or lane oken/Rocking cking slab causing Poor Surface Uneven surface by front gate On Tuesday the erly lady fell outside pavement surface. ce with a deep cut. I I might fall when come in and out of It is especially y young sons surface with	24/10/2017	Pavement outside 11 Cranford Roa Aberdeen	d Rocking Slab	Internal		Committed	71880
Batch: 54	10365 - Inspection	Batch		Route:	Adhoc Inspection				Date: 19/10/2017
466661 Lift a		600 x 600mm paving	19/10/2017	Cranford Road outside number 9'	Rocking Slab	Internal		Committed	71877
Batch: 53	38418 - Inspection	Batch		Route:	Week: 24 - Area: 24				Date: 07/09/2017
No a	ctionable defects	found							
Batch: 53	33977 - Inspection	Batch		Route:	Week: 12 - Area: 24				Date: 13/06/2017
No a	ctionable defects	found							
Batch: 52	27755 - Inspection	Batch		Route:	Week: 48 - Area: 24				Date: 16/03/2017
No a	ctionable defects	found							
Batch: 52	26486 - Inspection	Batch		Route:	Adhoc Inspection				Date: 23/02/2017
	ootpath lift 1x600x 0x500, and relay b BS.		23/02/2017	No104.	Rocking Slab	Internal		Committed	71277
	22064 - Inspection			Route:	Week: 36 - Area: 24				Date: 15/12/2016
No a	ctionable defects	found							

Site: CRANFORD ROAD (7601827)

Service: Roads Display Action Officer: No

Condition Survey

Defect No: Description	Log Date	Location	Defect Type	Class. Organisation	Status	Job No.
Asset: 1,002.00 Asset - Locn.:	1 - Footway		Feature Type:	RDS Footway	Area: Aberde	en South
Batch: 521332 - Inspection Batch		Route: Ad	lhoc Inspection			Date: 06/12/2016
461683 Remove depressed and broken slab causing trip hazard and replace with bitmac.	06/12/2016	On footway opposite house number 53	3. Sunken Footway	Internal	Committed	710429
Batch: 521331 - Inspection Batch		Route: Ad	lhoc Inspection			Date: 06/12/2016
461682 Reset dropped kerb causing trip hazard.	06/12/2016	Opposite house number 53.	Broken Kerb	Internal	Committed	710428
Batch: 516170 - Inspection Batch		Route: We	eek: 24 - Area: 24			Date: 01/10/2016
No actionable defects found						
Batch: 513001 - Inspection Batch		Route: Ad	lhoc Inspection			Date: 02/09/2016
460479 Remove rocking slab and replace with bitmac.	02/09/2016	On footwat croaaing outside number 96.	Rocking Slab	Internal	Archived	708267
Batch: 512999 - Inspection Batch		Route: Ad	lhoc Inspection			Date: 02/09/2016
460477 Remove 1 x sunken slab and 1 x depressed and broken slab causing trip hazards and replace with bitmac.	02/09/2016	Outside numbers 76 - 78.	Broken Slab	Internal	Archived	708265
Batch: 512998 - Inspection Batch		Route: Ad	lhoc Inspection			Date: 02/09/2016
460476 Remove 4 slabs causing trip hazards and replace with bitmac.	02/09/2016	Around tree outside number 103.	Tree Root Damage	Internal	Archived	708264
Batch: 512997 - Inspection Batch		Route: Ad	lhoc Inspection			Date: 02/09/2016
460475 Remove 3 slabs causing trip hazards and replace with bitmac.	02/09/2016	Around tree outside number 29.	Tree Root Damage	Internal	Archived	708263
Batch: 512996 - Inspection Batch		Route: Ad	lhoc Inspection			Date: 02/09/2016
460474 Remove 5 uneven slabs causing trip hazards and replace with bitmac.	02/09/2016	Around tree outside number 9.	Tree Root Damage	Internal	Archived	708262
Batch: 508654 - Inspection Batch			lhoc Inspection			Date: 05/08/2016
460062 Remove 3 rocking slabs and replace with bitmac.	05/08/2016	On footway outside number 68.	Rocking Slab	Internal	Archived	707540
Batch: 508650 - Inspection Batch		Route: Ad	lhoc Inspection			Date: 05/08/2016
460058 Remove depressed and broken slab and replace with bitmac.	05/08/2016	On footway outside number 15.	Broken Slab	Internal	Archived	707536
Batch: 505560 - Inspection Batch No actionable defects found		Route: We	eek: 12 - Area: 24			Date: 12/07/2016
Batch: 497576 - Inspection Batch		Route: We	eek: 48 - Area: 24			Date: 12/04/2016

No actionable defects found

Contract: Roads Contract (General Maint) (RD01)

Site: CRANFORD ROAD (7601827)

Service: Roads Display Action Officer: No

Feature Type: RDS Road Section

Feature Type: RDS Road Section

Enquiry Ref:

Customer Services

Logged by: Contact Centre **Enquiry No.:** 733920 on: 22/02/2018 11:54

Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** Service: Roads

Desc.: Reference No: ROADS32006

Site (Street/Park/etc): Cranford road

Location: Aberdeen

Locational Details: In front of house First Type of Fault: Poor Road Surface

Additional Information: Hello I'm just curious to see if Cranford road is on the list of streets to get resurfaced? The entire road is littered with pot holes and as people come over the speed bump at mine chunks of road are being flung up and damaging my wife's car. Your boys have in the past put cold lay tar into various holes but this hardly ever lasts a month before the hole reappears. I do have a picture of one set of potholes and the size of chunks being thrown out if you wish I can send them on. Thanks

on: 20/02/2018 10:57

Name: Address Line 1 Address Line 3: Postcode: Telephone Number: Email Address :

Location: CRANFORD ROAD Contact:

Plot Number: 1.000.00 Job Number: 721251

Logged by: Contact Centre **Enquiry No.:** 733755

Service: Roads Subject: General Enquiry Classification: Defect Report

Desc.: Reference No: ROADS31919

Site (Street/Park/etc): Cranford Road

Location: Mannofield

Locational Details: In front of house First Type of Fault: Poor Road Surface

First Fault Details: Road surface is wearing away in some places, particularly near speed bumps.

Feature Id - Location: S/31/0686 - CRANFORD ROAD

Second Type of Fault : Pothole

Second Fault Details: Several along the whole of Cranford Road right through tar surface.

Additional Information: This refers to areas down the whole of Cranford Road

Location: Cranford Road Contact:

Plot Number: 1,000.00 Feature Id - Location: S/31/0686 - CRANFORD ROAD

Job Number: 721251 Defect Number: 467822

Enquiry No.: 733722 Logged by: Contact Centre on: 19/02/2018 17:18

Service: Roads Subject: Pot Hole - Road Classification: Enquiry **Enquiry Ref:**

Desc.: Reference No: ROADS31886. Site (Street/Park/etc): Street. Location: cranford road, hammerfield avenue. Locational Details: In front of house. First Type of Fault: Poor Road Surface. Second

Type of Fault: Pothole. Additional Information: Both of the above roads are in appalling condition and have been for at least the last year

Name: Address Line 1: Address Line 2: Postcode: Email Address: Location: CRANFORD ROAD Contact:

Contract: Roads Contract (General Maint) (RD01)

Site: CRANFORD ROAD (7601827)

Service: Roads Display Action Officer: No

Customer Services

Logged by: Contact Centre **Enquiry No.:** 731436 on: 22/01/2018 13:14

Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** Service: Roads

Desc.: Reference No: PATHS18424 Site (Street/Park/etc): Cranford Road Location: 11 Cranford Road Locational Details: In front of house

First Type of Fault: Rocking/Low Manhole or Toby Cover

First Fault Details: The concrete around the toby cover is not level with the footpath

Additional Information: The issue may seem minor, however the gap between the toby cover and our footpath into 11 Cranford Road is just the right size to trap a pram wheel making it very difficult

to get our pram in and out of the house

Name: Telephone Number: Email Address:

Location: Cranford Road, Aberdeen

Contact:

Plot Number: 1.002.00 Feature Id - Location: 1 - Footway Feature Type: RDS Footway

Enquiry Ref:

Enquiry Ref:

Job Number: 720320

Enquiry No.: 729753 Logged by: Contact Centre

Service: Roads Subject: Pot Hole - Road Classification: Enquiry

Desc.: Reference No: ROADS31093

Site (Street/Park/etc): street Location: outside 35 Cranford rd Locational Details: In front of house First Type of Fault: Poor Road Surface

First Fault Details: speed hump too high after road has sunk in front of it

Second Type of Fault: Poor Road Surface

Additional Information: Whole length of Cranford Rd actually is in a poor state.

Location: CRANFORD ROAD roads31093

Contact:

Enquiry No.: 729621 Logged by: Contact Centre

Subject: General Enquiry

on: 31/12/2017 01:16 Classification: Defect Report

on: 03/01/2018 14:20

Service: Roads

Desc.: Reference No: ROADS31043

Site (Street/Park/etc): Cranford road

Location: The whole road

First Type of Fault: Poor Road Surface

Additional Information: Cranford Road has been deteriorating for many years now & amp; amp; has a bad surface for most of the road. I feel that this road badly needs resurfacing. When you see

the improvement in Hammersmith Road with speed tables perhaps this could be done with Cranford Road?

Location: Cranford Road

Enquiry No.: 721541 Logged by: Contact Centre on: 18/10/2017 14:22

Subject: General Enquiry Classification: Claim **Enquiry Ref:** Service: Roads

Desc.: THE ROAD SLABS ON THE PAVEMENT ACROSS THE ROAD FROM THE SQUASH CLUB ARE REALLY BAD AS FELL AS A RESULT OF A WOBBLY SLAB AND SHE HS HAD TO HAVE STICHES AND SHE HAS A HAEMATOMA AND HER VISION IS NOT GOOD. THE SWELLING IS CAUSING A BLOCKAGE FOR HER EYESITE . PLEASE CSEND OUT CLIAM

Contact:

TO DISCUSS WHAT HAPPENS NEXT FORMS AND CALL HER ON

Location: CRANFORD ROAD - SH Contact:

Contract: Roads Contract (General Maint) (RD01)

Site: CRANFORD ROAD (7601827)

Service: Roads Display Action Officer: No

Customer Services

Logged by: Contact Centre **Enquiry No.:** 708043 on: 09/06/2017 16:38

Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** Service: Roads

Desc.: FAO: ACC Roads Response service,

Reference No: PATHS17992 Site (Street/Park/etc): Cranford Road

Location: Mannofield

Locational Details: In front of house First Type of Fault : Poor Surface

First Fault Details: The footpath is dangerously slippy. Second Type of Fault: Other

Second Fault Details: Slime needs to be removed.

Additional Information: the pavement outside 66 Cranford road, on the corner of Cranford terrace is VERY dangerously slippy. The surface is coated with a thick coating of slime. This route is used by many parents from manofiled area walking children to school and elderly visitors to the Cranford Nursing home. This could cause serious injury as I have witnessed slips, trips and falls frequently

this year.

Name Telephone Number: Email Address:

Location: 66 Cranford Road Contact: **Enquiry No.:** 689156 Logged by: Contact Centre on: 16/02/2017 16:37

Subject: General Enquiry Classification: Defect Report **Enquiry Ref:** Service: Roads

Desc.: Paving slabs are raised and uneven, trip hazard for pedestrians -

Location: Outside Drvieway of 104 Cranford Drive

Plot Number: 1.002.00 Feature Id - Location: 1 - Footway Feature Type: RDS Footway

Job Number: 712778

Enquiry No.: 679936 Logged by: Contact Centre on: 15/11/2016 01:57

Subject: General Enquiry Service: Roads Classification: Defect Report **Enquiry Ref:**

Desc.: Reference No: ROADS28794

Site (Street/Park/etc): Cranford Road

Location: 79

Locational Details: In front of house

First Type of Fault: Pothole

Location: Contact

Feature Type: RDS Road Section Plot Number: 1.000.00 Feature Id - Location: S/31/0686 - CRANFORD ROAD

Job Number: 709935

Logged by: Contact Centre on: 12/04/2016 16:02 **Enquiry No.:** 659776

Service: Roads Subject: General Enquiry Classification: Defect Report **Enquiry Ref:**

Desc.: Good Afternoon, There is a badly broken area of road surface opposite 75 Cranford Road (see attached photo). I would be very grateful if this could be repaired. Regards, Contact:

Contact:

Location: 75 CRANFORD ROAD - ME027645 -

Plot Number: 1.000.00 Feature Id - Location: S/31/0686 - CRANFORD ROAD Feature Type: RDS Road Section

Job Number: 703551

Site: CRANFORD ROAD (7601827)

Service: Roads Display Action Officer: No

Maintenance Management

ob No.	Description		Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.0	0 A s	sset - Locn.: S/31/0686 - CRANFORD ROAD	Featu	re Type: RDS Road Section		Area: Aberdeen S	South
	Repair pothole appr x 60. (Pot Hole)	ox' 450 x 450	Outside number 37.	.RD 2 Day	Job Closed	03/03/2016	03/03/2016 Act.	RD01/22354
703321			Outside numbers 33 - 37.	.RD 7 Day	Job Closed	05/04/2016	08/04/2016 Act.	RD01/22714
703322		all approx' 200	Outside numbers 47 to 53.	.RD 7 Day	Job Closed	05/04/2016	08/04/2016 Act.	RD01/22714
	Repair 6 potholes, a x 400 x 50. (Pot Hol		Between number 47 and junction with CRANFORD TERRACE.	.RD 7 Day	Job Closed	05/04/2016	08/04/2016 Act.	RD01/22714
	Repair 14 potholes, 400 x 400 x 50. (Pot		Between junctions with CRANFORD TERRACE and BROOMHILL ROAD.	.RD 7 Day	Job Closed	05/04/2016	08/04/2016 Act.	RD01/22714
	Repair 3 potholes, a x 300 x 50. (Pot Hol		Opposite numbers 75 - 77.	.RD 7 Day	Job Closed	12/04/2016	12/04/2016 Act.	RD01/22791
	Repair pothole appr x 50. (Pot Hole)	ox' 300 x 200	At junction with CRANFORD TERRACE.	.RD 7 Day	Job Closed	12/04/2016	12/04/2016 Act.	RD01/22791
705269	Repair 2 potholes, b 450 x 300 x 50. (Pot		Outside 78 - 80.	.RD 7 Day	Job Closed	24/05/2016	24/05/2016 Act.	RD01/23325
706693	Approx 400 x 300 x Hole)	50. (Pot	At speed bump opposite number 59.	.RD 7 Day	Job Closed	12/07/2016	12/07/2016 Act.	RD01/23868
707038	clean and jet gullies	•	from great western road to Hutchison Terrace (cricket ground side)	.RD 14 Day	Job Closed	21/07/2016	27/07/2016 Act.	RD01/23976
	Repair 2 areas of da carriageway surface approx' 1 square me Hole)	e, total area	At edge of carriageway outside numbers 15 and 17.	.RD 7 Day	Job Closed	05/08/2016	06/08/2016 Act.	RD01/24194
708329	Find and fix 12 poth	ole filled by	various	.Routine Maintenance	Job Closed	06/09/2016	05/09/2016 Act.	
709935	repair pothole 600 x	400 70	79-81	.RD 2 Day	Job Closed	14/11/2016	14/11/2016 Act.	RD01/25150
709937	Repair all potholes a damage as required		whole street	.RD 14 Day	Job Closed	14/11/2016	22/11/2016 Act.	RD01/25168
	Repair approx' 8 squ of damaged carriage (Pot Hole)		Between junctions with HUTCHISON TERRACE and BROOMHILL ROAD.	.RD 14 Day	Contractor Completed	19/12/2016	30/12/2016 Act.	RD01/25573
	Repair 3 potholes, a x 300 x 50. (Pot Hol		Between number 88 and junction with BROOMHILL ROAD.	.RD 7 Day	Contractor Completed	06/02/2017	06/02/2017 Act.	RD01/26010
	Find and Fix 22 poth			.Routine Maintenance	Contractor Completed	30/03/2017	28/03/2017 Act.	
714466	Clean out bewteen spack with vuafux as		o/s 19	.RD 7 Day	Contractor Completed	17/04/2017	18/04/2017 Act.	RD01/26936
	Clean and jet blocke (Blocked Gully)	ed gulley.	Cranford Road outside Mr Chips opposite lampost number 1.	.RD 14 Day	Contractor Completed	15/05/2017	18/05/2017 Act.	RD01/27308
	Repair pothole appr x 50. (Pot Hole)		Adjacent to junction with CRANFORD TERRACE.	.RD 7 Day	Contractor Completed	11/07/2017	11/07/2017 Act.	RD01/27969

Effective: 01/03/2016 to 01/03/2018
Contract: Roads Contract (General Maint) (RD01)
Site: CRANFORD ROAD (7601827)

Service: Roads Display Action Officer: No

Maintenance Management											
Job No. De	scription	Location	Priority	Job Status	Entered	Completion	Works Order				
As	set: 1,000.00	Asset - Locn.: S/31/0686 - CRANFORD ROAD	Featur	e Type: RDS Road Section		Area: Aberdeen S	South				
	pair pothole approx' 300 x 20 0. (Pot Hole)	0 Lampost number 14.	.RD 7 Day	Contractor Completed	11/07/2017	11/07/2017 Act.	RD01/27969				
	pair 2 potholes, both approx' 0 x 300 x 60. (Pot Hole)	Outside numbers 74 and 104.	.RD 2 Day	Contractor Completed	28/08/2017	28/08/2017 Act.	RD01/28408				
by		d no. 55	.Routine Maintenance	Contractor Completed	26/09/2017	20/09/2017 Act.					
gul		outside 11	.RD 7 Day	Contractor Completed		25/01/2018 Act.					
	pair/fill (hot patch) multiple tholes	from Broomhill Road end of Cranford Road through to Great Western Road.	.RD 7 Day	Order Printed	28/02/2018	07/03/2018 Est.	RD01/29879				
	·	Asset - Locn.: 1 - Footway	Featur	e Type: RDS Footway		Area: Aberdeen S	South				
sla (Br	move depressed and broken b and replace with bitmac. roken Slab)		.RD 7 Day	Job Closed	05/08/2016	07/08/2016 Act.	RD01/24195				
rep Sla	,	On footway outside number 68.	.RD 7 Day	Job Closed		07/08/2016 Act.					
trip bitr	hazards and replace with mac. (Tree Root Damage)	g Around tree outside number 9.	.RD 14 Day	Job Closed	02/09/2016	07/09/2016 Act.	RD01/24423				
haz	move 3 slabs causing trip zards and replace with bitma ree Root Damage)	Around tree outside number 29.	.RD 14 Day	Job Closed	02/09/2016	07/09/2016 Act.	RD01/24423				
haz	move 4 slabs causing trip zards and replace with bitma ree Root Damage)	Around tree outside number 103.	.RD 14 Day	Job Closed	02/09/2016	07/09/2016 Act.	RD01/24423				
708265 Re de _l cau	move 1 x sunken slab and 1 pressed and broken slab using trip hazards and replac h bitmac. (Broken Slab)		.RD 7 Day	Job Closed	02/09/2016	07/09/2016 Act.	RD01/24423				
	move rocking slab and blace with bitmac. (Rocking lab)	On footway crossing outside number 96.	.RD 7 Day	Job Closed	02/09/2016	07/09/2016 Act.	RD01/24415				
	set dropped kerb causing trip zard. (Broken Kerb)	Opposite house number 53.	.RD 7 Day	Contractor Completed	06/12/2016	11/01/2017 Act.	RD01/25395				
710429 Re	place broken 2x2 broken slal	On footway opposite house number 53.	.RD 7 Day	Contractor Completed	06/12/2016	07/12/2016 Act.	RD01/25400				
hig	h and replace with bitmac	ng alongside Mannofield Squash Club	.RD 7 Day	Contractor Completed		02/02/2017 Act.					
711945 res	set 2 x sunken slab	alongside Mannofield Squash Club	.RD 7 Day	Contractor Completed	02/02/2017	02/02/2017 Act.	RD01/25973				

Contract: Roads Contract (General Maint) (RD01)

Site: CRANFORD ROAD (7601827)

Service: Roads
Display Action Officer: No

Mainter	nance Ma	nagement						
Job No.	Description	on	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset:	1,002.00	Asset - Locn.: 1 - Footway	Feat	ure Type: RDS Footway		Area: Aberde	en South
711946	utility box l concrete s	unken slabs round back to height of urround of box, repai ges to concrete	alongside Mannofield Squash Club ir	.RD 7 Day	Contractor Completed	02/02/2017	02/02/2017	Act. RD01/25973
711947	sitting prou	ound buchan trap is id , hauch round area high ridge .	alongside Mannofield Squash a Club	.RD 7 Day	Contractor Completed	02/02/2017	02/02/2017	Act. RD01/25973
711965		remove to slabs sittile place with bitmac	ng opp 17 at double white door	.RD 7 Day	Contractor Completed	03/02/2017	07/02/2017	Act. RD01/25978
712778	1x600x500	n lift 1x600x600, and b, and relay IG SLABS. (Rocking		.RD 2 Day	Contractor Completed	23/02/2017	23/02/2017	Act. RD01/26251
714166		insitu concrete and driveway in block per	o/s 69 as attached photo	.Routine Maintenance	Contractor Completed	05/04/2017	15/05/2017	Act. RD01/26833
718774	4 Lift and res 600mm pa	set rocking 600 x ving slab. See ic. (Rocking Slab)	Cranford Road outside number 9'	.RD 2 Day	Contractor Completed	19/10/2017	24/10/2017	Act. RD01/28779
718807	7 2 raised sl 25mm trip	abs - lift and relay -	Pavement outside 11 Cranford Road Aberdeen	.RD 2 Day	Contractor Completed	24/10/2017	26/10/2017	Act. RD01/28802

Contract: Roads Contract (General Maint) (RD01)

Site: CRANFORD ROAD (7601827)

Service: Roads Display Action Officer: No

Maintenance Management

Job No.	Description	n	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset:	1,002.00	Asset - Locn.: 1 - Footway		Feature Type: RDS Footway Area: Abero		Area: Aberdeen	South
72031	8 General Fi	nguiry - Refe	rence No : Cranford Road, Aberdeen	.RD 7 Day	Job Cancelled	23/01/2018	3 23/01/2018 Ac	<u> </u>

PATHS18424

Site (Street/Park/etc) : Cranford

Road

Location: 11 Cranford Road Locational Details: In front of

house

First Type of Fault : Rocking/Low

Manhole or Toby Cover

First Fault Details : The concrete around the toby cover is not level

with the footpath

Additional Information: The issue may seem minor, however the gap between the toby cover and our footpath into 11 Cranford Road is just the right size to trap a pram wheel making it very difficult to get our pram in and out of the house

Name:

Telephone Number :

Email Address:

731436) (Sunken Footway)

Contract: Roads Contract (General Maint) (RD01)

Site: CRANFORD ROAD (7601827)

Service: Roads
Display Action Officer: No

		Site: CRANFORD F	ROAD (7601827)					
Mainte	nance Ma	nagement						
Job No.	Description	on	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset:	1,002.00	Asset - Locn.: 1 - Footway		Feature Type: RDS Footway		Area: Aberdeen	South
72031	PATHS18 Site (Street Road Location: Locational house First Type Manhole of First Fault around the with the for Additional issue may the gap be and our for Road is ju a pram wh difficult to out of the	424 et/Park/etc): Cranfor 11 Cranford Road Details: In front of of Fault: Rocking/Lor r Toby Cover Details: The concre to toby cover is not levelopath Information: The seem minor, however etween the toby cover otpath into 11 Cranforst the right size to tra evel making it very get our pram in and house	ow te vel er r ord ap	.RD 7 Day	Job Cancelled	23/01/2018	23/01/2018 Act.	
72032	0 Repair/rearound To	Sunken Footway)	ea Cranford road outside number	.RD 7 Day	Contractor Completed	23/01/2018	29/01/2018 Act.	RD01/29484
	Asset:	1,010.00	Asset - Locn.: 9 - Cranford House-Duthie Place-Footway		Feature Type: RDS Footway		Area: Aberdeen	South

.RD 7 Day

Job Closed

08/10/2008 16/10/2008 Est.

relay.

55332 remove 1x3x2. slab, trim roots & at 119.