

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: SECOND AVENUE (39902153)

Site: SECOND AVENUE (39902153)

Locality: FRINTON ON SEA, ESSEX

Area: Frinton And Walton

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00011700	Feature Type: Local Road			Area: Frinton And Walton	
Batch:	6881352 - Ad Hoc Inspection Batch			Route: adhoc route				Date: 22/06/2022
3637606	RANSA Member led potholes - Title=A series of potholes, Cluster of potholes located in the road and in the 'cross junction' (Enquiry 2782778)	22/06/2022	Potholes in and around the cross junction at 5 Second Avenue, Frinton on Sea, Essex	HW: carriageway defect	Internal		Uncommitted	2332546
Batch:	6839882 - Inspection Batch No actionable defects found			Route: Area 01 Annual Nov Walked				Date: 16/11/2021
Batch:	6822517 - Inspection Batch			Route: adhoc route				Date: 26/08/2021
3598964	RA4=1x4 24m x 1.0m faded give way line 60%	26/08/2021	J/W Ashlyns Road	HW: worn or missing road mark	Internal		Action Required	
Batch:	6809197 - Inspection Batch			Route: adhoc route				Date: 05/07/2021
3588022	RA2=1x2 blocked gully	05/07/2021	Os 60	HW: blocked gully	Internal		Action Required	
Batch:	6809195 - Inspection Batch			Route: adhoc route				Date: 05/07/2021
3588021	RA2=1x2 8.0m x 0.5m standing water	05/07/2021	Os 58	HW: Standing Water	Internal		Action Required	
Batch:	6809186 - Inspection Batch			Route: adhoc route				Date: 05/07/2021
3588012	RA2=1x2 blocked gully	05/07/2021	Os 2	HW: blocked gully	Internal		Action Required	
Batch:	6753600 - Inspection Batch			Route: Area 02 Annual Nov Walked				Date: 06/11/2020
3509042	RESOLVED - RA3=1x3 f/w slab raised 0.6mx0.9 x20mm	06/11/2020	O/s68	HW: footway defect	Internal		No Action Required	
3509045	RESOLVED - RA2=2x1 0.6x0.6x25mm slab raised due to tree roots	06/11/2020	O/s21	HW: footway defect	Internal		No Action Required	
3509043	RESOLVED - RA2=1x2 f/w slab raised 0.6mx0.6 x20mm	06/11/2020	O/s60	HW: footway defect	Internal		No Action Required	
3509035	RA2=2x1 kerb misaligned 0.45x0.12 x20mm	06/11/2020	between no 3 and golf club, by bollard	HW: kerb mis-aligned	Internal		Action Required	
3509040	RESOLVED - RA3=1x3 f/w slab raised 0.6mx0.6 x20mm	06/11/2020	O/s 73	HW: footway defect	Internal		No Action Required	
3509046	RA2=2x1 surface broken up at base of bollard 0.5x0.3x30mm	06/11/2020	between no 3 and golf club, by bollard	HW: footway defect	Internal		Action Required	
3509039	RESOLVED - RA2=1x2 f/w slab raised 0.6mx0.9 x20mm	06/11/2020	O/s73	HW: footway defect	Internal		No Action Required	
3509044	RESOLVED - RA3=1x3 f/w slabs raised 0.6mx0.6 x20mm	06/11/2020	O/s56	HW: footway defect	Internal		No Action Required	
3509036	RESOLVED - RA2=1x2 f/w slabs raised 0.6mx0.6 x20mm	06/11/2020	O/s11	HW: footway defect	Internal		No Action Required	
3509037	RESOLVED - RA2=1x2 f/w slab raised 0.6mx0.9 x20mm	06/11/2020	O/s27	HW: footway defect	Internal		No Action Required	
3509041	RESOLVED - RA1=1x1 f/w slab uneven 0.6mx0.6 x20mm	06/11/2020	O/s68	HW: footway defect	Internal		No Action Required	

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: SECOND AVENUE (39902153)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00011700	Feature Type:	Local Road		Area:	Frinton And Walton
Batch:	6753600 - Inspection Batch			Route:	Area 02 Annual Nov Walked		Date:	06/11/2020
3509038	RA2=2x1 area of paving cracked/misaligned by vehicle/plant 4.8x1.8x25mm	06/11/2020	os 39	HW: footway defect	Internal		Action Required	
3509034	RESOLVED - Rangers, RA1=1x1, remains of fallen tree trunk in verge, old job number to remove fallen tree 2241234.	06/11/2020	Adj 2 The Esplanade.	Other	Internal		No Action Required	
3509047	RESOLVED - RA2=1x2 f/w slab raised 0.6mx0.6 x20mm	06/11/2020	O/s14	HW: footway defect	Internal		No Action Required	
Batch:	6669732 - Inspection Batch			Route:	Area 02 Annual Nov Walked		Date:	06/11/2019
3437989	Ra4=1x4 f/w breaking out edge of va 0.3x1.8x20mm	06/11/2019	O/s23	HW: footway defect	Internal		Committed	2285249
3437960	RA2=1x2 f/w slab raised 0.6mx0.6 x20mm	05/11/2019	O/s60	HW: footway defect	Internal		No Action Required	
3437987	Ra4=1x4 f/w breaking up on vx 2mx1.3x20mm	06/11/2019	O/s 4	HW: footway defect	Internal		Committed	2285249
3437964	RA2=1x2 C/w pot hole 0.4x0.3x50mm	05/11/2019	O/s2	HW: carriageway defect	Internal		Committed	2302681
3437985	RA6=2x3, Vehicle Access breaking up, eroded 3x3x25mm	06/11/2019	o/s no 58	HW: footway defect	Internal		Committed	2285249
3437963	RA2=1x2 C/w pot hole 0.4x0.3x50mm	05/11/2019	O/s2	HW: carriageway defect	Internal		Committed	2302681
3437966	RA2=1x2 C/w pot hole 0.4mx0.4x50mm	05/11/2019	O/s2	HW: carriageway defect	Internal		Committed	2302681
3437961	RA3=1x3 f/w slabs raised 0.6mx0.6 x20mm	05/11/2019	O/s56	HW: footway defect	Internal		No Action Required	
3437993	RA1=1x1 f/w slab uneven 0.6mx0.6 x20mm	05/11/2019	O/s68	HW: footway defect	Internal		No Action Required	
3437988	Ra4=1x4 f/w breaking up edge of va 0.4x1.8x20mm	06/11/2019	O/s 23	HW: footway defect	Internal		Committed	2285249
3437982	RA4=2x2, rocking slab, 1.2mx0.6mx25mm	06/11/2019	O/s 28	HW: footway defect	Internal		Committed	2285249
3437968	RA2=1x2 f/w slab raised 0.6mx0.9 x20mm	05/11/2019	O/s27	HW: footway defect	Internal		No Action Required	
3437990	Ra4=1x4 slabs sunk in footway 1.8x1.2x25mm	06/11/2019	O/s29	HW: footway defect	Internal		Committed	2285249
3437972	RA6=2x3 slabs uneven in f/w. 1.2m x 1.8m x 25mm	06/11/2019	boundary of 72 / 74	HW: footway defect	Internal		Committed	2285249
3437977	RA6=3x2 slabs raised uneven and rocking. 5.4m x 1.8m x 35mm	06/11/2019	O/s 28	HW: footway defect	Internal		Committed	2285249
3437975	Ra4=1x4 slabs sunk at edge of drive 0.6x1.2x20mm	06/11/2019	O/s 53	HW: footway defect	Internal		Committed	2285249
3437974	RA4=1x4 slabs sunk edge of va 0.3x1.8x20mm	06/11/2019	outside 57	HW: footway defect	Internal		Committed	2285249
3437973	RA6=3x2 slab broken and raised - 0.6x0.6x25mm	06/11/2019	os 80 - Opp79	HW: footway defect	Internal		Committed	2285249
3437980	DUPLICATE RA6=3x2 slabs uneven and rocking in f/w. 5.4m x 1.8m x 35mm	06/11/2019	O/s 28	HW: footway defect	Internal		Committed	2285249

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: SECOND AVENUE (39902153)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00011700	Feature Type:	Local Road		Area:	Frinton And Walton
Batch:	6669732 - Inspection Batch			Route:	Area 02 Annual Nov Walked		Date:	06/11/2019
3437969	RA2=1x2 c/w pot hole 2.0mx0.35mx50mm	05/11/2019	O/s35	HW: carriageway defect	Internal		Committed	2302681
3437976	RA6=2x3 slabs raised and rocking in f/w. 2.4m x 1.8m 30mm	06/11/2019	O/s 39	HW: footway defect	Internal		Committed	2285249
3437983	Ra6=2x3 slabs raised and rocking next to bt box 1.2x0.6x30mm	06/11/2019	Nr l/c11	HW: footway defect	Internal		Committed	2285249
3437970	RA2=1x2 f/w slab raised 0.6mx0.9 x20mm	05/11/2019	O/s73	HW: footway defect	Internal		No Action Required	
3437979	DUPLICATE Ra6=2x3 35mm slabs raised and rocking 5.4mx1.8mx35mm	06/11/2019	O/s28	HW: footway defect	Internal		Committed	2285249
3437984	RA2=1x2 slabs uneven and rocking in f/w.1.2m x 1.8m x 20mm	06/11/2019	O/s 38	HW: footway defect	Internal		Committed	2285249
3437981	Ra4=2x2 slabs raised and rocking 1.2x0.9x 30mm	06/11/2019	O/s28	HW: footway defect	Internal		Committed	2285249
3437986	RA4=2x2 fw ph on vx 2x2.5x30mm	06/11/2019	O/s 22	HW: footway defect	Internal		Committed	2285249
3437978	RA4=2x2, uneven slabs,1.2x0.6x25mm .	06/11/2019	O/s 28	HW: footway defect	Internal		Committed	2285249
3437991	Ra6=2x3 slabs raised due to tree roots 3.6x0.9x25mm	06/11/2019	O/s31	HW: footway defect	Internal		Committed	2285249
3437965	RA2=1x2 C/w pot hole 1.0x0.4x50mm	05/11/2019	O/s2	HW: carriageway defect	Internal		Committed	2302681
3437992	Ra4=1x4slabs lifted due to tree roots 3.6x1.8x25mm	06/11/2019	O/s 31	HW: footway defect	Internal		Committed	2285249
3437959	RA3=1x3 f/w slab raised 0.6mx0.9 x20mm	05/11/2019	O/s68	HW: footway defect	Internal		No Action Required	
3437967	RA2=1x2 f/w slabs raised 0.6mx0.6 x20mm	05/11/2019	O/s11	HW: footway defect	Internal		No Action Required	
3437971	RA3=1x3 f/w slab raised 0.6mx0.6 x20mm	05/11/2019	O/s 73	HW: footway defect	Internal		No Action Required	
3437962	RA2=1x2 f/w slab raised 0.6mx0.6 x20mm	05/11/2019	O/s14	HW: footway defect	Internal		No Action Required	
Batch:	6616920 - Inspection Batch			Route:	adhoc route		Date:	16/04/2019
3358827	Ra6=2x3, slab raised 0.6x0.9x30mm, superseded.	16/04/2019	O/s 38	HW: footway defect	Internal		Committed	2285249
Batch:	6533293 - Inspection Batch			Route:	adhoc route		Date:	31/12/2018
3309985	RA2=1x2, p/hole, 0.6x0.4x55mm, relocated.	31/12/2018	Jct with The Esplanade.	HW: carriageway defect	Internal		Committed	2297996
Batch:	6533270 - Inspection Batch			Route:	adhoc route		Date:	31/12/2018
3309975	RA2=1x2, p/hole, 0.6x0.4x55mm.	31/12/2018	Jct with The Esplanade.	HW: carriageway defect	Internal		No Action Required	
Batch:	6501383 - Inspection Batch			Route:	Area 02 Annual Nov Walked		Date:	16/11/2018
3288974	RA2=2x1 Paver cracked and raised 0.6x0.25x40mm	09/11/2018	os 6 by tree	HW: footway defect	Internal		Committed	2285249
3288904	RA9=3x3 0.6x0.6x45mm slab raised and rocking	16/11/2018	Between 68 & 72 :(Opposite 71)	HW: footway defect	Internal		Committed	2263663

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: SECOND AVENUE (39902153)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00011700	Feature Type:	Local Road		Area:	Frinton And Walton
Batch:	6501383 - Inspection Batch			Route:	Area 02 Annual Nov Walked		Date:	16/11/2018
3288902	RA9=3x3 - 1.2m x 1.2m x 50mm slabs rocking and misaligned	16/11/2018	O/s 34	HW: footway defect	Internal		Committed	2263663
3288918	RA6=2x3 1.2x1.8 x 35mm slabs raised and uneven.	09/11/2018	O/s 40 between tree and VA	HW: footway defect	Internal		Committed	2285249
3288965	Ra6=2x3 slabs raised and broken in footway 3.0x1.8x25mm	09/11/2018	O/s74 by LH VA	HW: footway defect	Internal		Committed	2285249
3288944	Ra6=2x3 slabs uneven & raised in f/w.1.2x1.8x35mm	09/11/2018	O/s 40 nr VA to 38	HW: footway defect	Internal		Committed	2285249
3288903	RA9=3x3 - 2 x slabs uneven & raised in f/w. 0.6x0.6 x35mm and 0.6x0.6x30mm	16/11/2018	between 68 & 72 (Opposite 71)	HW: footway defect	Internal		Committed	2263663
3289008	RA3=1x3 CW eroding by manhole cover 0.55x0.25 x50mm (not marked)	09/11/2018	os VA to 74 by manhole	HW: carriageway defect	Internal		Committed	2302681
3289006	RA2=2x1 FW Concrete paver slab raised 0.6x0.6x20mm	09/11/2018	between house No.s 53a and 55	HW: footway defect	Internal		Committed	2285249
3289005	DUPLICATE OF 3288958 - RA4=2x2 2.4m x 1.8m x 25mm slabs uneven in f/w.	09/11/2018	O/s 71	Defect Deleted	No Defect Found		No Action Required	
3289004	RA6=2x3 slabs raised and uneven.1.8x6.6x30mm	09/11/2018	O/s 74	HW: footway defect	Internal		Committed	2285249
3289003	DUPLICATE OF 20365535 - RA2=2x1 0.6x0.6x25mm slabs sunk in f/w.	09/11/2018	O/s 18	Defect Deleted	No Defect Found		No Action Required	
3289002	RA6=2x3 1.2m x 1.8m x 20mm slabs uneven in f/w.	09/11/2018	boundary of 72 / 74	HW: footway defect	Internal		No Action Required	
3289001	RA6=2X3 slabs uneven due to tree roots 1.8x0.6x20mm	09/11/2018	os 80 - opposite 79	HW: footway defect	Internal		Committed	2285249
3289000	RA6=2X3 slab uneven 0.6x0.6x25mm	09/11/2018	outside 74 by VA	HW: footway defect	Internal		Committed	2285249
3288998	DUPLICATE OF 3288944 - RA 2 2X1 3no 0.6x0.6 slabs uneven due to tree roots	09/11/2018	outside 40	Defect Deleted	No Defect Found		No Action Required	
3288997	DUPLICATE OF 3147884 - RA 2= 2X1 0.6x0.6 slab sunk	09/11/2018	outside 28	Defect Deleted	No Defect Found		No Action Required	
3288996	DFRE -RA 2 2X1 0.9x0.6 slab uneven due to tree roots	09/11/2018	outside 35	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3288994	DFRE - RA 2=2X1 footway uneven due to tree roots 12m2	09/11/2018	outside 45 to jnc holland road	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3288993	DFRE -RA 2 2X1 2no 0.6x0.6 slabs uneven	09/11/2018	outside 63	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3288992	DFRE - RA2= 2X1 footway 0.9x0.6 slab sunk	09/11/2018	outside 65	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3288990	DFRE - Ra6=2x3 1.8x1.8xupto 25mm slabs uneven in footway	09/11/2018	O/s 55	HW: FWSF 2008 STRATEGY	Internal		No Action Required	

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: SECOND AVENUE (39902153)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00011700	Feature Type:	Local Road		Area:	Frinton And Walton
Batch:	6501383 - Inspection Batch			Route:	Area 02 Annual Nov Walked		Date:	16/11/2018
3288989	RA2=2x1 slab raised due to tree roots 0.6x0.6x25mm	09/11/2018	O/s55	HW: footway defect	Internal		Committed	2285249
3288988	RESOLVED, REPAIR DONE - Ra2=1x2 0.9 channel kerb missing	09/11/2018	O/s15	HW: kerb missing	Internal		No Action Required	
3288987	Ra4=2x2 slab raised 0.6x0.9x30mm	09/11/2018	O/s 38	HW: footway defect	Internal		No Action Required	
3288986	Ra6=2x3 slabs raised and broken in footway 3.6x1.2x35mm	09/11/2018	O/s 40 by tree	HW: footway defect	Internal		Committed	2285249
3288985	DUPLICATE OF 3288965 - Ra4=2x2 - 0.6x0.6x25mm slab raised and rocking	09/11/2018	O/s74	Defect Deleted	No Defect Found		No Action Required	
3288991	RA4=2x2 - 0.6x0.6x20mm slab broken and raised	09/11/2018	os 80 - Opp79	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3288984	DUPLICATE OF 3288918 - Ra6=2x3 3m x 1.8x upto 40mm slabs raised and rocking	09/11/2018	O/s40	Defect Deleted	No Defect Found		No Action Required	
3288983	DFRE - Ra2=1x2 0.6x0.9x10mm slab broken and rocking	09/11/2018	O/s11	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3288982	DUPLICATE OF 3147885 - Ra4=1x4 0.6x1.2x25mm slabs sunk	09/11/2018	O/s39	Defect Deleted	No Defect Found		No Action Required	
3288995	DFRE - RA 2 2X1 2no 0.6x0.6 slabs uneven around water boxes	09/11/2018	outside 35	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3288980	DFRE - Ra2=1x2 0.6x0.6 loose and broken slab	09/11/2018	O/s link view	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3288979	RESOLVED, REPAIR DONE - Ra2=1x2 4mx2mx25mm f/w breaking out	09/11/2018	O/s 20	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3288978	DFRE - Ra2=1x2 - 0.6x0.6 loose and broken slab	09/11/2018	O/s 22	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3288999	RA4=2X2 slab uneven due to tree roots0.6x0.6x20mm	16/11/2018	outside 44	HW: footway defect	Internal		Committed	2285249
3288981	Ra4=2x2 - fillet round bt cover missing and loose 0.3x0.1x30mm	09/11/2018	O/s 47	HW: footway defect	Internal		Committed	2285249
3288977	RESOLVED, REPAIR DONE - Ra2=2x1 0.3 Kerb damaged	09/11/2018	J/w ashlyns rd	HW: kerb damaged	Internal		No Action Required	
3288976	Ra2=2x1 slabs sunk by radius of VA 0.9x1.3x30mm	09/11/2018	os 47 Ivanhoe (Opp 40)	HW: footway defect	Internal		Committed	2285249
3288973	RA6=2x3 slabs and cement fillet raised and uneven 1.2x1.5x25mm	09/11/2018	by alley between 68 & 70	HW: footway defect	Internal		Committed	2285249
3288972	RA4=2x2 FW pavers sunk by kerb of VA 1.20.5x25mm	09/11/2018	by VA to 71	HW: footway defect	Internal		Committed	2285249
3288975	DFRE -Ra4=1x4 1.2x1.5 loose and rocking paving slabs	09/11/2018	o/s 68	HW: FWST 2008 STRATEGY	Internal		No Action Required	
3288958	RA6=2x3 footway slabs cracked and uneven 2.4x1.8x25mm	09/11/2018	outside 71	HW: footway defect	Internal		Committed	2285249

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: SECOND AVENUE (39902153)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00011700	Feature Type:	Local Road		Area:	Frinton And Walton
Batch:	6501383 - Inspection Batch			Route:	Area 02 Annual Nov Walked		Date:	16/11/2018
3289007	RA6=2x3 paver uneven 0.9x0.6x20mm	09/11/2018	os 80 just past LHS VA of 74	HW: footway defect	Internal		Committed	2285249
Batch:	6490212 - Inspection Batch			Route:	adhoc route		Date:	01/11/2018
3278437	RA6=2x3 1.2m x 1.2m x 30mm slabs raised and rocking in f/w. (Superceded to new S3 status)	01/11/2018	O/s 34	HW: footway defect	Internal		No Action Required	
Batch:	6404417 - Inspection Batch			Route:	adhoc route		Date:	05/06/2018
3229812	Rangers, RA1=1x1, remains of fallen tree trunk in verge, old job number to remove fallen tree 2241234.	05/06/2018	Adj 2 The Esplanade.	Other	Internal		No Action Required	
Batch:	6399126 - Inspection Batch			Route:	adhoc route		Date:	24/05/2018
3226483	RA6=2x3, Vehicle Access breaking up, eroded 3x3x25mm	24/05/2018	o/s no 58	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
Batch:	6399092 - Inspection Batch			Route:	adhoc route		Date:	24/05/2018
3226457	RA4=2x2 fw ph on vx 2x2.5x30mm	24/05/2018	O/s 22	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
Batch:	6399077 - Inspection Batch			Route:	adhoc route		Date:	24/05/2018
3226436	Ra 2=2x1 gully inlet blocked 0.4x0.4 metal	24/05/2018	Os 3	HW: blocked gully	Internal		Committed	2254890
Batch:	6364528 - Inspection Batch			Route:	adhoc route		Date:	09/04/2018
3210954	Ra2=1x2 0.6x0.3x50mm c/w pothole	09/04/2018	O/s6	HW: CWSF 2008 STRATEGY	Internal		Committed	2269018
Batch:	6290907 - Inspection Batch			Route:	adhoc route		Date:	20/12/2017
3179663	Ra2=2x1 kerb offset blocked (full of leaves) Cleared leaves from entrance by inspector May still have a restriction further along No standing water at time of visit	20/12/2017	O.s.3	HW: blocked gully	Internal		Committed	2245677
Batch:	6285698 - Inspection Batch			Route:	adhoc route		Date:	09/12/2017
3177212	Make safe fallen tree following RTC	09/12/2017	Junction Esplanade	HW: debris/deposit on highway	Internal		Committed	2241111
Batch:	6262780 - Inspection Batch			Route:	Area 02 Annual November		Date:	02/11/2017
3165300	Ra2=1x2 0.9 channel kerb missing	02/11/2017	O/s15	HW: kerb missing	Internal		No Action Required	
3165299	Ra2=1x2 0.8x0.3x25mm f/w breaking out kerb edge	02/11/2017	O/s15	HW: FWSF 2008 STRATEGY	Internal		Committed	2285249
3165312	Ra6=2x3 1.2x0.6x30mm slabs raised and rocking next to bt box	02/11/2017	Nr l/c11	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3165308	RA4=1x4 0.3x1.8x20mm slabs sunk edge of va	02/11/2017	outside 57	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3165315	Ra4=2x2 0.6x0.5xupto 60mm c/w pothole	02/11/2017	J/w esplanade	HW: CWSF 2008 STRATEGY	Internal		Committed	2240170
3165314	Ra4=2x2 1.2x0.8xupto70mm c/w pothole	02/11/2017	J/w esplanade	HW: CWSF 2008 STRATEGY	Internal		Committed	2240170
3165313	Ra2=1x2 10mx0.2 x50mm c/w edge breaking out	02/11/2017	Opp5	HW: CWSF 2008 STRATEGY	Internal		Committed	2240170
3165311	Ra2=1x2 0.6x0.6x20mm slab sunk in footway	02/11/2017	O/s34	HW: FWSF 2008 STRATEGY	Internal		Committed	2285249

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: SECOND AVENUE (39902153)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00011700	Feature Type: Local Road			Area: Frinton And Walton	
Batch:	6262780 - Inspection Batch			Route: Area 02 Annual November			Date: 02/11/2017	
3165310	Ra4=2x2 0.6x0.6xupto40mm slab raised in f/w.	02/11/2017	O/s 40	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3165309	Ra2=1x2 .6x0.6x20mm slab broken and raised	02/11/2017	Opp79	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3165307	Ra6=2x3 1.8x1.8xupto 25mm slabs uneven in footway	02/11/2017	O/s 55	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3165306	Ra6=2x3 2.4x0.9x25mm slabs raised due to tree roots	02/11/2017	O/s55	HW: FWST 2008 STRATEGY	Internal		No Action Required	
3165305	Ra2=1x2 0.6x0.6x20mm slab raised in footway	02/11/2017	O/s31	HW: FWSF 2008 STRATEGY	Internal		Committed	2285249
3165304	Ra4=1x4 1.8x1.2xupto 25mm slabs sunk in footway	02/11/2017	O/s27	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3165303	Ra3=1x3 0.6x0.9x20mm slab raised in footway	02/11/2017	O/s27	HW: FWSF 2008 STRATEGY	Internal		Committed	2285249
3165302	Ra4=1x4 0.3x1.8x20mm f/w breaking out edge of va	02/11/2017	O/s23	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3165301	Ra2=2x1 0.6x0.6x25mm slab raised due to tree roots	02/11/2017	O/s21	HW: FWST 2008 STRATEGY	Internal		No Action Required	
3165316	Ra2=1x2 0.15x0.2x20mm concrete breaking out round water box	02/11/2017	O/s7	HW: FWSF 2008 STRATEGY	Internal		Committed	2285249
Batch:	6219065 - Inspection Batch			Route: adhoc route			Date: 31/08/2017	
3147893	Ra4=2x2 0.6x0.6x25mm slab raised and rocking	31/08/2017	O/s74	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
Batch:	6219064 - Inspection Batch			Route: adhoc route			Date: 31/08/2017	
3147892	Ra6=2x3 1.2x1.8x25mm slabs raised in footway	31/08/2017	O/s74	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
Batch:	6219062 - Inspection Batch			Route: adhoc route			Date: 31/08/2017	
3147891	Ra4=2x2 0.6x0.6x30mm slab raised and rocking	31/08/2017	Opp71	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
Batch:	6219061 - Inspection Batch			Route: adhoc route			Date: 31/08/2017	
3147890	Ra6=2x3 3m x 1. 8x upto 40mm slabs raised and rocking	31/08/2017	O/s40	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
Batch:	6219060 - Inspection Batch			Route: adhoc route			Date: 31/08/2017	
3147889	Ra4=2x2 1.8x1.2x30mm slabs raised in footway	31/08/2017	O/s40	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
Batch:	6219059 - Inspection Batch			Route: adhoc route			Date: 31/08/2017	
3147888	Ra4=2x2 0.6x0.9x30mm slab raised	31/08/2017	O/s 38	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
Batch:	6219058 - Inspection Batch			Route: adhoc route			Date: 31/08/2017	
3147887	RA6=2x3 1.2m x 1.2m x 30mm slabs raised and rocking in f/w.	31/08/2017	O/s 34	HW: FWSF 2008 STRATEGY	Internal		No Action Required	

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: SECOND AVENUE (39902153)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,000.00	Asset - Locn.: 00011700			Feature Type: Local Road			Area: Frinton And Walton	
Batch: 6219056 - Inspection Batch				Route: adhoc route				Date: 31/08/2017
3147885	RA6=2x3 2.4m x 1.8m upto 30mm slabs raised and rocking in f/w.	31/08/2017	O/s 39	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
Batch: 6219055 - Inspection Batch				Route: adhoc route				Date: 31/08/2017
3147884	Ra6=2x3 4.8x1.8xup to 35mm slabs raised and rocking	31/08/2017	O/s28	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
Batch: 6219052 - Inspection Batch				Route: adhoc route				Date: 31/08/2017
3147882	Ra4=2x2 1.2x0.9xup to 30mm slabs raised and rocking	31/08/2017	O/s28	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
Batch: 6219051 - Inspection Batch				Route: adhoc route				Date: 31/08/2017
3147881	Ra3=1x3 0.6x0.9x20mm slab broken and raised	31/08/2017	O/s 20	HW: FWSF 2008 STRATEGY	Internal		Committed	2285249
Batch: 6219050 - Inspection Batch				Route: adhoc route				Date: 31/08/2017
3147880	Ra2=1x2 0.6x0.9x10mm slab broken and rocking	31/08/2017	O/s11	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
Batch: 5158644 - Inspection Batch				Route: adhoc route				Date: 23/12/2016
20376383	Ra16=4x4 0.6x0.3x30mm f/w calapsed back of gully	23/12/2016	J/w ashlyns 6	HW: FWST 2008 STRATEGY	Internal		Committed	2220458
Batch: 5131717 - Inspection Batch				Route: Area 02 Annual November				Date: 16/11/2016
20365538	Ra4=1x4 0.6x1.2x25mm slabs sunk	16/11/2016	O/s33	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
20365537	Ra2=2x1 0.9 kerb damage	16/11/2016	O/s60	HW: kerb damaged	Internal		Action Required	
20365536	Ra2=1x2 0.5x0.5x50mm c/w edge pothole	16/11/2016	Opp57	HW: CWSF 2008 STRATEGY	Internal		Committed	2240170
20365535	Ra2=1x2 0.6x0.6x20mm slab sunk in f/w	16/11/2016	Opp31	HW: FWSF 2008 STRATEGY	Internal		Committed	2285249
20365534	Ra2=2x1 0.6x0.8x50mm c/w pothole	16/11/2016	J/w esplanade	HW: CWSF 2008 STRATEGY	Internal		No Action Required	
20365533	Ra1=1x1 hatchlings in center of c/w faded resolved	16/11/2016	J/w esplanade	HW: worn or missing road mark	Internal		No Action Required	
20365532	Ra4=2x2 1.8x0.9x25mm slabs raised due to tree roots	16/11/2016	O/s31	HW: FWST 2008 STRATEGY	Internal		No Action Required	
Batch: 5120829 - Ad Hoc Inspection Batch				Route: adhoc route				Date: 01/11/2016
20361318	RA 1x1 blocked gullies	27/10/2016	O/s 3	HW: blocked gully	Internal		Committed	2217527
Batch: 5105186 - Inspection Batch				Route: adhoc route				Date: 07/10/2016
20353180	Ra1=1x1 hatchlings in center of c/w faded	07/10/2016	J/w esplanade	HW: worn or missing road mark	Internal		No Action Required	
Batch: 2894189 - Inspection Batch				Route: adhoc route				Date: 28/09/2016
20350720	RA2=2x1, pipe connection from s/e gully full of leaves ect.	28/09/2016	O/s 40	HW: blocked gully connection	Internal		Committed	2218099
Batch: 2834251 - Inspection Batch				Route: adhoc route				Date: 17/06/2016
20323742	RA4=2x2, rocking slab, 0.6x22mm upstand	17/06/2016	O/s 28	HW: FWSF 2008 STRATEGY	Internal		No Action Required	

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: SECOND AVENUE (39902153)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00011700	Feature Type: Local Road		Area: Frinton And Walton		
Batch:	2834251 - Inspection Batch			Route: adhoc route		Date: 17/06/2016		
20323741	RA4=2x2, uneven slabs, 0.7x37mm upstand.	17/06/2016	O/s 28	HW: FWSF 2008 STRATEGY	Internal	No Action Required		
Batch:	2755968 - Inspection Batch			Route: adhoc route		Date: 05/01/2016		
20278007	RANSA void in carriageway. Excavated by national grid, however it is not their responsibility. Backfill required with type one and carriageway patch. 3.6x1.4x1.1	05/01/2016	Jnc Holland road	HW: CWST 2008 STRATEGY	Internal	Committed	1597811	

Customer Services

Enquiry No.:	2784447	Logged by:	CRM Connector	on:	01/07/2022 14:10			
Service:	Maintenance	Subject:	footway defects	Classification:	fault reports			
Desc.:	Title=More than 2cm,50m stretch of pavement with 3 dangerous slabs two identified with cones on top of them one not. The one without the cone on it is rocking with a height difference in excess of 30mm - this is the one that a member of the public injured herself on on Tuesday. The other two are also lethal.							
Location:	**MEMBER ENQUIRIES**50m stretch of pavement with 3 dangerous slabs			Contact:				
Enquiry No.:	2784287	Logged by:	CRM Connector	on:	30/06/2022 13:11			
Service:	Maintenance	Subject:	footway defects	Classification:	fault reports			
Desc.:	Title=More than 2cm,Three examples of dangerous pavements within 50metres of each other. One is rocking with a 40mm difference in height. This location a person was injured on Tuesday night accident and emergency confirmed head injuries. This will most likely become a claim. The other two are similar in nature again both dangerous and appear to be known to you because cones mark the spot (interestingly not on the database system for some reason). I have photos but for some reason your system will not upload them.							
Location:	**MEMBER ENQUIRIES**Outside 72 Second Avenue			Contact:				
Enquiry No.:	2776287	Logged by:	CRM Connector	on:	09/05/2022 17:01			
Service:	Maintenance	Subject:	footway defects	Classification:	fault reports			
Desc.:	Title=More than 2cm,Dropped kerb has been covered by shingles for a number of months,							
Location:	Drive/dropped kerb if 39 Second Avenue			Contact:				
Enquiry No.:	2775810	Logged by:	CRM Connector	on:	06/05/2022 04:42			
Service:	Maintenance	Subject:	footway defects	Classification:	fault reports			
Desc.:	Dangerous paving slab: Dangerous paving slab-pedestrians beware!							
Location:				Contact:				
Enquiry No.:	2754750	Logged by:	CRM Connector	on:	22/12/2021 14:03			
Service:	Maintenance	Subject:	footway defects	Classification:	fault reports			
Desc.:	Title=More than 2cm,Footpath and dropped kerb have been dug up and filled with loose shingle							
Location:	Outside 39 Second Avenue, Frinton on Sea.			Contact:				
Enquiry No.:	2646872	Logged by:	CRM Connector	on:	06/01/2020 09:48			
Service:	Maintenance	Subject:	footway defects	Classification:	fault reports			
Desc.:	Report Pavement / Kerb - pavement or cycle path - Caller states: (MS) There are some barriers around a raised pavement slab (at least 1.5 to 2 inches), these barriers have been there for about 4 months with no sign of any work being done. They are blocking the entire pavement, there doesn't seem to be any indication of work having been done here.							
Location:	O/S No 35			Contact:				

Effective: 01/01/2016 to 09/07/2022

Asset Number: 1000.00 to 1999.00

Service: Maintenance

Subject: footway defects (FWDF)

Display Action Officer: No

Site: SECOND AVENUE (39902153)

Customer Services

Enquiry No.: 2646507 Logged by: CRM Connector on: 02/01/2020 18:39
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report Pavement / Kerb - pavement or cycle path - slab raised over 2cm
 Location: 55 Second Avenue frinton Contact:

Enquiry No.: 2646506 Logged by: CRM Connector on: 02/01/2020 18:38
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report Pavement / Kerb - pavement or cycle path - paving slabs raised 2.5cm and 2cm
 Location: 51 Second Avenue Contact:

Enquiry No.: 2646505 Logged by: CRM Connector on: 02/01/2020 18:36
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report Pavement / Kerb - pavement or cycle path - slab raised 3cm
 Location: 39 Second Avenue Frinton Contact:

Enquiry No.: 2646503 Logged by: CRM Connector on: 02/01/2020 18:35
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report Pavement / Kerb - pavement or cycle path - slabs raised 3cm and 2.5cm
 Location: 31 Second Avenue Frinton Contact:

Enquiry No.: 2646502 Logged by: CRM Connector on: 02/01/2020 18:33
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report Pavement / Kerb - pavement or cycle path - slab raised 2.5cm
 Location: 27 Second Avenue Frinton Contact:

Enquiry No.: 2646501 Logged by: CRM Connector on: 02/01/2020 18:32
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report Pavement / Kerb - pavement or cycle path - paving slab rocking and cracked
 Location: 11 second avenue frinton Contact:

Enquiry No.: 2646500 Logged by: CRM Connector on: 02/01/2020 18:29
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report Pavement / Kerb - pavement or cycle path - slab raised 2.5cm
 Location: 18 Second Avenue,frinton Contact:

Enquiry No.: 2646499 Logged by: CRM Connector on: 02/01/2020 18:27
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report Pavement / Kerb - pavement or cycle path - paving slab raised 2cm and cracked badly
 Location: 20 Second Avenue Frinton Contact:

Enquiry No.: 2646498 Logged by: CRM Connector on: 02/01/2020 18:25
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report Pavement / Kerb - pavement or cycle path - slab raised 2cm
 Location: 26 second avenue frinton Contact:

Enquiry No.: 2646497 Logged by: CRM Connector on: 02/01/2020 18:24
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report Pavement / Kerb - pavement or cycle path - slabs raised 2cm, 3cm and 3.5cm
 Location: 28 Second Avenue frinton Contact:

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: SECOND AVENUE (39902153)

Customer Services

Enquiry No.: 2646495	Logged by: CRM Connector	on: 02/01/2020 18:22	
Service: Maintenance	Subject: footway defects	Classification: fault reports	
Desc.: Report Pavement / Kerb - pavement or cycle path - slab raised 2cm			
Location: 30 Second Avenue frinton	Contact:		
Enquiry No.: 2646494	Logged by: CRM Connector	on: 02/01/2020 18:21	
Service: Maintenance	Subject: footway defects	Classification: fault reports	
Desc.: Report Pavement / Kerb - pavement or cycle path - slab raised 3cm			
Location: 38 Second Avenue	Contact:		
Enquiry No.: 2646493	Logged by: CRM Connector	on: 02/01/2020 18:19	
Service: Maintenance	Subject: footway defects	Classification: fault reports	
Desc.: Report Pavement / Kerb - pavement or cycle path - slab raised 2.5cm and rocks (been like this for years and marked by council) slab raised 3.75cm cracked and rocks (been like this for years and marked by council) other slabs raised 2.5cm, 3cm and 3cm. Reported several years running from 2016, 2017, 2018. About time you repaired these very dangerous slabs!			
Location: 40 second avenue frinton	Contact:		
Enquiry No.: 2646491	Logged by: CRM Connector	on: 02/01/2020 18:16	
Service: Maintenance	Subject: footway defects	Classification: fault reports	
Desc.: Report Pavement / Kerb - pavement or cycle path - paving slab raised 2cm			
Location: 56 Second Avenue Frinton	Contact:		
Enquiry No.: 2646489	Logged by: CRM Connector	on: 02/01/2020 18:15	
Service: Maintenance	Subject: footway defects	Classification: fault reports	
Desc.: Report Pavement / Kerb - pavement or cycle path - paving slab raised 2.5cm			
Location: 60 Second Avenue	Contact:		
Enquiry No.: 2646486	Logged by: CRM Connector	on: 02/01/2020 18:11	
Service: Maintenance	Subject: footway defects	Classification: fault reports	
Desc.: Report Pavement / Kerb - pavement or cycle path - slabs raised 2.5cm and 2cm			
Location: 74 second avenue frinton	Contact:		
Enquiry No.: 2646485	Logged by: CRM Connector	on: 02/01/2020 18:09	
Service: Maintenance	Subject: footway defects	Classification: fault reports	
Desc.: Report Pavement / Kerb - pavement or cycle path - slabs raised 2.5cm x 2			
Location: 80 second avenue frinton	Contact:		
Enquiry No.: 2641835	Logged by: [REDACTED]	on: 28/11/2019 08:30	
Service: Maintenance	Subject: footway defects	Classification: fault reports	Enquiry Ref: M19TP000534
Desc.: PERSONAL INJURY - Proceeding towards Ashlyns Road, and tripped on protruding paving slab causing them to fall and sustain injury			
Location: INSURANCE CLAIM - Heading towards Ashlyns Road - approx 28yards before driveway of number 80 (Merryday Cottage) on same side	Contact:		
Plot Number: 1,000.00	Feature Id - Location: 00011700	Feature Type: Local Road	
Job Number: 2285249			

Effective: 01/01/2016 to 09/07/2022
 Service: Maintenance
 Display Action Officer: No

Asset Number: 1000.00 to 1999.00
 Subject: footway defects (FWDF)
 Site: SECOND AVENUE (39902153)

Customer Services

Enquiry No.: 2615028 **Logged by:** CRM Connector **on:** 27/04/2019 18:08
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - There are several trip hazards due to lifting paving slabs in Second Avenue. Several are raised in excess of 30mm out of alignment with other slabs.
 In this street alone, I would estimate that there are at least 20 paving slabs which are a potential trip hazard particularly to the elderly.
 Most are on the 'even number' side of the street due to movement by tree roots.
Location: 38 Second Avenue - Pathway **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011700 **Feature Type:** Local Road
Job Number: 2285249 **Defect Number:** 3437984

Enquiry No.: 2613812 **Logged by:** CRM Connector **on:** 15/04/2019 11:46
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: UPLIFTED/UNEVEN PAVEMENT SLABS
Location: OUTSIDE NUMBER 38 NEAR TO PROPERTY BOUNDARY WHERE PLANTS ARE **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011700 **Feature Type:** Local Road
Job Number: 2285249 **Defect Number:** 3358827

Enquiry No.: 2613709 **Logged by:** CRM Connector **on:** 13/04/2019 16:48
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path -
Location: Pavement uneven outside 28 Second Avenue. **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011700 **Feature Type:** Local Road
Job Number: 2285249 **Defect Number:** 3437980

Enquiry No.: 2603568 **Logged by:** CRM Connector **on:** 29/01/2019 12:34
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - Dropped kerb is breaking and every time it rains the water collects in the cracks and freezes causing a slip hazard for the locals
Location: 53 Second Avenue, Frinton-on-Sea **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011700 **Feature Type:** Local Road
Job Number: 2285249 **Defect Number:** 1559128

Enquiry No.: 2591268 **Logged by:** CRM Connector **on:** 12/10/2018 12:38
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: pavement or cycle path - Customer states that there are loose paving slab(s) that are needing attention, they are jutting up and move when you walk on them. Husband tripped on them this week.
Location: Outside 34 Second Avenue **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011700 **Feature Type:** Local Road
Job Number: 2263663 **Defect Number:** 3288902

Enquiry No.: 2580986 **Logged by:** CRM Connector **on:** 24/07/2018 11:53
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - caller states there are 4 paving slabs raised up causing a tripping hazard and one of the slabs is cracked.this has been like this for approx 3 years and getting worse
Location: Os 31 Second avenue **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011700 **Feature Type:** Local Road
Job Number: 2285249 **Defect Number:** 3165305

Effective: 01/01/2016 to 09/07/2022
 Service: Maintenance
 Display Action Officer: No

Asset Number: 1000.00 to 1999.00
 Subject: footway defects (FWDF)
 Site: SECOND AVENUE (39902153)

Customer Services

Enquiry No.: 2580984 Service: Maintenance Desc.: pavement or cycle path - caller states there are 6 paving slabs sticking up by approx 3CM and are rocking as you walk over them. This has been like this for approx 3 years and getting worse. Location: OS 28 Second avenue	Logged by: CRM Connector Subject: footway defects	on: 24/07/2018 11:51 Classification: fault reports	Contact:
Plot Number: 1,000.00 Job Number: 2285249	Feature Id - Location: 00011700 Defect Number: 3437981	Feature Type: Local Road	
Enquiry No.: 2580981 Service: Maintenance Desc.: Report Pavement / Kerb - pavement or cycle path - caller states there are a number of paving slabs that are sticking up at various heights from 2-4 CM also there are two slabs that are cracked. this has been like this for approx 3 years and getting worse. Location: Os 40 SECOND AVENUE	Logged by: CRM Connector Subject: footway defects	on: 24/07/2018 11:46 Classification: fault reports	Contact:
Plot Number: 1,000.00 Job Number: 2285249	Feature Id - Location: 00011700 Defect Number: 3358827	Feature Type: Local Road	
Enquiry No.: 2580952 Service: Maintenance Desc.: Report Pavement / Kerb - pavement or cycle path - Customer states: 3 pavement slabs are raise by aprox 4cm and are rocking, Location: in between nos 68 - 72	Logged by: CRM Connector Subject: footway defects	on: 24/07/2018 09:53 Classification: fault reports	Contact:
Plot Number: 1,000.00 Job Number: 2263663	Feature Id - Location: 00011700 Defect Number: 3288904	Feature Type: Local Road	
Enquiry No.: 2568755 Service: Maintenance Desc.: Report Pavement / Kerb - pavement or cycle path - Always 'pools' here beside steps to pavement and across the alleyway to 3rd Avenue. Location: Alleyway Beside 69 Second Avenue FoS	Logged by: CRM Connector Subject: footway defects	on: 02/05/2018 15:10 Classification: fault reports	Contact:
Enquiry No.: 2568754 Service: Maintenance Desc.: Report Pavement / Kerb - pavement or cycle path - Local flooding that DOES NOT go away in several hours. It has always 'pooled' in front of drive since I can remember. I attach photo of location. Location: Flemish House Second Avenue FoS	Logged by: CRM Connector Subject: footway defects	on: 02/05/2018 15:07 Classification: fault reports	Contact:
Enquiry No.: 2568753 Service: Maintenance Desc.: Report Pavement / Kerb - pavement or cycle path - Driveway across verge Location: 58 Second Avenue FoS	Logged by: CRM Connector Subject: footway defects	on: 02/05/2018 15:03 Classification: fault reports	Contact:
Plot Number: 1,000.00 Job Number: 2285249	Feature Id - Location: 00011700 Defect Number: 3437985	Feature Type: Local Road	
Enquiry No.: 2568752 Service: Maintenance Desc.: Report Pavement / Kerb - pavement or cycle path - Location: 22 Second Ave Frinton on Sea. Driveway across verge	Logged by: CRM Connector Subject: footway defects	on: 02/05/2018 14:58 Classification: fault reports	Contact:
Plot Number: 1,000.00 Job Number: 2285249	Feature Id - Location: 00011700 Defect Number: 3437986	Feature Type: Local Road	

Effective: 01/01/2016 to 09/07/2022
 Service: Maintenance

Asset Number: 1000.00 to 1999.00
 Subject: footway defects (FWDF)
 Site: SECOND AVENUE (39902153)

Display Action Officer: No

Customer Services

Enquiry No.: 2561932 Logged by: CRM Connector on: 26/03/2018 10:24
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: pavement or cycle path - rocking slabs
 Location: outside no 12 upper fourth ave Contact:

Enquiry No.: 2531539 Logged by: CRM Connector on: 29/08/2017 16:48
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report Pavement / Kerb - pavement or cycle path - slabs raised 2cm plus
 Location: outside 71 second avenue, 2 slabs past water hydrant Contact:

Plot Number: 1,000.00 Feature Id - Location: 00011700 Feature Type: Local Road
 Defect Number: 3289005

Enquiry No.: 2531537 Logged by: CRM Connector on: 29/08/2017 16:45
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report Pavement / Kerb - pavement or cycle path - slabs raised 2cm and 2.5cm
 Location: outside 39 second avenue 3 slabs before driveway and next slab Contact:

Plot Number: 1,000.00 Feature Id - Location: 00011700 Feature Type: Local Road
 Job Number: 2285249 Defect Number: 3437976

Enquiry No.: 2531535 Logged by: CRM Connector on: 29/08/2017 16:41
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report Pavement / Kerb - pavement or cycle path - slab is cracked and rocks
 Location: outside number 11 second avenue in front of driveway Contact:

Plot Number: 1,000.00 Feature Id - Location: 00011700 Feature Type: Local Road
 Defect Number: 3288983

Enquiry No.: 2531533 Logged by: CRM Connector on: 29/08/2017 16:38
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report Pavement / Kerb - pavement or cycle path - badly cracked paving slab
 Location: outside 20 second avenue Contact:

Plot Number: 1,000.00 Feature Id - Location: 00011700 Feature Type: Local Road
 Job Number: 2285249 Defect Number: 3147881

Enquiry No.: 2531531 Logged by: CRM Connector on: 29/08/2017 16:36
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report Pavement / Kerb - pavement or cycle path - slab raised 2.5cm and rocks
 Location: outside 28 second avenue 4 slabs after birch tree Contact:

Plot Number: 1,000.00 Feature Id - Location: 00011700 Feature Type: Local Road
 Job Number: 2285249 Defect Number: 3437981

Enquiry No.: 2531530 Logged by: CRM Connector on: 29/08/2017 16:32
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report Pavement / Kerb - pavement or cycle path - slab 3cm raised and next one rocks
 Location: outside 28 second avenue behind birch tree and next slab Contact:

Plot Number: 1,000.00 Feature Id - Location: 00011700 Feature Type: Local Road
 Job Number: 2285249 Defect Number: 3437981

Effective: 01/01/2016 to 09/07/2022
 Service: Maintenance

Asset Number: 1000.00 to 1999.00
 Subject: footway defects (FWDF)
 Site: SECOND AVENUE (39902153)

Display Action Officer: No

Customer Services

Enquiry No.: 2531529	Logged by: CRM Connector	on: 29/08/2017 16:27
Service: Maintenance	Subject: footway defects	Classification: fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - 2cm raised and rocks		
Location: outside 28 second avenue between gateway and drive		
Plot Number: 1,000.00	Feature Id - Location: 00011700	Feature Type: Local Road
Job Number: 2285249	Defect Number: 3437979	
Enquiry No.: 2531528	Logged by: CRM Connector	on: 29/08/2017 16:24
Service: Maintenance	Subject: footway defects	Classification: fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - raised slab 3cm and rocks		
Location: outside 34 second avenue behind rowan tree and next slab		
Plot Number: 1,000.00	Feature Id - Location: 00011700	Feature Type: Local Road
Job Number: 2263663	Defect Number: 3288902	
Enquiry No.: 2531527	Logged by: CRM Connector	on: 29/08/2017 16:22
Service: Maintenance	Subject: footway defects	Classification: fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - slab raised 3cm		
Location: outside 38 second avenue, 8 slabs after drive next to water hydrant		
Plot Number: 1,000.00	Feature Id - Location: 00011700	Feature Type: Local Road
Job Number: 2285249	Defect Number: 3358827	
Enquiry No.: 2531525	Logged by: CRM Connector	on: 29/08/2017 16:19
Service: Maintenance	Subject: footway defects	Classification: fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - raised 3cm		
Location: outside 40 second avenue 6 slabs before next drive		
Plot Number: 1,000.00	Feature Id - Location: 00011700	Feature Type: Local Road
Job Number: 2285249	Defect Number: 3358827	
Enquiry No.: 2531523	Logged by: CRM Connector	on: 29/08/2017 16:16
Service: Maintenance	Subject: footway defects	Classification: fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - raised 2cm plus		
Location: outside 40 second avenue 2 slabs before silver birch tree		
Plot Number: 1,000.00	Feature Id - Location: 00011700	Feature Type: Local Road
Job Number: 2285249	Defect Number: 3288984	
Enquiry No.: 2531522	Logged by: CRM Connector	on: 29/08/2017 16:13
Service: Maintenance	Subject: footway defects	Classification: fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - slab raised 2.5cm		
Location: outside 40 second avenue 3 slabs before silver birch tree		
Plot Number: 1,000.00	Feature Id - Location: 00011700	Feature Type: Local Road
Job Number: 2285249	Defect Number: 3288986	

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: SECOND AVENUE (39902153)

Customer Services

Enquiry No.: 2531520	Logged by: CRM Connector	on: 29/08/2017 16:10
Service: Maintenance	Subject: footway defects	Classification: fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - slab raised 4cm		
Location: outside 40 second avenue mid wall, 8 slabs before silver birch tree		
Plot Number: 1,000.00	Feature Id - Location: 00011700	Feature Type: Local Road
Job Number: 2285249	Defect Number: 3288986	
Enquiry No.: 2531519	Logged by: CRM Connector	on: 29/08/2017 16:07
Service: Maintenance	Subject: footway defects	Classification: fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - slab raised 2.5cm		
Location: near 76 second avenue opposite flagpole		
Plot Number: 1,000.00	Feature Id - Location: 00011700	Feature Type: Local Road
Job Number: 2263663	Defect Number: 3288903	
Enquiry No.: 2531516	Logged by: CRM Connector	on: 29/08/2017 16:04
Service: Maintenance	Subject: footway defects	Classification: fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - slab raised 3cm and rocks		
Location: second avenue nearly opposite flag pole near 76		
Plot Number: 1,000.00	Feature Id - Location: 00011700	Feature Type: Local Road
Job Number: 2263663	Defect Number: 3288904	
Enquiry No.: 2531513	Logged by: CRM Connector	on: 29/08/2017 15:59
Service: Maintenance	Subject: footway defects	Classification: fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - slab raised 2.5 cm		
Location: outside 74 secibd avenue mid wall		
Plot Number: 1,000.00	Feature Id - Location: 00011700	Feature Type: Local Road
Job Number: 2285249	Defect Number: 3288965	
Enquiry No.: 2531512	Logged by: CRM Connector	on: 29/08/2017 15:57
Service: Maintenance	Subject: footway defects	Classification: fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - slab rocking		
Location: outside 74 second avenue by water hydrant		
Plot Number: 1,000.00	Feature Id - Location: 00011700	Feature Type: Local Road
Job Number: 2285249	Defect Number: 3288985	
Enquiry No.: 2502614	Logged by: CRM Connector	on: 01/02/2017 14:15
Service: Maintenance	Subject: footway defects	Classification: fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - Pavement cracked, big crater between slabs and keeps buckling wheelchair.		
Location: Outside Number 28 Second Avenue.		
Plot Number: 1,000.00	Feature Id - Location: 00011700	Feature Type: Local Road
Job Number: 2285249	Defect Number: 3437980	

Effective: 01/01/2016 to 09/07/2022
Service: Maintenance

Asset Number: 1000.00 to 1999.00
Subject: footway defects (FWDF)
Site: SECOND AVENUE (39902153)

Display Action Officer: No

Customer Services

Enquiry No.: 2487359 **Logged by:** CRM Connector **on:** 21/09/2016 15:30
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Caller states quite a few paving slabs have risen up and are causing a trip hazard. He added that there is a similar problem further up the road on the same side.
Location: Outside no 38 - 40 Holland Road **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011700 **Feature Type:** Local Road
Job Number: 2285249 **Defect Number:** 3437984

Enquiry No.: 2469568 **Logged by:** Customer WebSite **on:** 14/06/2016 15:06
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Trip hazard from broken paving slabs. Several paving slabs are broken or lie unevenly, creating a serious trip hazard.
Location: Outside 28 Second Avenue, Frinton. **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011700 **Feature Type:** Local Road
Job Number: 2285249 **Defect Number:** 3437982

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.00	Asset - Locn.: 00011700		Feature Type: Local Road		Area: Frinton And Walton	
1597811	RANSA void in carriageway. Excavated by national grid, however it is not their responsibility. Backfill required with type one and carriageway patch. 3.6x1.4x1.1 (HW: carriageway struct defect)	Jnc Holland road	HW: L3 2008 STRATEGY	works completed	05/01/2016	25/01/2016	Act. EH/1548598
2217527	RA 1x1 blocked gulli (HW: blocked gully)	O/s 3	HW: P4 2008 STRATEGY	works completed	01/11/2016	27/10/2016	Act. EH/1562257
2218099	RA2=2x1, pipe connection from s/e gully full of leaves ect. (HW: blocked gully connection)	O/s 40	HW: P4 2008 STRATEGY	works completed	11/11/2016	04/11/2016	Act. EH/1562681
2220458	Ra16=4x4 0.6x0.3x30mm f/w calapsed back of gully (HW: footway structural defect)	J/w ashlyns 6	HW: P1 within 2 hours	works completed	23/12/2016	23/12/2016	Act. EH/1564324
2224720	RA3=1x3 Give way and all other lining faded (HW: worn or missing road mark)	J/w Esplanade	HW: P4 2008 STRATEGY	works completed	03/03/2017	21/02/2017	Act. EH/1567544
2224721	RA3=1x3 Give way lines starting to fade. (HW: worn or missing road mark)	J/w Ashlyns rd	HW: P4 2008 STRATEGY	works completed	03/03/2017	21/02/2017	Act. EH/1567544
2240170	Ra2=1x2 10mx0.2 x50mm c/w edge breaking out (HW: carriageway surface defect)	Opp5	HW: L4 2008 STRATEGY	works completed	24/11/2017	04/05/2018	Act. EH/1586327
2241111	Make safe fallen tree following RTC (HW: debris/deposit on highway)	Junction Esplanade	HW: P1 within 2 hours	works completed	09/12/2017	09/12/2017	Act. EH/1578785

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: SECOND AVENUE (39902153)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.00	Asset - Locn.: 00011700		Feature Type: Local Road		Area: Frinton And Walton	
2245677	Ra2=2x1 kerb offset blocked (full of leafs) Cleared leafs from entrance by inspector May still have a restriction further along No standing water at time of visit (HW: blocked gully)	O.s.3	HW: P4 2008 STRATEGY	works completed	13/02/2018	06/02/2018	Act. EH/1582220
2254818	Follow up for job for 2220458	J/w ashlyns 6	HW: P4 2008 STRATEGY	works completed	03/07/2018	01/10/2018	Act. EH/1592143
2254890	Ra 2=2x1 gully inlet blocked 0.4x0.4 metal (HW: blocked gully)	Os 3	HW: P4 2008 STRATEGY	works completed	03/07/2018	29/06/2018	Act. EH/1589534
2263663	Make safe with tarmac uneven slabs in FW 2.52m2	O/S 34, 68, 72	HW: Street S2	works completed	16/11/2018	20/11/2018	Act. EH/1595573
2266114	S2 follow up - Take up and renew slabs, Footway patching and renew kerbs and edgings	O/S 34, 68, 72	HW: S Follow up	works completed	10/12/2018	02/04/2019	Act. EH/1599997
2269018	Ra2=1x2 0.6x0.3x50mm c/w pothole (HW: CWSF 2008 STRATEGY)	O/s6	HW: L4 2008 STRATEGY	works completed	17/01/2019	25/01/2019	Act. PCPP/12844
2285249	2019-20 Capital Footway programme	Whole length	HW: Capital Scheme	works completed	16/09/2019	31/03/2020	Act. EH/1612488
2297996	Covid 19 Spot and fix - Make safe 11No potholes in carriageway	Jct with The Esplanade.	HW: L4 2008 STRATEGY	works completed	05/05/2020	20/04/2020	Act. EH/1618179
2302681	RA3=1x3 CW eroding by manhole cover 0.55x0.25 x50mm (not marked) (HW: carriageway defect)	os VA to 74 by manhole	HW: L4 2008 STRATEGY	works completed	06/08/2020	19/08/2020	Act. EH/1622101
2332546	Member Led Pothole Project - C/way patching 100mm - 6.46m2 - 5 patches	Potholes in and around the cross junction at 5 Second Avenue, Frinton on Sea, Essex	HW: Street S3	with programmer	22/06/2022	10/08/2022	Est.

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: UPPER SECOND AVENUE (39901929)

Site: UPPER SECOND AVENUE (39901929)

Locality: FRINTON ON SEA, ESSEX

Area: Frinton And Walton

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00011476 - ZU465 //	Feature Type:	Local Road		Area:	Frinton And Walton
Batch:	6839832 - Inspection Batch			Route:	Area 01 Annual Nov Walked			Date: 16/11/2021
	No actionable defects found							
Batch:	6834033 - Inspection Batch			Route:	adhoc route			Date: 21/10/2021
3605820	RA2=1x2 blocked gully	21/10/2021	Os 17	HW: blocked gully	Internal		Action Required	
Batch:	6834030 - Inspection Batch			Route:	adhoc route			Date: 21/10/2021
3605816	RA2=1x2 blocked gully	21/10/2021	Os 17	HW: blocked gully	Internal		Action Required	
Batch:	6822515 - Inspection Batch			Route:	adhoc route			Date: 26/08/2021
3598963	RA4=1x4 24m x 1.0m faded give way line 70%	26/08/2021	J/W Ashlyns Road	HW: worn or missing road mark	Internal		Action Required	
Batch:	6820013 - Inspection Batch			Route:	adhoc route			Date: 17/08/2021
3597576	RA16=4x4 0.6m x 0.6m x upto 70mm missing slab	17/08/2021	Os1	HW: footway defect	Internal		Committed	2320049
Batch:	6812707 - Inspection Batch			Route:	adhoc route			Date: 20/07/2021
	No actionable defects found							
Batch:	6812689 - Inspection Batch			Route:	adhoc route			Date: 20/07/2021
3591409	RA1=1x1 6 small pieces of concrete on verge	20/07/2021	Os 17	HW: debris/deposit on highway	Internal		No Action Required	
Batch:	6784586 - Inspection Batch			Route:	adhoc route			Date: 31/03/2021
3533256	RA12=3x4 FW 1.8m x 1.8m x upto 70mm	31/03/2021	Outside 12	HW: footway defect	Internal		Committed	2314331
Batch:	6755686 - Inspection Batch			Route:	Area 02 Annual Nov Walked			Date: 12/11/2020
3510365	RA4=2x2 f/w paver misaligned 0.6mx0.9m x25mm	12/11/2020	O/s 11	HW: footway defect	Internal		Action Required	
3510364	RA3=3x1 give way markings faded 50%	12/11/2020	jw Fifth Ave	HW: worn or missing road mark	Internal		Action Required	
3510363	RA6=2x3 pavers misaligned 1.8mx0.6mx25mm	12/11/2020	os 2 (side garden)	HW: footway defect	Internal		Action Required	
3510366	RA4=2x2 pavers misaligned and damaged (possibly by vehicles or plant as this is a new build) 6.0mx1.8mxup to 30mm	12/11/2020	new plot - side of 28 Ashlyns Rd	HW: footway defect	Internal		Action Required	
3510367	RA6=3x2 Give way markings worn 70%	12/11/2020	Junct with Ashlyn rd	HW: worn or missing road mark	Internal		Action Required	
Batch:	6669049 - Inspection Batch			Route:	Area 02 Annual Nov Walked			Date: 04/11/2019
3436915	RA3=1x3 f/w slab sunk .0.6mx0.9m x20mm	04/11/2019	S/o28 Ashlyn rd	HW: footway defect	Internal		Action Required	
3436916	RA2=1x2 Give way markings worn 50%	04/11/2019	Junct with Ashlyn rd	HW: worn or missing road mark	Internal		No Action Required	
3436914	RA3=1x3 f/w slab sunk .0.6mx0.9m x20mm	04/11/2019	O/s9	HW: footway defect	Internal		Action Required	
3436913	RA2=1x2 f/w slab sunk .0.6mx0.9m x20mm	04/11/2019	O/s11	HW: footway defect	Internal		No Action Required	

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: UPPER SECOND AVENUE (39901929)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00011476 - ZU465 //	Feature Type:	Local Road		Area:	Frinton And Walton
Batch:	6669049 - Inspection Batch			Route:	Area 02 Annual Nov Walked		Date:	04/11/2019
3436912	RA3=1x3 f/w slab sunk .0.6mx0.9m x20mm	04/11/2019	O/s11	HW: footway defect	Internal		Action Required	
3436908	RA2=1x2 f/w slab sunk .0.6mx1.8m x20mm	04/11/2019	S/o24 Ashlyn rd	HW: footway defect	Internal		Action Required	
3436909	RA2=1x2 f/w slab sunk and broken .0.6mx1.8m x20mm	04/11/2019	S/o 24 Ashlyn rd	HW: footway defect	Internal		Action Required	
3436911	RA2=1x2 f/w slabs broken and sunk .0.6mx1.8m x20mm	04/11/2019	O/s26	HW: footway defect	Internal		Action Required	
3436910	RA2=2x1 f/w slab sunk and broken .0.6mx0.6m x25mm	04/11/2019	S/o24 Ashlyn rd	HW: footway defect	Internal		Action Required	
Batch:	6495985 - Inspection Batch			Route:	Area 02 Annual Nov Walked		Date:	12/11/2018
3284660	Resolved, RA 3=1x3. 2x footway slabs raised. 1.8x0.6x20mm	12/11/2018	o/s 16	HW: FWST 2008 STRATEGY	Internal		No Action Required	
3284686	Resolved, Ra3=3x1 kerb misaligned .9x.2x70mm	12/11/2018	O.s15	HW: kerb mis-aligned	Internal		No Action Required	
3284658	Resolved, RA 3=1x3. 4xfootway slabs cracked and raised. 2x2x20mm	12/11/2018	o/s 20	HW: FWST 2008 STRATEGY	Internal		No Action Required	
3284657	Resolved, RA 2=1x2. damaged kerb	12/11/2018	o/s 22	HW: kerb damaged	Internal		No Action Required	
3284687	RA4=2x2, 0.6m sq x 30mm slab raised due to tree roots.	12/11/2018	O/s 19	HW: footway defect	Internal		Action Required	
3284659	Resolved, &RA 2=1x2. misaligned kerb	12/11/2018	o/s 20	HW: kerb mis-aligned	Internal		No Action Required	
3284690	Ra4=1x4 1.2x0.9x20mm slabs broken and sunk, superseded	12/11/2018	O/s 23	HW: footway defect	Internal		Action Required	
3284661	Resolved, RA 2=1x2. misaligned kerb	12/11/2018	o/s 16	HW: kerb mis-aligned	Internal		No Action Required	
3284682	Ra4=1x4 3mx1.8x20mm slabs sunk and broken, superseded.	12/11/2018	O/s7	HW: footway defect	Internal		Action Required	
3284656	RA6=2x3 1.8m x 1.2m xupto35mm slabs raised in f/w due to tree roots.	12/11/2018	O/s 22	HW: footway defect	Internal		Action Required	
3284655	Resolved, RA 2=1x2. misaligned kerb	12/11/2018	o/s 24	HW: kerb mis-aligned	Internal		No Action Required	
3284679	Resolved, RA2=2x1, f/w dropped across access, 2.4x36mm, imperial slabs with concrete access	12/11/2018	Outside 1 Upper second avenue, Frinton on sea.	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3284678	Resolved, RA3=3x1, f/w slabs uneven across access, 0.6x32mm, imperial slabs.	12/11/2018	Outside 1 Upper second avenue, Frinton on sea.	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3284654	Duplicate, ra 1=1x1. footway slab cracked. 0.9x0.6x20mm, superseded.	12/11/2018	o/s Iorric	Defect Deleted	No Defect Found		No Action Required	
3284676	Resolved, Ra3=3x1 concrete fillet missing.5x.2x30mm	12/11/2018	J.w.ashlyns road	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3284675	DFRE, Ra2=1x2 4.2x0.9x20mm slabs sunk	12/11/2018	S/o2	HW: footway defect	Internal		No Action Required	
3284674	DFRE, RA2=2x1 0.6m sq x 20mm slab and concrete fillet sunk in f/w, superseded.	12/11/2018	Next to 4	HW: footway defect	Internal		No Action Required	

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: UPPER SECOND AVENUE (39901929)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00011476 - ZU465 //	Feature Type:	Local Road		Area:	Frinton And Walton
Batch:	6495985 - Inspection Batch			Route:	Area 02 Annual Nov Walked		Date:	12/11/2018
3284673	Ra4=1x4 0.6x1.2x20mm slabs sunk	12/11/2018	O/s4	HW: footway defect	Internal		Action Required	
3284672	Ra4=2x2, 0.6x0.9x20mm, concrete breaking up, superseded	12/11/2018	Opp5	HW: footway defect	Internal		Action Required	
3284671	Resolved, RA2=2x1 0.8m sq up to 25mm concrete fillet sunk / missing around man hole cover.	12/11/2018	O/s Fairways	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3284670	Resolved, RA 1=1x1. footway breaking up around cover. 0.9x0.6x20mm	12/11/2018	o/s fairways	HW: FWST 2008 STRATEGY	Internal		No Action Required	
3284669	RA6=2x3 9.6m x 1.8m x 25mm slabs raised and uneven in f/w, superseded	12/11/2018	Side of 1 The Close.	HW: footway defect	Internal		Action Required	
3284668	Resolved, RA2=2x1 0.9m x 125mm x 25mm kerb broken in half protruding in to c/w and loose.	12/11/2018	Next to v/a for 1 The Close.	HW: kerb damaged	Internal		No Action Required	
3284677	RA6=2x3, 5.4m x 3.6m x 25mm slabs uneven and rocking in f/w,	12/11/2018	O/s 1	HW: footway defect	Internal		Action Required	
3284667	Resolved, RA 2=1x2. misaligned kerb	12/11/2018	s/o 1 the close	HW: kerb mis-aligned	Internal		No Action Required	
3284666	RA2=2x1, Slab sunk by 0.01x20mm.	12/11/2018	O/s 8	HW: footway defect	Internal		Action Required	
3284680	RA6=2x3, 3m x 1.8m x up to 40mm slabs rocking and uneven.	12/11/2018	O/s 3	HW: footway defect	Internal		Action Required	
3284681	DFRE, RA2=2x1 0.9m x 0.6m x 25mm slab broken and sunk around water box in f/w, superseded	12/11/2018	O/s 5	HW: footway defect	Internal		No Action Required	
3284665	Rangers, Ra4=1x4 tree branches overhanging f/w, superseded.	12/11/2018	O/s8	HW: overgrown vegetation (our)	Internal		No Action Required	
3284683	Duplicate, RA2=2x1 0.6m sq x 25mm slab sunk in f/w around water box.	12/11/2018	O/s 9	Defect Deleted	No Defect Found		No Action Required	
3284684	Resolved, RA4=2x2 1.8m sq x 25mm slabs uneven and slightly rocking in v/a.	12/11/2018	O/s 11	HW: footway defect	Internal		No Action Required	
3284685	Resolved, Ra 2=2x1 slab misaligned 1.8x1.8 x20mm (.6x.9 broken)	12/11/2018	O.s.15	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3284698	Resolved, RA 2=1x2. footway breaking up and raised by cover. 0.4x0.3x20mm	12/11/2018	jnc fifth ave	HW: footway defect	Internal		No Action Required	
3284664	DFRE, measured at 15mm, Ra2=1x2 0.6x0.6x20mm slab sunk, superseded.	12/11/2018	O/s 10	HW: footway defect	Internal		No Action Required	
3284688	Resolved, RA 4=2x2. misaligned and broken kerb	12/11/2018	outside 21	HW: kerb mis-aligned	Internal		No Action Required	
3284689	Resolved, RA 2=1x2. damaged kerb	12/11/2018	o/s 25	HW: kerb damaged	Internal		No Action Required	
3284697	Ra6=2x3 f.way slabs misaligned and rocking 1.2x0.8x45mm, superseded due to depth increase.	12/11/2018	O.s,35	HW: footway defect	Internal		Committed	2305917
3284691	RA4=2x2, slab raised, 0.64x25mm.	12/11/2018	O/s 23	HW: footway defect	Internal		Action Required	

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: UPPER SECOND AVENUE (39901929)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00011476 - ZU465 //	Feature Type:	Local Road		Area:	Frinton And Walton
Batch:	6495985 - Inspection Batch			Route:	Area 02 Annual Nov Walked		Date:	12/11/2018
3284692	Resolved, 1=1x1. footway slab cracked. 0.9x0.6x20mm	12/11/2018	o/s 29	HW: footway defect	Internal		No Action Required	
3284693	DFRE, Ra2=1x2 0.6x0.6x20mm slab raised in footway	12/11/2018	O/s31	HW: footway defect	Internal		No Action Required	
3284696	Resolved, RA 1=1x1. footway breaking up across v/a. 3x0.4x20mm	12/11/2018	o/s 33	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3284663	Resolved, RA2=2x1 0.9m x 0.6m x 25mm slab sunk in v/a.	12/11/2018	O/ 16	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3284695	DFRE, RA 1=1x1. footway slab raised. 0.9x0.6x20mm, superseded	12/11/2018	o/s 31	HW: FWST 2008 STRATEGY	Internal		No Action Required	
3284694	DFRE, RA 1=1x1. footway slab raised. 0.9x0.6x20mm, superseded.	12/11/2018	o/s 31	HW: footway defect	Internal		No Action Required	
3284662	Ra6=2x3 3m x1.2xupto30mm slabs raised due to tree roots, superseded.	12/11/2018	O/s 12	HW: footway defect	Internal		No Action Required	
3284699	Resolvedl, RA 2=1x2. 6xdamaged kerbs	12/11/2018	jnc fifth ave	HW: kerb damaged	Internal		No Action Required	
3284700	RA2=2x1, double yellow lines faded both sides of jct.	12/11/2018	JCT with Fifth Avenue	HW: parking partnership defect	Internal		No Action Required	
3284701	Ra4=1x4 0.6x1.8x20mm slabs raised due to tree roots, superseded.	12/11/2018	O/s lorric	HW: footway defect	Internal		Action Required	
Batch:	6374865 - Inspection Batch			Route:	adhoc route		Date:	19/04/2018
3215507	Ra4=1x4 tree branches overhanging f/w	19/04/2018	O/s8	HW: overgrown vegetation (our)	Internal		No Action Required	
Batch:	6318074 - Inspection Batch			Route:	adhoc route		Date:	31/01/2018
3190596	Ra6=2x3 f.way slab misaligned and rocking 1.2x0.8x40mm, superseded due to depth increase.	31/01/2018	O.s,35	HW: FWST 2008 STRATEGY	Internal		No Action Required	
Batch:	6263412 - Inspection Batch			Route:	Area 02 Annual November		Date:	02/11/2017
3165552	Ra2=1x2 0.6x0.9x20mm concrete breaking up	02/11/2017	Opp5	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3165551	Ra6=2x3 3m x1.2xupto30mm slabs raised due to tree roots	02/11/2017	O/s 12	HW: FWST 2008 STRATEGY	Internal		No Action Required	
3165550	RA6=2x3 1.8m x 1.2m xupto35mm slabs raised in f/w due to tree roots.	02/11/2017	O/s 22	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3165549	Ra2=1x2 0.6x0.6x20mm slab raised in footway	02/11/2017	O/s31	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3165548	Ra3=1x3 0.6x0.9x20mm slab broken and sunk	02/11/2017	O/s27	HW: FWSF 2008 STRATEGY	Internal		Action Required	
3165553	Ra2=1x2 give way markings faded.resolved	02/11/2017	J/w ashlyns rd	HW: worn or missing road mark	Internal		No Action Required	
3165547	Ra 2=2x1 slab misaligned back edge .6x.6x40mm	02/11/2017	O.s.9	HW: FWSF 2008 STRATEGY	Internal		Action Required	
3165546	RA6=2x3! 3m x 1.8m x uoto40mm slabs uneven in f/w.	02/11/2017	O/s 3	HW: FWSF 2008 STRATEGY	Internal		No Action Required	

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: UPPER SECOND AVENUE (39901929)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00011476 - ZU465 //	Feature Type:	Local Road		Area:	Frinton And Walton
Batch:	6173538 - Inspection Batch			Route:	adhoc route		Date:	28/06/2017
3129077	Ra6=2x3 f.way slab misaligned and rocking 1.2x.6x20/30mm	28/06/2017	O.s,35	HW: FWST 2008 STRATEGY	Internal		No Action Required	
Batch:	5132912 - Inspection Batch			Route:	Area 02 Annual November		Date:	17/11/2016
20366079	Ra2=1x2 give way markings faded	17/11/2016	J/w ashlyns rd	HW: worn or missing road mark	Internal		No Action Required	
20366078	Ra2=1x2 4.2x0.9x20mm slabs sunk	17/11/2016	S/o2	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
20366077	Ra4=1x4 0.6x1.2x20mm slabs sunk	17/11/2016	O/s4	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
20366076	Ra4=1x4 3mx1.8x20mm slabs sunk and broken	17/11/2016	O/s7	HW: FWSF 2008 STRATEGY	Internal		No Action Required	

Customer Services

Enquiry No.:	2784498	Logged by:	CRM Connector	on:	01/07/2022 17:00
Service:	Maintenance	Subject:	footway defects	Classification:	fault reports
Desc.:	Title=More than 2cm,Considderably worsened since last inspection - now dangerous				
Location:	**MEMBER ENQUIRIES**3284680				
Enquiry No.:	2779413	Logged by:	CRM Connector	on:	30/05/2022 11:30
Service:	Maintenance	Subject:	footway defects	Classification:	fault reports
Desc.:	Title=More than 2cm,Pavement is not in a good condition and our street light has gone out which makes it more of a danger for residents using the footpath				
Location:	Outside house number 10				
Enquiry No.:	2731105	Logged by:	CRM Connector	on:	23/07/2021 09:25
Service:	Maintenance	Subject:	footway defects	Classification:	fault reports
Desc.:	Title=More than 2cm,Paving slab has been removed leaving a hole about 2" deep				
Location:	outside 1 Upper Second Avenue				
Enquiry No.:	2709181	Logged by:	CRM Connector	on:	19/03/2021 10:25
Service:	Maintenance	Subject:	footway defects	Classification:	fault reports
Desc.:	Title=More than 2cm,Sticking up and wobbly loose paving slabs.				
Location:	Outside number 12 Upper second ave frinton on sea. Stretch of loose and sticking up paving slabs. Slabs sticking up much more than 2cm.				
Plot Number:	1,000.00	Feature Id - Location:	00011476 - ZU465 //	Feature Type:	Local Road
Job Number:	2314331	Defect Number:	3533256		
Enquiry No.:	2683433	Logged by:	[REDACTED]	on:	08/10/2020 13:56
Service:	Maintenance	Subject:	footway defects	Classification:	fault reports
Desc.:	JH: Area of f/way has been barriered off for about 18 months - cannot find confirm ref or job number for this - barriers are around a piece of f/way affected by root push				
Location:	o/side 35				
Enquiry No.:	2630231	Logged by:	CRM Connector	on:	23/08/2019 09:48
Service:	Maintenance	Subject:	footway defects	Classification:	fault reports
Desc.:	Report Pavement / Kerb - pavement or cycle path - Lifted Paving slabs, possible due to nearby tree.				
Location:	Upper Second Avenue, Frinton on Sea, nr junction with Fifth Avenue, outside nr 35.				

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: UPPER SECOND AVENUE (39901929)

Customer Services

Enquiry No.: 2621093 **Logged by:** CRM Connector **on:** 14/06/2019 11:27
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - Caller states pavement slabs sticking up and has fallen over near tree on verge
Location: Outside 22 Upper second Avenue, Frinton **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011476 - ZU465 // **Feature Type:** Local Road
Defect Number: 3284656

Enquiry No.: 2601913 **Logged by:** CRM Connector **on:** 15/01/2019 15:58
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - Caller states (Teresa Argent) claims handler advised a member of the public has reported this issue to her: Hi, a member of the public has reported to me that the pavement outside her house is dangerous.

Can you ask Highways to carry out an inspection please.

The address is 3 Upper Second Ave, Frinton – On- Sea, Co13 9LL

Location: Outside 3 Upper second Avenue **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011476 - ZU465 // **Feature Type:** Local Road
Defect Number: 3284680

Enquiry No.: 2566965 **Logged by:** CRM Connector **on:** 20/04/2018 18:24
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path -
Location: Number 3. Uneven paving slabs between new wall and flowering cherry tree. One broken slab moves and is hazardous to a pedestrian. A crack in the new wall completed in late October is 1 cm wide. Already phoned; ref no 2566851. Will claim compensation for rebuilding part of wall. **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011476 - ZU465 // **Feature Type:** Local Road
Defect Number: 3284680

Enquiry No.: 2566851 **Logged by:** CRM Connector **on:** 20/04/2018 10:43
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - customer states that the footpath is very badly damaged and has caused a crack to appear in her new wall. several slabs are raised and one has actually broken into 3 pieces

Location: outside number 3 **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011476 - ZU465 // **Feature Type:** Local Road
Defect Number: 3284680

Enquiry No.: 2551624 **Logged by:** CRM Connector **on:** 28/01/2018 11:09
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - Paving slab is loose and rocking, newly appeared, photo shows trip hazard of 4 cm.
Location: Upper Second Avenue pavement, outside Lindylou (35 Upper Second Avenue), near junction with Fifth Avenue **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011476 - ZU465 // **Feature Type:** Local Road
Job Number: 2305917 **Defect Number:** 3284697

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: UPPER SECOND AVENUE (39901929)

Customer Services

Enquiry No.: 2521069

Logged by: CRM Connector

on: 19/06/2017 10:04

Service: Maintenance

Subject: footway defects

Classification: fault reports

Desc.: Report Pavement / Kerb - pavement or cycle path - Caller states his brick wall is leaning as there is subsidence at front of property on f/path. Caller lives opposite Frinton Junior School. 19.6. 17 caller rang back as had been promised call back with reference number but did not get call back not sure who promised, Caller also stated has had Affinity water out and they have put sensors down to check water valves, meters and hydrant are no leaking to cause subsidence and they confirm no leakage

Location: outside 35 Upper Second Avenue and the junction with Fifth Avenue, Frinton

Contact:

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.00	Asset - Locn.: 00011476 - ZU465 //		Feature Type: Local Road		Area: Frinton And Walton	
2224722	RA 2=1x2. worn give way markings (HW: worn or missing road mark)	jnc ashlyns rd	HW: P4 2008 STRATEGY	works completed	03/03/2017	21/02/2017	Act. EH/1567544
2224727	RA 2=1x2. worn give way markings (HW: worn or missing road mark)	jnc fifth ave	HW: P4 2008 STRATEGY	works completed	03/03/2017	21/02/2017	Act. EH/1567544
2305917	Take up and relay footway slabs - 27.36m2	O.s,35	HW: Street S3	works completed	15/10/2020	01/12/2020	Act. EH/1626869
2314331	Make safe footway defect by removal of slab and replace with cold lay materials 1.8m x 1.8m x 70mm	Outside 12	HW: Street S2	works completed	31/03/2021	06/04/2021	Act. EH/1631785
2320049	RA16=4x4 0.6m x 0.6m x upto 70mm missing slab (HW: footway defect)	Os1	HW: Street S1	works completed	17/08/2021	17/08/2021	Act. EH/1636672

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: UPPER THIRD AVENUE (39901930)

Site: UPPER THIRD AVENUE (39901930)

Locality: FRINTON ON SEA, ESSEX

Area: Frinton And Walton

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00011477 - ZU462 //		Feature Type: Local Road		Area: Frinton And Walton	
Batch:	6839605 - Inspection Batch		Route: Area 01 Annual Nov Walked		Date: 15/11/2021			
3609141	SUPERCEDED RA6=2x3, cwph, 0.9m x 0.6m x 70mm	15/11/2021	Os 5	HW: carriageway defect	Internal		Action Required	
Batch:	6814503 - Ad Hoc Inspection Batch		Route: adhoc route		Date: 27/07/2021			
3593178	0.9m x 0.7m x 100mm CWPH	27/07/2021	Os 9	HW: carriageway defect	Internal		Action Required	
Batch:	6812767 - Inspection Batch		Route: adhoc route		Date: 20/07/2021			
3591443	RA16=4x4 0.9m x 0.7m x 100mm CWPH	20/07/2021	Os 9	HW: carriageway defect	Internal		Committed	2318843
Batch:	6812766 - Inspection Batch		Route: adhoc route		Date: 20/07/2021			
3591442	RA4=2x2 0.6m x 0.5m x 60mm CWPH	20/07/2021	Os 5	HW: carriageway defect	Internal		No Action Required	
Batch:	6812759 - Inspection Batch		Route: adhoc route		Date: 20/07/2021			
3591441	RA16=4x4 0.7m x 0.5m x 100mm CWPH directly in line with the crossing point	20/07/2021	J/W Ashlyns Road	HW: carriageway defect	Internal		Committed	2318841
Batch:	6753654 - Inspection Batch		Route: Area 02 Annual Nov Walked		Date: 06/11/2020			
3509094	RA4=2x2 - CW holing by gully line on radius 0.5x0.15x50mm (risk assessed for pedestrians as at crossing point)	06/11/2020	jw Ashlyns Rd	HW: carriageway defect	Internal		Action Required	
3509093	RESOLVED - Ra3=1x3 0.5x1.5x20mm concrete slab raised	06/11/2020	Pathway that leads from The Close to Upper Third Avenue	HW: footway defect	Internal		No Action Required	
3509095	RA6=2x3 f/w slabs uneven 2.4 x1.8x30mm	06/11/2020	O/s22a	HW: footway defect	Internal		Action Required	
3509092	RESOLVED - RA1=1x1, stump from cut tree on verge to be removed, new shoot growin	06/11/2020	O/s 25	Other	Internal		No Action Required	
Batch:	6740414 - Inspection Batch		Route: adhoc route		Date: 11/09/2020			
3499489	RA6=2x3 Shrubs and brambles from garden are overhanging and obstructing the footway in both streets.	11/09/2020	os corner property no 29 - in both Upper Third & Fifth Avenues	HW: overgrown vegetation (ext)	Internal		Action Required	
Batch:	6690251 - Inspection Batch		Route: adhoc route		Date: 12/02/2020			
3466135	RA8=2x4 c/w pot hole 1.1m x 1.1m x 90mm	12/02/2020	O/s 20	HW: carriageway defect	Internal		Committed	2293534
Batch:	6683677 - Inspection Batch		Route: adhoc route		Date: 14/01/2020			
3457601	RA4=2x2, C/w pot hole, 0.7mx0.5mx70mm	14/01/2020	Opp 35	HW: carriageway defect	Internal		Committed	2294618
Batch:	6669727 - Inspection Batch		Route: Area 02 Annual Nov Walked		Date: 06/11/2019			
3437954	RA2=1x2 kerb damaged 0.2mx0.15mx40mm	06/11/2019	O/s41 crossing point	HW: kerb damaged	Internal		Action Required	
3437957	RESOLVED Ra3=1x3 carriageway pothole 0.5x0.3x50mm	06/11/2019	10m from junction with Ashlyns Road	HW: carriageway defect	Internal		No Action Required	
3437956	RA4=1x4 f/w slabs uneven 2.4 x1.8x20mm	06/11/2019	O/s22a	HW: footway defect	Internal		No Action Required	

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: UPPER THIRD AVENUE (39901930)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00011477 - ZU462 //	Feature Type:	Local Road		Area:	Frinton And Walton
Batch:	6669727 - Inspection Batch			Route:	Area 02 Annual Nov Walked		Date:	06/11/2019
3437955	RA2=1x2 C/w pot hole 0.4mx0.3x50mm	06/11/2019	Opp35	HW: carriageway defect	Internal		No Action Required	
3437953	RA6 =2x3 c/w pot hole 0.9mx0.8mx60mm	06/11/2019	O/s20	HW: carriageway defect	Internal		No Action Required	
3437952	RESOLVED RA4=2x2, p/hole, 0.5x0.45x60mm.	06/11/2019	O/s 3	HW: carriageway defect	Internal		No Action Required	
Batch:	6668004 - Inspection Batch			Route:	adhoc route		Date:	30/10/2019
3435383	RA6 =2x3 c/w pot hole 0.9mx0.8mx60mm	30/10/2019	O/s20	HW: carriageway defect	Internal		No Action Required	
Batch:	6630422 - Inspection Batch			Route:	adhoc route		Date:	24/05/2019
3374587	Ra3=1x3 carriageway pothole 0.5x0.3x50mm	24/05/2019	10m from junction with Ashlyns Road	HW: carriageway defect	Internal		No Action Required	
Batch:	6630421 - Inspection Batch			Route:	adhoc route		Date:	24/05/2019
3374586	RA4=2x2, p/hole, 0.5x0.45x60mm.	24/05/2019	O/s 3	HW: carriageway defect	Internal		No Action Required	
Batch:	6580403 - Inspection Batch			Route:	adhoc route		Date:	25/02/2019
3334958	**APF** RA12=4x3, p/hole, 0.9x0.5x85mm, APF.	25/02/2019	O/s 11, Willow Cottage	HW: carriageway defect	Internal		Committed	2272590
Batch:	6526216 - Inspection Batch			Route:	adhoc route		Date:	17/12/2018
3305880	RA4=2x2, p/hole, 0.5x0.35x60mm.	17/12/2018	O/s 3	HW: carriageway defect	Internal		No Action Required	
Batch:	6526181 - Inspection Batch			Route:	adhoc route		Date:	17/12/2018
3305872	RA6=2x3, p/hole, 0.7x0.4x75mm.	17/12/2018	O/s 11, Willow Cottage	HW: carriageway defect	Internal		No Action Required	
Batch:	6501848 - Inspection Batch			Route:	Area 02 Annual Nov Walked		Date:	19/11/2018
3289261	RA2=2x1, c/w edge breaking away by concrete gutter, 0.57x0.14 x45mm, edge of walking line.	19/11/2018	Jct Ashlyns Rd.	HW: carriageway defect	Internal		Action Required	
Batch:	6408618 - Inspection Batch			Route:	adhoc route		Date:	11/06/2018
3231740	RA1=1x1, stump from cut tree on verge to be removed, new shoot growin	11/06/2018	O/s 25	Other	Internal		No Action Required	
Batch:	6263274 - Inspection Batch			Route:	Area 02 Annual November		Date:	02/11/2017
3165476	RA6=2x3 1.8m x 1.8m xuoto40mm slabs raised in v/a.	02/11/2017	O/s 12	HW: FWSF 2008 STRATEGY	Internal		Committed	2249733
3165475	RA6=2x3 0.9m x 0.6m x upto 40mm slab raised in f/w.	02/11/2017	O/s Willow Cottage	HW: FWSF 2008 STRATEGY	Internal		Committed	2249733
3165474	Ra3=1x3 0.6x0.9x20mm slabs sunk in footway	02/11/2017	O/s15	HW: FWSF 2008 STRATEGY	Internal		Committed	2249733
3165473	Ra4=2x2 0.6x1.2x25mm slabs sunk in f/w.	02/11/2017	O/s 29	HW: FWSF 2008 STRATEGY	Internal		Committed	2249733
3165472	Ra6=2x3 2.4x1.8xupto 30mm slabs raised due to tree roots	02/11/2017	o/s 24	HW: FWST 2008 STRATEGY	Internal		Committed	2249733
3165471	Ra9=3x3 3m x 1.8xupto50mm raised and rocking slabs	02/11/2017	O/s22a	HW: FWSF 2008 STRATEGY	Internal		Committed	2238501

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: UPPER THIRD AVENUE (39901930)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,000.00	Asset - Locn.: 00011477 - ZU462 //			Feature Type: Local Road			Area: Frinton And Walton	
Batch: 5132501 - Inspection Batch				Route: Area 02 Annual November				Date: 17/11/2016
20365841	Ra3=1x3 0.3x0.3x50mm c/w pothole	17/11/2016	O/s29	HW: CWSF 2008 STRATEGY	Internal		Committed	2242943
20365840	Ra3=1x3 0.4x0.2x50mm c/w pothole	17/11/2016	O/s27	HW: CWSF 2008 STRATEGY	Internal		Committed	2242943
20365839	Ra3=1x3 0.5x0.4x50mm c/w pothole	17/11/2016	O/s11	HW: CWSF 2008 STRATEGY	Internal		Committed	2242943
20365838	Ra6=2x3 2.4x1.8x25mm raised and rocking slabs	17/11/2016	O/s22	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
20365842	Ra4=1x4 1.2x1.5x20mm slabs raised and rocking	17/11/2016	O/s26	HW: FWSF 2008 STRATEGY	Internal		Committed	2238930
Batch: 2881543 - Inspection Batch				Route: adhoc route				Date: 08/09/2016
20346704	Ra4=2x2, 1.2x0.4x55mm, slab broken and lifted due to tree roots.	08/09/2016	Opp 3	HW: FWST 2008 STRATEGY	Internal		Committed	2249733
Batch: 2866990 - Inspection Batch				Route: adhoc route				Date: 12/08/2016
20341012	Ra2=2x1 0.6x0.6x35mm loose and broken slab	12/08/2016	Opp3	HW: FWSF 2008 STRATEGY	Internal		Committed	2249733
Batch: 2821683 - Inspection Batch				Route: adhoc route				Date: 26/05/2016
20317218	RA4=2x2, p/h in c/w, 0.65x0.4x82mm, dbm.	26/05/2016	25m from Ashlyns Rd jct	HW: CWSF 2008 STRATEGY	Internal		Committed	2212884
Batch: 2821660 - Inspection Batch				Route: adhoc route				Date: 26/05/2016
20317206	RA6=2x3, p/h in c/w, 0.9x0.5x75mm, dbm.	26/05/2016	O/s 19	HW: CWSF 2008 STRATEGY	Internal		Committed	2212884
Batch: 2821629 - Inspection Batch				Route: adhoc route				Date: 26/05/2016
20317197	RA4=2x2, c/w surface eroded, 0.7x0.7x76mm, dbm	26/05/2016	O/s 4	HW: CWSF 2008 STRATEGY	Internal		Committed	2212884
Batch: 2765804 - Inspection Batch				Route: adhoc route				Date: 26/01/2016
20283746	Ra4=2x2 4.2x1.8x25mm f/w raised due to tree roots	26/01/2016	Pavement lifted,serious trip hazard outside 8 upper third avenue Frinton	HW: FWST 2008 STRATEGY	Internal		Committed	2249733

Customer Services

Enquiry No.: 2784171

Logged by: CRM Connector

on: 29/06/2022 18:55

Service: Maintenance

Subject: footway defects

Classification: fault reports

Desc.: Title=More than 2cm,Issue reported to Chief Executive re dangerous situation here. Will sue County Council if a person is injured at this location.

Location: **MEMBER ENQUIRIES**Issue reported to Chief Executive re dangerous situation here 22a UPPER THIRD AVE

Contact:

Enquiry No.: 2709188

Logged by: CRM Connector

on: 19/03/2021 10:55

Service: Maintenance

Subject: footway defects

Classification: fault reports

Desc.: Title=More than 2cm,Pavements have gaps between slabs, some slightly raised. Just to inform you that my husband sustained a fall on these pavements on wednesday 17th march 2021 resulting in him being transferred to Colchester general hospital via ambulance, suffering a fractured nose and extensive facial bruising and blood loss. The pavement is on the opposite corner to house number 1, by the black wooden fence.

Location: **MEMBER ENQUIRIES** Near junction of upper third ave and ashlyns road.

Contact:

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: UPPER THIRD AVENUE (39901930)

Customer Services

Enquiry No.: 2561935 **Logged by:** CRM Connector **on:** 26/03/2018 10:29
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: pavement or cycle path - raised and rocking slabs
Location: outside no 16 upper fourth ave **Contact:**

Enquiry No.: 2560095 **Logged by:** CRM Connector **on:** 15/03/2018 10:41
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - Very raised slab next to a large tree caused by tree root. This is dangerous to pedestrians.
Location: In Upper Third Avenue, Frinton-on-Sea, at the junction with Ashlyns Road, on the righthand side as you enter Upper Third from Ashlyns **Contact:**

Enquiry No.: 2560092 **Logged by:** CRM Connector **on:** 15/03/2018 10:38
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - Paving Slab more than 1" out of alignment which is dangerous
Location: Outside No. 44 Upper Third Avenue, Frinton-on-Sea **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011477 - ZU462 // **Feature Type:** Local Road
Job Number: 2249733

Enquiry No.: 2560090 **Logged by:** CRM Connector **on:** 15/03/2018 10:35
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - Paving Slab more than 1" out of alignment which poses a danger to pedestrians.
Location: Outside No 24 Upper Third Avenue, Frinton-on-Sea **Contact:**

Enquiry No.: 2560089 **Logged by:** CRM Connector **on:** 15/03/2018 10:31
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - PAVING SLAB MORE 1" OUT OF ALIGNMENT - DANGEROUS
Location: OUTSIDE NO 29 UPPER THIRD AVENUE **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011477 - ZU462 // **Feature Type:** Local Road
Job Number: 2249733

Enquiry No.: 2560081 **Logged by:** CRM Connector **on:** 15/03/2018 10:19
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Report Pavement / Kerb - pavement or cycle path - Paving Slab dangerously more than 1" out of alignment
Location: Outside No 19 Upper Third Avenue, Frinton-on-Sea **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011477 - ZU462 // **Feature Type:** Local Road
Job Number: 2249733

Enquiry No.: 2495134 **Logged by:** CRM Connector **on:** 18/11/2016 12:38
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Report Pothole - - There are possibly 2 pavement slabs that are precariously stivking up. Dangeorous for elderly who might not see them
Location: Close to first house on the R/H side of Upper Third Avenue, Frinton **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011477 - ZU462 // **Feature Type:** Local Road
Job Number: 2249733 **Defect Number:** 20341012

Effective: 01/01/2016 to 09/07/2022
Service: Maintenance
Display Action Officer: No

Asset Number: 1000.00 to 1999.00
Subject: footway defects (FWDF)
Site: UPPER THIRD AVENUE (39901930)

Customer Services

Enquiry No.: 2489411 **Logged by:** CRM Connector **on:** 06/10/2016 10:28
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Caller states footpath in bad state of repair, very uneven, paving slabs all uneven, some slabs cracked, some lifting. very close to school and risk of children tripping on loose slabs.ongoing for past 3 years with no repair being carried out.
Location: located outside no 39 upper third ave, frinton. on same side of road **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011477 - ZU462 // **Feature Type:** Local Road
Job Number: 2249733 **Defect Number:** 20207002

Enquiry No.: 2485458 **Logged by:** CRM Connector **on:** 09/09/2016 09:53
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Caller states Raised Paving slabs causing people to trip up. been like this for about 3 years. The Paving slab has been raised about 5 inches.
Location: Outside 30 Upper Third Avenue **Contact:**

Enquiry No.: 2483810 **Logged by:** CRM Connector **on:** 30/08/2016 10:21
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Caller states raised opaving slab, states is raised by a few inches.
Location: near to j/w Ashlyns, on f/p **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011477 - ZU462 // **Feature Type:** Local Road
Job Number: 2249733 **Defect Number:** 20346704

Enquiry No.: 2481021 **Logged by:** CRM Connector **on:** 09/08/2016 15:28
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Caller states the path paving slabs are very raised by atleast 2 inches.
Location: Upper third Avenue. this is just off the ashlyns road on the right hand side. **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011477 - ZU462 // **Feature Type:** Local Road
Job Number: 2249733 **Defect Number:** 20341012

Enquiry No.: 2476048 **Logged by:** CRM Connector **on:** 12/07/2016 11:50
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Caller states Pavement slabs sticking up by an inch, has gotten worse, the tree roots are lifting it up
Location: Outside no 39 **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011477 - ZU462 // **Feature Type:** Local Road
Job Number: 2249733 **Defect Number:** 20207002

Enquiry No.: 2443407 **Logged by:** Customer WebSite **on:** 24/01/2016 11:46
Service: Maintenance **Subject:** footway defects **Classification:** fault reports
Desc.: Have recently moved to above address.had problem with large tree causing damage to property and wall pavement to front of property. Tree has now been removed advice required about how to make good pavement to outside our property.
Location: Pavement lifted,serious trip hazard outside 8 upper third avenue Frinton **Contact:**

Plot Number: 1,000.00 **Feature Id - Location:** 00011477 - ZU462 // **Feature Type:** Local Road
Job Number: 2249733 **Defect Number:** 20283746

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.00	Asset - Locn.: 00011477 - ZU462 //		Feature Type: Local Road		Area: Frinton And Walton	
2212884	carriageway patching 100mm - 3 o/s 1,4,19,18,21 defects - 66.68m2		HW: L3 2008 STRATEGY	works completed	16/08/2016	13/12/2016	Act. EH/1563880

Effective: 01/01/2016 to 09/07/2022

Asset Number: 1000.00 to 1999.00

Service: Maintenance

Subject: footway defects (FWDF)

Display Action Officer: No

Site: UPPER THIRD AVENUE (39901930)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.00	Asset - Locn.: 00011477 - ZU462 //		Feature Type: Local Road		Area: Frinton And Walton	
2238501	Ra9=3x3 3m x 1.8 x upto 50mm raised and rocking slabs (HW: footway surface defect)	O/s22a	HW: P2 end next working day	works completed	02/11/2017	03/11/2017	Act. EH/1577140
2238930	Follow up job for 2238501	O/s22a	HW: P4 2008 STRATEGY	works completed	09/11/2017	15/03/2018	Act. EH/1581578
2242943	2 PATCHES	O/s11	HW: L4 2008 STRATEGY	works completed	11/01/2018	30/01/2018	Act. EH/1581025
2249733	Capital Footways Programme 18/19	Whole Length	HW: P4 2008 STRATEGY	works completed	11/04/2018	10/07/2018	Act. EH/1588279
2272590	Make safe CW pothole with coldlay	O/s 11, Willow Cottage	HW: L2 2008 STRATEGY	works completed	25/02/2019	26/02/2019	Act. EH/1600080
2274657	L2 - follow up - Carriageway patching 100mm - 92.96m2	O/s 11, Willow Cottage	HW: L Follow up	works completed	19/03/2019	26/07/2019	Act. EH/1603045
2287089	RA3=3x1 Give way lines faded. (HW: worn or missing road mark)	J/w Ashlyns rd.	HW: Street S4	works completed	16/10/2019	21/07/2019	Act. EH/1609591
2293534	Make safe carriageway pothole with Cold Lay material 1.1m x 1.1m x 90mm	O/s 20	HW: Street S2	works completed	12/02/2020	13/02/2020	Act. EH/1614699
2294618	S2 follow up - Carriageway patching 100mm - 221.54m2	O/s 20, 22B and opp 35	HW: S Follow up	works completed	02/03/2020	18/05/2020	Act. EH/1616048
2298524	Covid 19 seek and fix - Fill carriageway pothole	Jct Ashlyns Rd.	HW: L4 2008 STRATEGY	works completed	14/05/2020	20/04/2020	Act. EH/1618537
2318841	RA16=4x4 0.7m x 0.5m x 100mm CWPH directly in line with the crossing point (HW: carriageway defect)	J/W Ashlyns Road	HW: Street S1	works completed	20/07/2021	20/07/2021	Act. EH/1635796
2318843	RA16=4x4 0.9m x 0.7m x 100mm CWPH (HW: carriageway defect)	Os 9	HW: Street S1	works completed	20/07/2021	20/07/2021	Act. EH/1635798

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: WALTHAM WAY (39901970)

Site: WALTHAM WAY (39901970)

Locality: FRINTON ON SEA, ESSEX

Area: Frinton And Walton

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00011517 - 317m from j/w Cliff Way		Feature Type: Local Road		Area: Frinton And Walton	
Batch:	6862222 - Ad Hoc Inspection Batch			Route: adhoc route		Date: 16/03/2022		
3623581	0.8m x 0.6m x upto 30mm section of slab missing also small section of concrete	16/03/2022	Os 31	HW: footway defect	Internal		Action Required	
Batch:	6854082 - Inspection Batch			Route: adhoc route		Date: 04/02/2022		
3618007	RA8=2x4 0.8m x 0.6m x upto 30mm section of slab missing also small section of concrete	04/02/2022	Os 31	HW: footway defect	Internal		Committed	2326723
Batch:	6847848 - Inspection Batch			Route: Area 01 Annual Jan Walked		Date: 05/01/2022		
3614307	RA3=1x3, paving slab cracked, loose and rocking, 0.9m x 0.6m x 20mm upstand	05/01/2022	O/s 28	HW: footway defect	Internal		Action Required	
Batch:	6812230 - Inspection Batch			Route: adhoc route		Date: 19/07/2021		
3591074	RA4=1x4 0.8m x 0.7m x upto 60mm CWPH	19/07/2021	J/W The Leas	HW: carriageway defect	Internal		Action Required	
Batch:	6766435 - Inspection Batch			Route: Area 02 Annual Jan Walked		Date: 08/01/2021		
3518937	RA6=2x3. uneven f/way slab 0.9mx0.6mx25mm	08/01/2021	o/s 28	HW: footway defect	Internal		Action Required	
Batch:	6689503 - Inspection Batch			Route: adhoc route		Date: 10/02/2020		
3465298	Ra16=4x4, tree blown down from verge, blocking footway and partially blocking cway, make safe	10/02/2020	O/s 7	HW: defect reviewed & settled	No Defect Found		No Action Required	
Batch:	6684291 - Inspection Batch			Route: Area 02 Annual Jan Walked		Date: 16/01/2020		
No actionable defects found								
Batch:	6538710 - Inspection Batch			Route: adhoc route		Date: 09/01/2019		
3315024	Dfire, 5mm of movement only, RA 4=2x2. rocking f/way slab. 0.6x0.6x30mm	09/01/2019	o/s 9	HW: footway defect	Internal		No Action Required	
3315027	Duplicate, RA 4=2x2 1.2x0.9x30mm slabs raised due to tree roots	09/01/2019	o/s 15	Defect Deleted	No Defect Found		No Action Required	
3315044	RA4=2x2, slab uneven, 0.4 x20mm.	09/01/2019	O/s 7	HW: footway defect	Internal		Action Required	
3315031	Ra4=2x2 . conc.v/a breaking up. 1.6x0.6x25mm	09/01/2019	o/s 31	HW: footway defect	Internal		Action Required	
3315026	Ra4=2x2 2.4x0.9xupto40mm slabs raised in f/w due to tree roots.	09/01/2019	O/s 15	HW: footway defect	Internal		Action Required	
3315030	RA6=2x3, slab raised, 0.5x25mm.	09/01/2019	O/s 25	HW: footway defect	Internal		Action Required	
3315033	Ra6=2x3 0.6x0.9x25mm slab raised in footway	09/01/2019	O/s28	HW: footway defect	Internal		Action Required	
3315028	Duplicate, RA2=2x1 0.9m x 0.6m x 25mm slab raised in f/w due to tree roots.	09/01/2019	O/s 15	Defect Deleted	No Defect Found		No Action Required	

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: WALTHAM WAY (39901970)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.: 00011517 - 317m from j/w Cliff Way		Feature Type: Local Road		Area: Frinton And Walton		
Batch:	6538710 - Inspection Batch			Route: adhoc route		Date: 09/01/2019		
3315037	Ra6=2x3, 1.2x0.75x25mm slabs sunk round water box, superseded	09/01/2019	O/s20	HW: footway defect	Internal		Action Required	
3315036	Ra4=1x4 1.2x1.5x20mm slabs raised due to tree roots	09/01/2019	O/s24	HW: footway defect	Internal		Action Required	
3315041	Ra4=2x2 0.6x0.6x25mm slab sunk in footway	09/01/2019	O/s2	HW: footway defect	Internal		Action Required	
3315043	Duplicate, RA 4=2x2. cracked and rocking f/way slab. 0.9x0.6x30mm	09/01/2019	o/s 7	Defect Deleted	No Defect Found		No Action Required	
3315038	RA4=2x2 Uneven and slightly rocking slabs in f/way 5m x 1.6m x 20mm.	09/01/2019	o/s 12	HW: footway defect	Internal		Action Required	
3315029	Ra4=1x4 2.4x1.5x20mm slabs sunk in footway	09/01/2019	O/s25	HW: footway defect	Internal		Action Required	
3315025	RA4=2x2 0.6x0.6xupto50mm slab raised due to tree roots	09/01/2019	o/s 11	HW: footway defect	Internal		Action Required	
3315040	Duplicate, RA4=2x2 Uneven and slightly rocking slabs in f/way 5m x 1.6m x 20mm.	09/01/2019	o/s 12	Defect Deleted	No Defect Found		No Action Required	
3315032	DFRE, RA2=2x1 0.6m sq x 20mm slab sunk in f/w.	09/01/2019	O/s 42	HW: footway defect	Internal		No Action Required	
3315034	Resolved, RA 2=1x2. uneven f/way slabs. 0.9x0.6x20mm	09/01/2019	o/s 30	HW: footway defect	Internal		No Action Required	
3315042	Duplicate, RA 2=1x2. uneven f/way slabs. 2x1.6x20mm	09/01/2019	o/s 2	Defect Deleted	No Defect Found		No Action Required	
3315039	Ra6=2x3 0.6x0.9xupto35mm slab broken and sunk	09/01/2019	O/s 12	HW: footway defect	Internal		Action Required	
3315035	DFRE, RA 2=1x2. uneven f/way slabs. 0.6x0.6x20mm	09/01/2019	o/s 30	HW: footway defect	Internal		No Action Required	
Batch:	6538516 - Inspection Batch			Route: Area 02 Annual Jan Walked		Date: 09/01/2019		
3314980	RA4=2x2. uneven loose slab in va, 0.4x40mm, not as old attached photos.	09/01/2019	o/s 5	HW: footway defect	Internal		Action Required	
3314979	RA6=2x3 5.4m x 1.5m x 35mm slabs uneven and rocking in f/w, superseded due to depth increase of upstanding slab.	09/01/2019	O/s 5	HW: footway defect	Internal		Action Required	
3314977	Duplicate, RA6=2x3 4.8m x 1.5m x 25mm slab uneven and rocking in f/w.	09/01/2019	O/s 1	Defect Deleted	No Defect Found		No Action Required	
3314986	RA3=1x3, 0.5 x 0.5m x 20mm slab uneven in f/w, downgraded.	09/01/2019	O/s 1	HW: footway defect	Internal		Action Required	
3314985	Duplicate, RA6=3x2, slabs raised due to tree roots, 1.65m x 0.6m x 30mm, superseded due to increased height of slabs.	09/01/2019	O/s 7	Defect Deleted	No Defect Found		No Action Required	

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: WALTHAM WAY (39901970)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00011517 - 317m from j/w Cliff Way	Feature Type:	Local Road		Area:	Frinton And Walton
Batch:	6538516 - Inspection Batch			Route:	Area 02 Annual Jan Walked		Date:	09/01/2019
3314978	RA6=2x3 0.6m x 1.5m x 25mm slabs sunk next to v/a, superseded.	09/01/2019	O/s 3	HW: footway defect	Internal		Action Required	
3314984	RA4=2x2, f/w slab broken and rocking across v/a, imperial slab.	09/01/2019	Outside 7 Waltham Way. Driveway	HW: footway defect	Internal		Action Required	
3314983	Duplicate, RA2=2x1 0.6m sq x 25mm slab raised in v/a.	09/01/2019	O/s 5	Defect Deleted	No Defect Found		No Action Required	
3314982	Duplicate, RA2=2x1 0.6m sq x 25mm slab raised in v/a.	09/01/2019	O/s 5	Defect Deleted	No Defect Found		No Action Required	
3314981	Ra6=2x3 4.8x0.9xupto30mm slabs uneven in footway	09/01/2019	O/s7	HW: footway defect	Internal		Action Required	
Batch:	6375625 - Inspection Batch			Route:	adhoc route		Date:	20/04/2018
3215958	Ra6=2x3 4.8x0.9xupto30mm slabs uneven in footway	20/04/2018	O/s7	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
Batch:	6375613 - Inspection Batch			Route:	adhoc route		Date:	20/04/2018
3215951	Ra6=2x3 0.6x0.9x25mm slab raised in footway	20/04/2018	O/s28	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
Batch:	6318178 - Inspection Batch			Route:	adhoc route		Date:	31/01/2018
3190642	RA4=2x2. uneven slab in va, 0.4x40mm, not as old attached photos.	31/01/2018	o/s 5	HW: FWST 2008 STRATEGY	Internal		No Action Required	
3190641	RA6=2x3 5.4m x 1.5m x 35mm slabs uneven and rocking in f/w, superseded due to depth increase of upstanding slab.	31/01/2018	O/s 5	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
Batch:	6308138 - Inspection Batch			Route:	Area 02 Annual January		Date:	19/01/2018
3187010	RA4=2x2 0.6m x 1.5m x 25mm slabs sunk next to v/a.	19/01/2018	O/s 3	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3187008	Ra6=2x3 0.6x0.9xupto35mm slab broken and sunk	19/01/2018	O/s 12	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3187007	RA9=3x3 3.6x1.5xupto50mm slabs broken and rocking	19/01/2018	o/s 18	HW: FWST 2008 STRATEGY	Internal		Committed	2243695
3187006	Ra4=2x2 1.2x0.75x25mm slabs sunk round water box	19/01/2018	O/s20	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3187005	Ra4=1x4 1.2x1.5x20mm slabs raised due to tree roots	19/01/2018	O/s24	HW: FWST 2008 STRATEGY	Internal		No Action Required	
3187004	Ra4=2x2 . conc.v/a breaking up. 1.6x0.6x25mm	19/01/2018	o/s 31	HW: FWST 2008 STRATEGY	Internal		No Action Required	
3187003	Ra4=1x4 2.4x1.5x20mm slabs sunk in footway	19/01/2018	O/s25	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3187002	Ra3=1x3 0.6x0.6x20mm slab broken and sunk	19/01/2018	O/s23	HW: FWSF 2008 STRATEGY	Internal		Action Required	

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: WALTHAM WAY (39901970)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.:	00011517 - 317m from j/w Cliff Way	Feature Type:	Local Road		Area:	Frinton And Walton
Batch:	6308138 - Inspection Batch			Route:	Area 02 Annual January		Date:	19/01/2018
3187001	Ra4=2x2 2.4x0.9xupto40mm slabs raised in f/w due to tree roots.	19/01/2018	O/s 15	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3187000	RA4=2x2 0.6x0.6xupto50mm slab raised due to tree roots	19/01/2018	o/s 11	HW: FWST 2008 STRATEGY	Internal		No Action Required	
3186999	Ra4=2x2 4.8x0.9x20mm slabs uneven in footway	19/01/2018	O/s7	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
3187009	Ra4=2x2 0.6x0.6x25mm slab sunk in footway	19/01/2018	O/s2	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
Batch:	6269060 - Inspection Batch			Route:	adhoc route		Date:	14/11/2017
3168995	Ra3=1x3 tree branches overhanging f/w job for rangers	14/11/2017	Opp34	HW: overgrown vegetation (our)	Internal		No Action Required	
Batch:	6213358 - Inspection Batch			Route:	adhoc route		Date:	22/08/2017
3146184	RA6=3x2, slabs raised due to tree roots, 1.65m x 0.6m x 30mm, superseded due to increased height of slabs.	22/08/2017	O/s 7	HW: FWSF 2008 STRATEGY	Internal		No Action Required	
Batch:	5161846 - Inspection Batch			Route:	Area 02 Annual January		Date:	09/01/2017
20378207	RA 4=2x2 1.2x0.9x30mm slabs raised due to tree roots	09/01/2017	o/s 15	HW: FWST 2008 STRATEGY	Internal		No Action Required	
Batch:	2762006 - Inspection Batch			Route:	Area 02 Annual January		Date:	19/01/2016
20281605	Ra2=1x2 3mx2mx25mm va breaking up and sunk	19/01/2016	O/s 44	HW: FWSF 2008 STRATEGY	Internal		Action Required	
20281606	Ra2=1x2 0.4x0.3x50mm c/w pothole	19/01/2016	O/s 2	HW: CWSF 2008 STRATEGY	Internal		Committed	2268759
20281604	Ra3=1x3 0.6x0.9x20mm loose and rocking slab	19/01/2016	O/s 28	HW: FWSF 2008 STRATEGY	Internal		Action Required	
20281603	Ra3=1x3 0.6x0.9x20mm slab broken and sunk	19/01/2016	O/s 12	HW: FWSF 2008 STRATEGY	Internal		No Action Required	

Customer Services

Enquiry No.:	2785555	Logged by:	CRM Connector	on:	08/07/2022 14:47
Service:	Maintenance	Subject:	footway defects	Classification:	fault reports
Desc.:	Title=More than 2cm,We have just moved into 28 Waltham Way and the paving next to the driveway is dangerously loose when stepping onto it the slabs tip up. Elderly/disabled people are having to walk in the road to avoid it and when my 88yr old mum uses her walker when leaving our property we have to manoeuvre around to find a safe place for her to step onto				
Location:	Paving outside 28 Waltham Way.		Contact:		
Enquiry No.:	2784445	Logged by:	CRM Connector	on:	01/07/2022 13:55
Service:	Maintenance	Subject:	footway defects	Classification:	fault reports
Desc.:	Title=More than 2cm,Crossover become seriously dangerous with rocking slabs difference average of 30mm over 5 rows of slabs. All of these are rocking so look innocuous on first inspection but when you walk over them become obviously dangerous.				
Location:	**MEMBER ENQUIRIES**28 Waltham Way		Contact:		

Effective: 01/01/2016 to 09/07/2022
 Service: Maintenance

Asset Number: 1000.00 to 1999.00
 Subject: footway defects (FWDF)
 Site: WALTHAM WAY (39901970)

Display Action Officer: No

Customer Services

Enquiry No.: 2784441 Logged by: CRM Connector on: 01/07/2022 13:48
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Title=More than 2cm,Become worse
 Location: **MEMBER ENQUIRIES**Outside no 5 by tree Contact:

Enquiry No.: 2760923 Logged by: CRM Connector on: 04/02/2022 10:03
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Title=More than 2cm,Caller states:- Paving slab that's had broken away and there are bits missing which has caused a fall by a resident who is now in hospital.
 -JMN
 Location: **150** O/s 31 Contact:

Plot Number: 1,000.00 Feature Id - Location: 00011517 - 317m from j/w Cliff Way Feature Type: Local Road
 Job Number: 2326723 Defect Number: 3618007

Enquiry No.: 2760494 Logged by: CRM Connector on: 01/02/2022 21:53
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Title=More than 2cm,Raised paving slabs which have caused injury on at least 3 occasions that residents have advised me. The last one being last night when a resident fell and had to wait nearly 3 hrs for an ambulance. Fortunatly my husband (a doctor) saw the incident and other residents came out to help as did the police.
 Location: various raised pavements all along Quendon way and waltham way opposite Quendon way. Contact:

Enquiry No.: 2564398 Logged by: CRM Connector on: 06/04/2018 16:44
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report Pavement / Kerb - pavement or cycle path - 6 slabs cracked and 2 rocking
 Location: no.34 waltham way frinton on sea Contact:

Enquiry No.: 2564396 Logged by: CRM Connector on: 06/04/2018 16:39
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report Pavement / Kerb - pavement or cycle path - raised 2.6cm
 Location: no.28 waltham way frinton on sea Contact:

Plot Number: 1,000.00 Feature Id - Location: 00011517 - 317m from j/w Cliff Way Feature Type: Local Road
 Defect Number: 3315033

Enquiry No.: 2564395 Logged by: CRM Connector on: 06/04/2018 16:33
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: Report all issues - pavement or cycle path - raised 3.5cm
 Location: no. 5 waltham way, behind tree Contact:

Plot Number: 1,000.00 Feature Id - Location: 00011517 - 317m from j/w Cliff Way Feature Type: Local Road
 Defect Number: 3314979

Enquiry No.: 2564394 Logged by: CRM Connector on: 06/04/2018 16:29
 Service: Maintenance Subject: footway defects Classification: fault reports
 Desc.: raised 4 cm
 Location: outside no.5 Waltham way, edge of drive Contact:

Plot Number: 1,000.00 Feature Id - Location: 00011517 - 317m from j/w Cliff Way Feature Type: Local Road
 Defect Number: 3314980

Effective: 01/01/2016 to 09/07/2022
 Service: Maintenance

Asset Number: 1000.00 to 1999.00
 Subject: footway defects (FWDF)
 Site: WALTHAM WAY (39901970)

Display Action Officer: No

Customer Services

Enquiry No.: 2564343 Service: Maintenance Desc.: Report Pavement / Kerb - pavement or cycle path - raised 2.6cm Location: no. 7 waltham way, frinton, CO13 9JE four slabs before tree	Logged by: CRM Connector Subject: footway defects	on: 06/04/2018 13:55 Classification: fault reports	Contact:
Plot Number: 1,000.00 Feature Id - Location: 00011517 - 317m from j/w Cliff Way Defect Number: 3314981	Feature Type: Local Road		
Enquiry No.: 2564341 Service: Maintenance Desc.: Report Pavement / Kerb - pavement or cycle path - raised 3.5cm Location: no. 11 Waltham way Frinton on sea, CO139JE behind tree	Logged by: CRM Connector Subject: footway defects	on: 06/04/2018 13:51 Classification: fault reports	Contact:
Plot Number: 1,000.00 Feature Id - Location: 00011517 - 317m from j/w Cliff Way Defect Number: 3314981	Feature Type: Local Road		
Enquiry No.: 2564334 Service: Maintenance Desc.: pavement or cycle path - raised 3cm Location: pavement raised 3cm outside 15 Waltham way behind tree	Logged by: CRM Connector Subject: footway defects	on: 06/04/2018 13:45 Classification: fault reports	Contact:
Plot Number: 1,000.00 Feature Id - Location: 00011517 - 317m from j/w Cliff Way Defect Number: 3315026	Feature Type: Local Road		
Enquiry No.: 2550499 Service: Maintenance Desc.: Report Pavement / Kerb - pavement or cycle path - Customer states - tree roots have broken pavement causing a crack that people trip over, paving slabs around it are unbalanced and roots are visible; has also split the wall on customer's front garden which he feels is now be dangerous and may make a claim. Location: Outside no.5	Logged by: CRM Connector Subject: footway defects	on: 23/01/2018 11:09 Classification: fault reports	Contact:
Plot Number: 1,000.00 Feature Id - Location: 00011517 - 317m from j/w Cliff Way Defect Number: 3314980	Feature Type: Local Road		

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,000.00	Asset - Locn.: 00011517 - 317m from j/w Cliff Way		Feature Type: Local Road		Area: Frinton And Walton	
2243695	RA9=3x3 3.6x1.5xupto50mm slabs broken and rocking (HW: footway structural defect)	o/s 18	HW: P2 end next working day	works completed	19/01/2018	23/01/2018	Act. EH/1580742
2268759	RA2=1x2 0.4x0.3x50mm c/w pothole (HW: CWSF 2008 STRATEGY)	O/s 2	HW: L4 2008 STRATEGY	works completed	16/01/2019	21/02/2019	Act. PCPP/12728
2277811	**Lining** white intermittent centre of carriageway marking for reinstatement	O/s 2 where patching works have been carried out.	HW: L4 2008 STRATEGY	works completed	08/05/2019	18/07/2019	Act. PCPP/14760
2287248	RA3=3x1 Give way lines faded. (HW: worn or missing road mark)	J/w Cliff way.	HW: Street S4	works completed	18/10/2019	21/07/2019	Act. EH/1610253
2326723	RA8=2x4 0.8m x 0.6m x upto 30mm section of slab missing also small section of concrete (HW: footway defect)	Os 31	HW: Street S2 Local	works completed	04/02/2022	07/02/2022	Act. EH/1641903

Effective: 01/01/2016 to 09/07/2022

Service: Maintenance

Display Action Officer: No

Asset Number: 1000.00 to 1999.00

Subject: footway defects (FWDF)

Site: WALTHAM WAY (39901970)
