

Communities, Housing & Infrastructure Land and Property Assets Condition Survey Report File No. 227 Overall Grade: - B

Location:

Beach Leisure Centre
Beach Esplanade
Aberdeen. AB24 5NR

Abeldeen. Ab24 5Nr

Survey Date

29/08/2017

Weather

Dry



Description

The Beach Leisure Centre comprises of a 2 storey multi-use leisure facility with swimming pool, flumes, sports hall, fitness studio, spa, crèche and café area. The main access is at the upper level off the Beach Esplanade. There is a secondary entrance open only when events are on in the sports hall at the lower level directly from the car park.

GRADING CRITERIA

D	0 -2 Years	(Less than 40%) - Bad (Life expired and/or serious risk of imminent failure)
С	2- 4 Years	(Between 40% and 60%) - Poor (Showing major defects and/or not operating efficiently)
В	4- 6 Years	(Between 60% and 85%) - Satisfactory (Performing adequately but showing minor deterioration)
A	6+ Years	(More than 85%) - Good (Performing well and operating efficiently)

ELEMENT	OVERALL CONDITION GRADING
- Roof (Structure & Coverings)	В

Notes:

Main Building has a series of low profile metal sheeted roofs on a steel support structure around a glazed atrium which runs full length east to west over entrance and north to south over swimming pool. Sports hall also has a low profile metal sheeted roof set behind parapet walls. Overall roofs are in a satisfactory condition.

- Roof (Drainage) B

Notes:

Aluminium profiled gutters with down-pipes dropping internally. Vegetation visible above glazing to front elevation. But generally clear. Overall satisfactory condition applied.

- Floors & Stairs B

Notes:

Concrete floors and stairs throughout with metal staircase to flume. Timber battened floors to sports hall and dance studio. All in satisfactory condition.

- Ceilings B

Notes:

Exposed roof structure and underside of roof cladding to Swimming pool and sports hall. Ceilings elsewhere vary from coated aluminium plank ceilings in changing rooms, exposed grid suspended ceilings and textured finished plastered ceiling. Some minor damage to aluminium plank ceilings. Overall satisfactory condition applied.

|--|

Notes:

External walls are formed from facing block-work, rendered panels and glazed curtain walling. There is some staining to the block-work and some of the glazing units have failed, in that there is condensation between some of the panes of glass. But overall, the external walls are in satisfactory condition.

ELEMENT	OVERALL CONDITION GRADING				
- Windows	В				
Notes: Powder coated aluminium framed double glazed units. Sor have failed and there misting between panes. Overall satis					
- External Doors	В				
Notes: The fire escape doors are all timber with a painted finish. A lost part of their weather bars and have poor external decor glazed entrance doors to both the leisure centre and sports satisfactory condition. Overall satisfactory condition applied	ation. Aluminium framed centre and are in				
- External Ramps / Stairs / Fire Escapes	В				
Notes: The main entrance is level formed in concrete slabs. The events entrance (sports hall) is accessed from the car park and is level. There are concrete plats external to all of the fire escape doors, which are in satisfactory condition. There is a set of external steps which leads from the car park to the ground floor level. Overall satisfactory condition applied.					
- Internal Walls	В				
Notes: Generally painted blockwork. Skimmed plaster walls in som satisfactory condition applied.	e areas. Overall				
- Internal Doors					
Notes:	В				
Notes: Laminate faced or painted timber doors with single glazed presented doors in main circulation routes. Overall satisfactor	powder coated aluminium				
Laminate faced or painted timber doors with single glazed p	powder coated aluminium				
Laminate faced or painted timber doors with single glazed part framed doors in main circulation routes. Overall satisfactor	powder coated aluminium ry condition applied.				
Laminate faced or painted timber doors with single glazed programed doors in main circulation routes. Overall satisfactors - Sanitary Services Notes:	powder coated aluminium ry condition applied.				
Laminate faced or painted timber doors with single glazed programed doors in main circulation routes. Overall satisfactors - Sanitary Services Notes: Fittings in satisfactory condition throughout.	powder coated aluminium ry condition applied.				
Laminate faced or painted timber doors with single glazed programed doors in main circulation routes. Overall satisfactors - Sanitary Services Notes: Fittings in satisfactory condition throughout. - Mechanical (Heating) Notes:	powder coated aluminium ry condition applied.				

ELEMENT	OVERALL CONDITION GRADING
- Mechanical (Ventilation)	-
Notes:	
To be completed by inspector.	
- Mechanical (Air Conditioning)	-
Notes: To be completed by inspector.	
To be completed by inspector.	
- Electrical (General) Notes:	-
To be completed by inspector.	
- Electrical (Lifts)	_
Notes:	_
To be completed by inspector.	
- Decoration	
- Decoration	В
Notes:	_
Notes: The ground floor main reception area, crèche and gym all h	ave decoration which is in
Notes: The ground floor main reception area, crèche and gym all h good condition. Elsewhere, the decoration is satisfactory.	ave decoration which is in Some of the tiles on the
Notes: The ground floor main reception area, crèche and gym all h	ave decoration which is in Some of the tiles on the f wear and tear. The
Notes: The ground floor main reception area, crèche and gym all h good condition. Elsewhere, the decoration is satisfactory. walls within toilets and changing areas are showing signs o	ave decoration which is in Some of the tiles on the f wear and tear. The
Notes: The ground floor main reception area, crèche and gym all h good condition. Elsewhere, the decoration is satisfactory. walls within toilets and changing areas are showing signs o decoration within the flume tower is poor. Overall satisfacto	ave decoration which is in Some of the tiles on the f wear and tear. The
Notes: The ground floor main reception area, crèche and gym all h good condition. Elsewhere, the decoration is satisfactory. walls within toilets and changing areas are showing signs o	ave decoration which is in Some of the tiles on the f wear and tear. The ry condition applied.
Notes: The ground floor main reception area, crèche and gym all h good condition. Elsewhere, the decoration is satisfactory. walls within toilets and changing areas are showing signs o decoration within the flume tower is poor. Overall satisfacto - Fixtures & Fittings Notes: The main reception and corridor areas have ceramic floor to	ave decoration which is in Some of the tiles on the f wear and tear. The ry condition applied. B tiles which are satisfactory
Notes: The ground floor main reception area, crèche and gym all h good condition. Elsewhere, the decoration is satisfactory, walls within toilets and changing areas are showing signs o decoration within the flume tower is poor. Overall satisfacto - Fixtures & Fittings Notes: The main reception and corridor areas have ceramic floor to overall. The café area has a wooden effect laminate floor to	ave decoration which is in Some of the tiles on the f wear and tear. The ry condition applied. B illes which are satisfactory which is in satisfactory
Notes: The ground floor main reception area, crèche and gym all h good condition. Elsewhere, the decoration is satisfactory. walls within toilets and changing areas are showing signs o decoration within the flume tower is poor. Overall satisfacto - Fixtures & Fittings Notes: The main reception and corridor areas have ceramic floor to	ave decoration which is in Some of the tiles on the f wear and tear. The ry condition applied. B illes which are satisfactory which is in satisfactory ch overall, are fine. There
Notes: The ground floor main reception area, crèche and gym all h good condition. Elsewhere, the decoration is satisfactory, walls within toilets and changing areas are showing signs of decoration within the flume tower is poor. Overall satisfactory. - Fixtures & Fittings Notes: The main reception and corridor areas have ceramic floor to overall. The café area has a wooden effect laminate floor wood condition. The swimming pool has small ceramic tiles, which are small areas where the tiles have cracked or the grout is hall and dance studio has a battened timber floor which is in	ave decoration which is in Some of the tiles on the f wear and tear. The ry condition applied. B illes which are satisfactory which is in satisfactory ch overall, are fine. There damaged. The sports in satisfactory condition.
Notes: The ground floor main reception area, crèche and gym all higood condition. Elsewhere, the decoration is satisfactory, walls within toilets and changing areas are showing signs of decoration within the flume tower is poor. Overall satisfactory. - Fixtures & Fittings Notes: The main reception and corridor areas have ceramic floor overall. The café area has a wooden effect laminate floor overall. The swimming pool has small ceramic tiles, which are small areas where the tiles have cracked or the grout is hall and dance studio has a battened timber floor which is in The reception desk is satisfactory and the kitchen / staff factory.	ave decoration which is in Some of the tiles on the f wear and tear. The ry condition applied. B illes which are satisfactory which is in satisfactory ch overall, are fine. There damaged. The sports in satisfactory condition.
Notes: The ground floor main reception area, crèche and gym all h good condition. Elsewhere, the decoration is satisfactory, walls within toilets and changing areas are showing signs of decoration within the flume tower is poor. Overall satisfactory. - Fixtures & Fittings Notes: The main reception and corridor areas have ceramic floor to overall. The café area has a wooden effect laminate floor wood condition. The swimming pool has small ceramic tiles, which are small areas where the tiles have cracked or the grout is hall and dance studio has a battened timber floor which is in	ave decoration which is in Some of the tiles on the f wear and tear. The ry condition applied. B illes which are satisfactory which is in satisfactory ch overall, are fine. There damaged. The sports in satisfactory condition.
Notes: The ground floor main reception area, crèche and gym all h good condition. Elsewhere, the decoration is satisfactory, walls within toilets and changing areas are showing signs o decoration within the flume tower is poor. Overall satisfactory. - Fixtures & Fittings Notes: The main reception and corridor areas have ceramic floor overall. The café area has a wooden effect laminate floor overall. The swimming pool has small ceramic tiles, which are small areas where the tiles have cracked or the grout is hall and dance studio has a battened timber floor which is in The reception desk is satisfactory and the kitchen / staff faction condition also. Overall satisfactory condition applied.	ave decoration which is in Some of the tiles on the f wear and tear. The ry condition applied. B tiles which are satisfactory which is in satisfactory ch overall, are fine. There damaged. The sports in satisfactory condition. tilities are in satisfactory
Notes: The ground floor main reception area, crèche and gym all h good condition. Elsewhere, the decoration is satisfactory, walls within toilets and changing areas are showing signs o decoration within the flume tower is poor. Overall satisfactory. - Fixtures & Fittings Notes: The main reception and corridor areas have ceramic floor overall. The café area has a wooden effect laminate floor overall. The swimming pool has small ceramic tiles, which are small areas where the tiles have cracked or the grout is hall and dance studio has a battened timber floor which is in The reception desk is satisfactory and the kitchen / staff factory condition also. Overall satisfactory condition applied. - Roads & Car Parks	ave decoration which is in Some of the tiles on the f wear and tear. The ry condition applied. B illes which are satisfactory which is in satisfactory ch overall, are fine. There damaged. The sports in satisfactory condition.
Notes: The ground floor main reception area, crèche and gym all h good condition. Elsewhere, the decoration is satisfactory, walls within toilets and changing areas are showing signs o decoration within the flume tower is poor. Overall satisfactory. - Fixtures & Fittings Notes: The main reception and corridor areas have ceramic floor overall. The café area has a wooden effect laminate floor overall. The swimming pool has small ceramic tiles, which are small areas where the tiles have cracked or the grout is hall and dance studio has a battened timber floor which is in The reception desk is satisfactory and the kitchen / staff faction condition also. Overall satisfactory condition applied.	ave decoration which is in Some of the tiles on the f wear and tear. The ry condition applied. B illes which are satisfactory which is in satisfactory ch overall, are fine. There damaged. The sports in satisfactory condition. is illities are in satisfactory.

ELEMENT	OVERALL CONDITION GRADING
- Paths / Playgrounds / Equipment	N/A
Notes:	
- Walls / Fences / Gates	В
Notes: Rendered walls and metal gates enclosing yard area at rear	in satisfactory condition.
- Surface Drainage / Shelters / External Lighting	В
Notes: External lighting provided street lights or bulkhead lights on Surface drainage appears satisfactory.	walls.
- Sports Facilities	В
Notes:	
- Matters Raised by Building Management	
None	
- Investment Requirements	
Making good of fire exit doors Repair of flume tower walls.	
- Accessibility	
Access Audit 16/02/2017 Grade B	

OVERALL GRADE: - B

Further notes:



