Effective: 01/12/2017 to 31/12/2018

Display Action Officer: No

Street: Wood End Lane (10325129)	2.00						
Street: Wood End Lane (10325129)	Locality: Markyate, Hertfordshire			Area: Flamstead				
ondition Survey								
Defect No: Description	Log Date	Location	Defect Type	Class.	Organisation Sta	itus	Job No.	
Section: 10.00 Road No Locn.: 2	2U68/10 - Mai	kyate Street Lane To Track At Scratch Wo	ood C/Way Type: HW:Netw	ork	Area:	SW: 2-Da	corum Area	
Batch: 1927113 - Inspection Batch		Route: Adho	c Inspection				Date: 16/01/2018	
934001 Temp road closure required x1 c/w patch 500x500 I parker (Enquiry 2241361)	16/01/2018	By public footpath sign (sprayed hedge as standing water) CPH4-C/way pothole-20 Days	Interna	Cor	mmitted	1772275	
Batch: 1925554 - Inspection Batch		Route: Adho	c Inspection				Date: 11/01/2018	
932527 Temp road closure needed x1 c/w patch required unsure on size due to being under water , but is very deep and dangerous (Enquiry 2234609)	11/01/2018	Approximately half way down the lane, have marked the hedge line	CPH4-C/way pothole-20 Days	Internal	Cor	mmitted	1771291	
Batch: 1920206 - Inspection Batch		Route: Annu	al Combined				Date: 18/12/2017	
926790 Wearing course deteriorating and uneven with shallow potholes forming at various points and edge of carriageway runoff mud and leaves and water all over section		Throughout section	RSU7-Rough/uneven surface-2L	Interna	Una	actioned		
Batch: 1919495 - Inspection Batch		Route: Adho	c Inspection				Date: 15/12/2017	
926124 Temp road closure required x1 c/w patch 900x300 marked but let's of standing water I parker (Enquiry 2231655)	15/12/2017	By farm gate	CPH4-C/way pothole-20 Days	Interna	Cor	mmitted	1766444	
Customer Services								
Service: ROAD AND CYCLELANE DMA Subsection S	f the road whening. PLEASE	LE Classification	at stops people seeing the holes. The sand causing damage to cars.					
Plot Number: 10.00 Feature Id - Loca	tion: 2U68/10) - Markyate Street Lane To Track At Scrat	ch Wood Feature Type: HW	:Network				
Service: ROAD AND CYCLELANE DMA Subsection: 8 - 10 Location: Wood End Lane,,,Markyate,	d by: ePortal oject: POTHO		n: 22/03/2018 09:01 n: Service Request t:					
Plot Number: 10.00 Feature Id - Loca	tion: 2U68/10) - Markyate Street Lane To Track At Scrat	ch Wood Feature Type: HW	:Network				
	d by: ePortal bject: POTHO	or LE Classification	n: 19/03/2018 13:30 n: Service Request					
	ition: 2U68/10) - Markyate Street Lane To Track At Scrat	•	:Network				

Street: Wood End Lane (10325129)

Customer Services

Enquiry No.: 2253480 Logged by: ePortal on: 15/02/2018 14:18
Service: FLOODING AND DRAINAGE Subject: ROAD FLOODED Classification: Service Request

DMA

Desc.: The road resembles a river accessible only to large 4x4. No motorcycles, pedestrians or cyclists can get through. Pot holes beneath are submerged so impossible to see conditions of road.

Appalling stretch of road.

Location: Wood End Lane,,,,Markyate,Road flooded

Contact:

Report Time - 2018-02-15T14:18:06+00:00

Service - Flooding and Drainage (FL1)

Subject - Road flooded (DCF)

Questions

Is it affecting the flow of traffic? - Yes, cycle traffic Is the road flooded at the moment? - Yes

Description - The road resembles a river accessible only to large 4x4. No motorcycles, pedestrians or cyclists can get through. Pot holes beneath are submerged so impossible to see conditions of road. Appalling stretch of road.

mapusrn - 10325129

assetID - HWCW523067

Ownership - HH: Hertfordshire Highways

Class - Unclassified Road - U

Road Name - Wood End Lane

Town - Markyate

District - SW: 2-Dacorum Area

Easterly - 506576

Northerly - 213622

Postcode -

Address 1 -

Feature ID - 2U68/10

Street: Wood End Lane (10325129)

Customer Services

First name -

Last name -

Address Line 1 -

Address Line 2 -

Town -

Post code -

Phone number -

Plot Number: 10.00 Feature Id - Location: 2U68/10 - Markyate Street Lane To Track At Scratch Wood Feature Type: HW:Network

Job Number: 1780374

Enquiry No.: 2249010 Logged by: ePortal on: 01/02/2018 14:34

Service: ROAD AND CYCLELANE DMA Subject: POTHOLE Classification: Service Request

Desc.: Wood end lane in flamstead half way up this single lane with no lighting is a huge flooded area that does never seen to drain away water and within it is a huge pothole that you cannot see. I have reported this this morning to hearts county council as I was traveling with last night 31/1/18 back home to flamstead when we hit the huge pothole which you cannot see forms part of the flood area. My damage to my driver side front tyre and rim is so bad I have to wait for the AA to come out they could not get my tyre off as so much damage to the rim also I then has to wait for a recovery to tow me, which took six hours in total down a very dark non lit road This road is leather And I don't know know how much damage has been done to my car as yet awaiting garage to call me I called first thing to report this pothole I don't know if it has been logged as non on my details were taken. After I came through the dangerous area. Unable to drive my car I pulled over and another behind me came past and ten mins later the and had also done exactly the same I have enclosed photos I went back this and his tyre was also damaged. luckily although I have morning to take pictures as it was so pitch black last night you can't see down this single track lane. It's so deep the hole it covered my whole footing of my wellie boot it measured 15.5cm deep and I used a broom handle to show you the width which is ove the width of the broom I also enclose a pic of in pothole with one wellie out so you can see how bad it is. I have more photos which is only letting me submit 4 pictures.

Location: Wood End Lane,,,Markyate, Contact:

Plot Number: 10.00 Feature Id - Location: 2U68/10 - Markyate Street Lane To Track At Scratch Wood Feature Type: HW:Network

Page 4 of 9

Effective: 01/12/2017 to 31/12/2018 Display Action Officer: No

Street: Wood End Lane (10325129)

Customer Services

Enquiry No.: 2248475 Logged by: ePortal on: 31/01/2018 11:16
Service: ROAD AND CYCLELANE DMA Subject: POTHOLE Classification: Service Request

Desc.: Pothole

Report Time - 2018-01-31T11:16:06+00:00

Service - Road and Cycle lane defects e.g. potholes (CW1)

Subject - Pothole (CPH)

Questions

Where is the pothole? - Centre of Road

What is the depth? Please provide your best estimate - More than 100mm (4 inch, roughly the size of a compact disk) What is the width? Please provide your best estimate - More than 300mm (12 inch/1 foot, roughly the size of a rugby ball)

Description - Completely covered with water so unable to determine exact location or depth and width.

Caused damage to callers car. its by woodend farm and a wooded area.

mapusrn - 10325129

assetID - HWCW523067

Ownership - HH: Hertfordshire Highways

Class - Unclassified Road - U

Road Name - Wood End Lane

Town - Markyate

District - SW: 2-Dacorum Area

Easterly - 506118

Northerly - 213463

Postcode -

Address 1 -

Feature ID - 2U68/10

Email -

Street: Wood End Lane (10325129)

Customer Services

Last name -

Address Line 1 -

Address Line 2 -

Town -

Post code -

Phone number -

Location: Wood End Lane...Markyate. Contact:

Plot Number: 10.00 Feature Id - Location: 2U68/10 - Markyate Street Lane To Track At Scratch Wood Feature Type: HW:Network

Enquiry No.: 2242327 Logged by: ePortal on: 17/01/2018 09:40 Service: ROAD AND CYCLELANE DMA Subject: POTHOLE Classification: Service Request

Desc.: Unsure how long the pot hole has been on Wood End Lane. I was on the yesterday, so it was dark. Because of this I was going slow at 20mph or less. I saw the pot hole and tried to swerve around it but still went over it because of where it was in the road. It has caused damage to my tire. It would be great if the pot hole would get fixed so that it won't cause damage

to other drives. Because it was dark I am unsure on how deep it is.

Location: Wood End Lane,,,Markyate,

Plot Number: 10.00 Feature Id - Location: 2U68/10 - Markyate Street Lane To Track At Scratch Wood Feature Type: HW:Network

Enquiry No.: 2241361 Logged by: ePortal on: 15/01/2018 12:12 Service: ROAD AND CYCLELANE DMA Subject: POTHOLE Classification: Service Request

Desc.: The pothole was on the edge of the road however because it comes out into the road and the size of the pot hole, cars still need to go over this because there isn't much space on the other side.

When I was driving down there its was so was dark meaning I couldn't see many reference points.

I am unsure if any work has been carried out on the road however there was nothing warning me of the pot hole.

Because I went over the pot hole, it caused a flat tyre on my front left tyre. As it was dark, we left the hazard lights on to warn any oncoming vehicles but by the time we filled the tyre with

Contact:

expandable foam, the battery had died. We left the car off the road on the lane as we couldn't move it any further. I have already contacted my local garage and they will be collecting the car today.

Location: Wood End Lane,...Markyate,

Plot Number: 10.00

Feature Id - Location: 2U68/10 - Markvate Street Lane To Track At Scratch Wood Feature Type: HW:Network

Job Number: 1772275 Defect Number: 934001

Enquiry No.: 2237924 Logged by: ePortal on: 05/01/2018 11:38 Service: FLOODING AND DRAINAGE Subject: ROAD FLOODED Classification: Service Request

DMA

Desc.: Customer reports this spot floods frequently and always has. Used to have a septic tank going from the road down into the ground. Please assess drainage for the road.

Location: Wood End Lane,,,Markyate, Contact:

Plot Number: 10.00 Feature Id - Location: 2U68/10 - Markyate Street Lane To Track At Scratch Wood

Feature Type: HW:Network

Street: Wood End Lane (10325129)

Customer Services

Enquiry No.: 2234610 Logged by: ePortal on: 22/12/2017 19:21
Service: ROAD AND CYCLELANE DMA Subject: POTHOLE Classification: Service Request

Desc.: Located near the first entrance to Wood Emd Farm as you enter Wood End Lane from the Markyate end.

It is significant to do damage if hit unknowingly while driving.

Location: Wood End Lane,,,Markyate,

Plot Number: 10.00 Feature Id - Location: 2U68/10 - Markyate Street Lane To Track At Scratch Wood Feature Type: HW:Network

Enquiry No.: 2234609 Logged by: ePortal on: 22/12/2017 19:17
Service: ROAD AND CYCLELANE DMA Subject: POTHOLE Classification: Service Request

Desc.: Travelling from Trowley Bottom towards Wood End Farm the pothole is on the road just after passing Scratch Wood,

As the road is often covered with water it is difficult to see & as a result is very dangerous,

Please fill this as a matter of urgency.

Location: Wood End Lane,,,Markyate, Contact:

Plot Number: 10.00 Feature Id - Location: 2U68/10 - Markyate Street Lane To Track At Scratch Wood Feature Type: HW:Network

Job Number: 1771291 Defect Number: 932527

Enquiry No.: 2231655 Logged by: ePortal on: 11/12/2017 11:39
Service: ROAD AND CYCLELANE DMA Subject: POTHOLE Classification: Service Request

Desc.: Large pothole in the lane of travel. Please call and repair asap as hazardous to cars

Location: Wood End Lane,,,,Markyate, Contact:

Plot Number: 10.00 Feature Id - Location: 2U68/10 - Markyate Street Lane To Track At Scratch Wood Feature Type: HW:Network

Job Number: 1766444 Defect Number: 926124

(Enquiry 2241361) (CPH4-C/way pothole-20 Days)

Maintenance Management

Job No.	Description		Location	Priority	Job Status	Entered	Completion	Works Order
	Section:	10.00 R	oad No Locn.: 2U68/10 - Markyate Stree	et Lane To Track At Scratch Wood C/W	ay Type: HW:Network		Area: SW: 2-Dac	rum Area
17664	water	900x300 et's of standing 1655) (CPH4-C	By farm gate	Permanent repair (20 days)	Job Completed	15/12/2017	11/01/2018 Act.	HH12/2502446
17712	91 **8/2**Temp needed x1 c/w patch size due to be but is very de	road closure required unsure eing under wate ep and dangero 4609) (CPH4-C/	r, us	Permanent repair (20 days)	Job Completed	11/01/2018	01/02/2018 Act.	HH12/2507299
17722	75 **13.02**Tem required <u>x1 c/w p</u> atch	•	By public footpath sign (sprayed hedge) as standing water	Permanent repair (20 days)	Job Completed	16/01/2018	01/02/2018 Act.	HH12/2508280

Effective: 01/12/2017 to 31/12/2018

Street: Wood End Lane (10325129)

Town - Markyate

Easterly - 506576 Northerly - 213622

District - SW: 2-Dacorum Area

Display Action Officer: No

Mainte	enance Mana	gement						
	Description	gomone	Location	Priority	Job Status	Entered	Completion	Works Order
	Section:	10.00 Ro a	ad No Locn.: 2U68/10 - Markyate Street Lane To Track At S	Scratch Wood	C/Way Type: HW:Network		Area: SW: 2-D	acorum Area
17803	road resemble accessible on motorcycles, p cyclists can go holes beneath impossible to	es a river ly to large 4x4. No pedestrians or et through. Pot a are submerged s see conditions of g stretch of road.	Report Time - 2018-02-15T14:18:06+00:00 so	Urgent Respon	nse (5 days) Job Comp Further Wrk required	16/02/2018	20/02/2018 /	Act. HH12/2515760
			mapusrn - 10325129 assetID - HWCW523067 Ownership - HH: Hertfordshire Highways					
			Class - Unclassified Road - U Road Name - Wood End Lane					

Effective: 01/12/2017 to 31/12/2018 **Display Action Officer: No** Street: Wood End Lane (10325129) Postcode -**Maintenance Management** Addates n1 -Job No. Description **Priority Job Status Entered** Completion **Works Order** Feature ID - 2U68/10 Email First name -Last name -Address Line 1 -Address Line 2 -Town -Post code -Phone number **Street Works Notices** Organisation: Ringway (RING) Works Ref: BR6101000154523 Version: 2 Work Desc: c/w patching Notice Type: Works Stop **Start:** 11/01/2018 13:03:00 Work Status: Works Stopped Issued: 11/01/2018 13:49:01 Work Type: EToN 4: Immediate - Urgent Est. End: 15/01/2018 Completion: 11/01/2018 Site No. Location **Position** Depth Length Width Status Site Date Interim Perm. Prop. End 1 by farm gate Not Specified by Undertaker Not Specified by Undertaker 0.00 0.00 Site Closed 11/01/2018 15/01/2018 Works Ref: BR6101000155922 Work Desc: c/w patching Version: 3 Notice Type: Works Stop **Start:** 29/01/2018 08:20:00 Work Status: Works Stopped Issued: 30/01/2018 08:45:24 Work Type: EToN 4: Immediate - Urgent Est. End: 30/01/2018 Completion: 30/01/2018

Width Status

0.00 Site Closed

Site Date Interim

30/01/2018

Perm.

Prop. End

30/01/2018

Length

0.00

Position

Depth

Not Specified by Undertaker Not Specified by Undertaker

Site No. Location

1 Approximately half way down the lane, have

marked the hedge line

Street: Wood End Lane (10325129)

Street Works Notices

Organisation: Ringway (RING)

Works Ref: BR6101000156336

Notice Type: Works Stop Work Status: Works Stopped Work Type: EToN 4: Immediate - Urgent Version: 3

Work Desc: c/w patching

Start: 01/02/2018 08:20:00 **Issued:** 01/02/2018 08:57:02

Est. End: 05/02/2018 **Completion:** 01/02/2018

Site No. LocationPositionDepthLengthWidth StatusSite DateInterimPerm.Prop. End1By public footpath signNot Specified by Undertaker Not Specified by Undertaker0.000.00 Site Closed01/02/201805/02/2018