From:				
Sent:	24 July 2017 11:08			
To: Cc:	12.			
Subject:	Fw: Update on Preston	New Dood		
Subject.	i w. opdate on rieston	New Road		3
Hello, I see that as we head towards the myself or know.	is away at the moment nain drilling phase. Should		is intended as an update ion be required, please	
Thanks and regards,				
manks and regards,				
		4		72
	1 1 1 1			
From:				60° E1
Sent: 24 July 2017 10:45	1			
To:		- *		
Cc:	Nav. Dand			"n *
Subject: Update on Preston	New Koad		*	
	er the weekly report subm Preston New Road. We are			n works
option of either using a 29 that we have selected the after confirming no flow r	ted in the Notifications, for 0-1/2" diverter or of drilling option of drilling a 16" pil- isk, opening the hole up to ents. Having re-assessed to isidered to be very low.	g a pilot hole using a ot hole with the 21-1 26" with a riser. This	21-1/4" diverter. I can c /4" diverter in place, an s will best facilitate hand	onfirm d then lling of
I can also confirm that we	have no outstanding well	examination issues	with the well construction	n nhacac
covered by the Notificatio		CAGITITIACION ISSUES (	with the well constitiction	ni hiiases
Best regards,				
			2	

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit <a href="http://www.symanteccloud.com">http://www.symanteccloud.com</a>