
From:
Sent: 19 April 2017 16:33
To: Well Notifications
Cc:
Subject: Notification to Drill Well PNR-2 on LJ/06
Attachments: BSOR Notification PNR-2 Drilling 19-Apr-17.pdf

Good afternoon, attached please find the Notification relating to the drilling of exploration well Preston New Road 2 on LJ/06.

Further to my e-mail of 12 April with the Notification to Drill well Preston New Road 1 / 1Z, would you please note one correction:
In Table 2, first row (Section C - Tubing Head) - the flange is 13-5/8" 10,000psi (and not 11" 10,000psi as stated) x 5-1/8" 10,000psi.
My apologies for any inconvenience.

Best regards,

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

From: on behalf of Well Notifications
Sent: 20 April 2017 08:46
To:
Cc:

Subject: RE: Notification to Drill Well PNR-2 on LJ/06

Good Morning

Thank you for your HSE Notification Documents which are receiving attention.

Regards

• Well Operations Administration

Lord Cullen House
Fraser Place
Aberdeen
AB25 3UB

From:
Sent: 19 April 2017 16:33
To: Well Notifications
Cc:
Subject: Notification to Drill Well PNR-2 on LJ/06

Good afternoon, attached please find the Notification relating to the drilling of exploration well Preston New Road 2 on LJ/06.

Further to my e-mail of 12 April with the Notification to Drill well Preston New Road 1 / 1Z, would you please note one correction:

In Table 2, first row (Section C - Tubing Head) - the flange is 13-5/8" 10,000psi (and not 11" 10,000psi as stated) x 5-1/8" 10,000psi.

My apologies for any inconvenience.

Best regards,

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>
