DisplayAction Officer: No

Site: Bretby Lane (35400128) Locality: Bretby, Derbyshire Area: South Derbyshire District

Condition S	urvey
-------------	-------

Defect No: Desc	ription	Log Date Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1,000.00	Asset - Locn.: QH - Bretby Ln, Bretby	Feature Type: High	nway Inspe	ction	Area: South	Derbyshire District
Batch: 89009627 - Ad Hoc Inspection Batch			Route: Ad-hoc route				Date: 09/04/2018
61009451 HP - Carriageway Pothole/Trip - Extremely 09/04/2018 Bretby Lane Bretby			carriageway pothole	Interna	ı	Committed	53262500

Deep pothole At 715pm today (080418) I hit a very deep pothole on Bretby lane located on the bend between bretby nurseries and the post box I was travelling towards Winshill I could not avoid the crater as there was traffic coming the other way The hole was full of water and not obvious until it is too late There was a massive bang My nearside front wheel is damaged and the tyre poppedflattened My spare wheel has been used and I will be taking the car to the mechanic and tyre fitter tomorrow to be checked and fixed Please can you inform me of how to claim for the costs of the repair I have several photographs of the pot hole and damage to my car has just informed me that she reported the pothole a few weeks ago along with another pothole near to the entrance of Bretby nurseries She received an email stating that they had been repaired This was obviously not true It is a very dangerous road fault and could cause serious injury to someone (Enquiry

Batch: 89008556 - Ad Hoc Inspection Batch Route: Ad-hoc route Date: 02/03/2018 61008380 HP - Carriageway Pothole/Trip - Deep 02/03/2018 Bretby Lane Bretby carriageway pothole Internal Committed 53261274

Pothole on the junction of Bretby Lane Mount Road Close to the entrance of Planters Garden Centre (Bretby Nurseries) As you drive along Bretby Lane the pothole is on the left hand side just before you turn in to Planters Garden Centre - I first noticed this on the 12022018 - this has been a reoccurring problem (Enquiry

Batch: 89008211 - Ad Hoc Inspection Batch Date: 12/02/2018 Route: Ad-hoc route 61008035 HP - Carriageway Pothole/Trip - 4 Deep 12/02/2018 Bretby Lane Bretby Internal Committed

potholes at number 76 Bretby Lane Saturday 8th Feb 2018 (Enquiry

carriageway pothole

53260843

Defect No: Description	Log Date	Location	Defect Type	Class. Organisation	Status	Job No.
<b>Asset:</b> 1,000.00 <b>Asset - Locn.</b> :	QH - Bretby L	n, Bretby	Feature Type: ⊦	lighway Inspection	Area: South D	Derbyshire District
Batch: 89006334 - Ad Hoc Inspection Batch		Route: Ad-	hoc route			Date: 31/08/2017
61006158 Subsidence affecting hway - Subsidence and developing pothole causes vibrations through house as heavy traffic passesreported 30-08-17 (Enquiry	31/08/2017	Bretby Lane Bretby	carriageway pothole	Internal	Committed	53258138
Batch: 89006204 - Ad Hoc Inspection Batch		Route: Ad-	hoc route			Date: 11/08/2017
61006028 HP - Carriageway Pothole/Trip - Deep pothole entrance to Bretby Garden Centre progressivly getting worse over the past months Takes plenty of traffic and may cause a hazard with drivers swerving to avoid it Date Issue raised: 11082017 (Enquiry)	11/08/2017	Bretby Lane Bretby	carriageway pothole	Internal	Committed	53257945
Batch: 89004686 - Ad Hoc Inspection Batch		Route: Ad-	hoc route			Date: 01/03/2017
61004510 HP - Footway Pothole/Trip - Damage to kerb (Enquiry	01/03/2017	Bretby Lane Bretby Caller reports very loose kerb stone which is sticking up 2 or 3 quote at one end at Bretby Lane		Internal	Committed	53255798
Batch: 89002468 - Ad Hoc Inspection Batch		Route: Ad-	hoc route			Date: 25/05/2016
61002292 HP - Carriageway Pothole/Trip - Deep pothole - Received via Contact Centre email: write to report a pothole in the tarmacadam road surface at the base of the concrete speed bump location is outside 34 Bretby Lane DE15 0QW nearsideRegards (Enquiry	25/05/2016	Bretby Lane Bretby outside number 34	carriageway pothole	Internal	Committed	53252685
Batch: 89002398 - Ad Hoc Inspection Batch		Route: Ad-	hoc route			Date: 19/05/2016
61002222 HP - Carriageway Pothole/Trip - Deep pothole - Not very wide but it is very deep (Enquiry	19/05/2016	53 53a Bretby Lane Bretby DE15 0QW	carriageway pothole	Internal	Committed	53252603
Batch: 89001986 - Ad Hoc Inspection Batch		Route: Ad-	hoc route			Date: 12/04/2016
S1001810 HP - Carriageway Pothole/Trip - Deep pothole near to speed bump Large area of deteriorated road around it alsoCars swerving to avoid (Enquiry	12/04/2016	Bretby Lane Bretby	carriageway pothole	Internal	Committed	53252129
Batch: 70096894 - Inspection Batch		Route: 058	S - Qrtrly Hwy - Melbourne			Date: 03/04/2018
40069440 Cut and sweep out, fill and trim to reinstate deep cway edge pothole to make safe	03/04/2018	Travelling from Garden Centre Betwee Pease Hill and No 135 on opposite side cway edge		Internal	Committed	50051711

Condition Survey
------------------

Defect No: Description	Log Date	Location	Defect Type	Class. Organisation	Status	Job No
Asset: 1,000.00 Asset - Locn.	: QH - Bretby L	n, Bretby	Feature Type: Highwa	ay Inspection	Area: South D	erbyshire District
Batch: 70094934 - Inspection Batch		Route: A	d-hoc route			Date: 15/03/2018
40068031 Cut and sweep out, fill and trim to reinstate four cway potholes to make safe	15/03/2018 e.	2 x cway edge potholes opposite No 219, 1 x cway pothole o/side 72 and cway o/side 76 near to speed hump.		Internal	Committed	50050519
Batch: 70092276 - Inspection Batch		Route: A	d-hoc route			Date: 21/02/2018
40065923 Cut and sweep out, fill and trim to reinstate 7 cway potholes. (Enquiry and add.)	21/02/2018	1 x cw pothole o/s garden centre, 5 cway potholes around speed hump between 76 and 74, 1 x cw pothole o 23 around gully.	carriageway pothole /s	Internal	Committed	50048699
Batch: 70084615 - Inspection Batch		Route: 0	58S - Qrtrly Hwy - Melbourne			Date: 02/01/2018
40060499 Take up and replace 6 x 5 BN Kerb.	02/01/2018	o/s 79	kb-kerb missg/ damagd/ upstand	Internal	Committed	50043729
Batch: 70084323 - Inspection Batch		Route: A	d-hoc route			Date: 20/12/2017
40060272 Please clear and take away fallen tree ar leave access clear	nd 20/12/2017	at beginning of link path between Bre Lane and Geary Lane Bretby Lane		Internal	Uncommitted	50043506
Batch: 70079976 - Inspection Batch		Route: 0	58S - Qrtrly Hwy - Melbourne			Date: 20/11/2017
No actionable defects found						
Batch: 70065396 - Inspection Batch		Route: 0	58S - Qrtrly Hwy - Melbourne			Date: 03/07/2017
40050618 potholes edge of road	03/07/2017	outside 252	carriageway pothole	Internal	Committed	5003479
Batch: 70064358 - Inspection Batch		Route: A	d-hoc route			Date: 21/06/2017
40049990 Cway deterioration - Multiple repairs both sides of the road hump (Enquiry - Reinstate fillet around speed hump where potholing	21/06/2017	Outside 29 Bretby Lane, Bretby	carriageway pothole	Internal	Committed	5003422 <sup>-</sup>
Batch: 70056772 - Inspection Batch		Route: 0	58S - Qrtrly Hwy - Melbourne			Date: 18/04/2017
40045340 deep pothole at edge of road	18/04/2017	approx 100m east of property no 190	carriageway pothole	Internal	Committed	50030273
40045342 deep pothole	18/04/2017	outside 74	carriageway pothole	Internal	Committed	50030275
Batch: 70047927 - Inspection Batch			d-hoc route			Date: 06/02/2017
40039116 pothole in patch	06/02/2017	just past bretby garden centre entrar close to no 252		Internal	Committed	50025287
Batch: 70045475 - Inspection Batch		Route: 0	58S - Qrtrly Hwy - Melbourne			Date: 17/01/2017
40037309 potholes	17/01/2017	between 76 and 74	carriageway pothole	Internal	Committed	5002397
Batch: 70035605 - Inspection Batch		Route: 0	58S - Qrtrly Hwy - Melbourne			Date: 12/10/2016
40030962 fillet needs reinstating at speed hump	12/10/2016	close to no 32	carriageway pothole	Internal	Committed	5001985
Batch: 70027036 - Inspection Batch			58S - Qrtrly Hwy - Melbourne			Date: 26/07/2016
40025075 deep pothole in wheel tracks 40025074 LP - Carriageway Pothole/Trip - Shallow pothole by speed pad outside no 34 (Enquiry	26/07/2016 26/07/2016	by road gully close to 55A Bretby Lane Bretby	carriageway pothole carriageway pothole	Internal Internal	Committed Committed	50012180 50012179

DisplayAction Officer: No

Condition	Survey
-----------	--------

Defect No: Description	Log Date Location	Defect Type	Class. Organisation	Status	Job No.
<b>Asset:</b> 1,000.00 <b>Asset - Locn.:</b>	QH - Bretby Ln, Bretby	Feature Type: Hig	hway Inspection	Area: South D	erbyshire District
Batch: 70019562 - Inspection Batch		Route: Ad-hoc route			Date: 26/05/2016
40018217 potholes against kerbline	26/05/2016 opposite no 103	carriageway pothole	Internal	Committed	50012208
Batch: 70019492 - Inspection Batch		Route: Ad-hoc route			Date: 26/05/2016
40018179 deep pothole in wheel tracks	26/05/2016 by road gully close to 55A	carriageway pothole	Internal	Committed	50012180
Batch: 70019491 - Inspection Batch		Route: Ad-hoc route			Date: 26/05/2016
40018178 LP - Carriageway Pothole/Trip - Shallow pothole by speed pad outside no 34 (Enquiry	26/05/2016 Bretby Lane Bretby	carriageway pothole	Internal	Committed	50012179
Batch: 70014606 - Inspection Batch		Route: 058S - Qrtrly Hwy - Melbourne			Date: 19/04/2016
No actionable defects found					
<b>Asset:</b> 100,001.00 <b>Asset - Locn.</b> :	007461 - Outside No 51 (Bretby)	Feature Type: Lig	hting Column 5m	Area: SL: Nigh	nt Scout S02
Batch: 74008544 - Inspection Batch		Route: SL: South Area Test			Date: 16/05/2016
No actionable defects found					
<b>Asset:</b> 100,002.00 <b>Asset - Locn.</b> :	007460 - Opposite No 32 (Bretby)	Feature Type: Lig	hting Column 5m	Area: SL: Nigh	nt Scout S02
Batch: 74008544 - Inspection Batch		Route: SL: South Area Test			<b>Date</b> : 16/05/2016
No actionable defects found					
<b>Asset:</b> 100,003.00 <b>Asset - Locn.</b> :	007459 - Outside 22 (Bretby)	Feature Type: Lig	hting Column 5m	Area: SL: Nigh	nt Scout S02
Batch: 74008544 - Inspection Batch		Route: SL: South Area Test			<b>Date</b> : 16/05/2016
No actionable defects found					
<b>Asset:</b> 100,004.00 <b>Asset - Locn.</b> :	007458 - Outside 15/17 (Bretby)	Feature Type: Lig	hting Column 5m	Area: SL: Nigh	nt Scout S02
Batch: 74008544 - Inspection Batch		Route: SL: South Area Test			<b>Date</b> : 16/05/2016
No actionable defects found					
<u> </u>	007457 - Outside No 5 (Bretby)	Feature Type: Lig	hting Column 5m	Area: SL: Nigh	nt Scout S02
Batch: 74008544 - Inspection Batch		Route: SL: South Area Test			<b>Date</b> : 16/05/2016
No actionable defects found					
	007477 - Opposite Mount Road. Outside	••••	hting Column 5m	Area: SL: Nigh	
Batch: 74008544 - Inspection Batch		Route: SL: South Area Test			<b>Date:</b> 16/05/2016
No actionable defects found					
<b>Asset:</b> 100,007.00 <b>Asset - Locn.</b> :	007476 - Outside 254 (Bretby)	Feature Type: Lig	hting Column 5m	Area: SL: Nigh	nt Scout S02
Batch: 74017929 - Ad Hoc Inspection Batch		Route: Street Lighting Ad Hoc Testing			Date: 29/11/2016
44017081 out	29/11/2016	2 - Lighting Fault - Out	Internal	Committed	54021578
Batch: 74008544 - Inspection Batch No actionable defects found		Route: SL: South Area Test			<b>Date</b> : 16/05/2016
<b>Asset:</b> 100,008.00 <b>Asset - Locn.:</b>	007475 - Opposite Nos 215/217 (Bretby)	Feature Type: Lig	hting Column 5m	Area: SL: Nigh	nt Scout S02
Batch: 74008544 - Inspection Batch		Route: SL: South Area Test			Date: 16/05/2016
No authorable defents formal					

No actionable defects found

Condition Survey
------------------

Defect No: Description	Log Date Location	Defect Type	Class. Organisation	Status	Job No.
<b>Asset</b> : 100,009.00	Asset - Locn.: 007474 - Outside 222 (Bretby)	Feature Type:	Lighting Column 5m	Area: SL: Nig	ht Scout S02
Batch: 74008544 - Inspect	ion Batch	Route: SL: South Area Test			Date: 16/05/2016
No actionable defects	found				
<b>Asset:</b> 100,010.00	Asset - Locn.: 007473 - Near No 222 (Bretby)	Feature Type:	Lighting Column 5m	Area: SL: Nig	ht Scout S02
Batch: 74067852 - Ad Hoc	Inspection Batch	Route: Street Lighting Ad Hoc Testing			Date: 23/01/2018
44037587 out	23/01/2018	2 - Lighting Fault - Out	Internal	Committed	54045988
Batch: 74008544 - Inspect	ion Batch	Route: SL: South Area Test			Date: 16/05/2016
No actionable defects	found				
<b>Asset:</b> 100,011.00	Asset - Locn.: 007471 - Outside 188/190 (Bretby)	Feature Type:	Lighting Column 5m	Area: SL: Nig	ht Scout S02
Batch: 74051563 - Ad Hoc	Inspection Batch	Route: Street Lighting Ad Hoc Testing			Date: 13/09/2017
44029427 Out	13/09/2017	2 - Lighting Fault - Out	Internal	Committed	54036468
Batch: 74008544 - Inspect	ion Batch	Route: SL: South Area Test			Date: 16/05/2016
No actionable defects	found				
<b>Asset:</b> 100,012.00	Asset - Locn.: 007470 - Outside No 135 (Bretby)	Feature Type:	Lighting Column 5m	Area: SL: Nig	ht Scout S02
Batch: 74008544 - Inspect	ion Batch	Route: SL: South Area Test			Date: 16/05/2016
No actionable defects	found				
<b>Asset:</b> 100,013.00	Asset - Locn.: 007469 - Outside 127A (Bretby)	Feature Type:	Lighting Column 5m	Area: SL: Nig	ht Scout S02
Batch: 74008544 - Inspect	ion Batch	Route: SL: South Area Test			Date: 16/05/2016
No actionable defects	found				
<b>Asset:</b> 100,014.00	Asset - Locn.: 007468 - Outside No 121 (Bretby)	Feature Type:	Lighting Column 5m	Area: SL: Nig	ht Scout S02
Batch: 74008544 - Inspect	ion Batch	Route: SL: South Area Test			Date: 16/05/2016
No actionable defects	found				
<b>Asset:</b> 100,015.00	Asset - Locn.: 007467 - Outside 105 (Bretby)	Feature Type:	Lighting Column 5m	Area: SL: Nig	ht Scout S02
Batch: 74008544 - Inspect	ion Batch	Route: SL: South Area Test			Date: 16/05/2016
No actionable defects	found				
<b>Asset:</b> 100,016.00	Asset - Locn.: 007466 - Opposite 90 (Bretby)	Feature Type:	Lighting Column 5m	Area: SL: Nig	ht Scout S02
Batch: 74008544 - Inspect	ion Batch	Route: SL: South Area Test			Date: 16/05/2016
No actionable defects	found				
<b>Asset:</b> 100,017.00	Asset - Locn.: 007465 - By No 91 (Bretby)	Feature Type:	Lighting Column 5m	Area: SL: Nig	ht Scout S02
Batch: 74008544 - Inspect	ion Batch	Route: SL: South Area Test			Date: 16/05/2016
No actionable defects	found				
Batch: 74008422 - Ad Hoc	Inspection Batch	Route: Street Lighting Ad Hoc Testing			Date: 13/05/2016
44007827 OUT	13/05/2016	2 - Lighting Fault - Out	Internal	Committed	5401064
<b>Asset:</b> 100,018.00	Asset - Locn.: 007464 - Outside Nos 83/85 (Bretby)	Feature Type:	Lighting Column 5m	Area: SL: Nig	ht Scout S02
Batch: 74050255 - Ad Hoc	Inspection Batch	Route: Street Lighting Ad Hoc Testing			Date: 31/08/2017
44028690 dim	31/08/2017	2 - Lighting Fault - Dim	Internal	Committed	54035578

DisplayAction Officer: No

Condition Survey
------------------

Defect No: Description	Log Date Location	Defect Type	Class. Organisation	Status	Job No.
<b>Asset:</b> 100,018.00	Asset - Locn.: 007464 - Outside Nos 83/85 (Bretby)	Feature Type: Ligi	nting Column 5m	Area: SL: Nig	ht Scout S02
Batch: 74008544 - Inspection Batch		Route: SL: South Area Test			Date: 16/05/2016
No actionable defects	s found				
<b>Asset:</b> 100,019.00	Asset - Locn.: 007462 - Outside 61/63 (Bretby)	Feature Type: Ligi	nting Column 5m	Area: SL: Nig	ht Scout S02
Batch: 74039289 - Ad Hoo	c Inspection Batch	Route: Street Lighting Ad Hoc Testing			Date: 16/05/2017
44025059 out	16/05/2017	2 - Lighting Fault - Out	Internal	Committed	54030778
Batch: 74038181 - Ad Hoo	c Inspection Batch	Route: Street Lighting Ad Hoc Testing			Date: 09/05/2017
44024889 Out	09/05/2017	2 - Lighting Fault - Out	Internal	Committed	54030545
Batch: 74008544 - Inspec	tion Batch	Route: SL: South Area Test			Date: 16/05/2016
No actionable defects	s found				
<b>Asset:</b> 100,020.00	Asset - Locn.: 007463 - Opposite Oldcote Lane (Bretby	) Feature Type: Ligi	nting Column 5m	Area: SL: Nig	ht Scout S02
Batch: 74019177 - Ad Hoo	c Inspection Batch	Route: Street Lighting Ad Hoc Testing			Date: 14/12/2016
44018249 Light No7463 which is fault Its burning hours Dawn The fault is: - F	s shold be: Dusk to	2 - Lighting Fault - Out	Internal	Committed	54022818
Batch: 74008544 - Inspec	tion Batch	Route: SL: South Area Test			Date: 16/05/2016
No actionable defects	s found				
Sustomer Services					
Enquiry No.:	Logged by  stenance Subject: Emergency tree works	on: 24/09/2016 11:58 Classification: Highways Maintenance	Enquiry Ref: INC	\ 072	
Service: H - Highway Main	n/way - looks like its being held up by another tree.	Classification: Figureays Maintenance	Enquiry Ref. INC	, 213	
Location: near nursery	with the terms from up by unterner area.	Contact:			
Enquiry No.:	Logged by:	on: 09/05/2016 07:22			
Service: H - Highway Main Desc.: Pothole in c/way	tenance Subject: HP - Carriageway Pothole/Trip	Classification: Highways Maintenance			
Location: o/s 27 Bretby Lan		Contact:			
Plot Number: 1,000.00	Feature Id - Location: QH - Bretby Ln, Bretby	Feature Typ	e: Highway Inspection		
Enquiry No.:	Logged by: REPORT IT WEBFORMS	on: 10/04/2018 15:53			
Service: Traffic & Safety M	fiscellaneous Subject: Temp Traffic Signals hts - Gas service works - 30/05/2018 to 05/06/2018 - 24hrs	Classification: Traffic	Enquiry Ref: ILF	292/706959	
Location: Bretby Lane		Contact:			
Enquiry No.:	Logged by: REPORT IT WEBFORMS	on: 09/04/2018 09:20			
Service: H - Highway Main	stenance Subject: HP - Carriageway Pothole/Trip	Classification: Highways Maintenance			
	Iller has called to report a pothole that has made their vehicle ates that the pothole is situated in the middle of the driveway.	not driveable. Caller states that the pothole i	s measuring approximately 6	3 inches deep and	I measuring approxim
Leastien, Prothy Long Prot	by	Camtanti			

Contact:

Location: Bretby Lane, Bretby,

Site: Bretby Lane (35400128)

## **Customer Services**

Enquiry No.: Service: H - Highway Maintenance Subject: HP - Carriageway Pothole/Trip Classification: Highways Maintenance

Desc.: Extremely Deep pothole At 715pm today ( 080418) I hit a very deep pothole on Bretby lane located on the bend between bretby nurseries and the post box I was travelling towards Winshill I could not avoid the crater as there was traffic coming the other way The hole was full of water and not obvious until it is too late There was a massive bang My nearside front wheel is damaged and the tyre poppedflattened My spare wheel has been used and I will be taking the car to the mechanic and tyre fitter tomorrow to be checked and fixed Please can you inform me of how to claim for the costs of the repair I have several photographs of the pot hole and damage to my car has just informed me that she reported the pothole a few weeks ago along with another pothole near to the entrance of Bretby nurseries She received an email stating that they had been repaired This was obviously not true It is a very dangerous road fault and could cause serious injury to

someone

Location: Bretby Lane Bretby Contact:

Plot Number: 1,000.00 Feature Id - Location: QH - Bretby Ln, Bretby Feature Type: Highway Inspection

Enquiry No.: Logged by: REPORT IT WEBFORMS on: 07/04/2018 16:11

Service: H - Highway Maintenance Subject: HP - Carriageway Pothole/Trip Classification: Highways Maintenance

Desc.: Deep pothole on bend of Bretby Lane travelling from Repton to Bretbynoted 2355 6th april 2018

Location: Bretby Lane Bretby

Contact:

Plot Number: 1,000.00 Feature Id - Location: QH - Bretby Ln, Bretby Feature Type: Highway Inspection

Job Number: 53262500

Enquiry No.: Logged by: REPORT IT WEBFORMS on: 06/04/2018 14:08

Service: H - Highway Maintenance Subject: HP - Carriageway Pothole/Trip Classification: Highways Maintenance

Desc.: Deep pothole on outside of bend some cars already damaged 05-94-18

Location: Bretby Lane Bretby Contact:

Plot Number: 1,000.00 Feature Id - Location: QH - Bretby Ln, Bretby Feature Type: Highway Inspection

Job Number: 50051711

Enquiry No.: Logged by: REPORT IT WEBFORMS on: 29/03/2018 15:06
Service: H - Highway Maintenance Subject: HP - Carriageway Pothole/Trip Classification: Highways Maintenance

Desc.: Deep pothole. Caller reports that there is a large pothole on the speed hump. She has said that this is not too bad as people will slow down for the speed hump but there is another one up the road

which is a curved pothole and the road here is 70mph and she is worried about what would happen if a car hit it.

Location: Bretby Lane, Bretby, as you come out of the drive between 215 and 217 Turn right. Contact:

Carry on down the road to the speed hump

Enquiry No.: Logged by: REPORT IT WEBFORMS on: 26/03/2018 12:29

Service: H - Highway Maintenance Subject: HP - Carriageway Pothole/Trip Classification: Highways Maintenance

Desc.: Deep potholes. Caller states that there is a large pothole on the road just in front of the post box. He stated that they were reported around 3-4 weeks ago and were refilled but they have now come

back and are worse than before. This is a busy road and the potholes are just before speed bumps and so these are causing an issue.

Location: Bretby Lane, Bretby, (Next to the post box )

Plot Number: 1.000.00 Feature Id - Location: QH - Bretby Ln. Bretby Feature Type: Highway Inspection

Job Number: 50048699

Enquiry No.

Service: H - Highway Maintenance

Logged by: REPORT IT WEBFORMS

Subject: HP - Carriageway Pothole/Trip

Classification: Highways Maintenance

Desc.: Hit Deep pothole just past mount road approximately 750 pm on 24th March 2018 Not going above 25 mph but Impossible to see in the dark and may have caused damage to my car as warning

steering light has come on

Location: Bretby Lane Bretby Contact:

Plot Number: 1,000.00 Feature Id - Location: QH - Bretby Ln, Bretby Feature Type: Highway Inspection

Job Number: 50048699

Site: Bretby Lane (35400128)

Customer Services

Enquiry No.:

Logged by: REPORT IT WEBFORMS

on: 23/03/2018 19:18

Service: H - Highway Maintenance Subject: HP - Carriageway Pothole/Trip

Classification: Highways Maintenance

Desc.: Deep pothole directly at the entrance to planters of Bretby You have to drive on the wrong side of the rd to avoid it

Location: Bretby Lane Bretby Contact:

Plot Number: 1.000.00 Feature Id - Location: QH - Bretby Ln, Bretby Feature Type: Highway Inspection

Job Number: 50048699

**Enquiry No.:** 

Logged by: REPORT IT WEBFORMS

on: 23/03/2018 19:18

Service: H - Highway Maintenance Subject: HP - Carriageway Pothole/Trip Classification: Highways Maintenance

Desc.: Very Deep pothole on Bretby lane not very far from Planters of Bretby heading towards Winshill it is on the left hand side toward the edge of the rd If something is coming the other way the road is too narrow to avoid it Today (23032018) I hit the Pot hole an it made an almighty bang I stopped further along Bretby lane on reaching my parents house to check for damage Nothing visible but it

cant have done the car any good This pothole could cause serious injury to someone particularly cyclists or motorcyclists if not dealt with immediately not to mention the cost of repairs

**Location:** Bretby Lane Bretby Contact:

Plot Number: 1.000.00

Feature Id - Location: QH - Bretby Ln, Bretby

Feature Type: Highway Inspection

Job Number: 50048699

Enquiry No.:

Logged by: REPORT IT WEBFORMS

on: 17/03/2018 23:16 Classification: Highways Maintenance

Service: H - Highway Maintenance Subject: Cway deterioration **Desc.:** Shallow pothole and major deterioration of edges of road

Location: Bretby Lane Bretby

Contact:

Contact:

Feature Id - Location: QH - Bretby Ln, Bretby

Feature Type: Highway Inspection

Plot Number: 1.000.00 Job Number: 50050519

Enquiry No.

Logged by: REPORT IT WEBFORMS

on: 17/03/2018 23:10

Service: H - Highway Maintenance

Subject: HP - Carriageway Pothole/Trip

Classification: Highways Maintenance

Desc.: Deep pothole

Location: Bretby Lane Bretby

Location: Bretby Lane Bretby

Contact:

**Plot Number: 1,000.00** 

Feature Id - Location: QH - Bretby Ln, Bretby

Feature Type: Highway Inspection

Job Number: 53261274

**Enquiry No.:** Service: H - Highway Maintenance

Logged by: REPORT IT WEBFORMS on: 17/03/2018 23:06 Subject: HP - Carriageway Pothole/Trip Classification: Highways Maintenance

**Desc.:** Deep pothole and general surface deterioration

Plot Number: 1,000.00

Feature Id - Location: QH - Bretby Ln, Bretby

Feature Type: Highway Inspection

Job Number: 50048699

Enquiry No.

Logged by: REPORT IT WEBFORMS

on: 01/03/2018 16:44

Service: H - Highway Maintenance

Subject: HP - Carriageway Pothole/Trip

Classification: Highways Maintenance

Desc.: Deep Pothole on the junction of Bretby Lane Mount Road Close to the entrance of Planters Garden Centre (Bretby Nurseries) As you drive along Bretby Lane the pothole is on the left hand side

just before you turn in to Planters Garden Centre - I first noticed this on the 12022018 - this has been a reoccurring problem

Location: Bretby Lane Bretby Contact:

**Plot Number: 1,000.00** 

Feature Id - Location: QH - Bretby Ln, Bretby

Feature Type: Highway Inspection

Job Number: 53261274

Defect Number: 61008380

Site: Bretby Lane (35400128)

Customer Services

**Enquiry No.:** 

**Enquiry No.:** 

Logged by: REPORT IT WEBFORMS

Subject: HP - Carriageway Pothole/Trip

on: 19/02/2018 17:30 Classification: Highways Maintenance

Desc.: Deep pothole x4

Location: Bretby Lane, Bretby,

Feature Id - Location: QH - Bretby Ln, Bretby

Feature Type: Highway Inspection

Plot Number: 1.000.00 Job Number: 53260843

Logged by: REPORT IT WEBFORMS

on: 19/02/2018 14:32

Service: H - Highway Maintenance

Service: H - Highway Maintenance

Subject: HP - Carriageway Pothole/Trip

Classification: Highways Maintenance

Desc.: Deep pothole

Location: Bretby Lane Bretby

Contact:

Contact:

Plot Number: 1.000.00

Feature Id - Location: QH - Bretby Ln, Bretby

Feature Type: Highway Inspection

Job Number: 53260843

**Enquiry No.:** Service: H - Highway Maintenance Logged by: REPORT IT WEBFORMS

on: 19/02/2018 13:25

Classification: Highways Maintenance

Subject: HP - Carriageway Pothole/Trip

Desc.: Deep pothole There are three potholes on either side of a speed bump on a bend in the road this makes it dangerous to try and avoid the deep holes

Location: Bretby Lane Bretby

Contact:

**Plot Number: 1.000.00** 

**Enquiry No.:** 

Feature Id - Location: QH - Bretby Ln. Bretby

Feature Type: Highway Inspection

Feature Type: Highway Inspection

Job Number: 53260843

Logged by: REPORT IT WEBFORMS Subject: LP - Carriageway Pothole/Trip

on: 19/02/2018 10:52 Classification: Highways Maintenance

**Desc.**: Shallow pothole Several potholes at the kerb side of speed bumps

Location: Bretby Lane Bretby

Service: H - Highway Maintenance

Contact:

Plot Number: 1.000.00

Feature Id - Location: QH - Bretby Ln, Bretby

Job Number: 50048699

Defect Number: 40065923

Enquiry No.:

Logged by: REPORT IT WEBFORMS Subject: HP - Carriageway Pothole/Trip on: 15/02/2018 21:10

Service: H - Highway Maintenance Classification: Highways Maintenance

Desc.: Deep potholes right next to the speed bump there are at least 3 together and with the speed bump its really hard to avoid them! There are more pot holes along the Lane if these could get done at

the same time it would be a bonus Many thanks

Location: Bretby Lane Bretby

Contact:

**Plot Number: 1,000.00** 

Feature Id - Location: QH - Bretby Ln, Bretby

Feature Type: Highway Inspection

Enquiry No.:

Job Number: 53260843

Logged by: REPORT IT WEBFORMS

on: 14/02/2018 10:42

Service: H - Highway Maintenance

Subject: HP - Carriageway Pothole/Trip

Classification: Highways Maintenance

Desc.: Deep pothole Caller has brought a new car a couple of weeks ago and is worried that this may have been damaged. There are a few potholes here which are unavoidable unless you go on the

other side of the road. There are 4 or 5 in a line. They were repaired a under a year ago.

Location: Bretby Lane, Bretby, coming from the garden centre with Olidcote lane on the left hand side.

Contact:

**Plot Number: 1.000.00** Job Number: 53260843

Feature Id - Location: QH - Bretby Ln, Bretby

Feature Type: Highway Inspection

Site: Bretby Lane (35400128)

Customer Services

Enquiry No.:

Logged by: REPORT IT WEBFORMS

Subject: HP - Carriageway Pothole/Trip

Classification: Highways Maintenance

on: 10/02/2018 14:59

Desc.: 4 Deep potholes at number 76 Bretby Lane Saturday 8th Feb 2018

Location: Bretby Lane Bretby

Service: H - Highway Maintenance

Contact:

Contact:

Plot Number: 1.000.00

Feature Id - Location: QH - Bretby Ln, Bretby

Feature Type: Highway Inspection

Job Number: 53260843 Defect Number: 61008035

Enquiry No.:

Logged by: REPORT IT WEBFORMS

on: 29/01/2018 13:11 Classification: Street Lighting

Service: SL - Street Lighting \*NEW Subject: 3 - Lighting Fault - Out

Desc.: Light No7473 which is made from Wood has a fault Its burning hours should be: Dusk to Dawn The fault is: - Fault: Light out

Location: Bretby Lane Near No 222 (Bretby) |Other details| Colum No. = 7473

Plot Number: 100.010.00

Feature Id - Location: 007473 - Near No 222 (Bretby)

Feature Type: Lighting Column 5m

Job Number: 54045988

Enquiry No.:

Logged by: REPORT IT WEBFORMS

on: 15/01/2018 14:47

Service: SL - Street Lighting \*NEW

Subject: 3 - Lighting Fault - Out

Classification: Street Lighting

Desc.: Light No7473 which is made from Wood has a fault Its burning hours should be: Dusk to Dawn The fault is: - Fault: Light out just before Christmas

Location: Bretby Lane Near No 222 (Bretby) |Other details| Colum No. = 7473

Contact:

Plot Number: 100.010.00 Job Number: 54045988

Feature Id - Location: 007473 - Near No 222 (Bretby)

Feature Type: Lighting Column 5m

Enquiry No.:

Logged by: REPORT IT WEBFORMS

on: 11/01/2018 14:23

Service: Traffic Signs & Road Markings Subject: Road signs Classification: Traffic

Desc.: Request new road sign, Received via contact centre emails. I am looking for information on the possibility on having a road sign put up that directs people to St Wystans Church Bretby, the church is tucked back from the Road and people find it difficult to locate. It doesnt fit under the tourist attraction bracket. Advise and a point of contact to discuss this matter would be very help full

Location: Bretby Lane, Bretby, St Wystans Church Bretby.

Contact:

Logged by: REPORT IT WEBFORMS **Enquiry No.:** 

on: 05/01/2018 09:03

Service: SL - Street Lighting \*NEW

Subject: 1 - Damaged Equipment

Classification: Street Lighting

Desc.: Light No.7463 which is made from Sheet Steel has a fault. Its burning hours should be: Dusk to Dawn. The fault is: - Fault: Column damaged. Caller reported that a lorry went into this lamppost yesterday and now the column is wobbly. She has a picture of the lorry but she doesnt have a registration number. Caller reports that there is a 3-4 inch gap at the bottom of the post.

Location: Bretby Lane Opposite Oldcote Lane (Bretby) |Other details| Colum No. = 7463

Contact:

Plot Number: 100.020.00

Feature Id - Location: 007463 - Opposite Oldcote Lane (Bretby)

Feature Type: Lighting Column 5m

Enquiry No.:

Logged by: REPORT IT WEBFORMS

on: 15/12/2017 11:52

Service: Maintenance Winter Service Subject: Gritting - route not done Classification: Highways Maintenance

Desc.: Report route as ungritted - Caller reported that the road is thick ice and that cars are sliding all over the place. Caller has requested this is looked at, as a matter of urgency.

Location: Bretby Lane, Bretby,

Contact:

Logged by: REPORT IT WEBFORMS **Enquiry No.:** 

on: 15/12/2017 11:47

Service: Maintenance Winter Service

Subject: Gritting - route not done

Classification: Highways Maintenance

Desc.: Report route as ungritted. Caller reports road is very icy

Location: Bretby Lane, Bretby,

Contact:

**Enquiry No.:** 

Logged by: REPORT IT WEBFORMS

on: 15/12/2017 11:05

Service: Maintenance Winter Service

Subject: Gritting - route not done

Classification: Highways Maintenance

Desc.: Report route as ungritted - caller says this route has never been gritted since last week and that it is like an quote ice rink quote . Advised the route was gritted yesterday and caller says this is lies. Caller would like a call back preferably from a manager.

Location: Bretby Lane, Bretby,

Contact:

Site: Bretby Lane (35400128)

Customer Services

**Enquiry No.:** 

Logged by: REPORT IT WEBFORMS

on: 31/08/2017 09:08

Service: H - Highway Maintenance Subject: Tree Maintenance Classification: Highways Maintenance

Desc.: Received via contact centre email Bretby ORPA from Geary Road to Bretby Lane The line of this highway may have changed due to work by National Grid at southern end One wooden gate

halfway along seems to be redundant has the route changed? A tree has come down across its northern end

Location: Bretby Lane Bretby

Contact:

**Enquiry No.:** Service: H - Highway Maintenance

Logged by: REPORT IT WEBFORMS Subject: Subsidence affecting hway

on: 30/08/2017 20:56 Classification: Highways Maintenance

Desc.: Subsidence and developing pothole causes vibrations through house as heavy traffic passesreported 30-08-17

Location: Bretby Lane Bretby

Contact:

Plot Number: 1.000.00 Feature Id - Location: QH - Bretby Ln, Bretby

Feature Type: Highway Inspection

Job Number: 53258138

Enquiry No.:

Defect Number: 61006158

Logged by: REPORT IT WEBFORMS

on: 30/08/2017 20:51

Service: SL - Street Lighting \*NEW

Subject: 3 - Lighting Fault - Flashing Classification: Street Lighting

Desc.: Light No7471 which is made from has a fault its burning hours should be: Part Night The fault is: - Fault: Flashing

Location: Bretby Lane Outside 188190 (Bretby) |Other details| Colum No. = 7471

Contact:

Plot Number: 100.011.00

Feature Id - Location: 007471 - Outside 188/190 (Bretby)

Feature Type: Lighting Column 5m

**Job Number:** 54036468

Enquiry No.:

Logged by: REPORT IT WEBFORMS

on: 30/08/2017 20:51

Service: SL - Street Lighting \*NEW

Subject: 3 - Lighting Fault - Out

Classification: Street Lighting

Desc.: Light No7471 which is made from has a fault Its burning hours should be: Part Night The fault is: - Fault: Light out

Location: Bretby Lane Outside 188190 (Bretby) |Other details| Colum No. = 7471

Contact:

Plot Number: 100,011.00

Feature Id - Location: 007471 - Outside 188/190 (Bretby)

Feature Type: Lighting Column 5m

Job Number: 54036468

Enquiry No.:

Logged by: REPORT IT WEBFORMS

on: 16/08/2017 09:44

Service: SL - Street Lighting \*NEW

Subject: 3 - Lighting Fault - Dim

Classification: Street Lighting

Desc.: Light No7464 which is made from has a fault Its burning hours should be: Dusk to Dawn The fault is: - Fault: Dim lightCaller says that the light is glowing red and the lane is very dark

Location: Bretby Lane Outside Nos 8385 (Bretby) |Other details| Colum No. = 7464

Contact:

Plot Number: 100.018.00

Feature Id - Location: 007464 - Outside Nos 83/85 (Bretby)

Feature Type: Lighting Column 5m

Job Number: 54035578

Logged by: REPORT IT WEBFORMS

on: 11/08/2017 12:05

Enquiry No.: Service: H - Highway Maintenance

Subject: HP - Carriageway Pothole/Trip

Classification: Highways Maintenance

Desc.: Deep pothole entrance to Bretby Garden Centre progressivly getting worse over the past months Takes plenty of traffic and may cause a hazard with drivers swerving to avoid it Date Issue raised:

11082017

Location: Bretby Lane Bretby

Contact:

Plot Number: 1.000.00

Feature Id - Location: QH - Bretby Ln, Bretby

Feature Type: Highway Inspection

Job Number: 53257945

Defect Number: 61006028

Logged by: REPORT IT WEBFORMS Subject: Verge Damaged Overgrown

on: 20/06/2017 11:25 Classification: Highways Maintenance

Service: H - Highway Maintenance Desc.: Verge overgrown or damaged

Location: Bretby Lane Bretby Caller complaining of the mess caused after cutting back the verges on Bretby lane Caller has reported the problem for the last 2 years and

Contact:

nothing appears to be done about the mess caused please call back to

Enquiry No.:

Site: Bretby Lane (35400128)

Customer Services

Enquiry No.:

**Enquiry No.:** 

Logged by: REPORT IT WEBFORMS

on: 08/05/2017 19:28 Subject: 3 - Lighting Fault - Out Classification: Street Lighting

Desc.: Light out

Location: Bretby Lane Bretby outside of number 61 there is a street light that is not showing Contact:

on the map The number on the street light column is 7462 but on the map this is showing as being outside of number 105Please look in area for furthers out as this

was reported several times and months ago

Plot Number: 100.019.00

Feature Id - Location: 007462 - Outside 61/63 (Bretby)

Feature Type: Lighting Column 5m

Job Number: 54030778

Logged by: REPORT IT WEBFORMS

on: 31/03/2017 17:05

Service: H - Highway Maintenance

Service: SL - Street Lighting \*NEW

Subject: Obstruction in Hway

Classification: Highways Maintenance Desc.: Any other type of obstruction cars parking on the pavement all the way along the road causing obstruction to the pavement

Location: Bretby Lane Bretby

Contact:

Contact:

Enquiry No.: Service: H - Highway Maintenance

Logged by: REPORT IT WEBFORMS on: 01/03/2017 11:31

Subject: HP - Footway Pothole/Trip Classification: Highways Maintenance

Desc.: Damage to kerb

Location: Bretby Lane Bretby Caller reports very loose kerb stone which is sticking up 2 or 3

quote at one end Bretby Lane

**Plot Number: 1,000.00** 

Feature Id - Location: QH - Bretby Ln, Bretby

Feature Type: Highway Inspection

Job Number: 53255798

Service: SL - Street Lighting \*NEW

Defect Number: 61004510

Logged by: REPORT IT WEBFORMS Enquiry No.:

on: 12/12/2016 13:33 Subject: 3 - Lighting Fault - Out Classification: Street Lighting

Desc.: Light No7463 which is made from has a fault Its burning hours shold be: Dusk to Dawn The fault is: - Fault: Light out

Location: Bretby Lane Opposite Oldcote Lane (Bretby) |Other details| Colum No. = 7463 Contact:

Plot Number: 100.020.00 Feature Id - Location: 007463 - Opposite Oldcote Lane (Bretby) Feature Type: Lighting Column 5m

Job Number: 54022818

Logged by: REPORT IT WEBFORMS

on: 09/12/2016 13:42

Enquiry No.: Service: H - Highway Maintenance

Subject: Fly Tipping hway

Classification: Highways Maintenance

**Desc.:** Fly tipping kerbstones and tarmac rubble fly tipped in layby

Location: Bretby Lane Bretby layby about 150m from Planters Garden Centre

Contact:

**Enquiry No.:** 

Logged by: REPORT IT WEBFORMS

on: 23/11/2016 16:02 Classification: Street Lighting

Service: SL - Street Lighting \*NEW Subject: 3 - Lighting Fault - Out

Desc.: Light No7476 which is made from Wood has a fault Its burning hours shold be: Part Night The fault is: - Fault: Light out

Location: Bretby Lane OS 254 (BRETBY) |Other details| Colum No. = 7476

Bretby Lane Bretby

Contact:

Plot Number: 100.007.00

Feature Id - Location: 007476 - Outside 254 (Bretby)

Feature Type: Lighting Column 5m

**Job Number:** 54021578

Logged by: REPORT IT WEBFORMS

on: 03/10/2016 12:07

Service: H - Highway Maintenance

Subject: Drains/gully blocked

Classification: Highways Maintenance

Desc.: Caller is complaining about a blocked gulley that runs slightly under his land and is contributing to flooding

Location:

**Enquiry No** 

Contact

Site: Bretby Lane (35400128)

Customer Services

Enquiry No.:

Logged by: REPORT IT WEBFORMS on: 05/08/2016 12:12 Subject: HP - Carriageway Pothole/Trip Classification: Highways Maintenance

Service: H - Highway Maintenance **Desc.:** Deep pothole - 1ft across reporting previously now getting worse

Location: Bretby Lane Bretby 0s no 55

Contact:

Plot Number: 1.000.00 Feature Id - Location: QH - Bretby Ln, Bretby Feature Type: Highway Inspection

Job Number: 50012180 Defect Number: 40025075

Enquiry No.: Service: H - Highway Maintenance Logged by: REPORT IT WEBFORMS on: 30/06/2016 11:39 Subject: Verge Damaged Overgrown Classification: Highways Maintenance

Desc.: Verge overgrown or damaged Caller says the verges on Bretby Lane heading towards Bretby nursery by the national forest have been cut but that the cut strip is not wide enough and has left 7ft

plants on the verge obscuring a deep flooding ditch behind them causing a safety hazard Location: Bretby Lane Bretby Contact:

Enquiry No.: Service: H - Highway Maintenance

Logged by: REPORT IT WEBFORMS on: 25/05/2016 11:13 Subject: HP - Carriageway Pothole/Trip Classification: Highways Maintenance

Desc.: Deep pothole - Received via Contact Centre email: write to report a pothole in the tarmacadam road surface at the base of the concrete speed bump location is outside 34 Bretby Lane DE15 0QW

nearsideRegards

Location: Bretby Lane Bretby outside number 34

Contact:

Contact:

**Plot Number: 1.000.00** Feature Id - Location: QH - Bretby Ln, Bretby

Defect Number: 61002292

Logged by: REPORT IT WEBFORMS on: 25/05/2016 09:45 Enquiry No.:

Service: H - Highway Maintenance Subject: LP - Carriageway Pothole/Trip Classification: Highways Maintenance

Desc.: Shallow pothole

Job Number: 53252685

Location: Bretby Lane Bretby

Feature Id - Location: QH - Bretby Ln, Bretby Plot Number: 1.000.00 Feature Type: Highway Inspection

Job Number: 50012179 Defect Number: 40025074

Logged by: REPORT IT WEBFORMS on: 18/05/2016 14:56 **Enquiry No.:** Service: H - Highway Maintenance Subject: HP - Carriageway Pothole/Trip Classification: Highways Maintenance

Desc.: Deep pothole - Not very wide but it is very deep

Location: 53 53a Bretby Lane Bretby DE15 0QW

Contact:

**Plot Number: 1.000.00** Feature Id - Location: QH - Bretby Ln, Bretby Job Number: 53252603

Defect Number: 61002222

Feature Type: Highway Inspection

Feature Type: Highway Inspection

Logged by: REPORT IT WEBFORMS on: 08/05/2016 19:52 Enquiry No.:

Service: H - Highway Maintenance Subject: Subsidence affecting hway Classification: Highways Maintenance

Desc.: \*\*\* I WOULD REGARD THIS AS POTENTIALLY DANGEROUS \*\*\*Sun 8th May 19:32A hole has opened up in the carriageway outbound from Burton. At present it is about 1 foot by 10 inches but it has exposed a cavity below the tarmac where there is no material and where the surface can be seen to have collapsed in The size of the cavity is unclear but there is clearly surface material

which is unsupported and the hole could grow under weight

Location: Bretby Lane Bretby Contact:

**Enquiry No.:** Logged by: REPORT IT WEBFORMS on: 25/04/2016 11:09

Service: H - Highway Maintenance Subject: Drains/gully blocked Classification: Highways Maintenance

Desc.: Received via contact centre email The drains are blocked in the road outside 131 Bretby lane Bretby DE15 0PQ

Location: Bretby Lane Bretby

Contact:

Site: Bretby Lane (35400128)

Customer Services

Enquiry No.:

Logged by: REPORT IT WEBFORMS

Service: H - Highway Maintenance

Subject: HP - Carriageway Pothole/Trip

Classification: Highways Maintenance

on: 12/04/2016 13:30

Desc.: Deep pothole near to speed bump Large area of deteriorated road around it alsoCars swerving to avoid Location: Bretby Lane Bretby

Contact:

**Plot Number: 1.000.00** Job Number: 53252129 Feature Id - Location: QH - Bretby Ln, Bretby

Feature Type: Highway Inspection

Enquiry No.:

Defect Number: 61001810 Logged by:

on: 19/07/2017 10:26

on: 03/04/2018 12:16

Service: Traffic Regulation Orders

Subject: Request for Enforcement

Classification: Traffic

Desc.: Footway parking

Location: Bretby Lane, Bretby

Contact:

Enquiry No.: Service: Maintenance Miscellaneous

Subject: Other enquiry Classification: Highways Maintenance has had a traffic cone thrown into her garden and would like someone to collect it. She has put it behind her dustbin at the front of the property. Is this something you are able to do?

Location: 4 Bretby Lane, Bretby Logged by:

Logged by:

Contact:

**Enquiry No.:** Service: H - Highway Maintenance

Subject: Cway deterioration

on: 28/02/2018 11:00 Classification: Highways Maintenance

Desc.: Road edge breaking up and forming holes

Location: Tree limes

Contact:

**Plot Number: 1.000.00** Job Number: 50050519 Feature Id - Location: QH - Bretby Ln, Bretby Defect Number: 40068031

Feature Type: Highway Inspection

Enquiry No.:

Service: Development Control

Logged by: Subject: Planning appeal

on: 06/02/2018 09:10 Classification: Development Control

Desc.: e - PAPE

Contact:

Location: Agricultural shed at 2 Newton Mount Cottages, Bretby Lane Enquiry No.:

Logged by:

on: 21/07/2017 15:26

Service: Development Control

Subject: Planning Apps - Referred

Classification: Development Control

Desc.: Due By: 10/08/17. THE ERECTION OF AN AGRICULTURAL SHED.

Location: Newton Mount Cottages 2 Bretby Lane Burton on Trent

Contact: Jn

**Enquiry No.:** Service: H - Highway Maintenance

Subject: Cway deterioration

on: 20/06/2017 15:30 Classification: Highways Maintenance

**Desc.:** Multiple repairs both sides of the road hump

Location: Outside 29 Repton Road, Bretby

Contact:

**Plot Number: 1.000.00** 

Feature Id - Location: QH - Bretby Ln, Bretby

Feature Type: Highway Inspection

Job Number: 50034221

Defect Number: 40049990 Logged by:

Logged by:

on: 08/06/2017 15:29

Enquiry No.: Service: Development Control

Subject: Search and H'way record issues

Classification: Development Control

Desc.: E Highway extent - £40 payment requested

Location: 18, Bretby Lane, Bretby, Burton on Trent, Derbyshire, DE115 0QN

on: 06/04/2017 09:12

Enquiry No.: Service: Development Control Logged by: Subject: Planning Apps - Referred

Classification: Development Control

Desc.; DUE DATE=26/4 ERECTION OF AN EXTENSION TO PROVIDE A MAIN ENTRANCE, ADDITIONAL SALES AREA AND STORE Location: PLANTERS AT BRETBY BRETBY LANE BRETBY BURTON ON TRENT

Contact:

Contact:

Effective: 11/04/2016 to 11/04/2018

**Site:** Bretby Lane (35400128)

**DisplayAction Officer: No** 

Customer Services

Logged by: Enquiry No.: on: 24/01/2017 14:30

Subject: Personal Injury Claims Classification: Insurance Enquiry Ref: 6000/31723 Service: Insurance

Desc.: PI claim - 25/07/16 pothole in carriageway

**Location:** opposite 55a, pothole next to gully grate

on: 27/09/2016 15:41 Enquiry No.: Logged by:

Service: Traffic Regulation Orders Subject: Speed limits Classification: Traffic

Desc.: Bretby Parish Council has for a number of years raised concerns about the speed and volume of traffic along Knights Lane and Bretby Lane and has made several requests for the 30 mph speed limit to be extended. In the last 2 months there have been 2 serious head on accidents along this stretch, each requiring the air ambulance to attend the scene and transport the injured away. Sadly, this is something which the Parish Council has been predicting and it will again make the request for the extension of the 30 mph limit and for white lines to be installed along the centre of the lane, this may just help focus motorists to at least keep to their side of the road. Please can this request of the speed limit and the white lines be considered again.

Contact:

Location: along Knights Lane and Bretby Lane Contact:

on: 27/09/2016 15:08 Logged by: **Enquiry No.:** 

Service: H - Highway Maintenance Subject: Cway deterioration Classification: Highways Maintenance

Desc.: I wish to report the deteriorating condition of the road surface along Bretby Lane, in particular the surface around the speed bumps on the Lane appears to be crumbling. This is a busy lane and suffers from significant traffic flow and it has been noticed that the surface is deteriorating quickly. In addition, there is a large pothole outside 55 Bretby Lane. This is deep and could have the potential to cause damage to any vehicle travelling over it.

Location: Bretby Lane, Bretby Contact:

on: 24/08/2016 17:08 Logged by: **Enquiry No.:** 

Service: Development Control Subject: Planning Apps - Referred Classification: Development Control

Desc.: THE ERECTION OF ONE DWELLING

Location: 219 BRETBY LANE BRETBY BURTON ON TRENT DERBYSHIRE DE15 0OR Contact:

on: 12/08/2016 12:00 **Enquiry No.:** Logged by:

Service: Development Control Subject: Search and H'way record issues Classification: Development Control

Desc.: E - Extent - £40 payment reg

Location: 34 Bretby Lane Bretby Burton on Trent DE15 0QW Contact:

on: 29/07/2016 10:08 Logged by: Enquiry No.:

Service: Development Control Subject: Search and H'way record issues Classification: Development Control

Desc.: E - Ena -

Location: 34 Bretby Lane DE15 0QW Contact:

on: 21/04/2016 07:54 Enquiry No.: Logged by:

Service: H - Highway Maintenance Subject: Drains/gully blocked Classification: Highways Maintenance

Desc.: Request on behalf of Local Member for update in regard to the ongoing drainage issues.

Location: Bretby Lane, Bretby. Contact:

Maintenance Management

Job No.	Descript	ion	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset:	1,000.00	Asset - Locn.: QH - Bretby Ln, Bretby	Featur	re Type: Highway Inspection		Area: South Der	byshire District
111050	5 pothole (	carriageway pothole)	o/s 72	*** 5 days	Job Closed - Data Cleansing	10/07/2015	07/11/2016 Ac	t. RM16/528007
50011036	•	ole & repair as ry void in road	O/S no 27	Planned Maintenance programme	SAP - Technically Complete	11/05/2016	20/05/2016 Ac	t.

Mainten	nance Management						
Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1,000.00 <b>A</b>	sset - Locn.: QH - Bretby Ln, Bretby		Feature Type: Highway Inspection		Area: South Derb	yshire District
50012179	9 LP - Carriageway Pothole/Trip - Shallow pothole by speed pad outside no 34 (Enquiry (carriageway pothole)	Bretby Lane Bretby	*** 5 days	Job completed	26/05/2016	31/08/2016 Act.	RM1617/89003867
50012180	D deep pothole in wheel tracks (carriageway pothole)	by road gully close to 55A	*** 5 days	Job completed	26/05/2016	31/08/2016 Act.	RM1617/89003868
50012208	B potholes against kerbline (carriageway pothole)	opposite no 103	*** 5 days	Job completed	26/05/2016	01/09/2016 Act.	RM1617/89003898
50019853	3 fillet needs reinstating at speed hump (carriageway pothole)	close to no 32	*** 5 days	Job completed	12/10/2016	17/10/2016 Act.	RM1617/89010706
50023977	7 potholes (carriageway pothole)	between 76 and 74	*** 5 days	Job completed	17/01/2017	18/01/2017 Act.	RM1617/89014387
50025287	7 pothole in patch (carriageway pothole)	just past bretby garden centre entrance close to no 252	*** 5 days	Job completed	06/02/2017	07/02/2017 Act.	RM1617/89015716
50030273	3 deep pothole at edge of road (carriageway pothole)	approx 100m east of property no 190	*** 5 days	Job completed	18/04/2017	20/04/2017 Act.	RM1718/89020479
50030275	5 deep pothole (carriageway pothole)	outside 74	** 32 hours	Job completed	18/04/2017	19/04/2017 Act.	RM1718/89020402
50034221	1 Cway deterioration - Multiple repairs both sides of the road hump (Enquiry - Reinstate fillet around speed hump where potholing (carriageway pothole)	Outside 29 Bretby Lane, Bretby	*** 5 days	Job completed	21/06/2017	23/06/2017 Act.	RM1718/89023743
50034790	O potholes edge of road (carriageway pothole)	outside 252	*** 5 days	Job completed	03/07/2017	04/07/2017 Act.	RM1718/89024339
50043506	6 Please clear and take away	at beginning of link path between r Bretby Lane and Geary Lane o/s 222 Bretby Lane	**** 28 days	Job cancelled	20/12/2017	17/01/2018 Est.	
	9 Take up and replace 6 x 5 BN Kerb. (kb-kerb missg/ damagd/ upstand)	o/s 79	*** 5 days	Job completed	02/01/2018	09/01/2018 Act.	RM1718/89033168
50048699	O Cut and sweep out, fill and trim to reinstate 7 cway potholes. (Enquiry and add.) (carriageway pothole)	1 x cw pothole o/s garden centre, 5 cway potholes around speed hump between 76 and 74, 1 x cw pothole o/s 23 around gully.	*** 5 days	Job completed	21/02/2018	29/03/2018 Act.	RM1718/89038721
50050519	O Cut and sweep out, fill and trim to reinstate four cway potholes to make safe. (Enquiry (carriageway pothole)	2 x cway edge potholes opposite No 219, 1 x cway pothole o/side 72 and 1 x cway o/side 76 near to speed hump.	*** 5 days	Job completed	15/03/2018	28/03/2018 Act.	RM1718/89040869
50051711	1 Cut and sweep out, fill and trim to reinstate deep cway edge pothole to make safe (carriageway pothole)	Travelling from Garden Centre Between Pease Hill and No 135 on opposite side cway edge	*** 5 days	Job completed	03/04/2018	18/04/2018 Act.	RM1819/89042397

Mainten	nance Management						
Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1,000.00 <b>A</b>	sset - Locn.: QH - Bretby Ln, Bretby		Feature Type: Highway Inspection		Area: South Derb	yshire District
53250697	7 Subsidence affecting hway - Subsidence (Enquiry (F/way deterioration <= 20 sq m)	Bretby Lane BretbyThe caller has reported that the pavement is sinking again Outside No 33 on Bretby Lane pavement area at the top of the drive - repaired previously 1 to 2 years agon	**** 28 days	Job completed	15/01/2016	13/09/2016 Act.	REMT16/70003149
53251791	1 HP - Carriageway Pothole/Trip - pot holes (Enquiry (carriageway pothole)	located on the left hand side, when travelling in the direction of Repton to Burton and are prior to the first right hand bend, close to the gas substation.	*** 5 days	Job completed	18/03/2016	14/04/2016 Act.	REMT16/70008605
53252129	9 HP - Carriageway Pothole/Trip - Deep pothole near to speed bump Large area of deteriorated road around it alsoCars swerving to avoid (Enquiry (carriageway pothole)	Bretby Lane Bretby	*** 5 days	Job completed	12/04/2016	14/04/2016 Act.	RM1617/89000765
53252603	3 HP - Carriageway Pothole/Trip - Deep pothole - Not very wide but it is very deep (Enquiry (carriageway pothole)	DE15 0QW	*** 5 days	Job completed	19/05/2016	31/08/2016 Act.	RM1617/89003297
53252685	DHP - Carriageway Pothole/Trip - Deep pothole - Received via Contact Centre email:I write to report a pothole in the tarmacadam road surface at the base of the concrete speed bump location is outside 34 Bretby Lane DE15 0QW nearsideRegards (Enquiry (carriageway pothole)	Bretby Lane Bretby outside number 34	*** 5 days	Job completed	25/05/2016	31/08/2016 Act.	RM1617/89003784
53255798	B HP - Footway Pothole/Trip - Damage to kerb (Enquiry (f/way trip hazard)	Bretby Lane Bretby Caller reports very loose kerb stone which is sticking up 2 or 3 quote  27 Bretby Lane	*** 5 days	Job completed	01/03/2017	02/03/2017 Act.	RM1617/89017264
53257945	DHP - Carriageway Pothole/Trip - Deep pothole entrance to Bretby Garden Centre progressivly getting worse over the past months Takes plenty of traffic and may cause a hazard with drivers swerving to avoid it Date Issue raised: 11082017 (Enquiry (carriageway pothole)	Bretby Lane Bretby	*** 5 days	Job completed	11/08/2017	15/08/2017 Act.	RM1718/89026422

DisplayAction Officer: No

Mainter	nance Management						
Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1,000.00 <b>A</b>	Asset - Locn.: QH - Bretby Ln, Bretby		Feature Type: Highway Inspection		Area: South Derb	yshire District
53258138	Subsidence affecting hway - Subsidence and developing pothole causes vibrations through house as heavy traffic passesreported 30-08-17 (Enquing (carriageway pothole)	Bretby Lane Bretby	*** 5 days	Job completed	31/08/2017	31/08/2017 Act.	RM1718/89027224
5326084	3 HP - Carriageway Pothole/Trip - 4 Deep potholes at number 76 Bretby Lane Saturday 8th Feb 2018 (Enquiry (carriageway pothole)	Bretby Lane Bretby	*** 5 days	Job completed	12/02/2018	20/02/2018 Act.	RM1718/89037550
5326127	4 HP - Carriageway Pothole/Trip -	Bretby Lane Bretby	*** 5 days	Job completed	02/03/2018	26/03/2018 Act.	RM1718/89039416

Deep Pothole on the junction of Bretby Lane Mount Road Close to the entrance of Planters Garden Centre (Bretby Nurseries) As you drive along Bretby Lane the pothole is on the left hand side just before you turn in to Planters Garden Centre - I first noticed this on the 12022018 - this has been a reoccurring problem (Enquiry (carriageway pothole)

Report generated by:

Effective: 11/04/2016 to 11/04/2018

	EII	Site: Bretby Lane (3		DisplayAction	Jilicer: N	10			
Mainten	nance M	anagement							
Job No.	Descript	tion	Location	Priority		Job Status	Entered	Completion	Works Order
	Asset:	1,000.00	Asset - Locn.: QH - Bretby Ln, Bretby		Feature	Type: Highway Inspection		Area: South Derby	shire District
53262500	Extremel 715pm to very dee located of bretby nu I was tra could no there was way The and not of There was nearside and the tanger will be tanged to be checan you claim for have sever pot hole that she few weel another pentrance received they had obviously dangerod	riageway Pothole/Triply Deep pothole At oday ( 080418) I hit a p pothole on Bretby la on the bend between urseries and the post by velling towards Winsh t avoid the crater as s traffic coming the othole was full of water obvious until it is too lass a massive bang My front wheel is damage tyre poppedflattened Meel has been used an iking the car to the cand tyre fitter tomorrecked and fixed Please inform me of how to the costs of the repaireral photographs of the and damage to my can has just informed a fer ported the pothole at ks ago along with pothole near to the of Bretby nurseries S an email stating that been repaired This we ynot true It is a very us road fault and could be in the costs of the repaired This we ynot true It is a very us road fault and could be in the costs of the repaired This we ynot true It is a very us road fault and could be in the costs of the repaired This we ynot true It is a very us road fault and could be in the costs of the repaired This we ynot true It is a very us road fault and could be in the costs of the repaired This we ynot true It is a very us road fault and could be in the costs of the repaired This we ynot true It is a very us road fault and could be in the costs of the repaired This we ynot true It is a very us road fault and could be in the costs of the repaired This we ynot true It is a very us road fault and could be in the costs of the costs of the repaired This we ynot true It is a very us road fault and could be in the costs of	nne  pox ill I  her ate ed My dd I  row ee r I  ne r ne a  he as d ne	*** 5 days		Job completed	09/04/2018	18/04/2018 Act.	RM1819/89043139
	Asset:	100,007.00	<b>Asset - Locn.:</b> 007476 - Outside 254 (Bretby)		Feature	Type: Lighting Column 5m		Area: SL: Night So	cout S02
54021578	3 out (2 - L	ighting Fault - Out)		SL - Five day		Job completed	29/11/2016	16/01/2017 Act.	SLR16/74011105
	Asset:	100,010.00	Asset - Locn.: 007473 - Near No 222 (Bretby)		Feature	Type: Lighting Column 5m		Area: SL: Night So	cout S02
54045988	3 out (2 - L	ighting Fault - Out)		SL - Twenty Eig	ght Days	Job completed	23/01/2018	06/03/2018 Act.	SLR17/74032593
	Asset:	100,011.00	Asset - Locn.: 007471 - Outside 188/190 (Bretby)		Feature	Type: Lighting Column 5m		Area: SL: Night So	cout S02
54036468	3 Out (2 - I	Lighting Fault - Out)		SL - Five day		Job completed	13/09/2017	04/10/2017 Act.	SLR17/74024306
	Asset:	100,017.00	Asset - Locn.: 007465 - By No 91 (Bretby)		Feature	Type: Lighting Column 5m		Area: SL: Night So	cout S02
54010646	OUT (2 -	Lighting Fault - Out)		SL - Five day		Job completed	13/05/2016	23/05/2016 Act.	SLR16/74001695
	Asset:	100,018.00	Asset - Locn.: 007464 - Outside Nos 83/85 (Bretby)		Feature	e Type: Lighting Column 5m		Area: SL: Night So	cout S02
54035578	3 dim (2 - I	Lighting Fault - Dim)		SL - Five day		Job completed	31/08/2017	12/09/2017 Act.	SLR17/74023521

DisplayAction Officer: No

Mainter	Maintenance Management											
Job No.	Descrip	tion	Location	Priority	Job Status	Entered	Completion	Works Order				
	Asset:	100,019.00	Asset - Locn.: 007462 - Outside 61/63 (Bretby)	Fe	eature Type: Lighting Column 5m		Area: SL: Night S	cout S02				
5403054	5 Out (2 - I	Lighting Fault - Out)		SL - Five day	Job completed	09/05/2017	09/05/2017 Act.	SLR17/74019329				
54030778	3 out (2 - L	ighting Fault - Out)		SL - Five day	Job completed	16/05/2017	31/05/2017 Act.	SLR17/74019520				
	Asset:	100,020.00	Asset - Locn.: 007463 - Opposite Oldcote Lane (Bretby)	Fe	eature Type: Lighting Column 5m		Area: SL: Night S	cout S02				
54022818 Light No7463 which is made from has a fault Its burning hours shold be: Dusk to Dawn The fault is: - Fault: Light out (2 - Lighting Fault - Out)				SL - Five day	Job completed	14/12/2016	16/01/2017 Act.	SLR16/74012283				
54044668		RICIANS CALL-OUT T N HIT AND LEANING	0	SL Emergency Atte	ended Job Committed	05/01/2018	12/01/2018 Est.	SLR17/74031475				
54044669		RDER TO STRAIGHT CURE 5M STEEL N	EN	SL Planned Works	Job completed	05/01/2018	12/03/2018 Act.	SLEON2/54003474				

Report generated by: 10:09:08