

Effective: 01/02/2017 to 01/03/2018

Display Action Officer: Yes

Street: LONDON ROAD NORTHBOUND (9700023)

Street: LONDON ROAD NORTHBOUND (9700023)			Locality: LANGLEY GREEN, CRAWLEY, WEST SUSSEX			Area: CRAWLEY		
Condition Survey								
Defect No: Description		Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section:	9,999.00	Road No. - Locn.:	C/Way Type: Whole Street Feature			Area: CRAWLEY		
Batch: 688695 - Inspection Batch			Route: A + B Dual Carriageways		Officer:	Ian Brett (HS-Mid Sussex)		Date: 05/02/2018
3096270	Cut square & patch 1.2 x 0.8m by 80mm depth hole in offside lane of two lane westbound carriageway (n.b. Nearside lane is designated bus lane) (1 of 6)	05/02/2018	By lamp column no.808 (75m north of Gatwick South Terminal underpass)	Potholes	Internal		Committed	979473
3096272	Cut square & patch 0.8 x 0.6m by 60mm depth hole in offside lane of two lane westbound carriageway (n.b. Nearside lane is designated bus lane) (1 of 6)	05/02/2018		Potholes	Internal		Committed	979476
3096271	Cut square & patch 0.3 x 0.3m by 40mm depth hole in offside lane of two lane westbound carriageway (n.b. Nearside lane is designated bus lane) (1 of 6)	05/02/2018	By lamp column no.808 (75m north of Gatwick South Terminal underpass)	Potholes	Internal		Committed	979475
3096273	Cut square & patch 0.6 x 0.6m by 60mm depth hole in offside lane of two lane northbound carriageway (n.b. Nearside lane is designated bus lane) (1 of 6)	05/02/2018	By lamp column no.808 (75m north of Gatwick South Terminal underpass)	Potholes	Internal		Committed	979477
3096275	Cut square & patch 0.4 x 0.3m by 40mm depth hole in offside lane of two lane northbound carriageway (n.b. Nearside lane is designated bus lane) (1 of 6)	05/02/2018	Between lamp column no.809 & 810 (120m north of Gatwick South Terminal underpass)	Potholes	Internal		Committed	979479
3096274	Cut square & patch 0.4 x 0.2m by 40mm depth hole in offside lane of two lane northbound carriageway (n.b. Nearside lane is designated bus lane) (1 of 6)	05/02/2018	Between lamp column no.809 & 810 (120m north of Gatwick South Terminal underpass)	Potholes	Internal		Committed	979478
Batch: 687006 - Inspection Batch No actionable defects found			Route: A + B Dual Carriageways		Officer:	Ian Brett (HS-Mid Sussex)		Date: 05/01/2018
Batch: 686004 - Inspection Batch No actionable defects found			Route: W Green/Industr/Ngate Annual		Officer:	Ian Brett (HS-Mid Sussex)		Date: 06/12/2017
Batch: 685844 - Inspection Batch No actionable defects found			Route: A + B Dual Carriageways		Officer:	Ian Brett (HS-Mid Sussex)		Date: 04/12/2017
Batch: 684095 - Inspection Batch No actionable defects found			Route: A + B Dual Carriageways		Officer:	Ian Brett (HS-Mid Sussex)		Date: 06/11/2017
Batch: 683189 - Ad Hoc Inspection Batch			Route: Ad-Hoc Northern2		Officer:	John Cunningham (TE Craw) [BL]		Date: 11/10/2017
3093180	R9 works. REMOVE 1x damaged sign & 2x damaged posts. INSTALL 2x new posts (89mm dia. x 5350mm long). ATTACH 1x new "2 Lanes merge into 1 Lane / 200 yrds" Sign (diag. 872.1v) (2500mm high x 1250mm wide). C/C = 900mm. Mount Height = 2.2m.	11/10/2017	North side verge approx. 60m east of Airport Roundabout. Grid Ref: 528389, 140157.	Signs / Bollards Planned	Internal		Committed	976345

Effective: 01/02/2017 to 01/03/2018

Display Action Officer: Yes

Street: LONDON ROAD NORTHBOUND (9700023)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section:	9,999.00	Road No. - Locn.:		C/Way Type:	Whole Street Feature		Area: CRAWLEY	
Batch: 682496 - Inspection Batch				Route: A + B Dual Carriageways	Officer:	Ian Brett (HS-Mid Sussex)	Date: 02/10/2017	
No actionable defects found								
Batch: 680691 - Inspection Batch				Route: A + B Dual Carriageways	Officer:	Ian Brett (HS-Mid Sussex)	Date: 04/09/2017	
No actionable defects found								
Batch: 679529 - Inspection Batch				Route: A + B Dual Carriageways	Officer:	Ian Brett (HS-Mid Sussex)	Date: 07/08/2017	
No actionable defects found								
Batch: 677873 - Inspection Batch				Route: A + B Dual Carriageways	Officer:	Ian Brett (HS-Mid Sussex)	Date: 03/07/2017	
No actionable defects found								
Batch: 676028 - Inspection Batch				Route: A + B Dual Carriageways	Officer:	Ian Brett (HS-Mid Sussex)	Date: 05/06/2017	
No actionable defects found								
Batch: 674735 - Inspection Batch				Route: A + B Dual Carriageways	Officer:	Ian Brett (HS-Mid Sussex)	Date: 04/05/2017	
3089555	Apply Tack Coat & patch 2.0 x 0.1m holed strip at edge of nearside lane of two lane northbound carriageway	04/05/2017	By start of slip lane onto Airport Way Access Northbound (by lamp column no.392/01)	Potholes	Internal		Committed	972651
Batch: 674169 - Inspection Batch				Route: Ad-Hoc Northern2	Officer:	Eleanor Harries (HS-Crawley)	Date: 19/04/2017	
3089026	Cut out and patch pothole .6 X .4m X 60mm estimated in lane 1 just by hatching	19/04/2017	Adjacent to slip road to garlicky and m23 London Road, Gatwick, RH6 0 between col 392/06 and 392/07	Potholes	Internal		Committed	972116
Batch: 674168 - Inspection Batch				Route: Ad-Hoc Northern2	Officer:	Eleanor Harries (HS-Crawley)	Date: 19/04/2017	
3089025	Reset loose noisy rattling inspection cover and Cut out and patch pothole developing around cover .1m X .1m X 100mm estimated	19/04/2017	At the beginning of the filter lane to gatwick and m23 by base of col 392/03	Potholes	Internal		Committed	972115
Batch: 673284 - Inspection Batch				Route: A + B Dual Carriageways	Officer:	Ian Brett (HS-Mid Sussex)	Date: 03/04/2017	
No actionable defects found								
Batch: 671953 - Inspection Batch				Route: A + B Dual Carriageways	Officer:	Ian Brett (HS-Mid Sussex)	Date: 03/03/2017	
No actionable defects found								
Batch: 670417 - Inspection Batch				Route: A + B Dual Carriageways	Officer:	Ian Brett (HS-Mid Sussex)	Date: 03/02/2017	
No actionable defects found								

Effective: 01/02/2017 to 01/03/2018

Display Action Officer: Yes

Street: LONDON ROAD NORTHBOUND (9700023)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section:	9,999.00	Road No. - Locn.:		C/Way Type:	Whole Street Feature		Area:	CRAWLEY
Batch:	183942 - Ad Hoc Inspection Batch		Route:	Ad-Hoc Western	Officer:	Crawley District	Date:	26/05/2017
10155186	Clear and make safe - Rubbish and spillages - Police are reporting debris and mud on the road following an rtc. They said the car hit the crash barrier and the police said the crash barrier in tact and doesn't require repairs its just the mud and debris on the road. There is no fuel on the road. Police ref 36126/05/17. The carriageway is open #OVRD : Called by police #How large? : Across lane 2 car ended up in lane 1 going north bound #Issue Type : Other #Is it causing an obstruction? : No	26/05/2017	Under the Airport way link road	WS Obst flood,spill,tree,hedge	Internal		Committed	737386
Section:	2,000,001.00	Road No. - Locn.:	2015 - GATWICK SUBWAY I	C/Way Type:	ST:Bridge-Underpass/Subway:Pe		Area:	CRAWLEY
Batch:	20000011 - Subway HS Observations (HS UID 1)		Route:	Structures Data takeon	Officer:	Structures Legacy	Date:	24/08/2017
	No actionable defects found							
Section:	2,000,002.00	Road No. - Locn.:	8011 - AIRPORT BUILDING	C/Way Type:	ST:Bridge		Area:	CRAWLEY
Batch:	20009874 - 31/05/2017 8011 I:Robert McMillan and M		Route:	BCI:General Inspection	Officer:	Structures Legacy	Date:	31/05/2017
	No actionable defects found							
Section:	2,000,003.00	Road No. - Locn.:	8013 - RAPID TRANSIT LINK	C/Way Type:	ST:Bridge		Area:	CRAWLEY
Batch:	20009873 - 31/05/2017 8013 I:Robert McMillan and M		Route:	BCI:General Inspection	Officer:	Structures Legacy	Date:	31/05/2017
	No actionable defects found							
Section:	2,001,001.00	Road No. - Locn.:	8011/1 - AIRPORT BUILDING Span: 1 ()	C/Way Type:	ST:Bridge Span		Area:	CRAWLEY
Batch:	20009874 - 31/05/2017 8011 I:Robert McMillan and M		Route:	BCI:General Inspection	Officer:	Structures Legacy	Date:	31/05/2017
20667112	.1 No Signs Of Rusting Or Damage	31/05/2017		METALWORK-Rust/Pitts/Corrosi	Internal		Action Required	
20667111	.1 Minor Surface Rusting	31/05/2017		METALWORK-Rust/Pitts/Corrosi	Internal		Action Required	
20667109	.1 No Damage	31/05/2017		IMPACT DAMAGE	Internal		Action Required	
20667114	.1 Slight Surface Scoring; Minor Displacement Of Element E.G. Marking And Chipping Of Beam Faces; Several Bricks Across Arch Barrel Width; Slight Impact Deformation Of Steelwork	31/05/2017		IMPACT DAMAGE	Internal		Action Required	
20667107	.1 No Visible Sign Of Seepage	31/05/2017		WATERPROOFING-Seepage	Internal		Action Required	
20667121	.1 No Evidence Of Deformation	31/05/2017		M/BW/MC-Deformation	Internal		Action Required	
20667116	.1 No Visible Settlement Of Structure	31/05/2017		FOUND- Settlement	Internal		Action Required	
Section:	2,001,002.00	Road No. - Locn.:	8011/2 - AIRPORT BUILDING Span: 2 ()	C/Way Type:	ST:Bridge Span		Area:	CRAWLEY
Batch:	20009874 - 31/05/2017 8011 I:Robert McMillan and M		Route:	BCI:General Inspection	Officer:	Structures Legacy	Date:	31/05/2017
20667120	.2 No Spalls	31/05/2017		RC/PC/FJ-Spalling	Internal		Action Required	
20667119	.2 No Spalls	31/05/2017		RC/PC/FJ-Spalling	Internal		Action Required	
20667118	.1 No Visible Settlement Of Structure	31/05/2017		FOUND- Settlement	Internal		Action Required	

Effective: 01/02/2017 to 01/03/2018

Display Action Officer: Yes

Street: LONDON ROAD NORTHBOUND (9700023)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section: 2,001,002.00		Road No. - Locn.: 8011/2 - AIRPORT BUILDING Span: 2 ()		C/Way Type: ST:Bridge Span		Area: CRAWLEY		
Batch: 20009874 - 31/05/2017		8011 I:Robert McMillan and M		Route: BCI:General Inspection		Officer: Structures Legacy	Date: 31/05/2017	
20667117	.1 Slight Surface Scoring; Minor Displacement Of Element E.G. Marking And Chipping Of Beam Faces; Several Bricks Across Arch Barrel Width; Slight Impact Deformation Of Steelwork	31/05/2017		IMPACT DAMAGE	Internal		Action Required	
20667110	.1 Minor Surface Rusting	31/05/2017		METALWORK-Rust/Pitts/Corrosion	Internal		Action Required	
20667108	.1 No Damage	31/05/2017		IMPACT DAMAGE	Internal		Action Required	
20667106	.1 No Visible Sign Of Seepage	31/05/2017		WATERPROOFING-Seepage	Internal		Action Required	
20667115	.2 Minor Localised Spalls Exposing Shear Links	31/05/2017		RC/PC/FJ-Spalling	Internal		Action Required	
20667113	.1 No Signs Of Rusting Or Damage	31/05/2017		METALWORK-Rust/Pitts/Corrosion	Internal		Action Required	
Section: 2,001,003.00		Road No. - Locn.: 8013/1 - RAPID TRANSIT LINK Span: 1 ()		C/Way Type: ST:Bridge Span		Area: CRAWLEY		
Batch: 20009873 - 31/05/2017		8013 I:Robert McMillan and M		Route: BCI:General Inspection		Officer: Structures Legacy	Date: 31/05/2017	
20667123	.2 Causing Minor Staining	31/05/2017		DRAIN-Staining/ Req. Cleaning	Internal		Action Required	
20667133	.2 No Spalls	31/05/2017		RC/PC/FJ-Spalling	Internal		Action Required	
20667131	.1 Minor Surface Rusting	31/05/2017		METALWORK-Rust/Pitts/Corrosion	Internal		Action Required	
20667128	.1 No Visible Settlement Of Structure	31/05/2017		FOUND- Settlement	Internal		Action Required	
20667127	.1 All Coats Failed	31/05/2017		PAINT/COAT-Finishing Coating	Internal		Action Required	
20667124	.1 Little To No Wear And Weathering	31/05/2017		SURF- Wear/Weathering	Internal		Action Required	
Section: 2,001,004.00		Road No. - Locn.: 8013/2 - RAPID TRANSIT LINK Span: 2 ()		C/Way Type: ST:Bridge Span		Area: CRAWLEY		
Batch: 20009873 - 31/05/2017		8013 I:Robert McMillan and M		Route: BCI:General Inspection		Officer: Structures Legacy	Date: 31/05/2017	
20667122	.2 Causing Minor Staining	31/05/2017		DRAIN-Staining/ Req. Cleaning	Internal		Action Required	
20667132	.2 No Spalls	31/05/2017		RC/PC/FJ-Spalling	Internal		Action Required	
20667130	.1 Minor Surface Rusting	31/05/2017		METALWORK-Rust/Pitts/Corrosion	Internal		Action Required	
20667129	.1 No Visible Settlement Of Structure	31/05/2017		FOUND- Settlement	Internal		Action Required	
20667126	.1 All Coats Failed	31/05/2017		PAINT/COAT-Finishing Coating	Internal		Action Required	
20667125	.1 Little To No Wear And Weathering	31/05/2017		SURF- Wear/Weathering	Internal		Action Required	
Section: 2,001,005.00		Road No. - Locn.: 2015/1 - GATWICK SUBWAY I Span: 1()		C/Way Type: ST:Subway Span		Area: CRAWLEY		
Batch: 20006739 - 31/05/2017		2015 I:Robert McMillan and M		Route: BCI:General Inspection		Officer: Structures Legacy	Date: 31/05/2017	
No actionable defects found								
Batch: 20006675 - 28/01/2010		2015 I:DW Butler E:Ian Steel		Route: BCI:Principal Inspection		Officer: Structures Legacy	Date: 31/05/2017	
20611560	.6 Few Bricks/Stones Missing (No Adjacent Ones Missing); Major Surface Weathering	31/05/2017		M/BW/MC-Brck/Stn Loss/S.Wthrr	Internal		Action Required	
20611559	.2 Major Localised Spalls Exposing Shear Links And Main Bars With General Corrosion	31/05/2017		RC/PC/FJ-Spalling	Internal		Action Required	
20611558	.1 No Signs Of Rusting Or Damage	28/01/2010		METALWORK-Rust/Pitts/Corrosion	Internal		Action Required	
20611557	.1 No Evidence Of Deformation	28/01/2010		M/BW/MC-Deformation	Internal		Action Required	
20611556	.1 Minor Wear/Weathering	31/05/2017		SURF- Wear/Weathering	Internal		Action Required	
20611555	.1 No Evidence Of Deformation	31/05/2017		M/BW/MC-Deformation	Internal		Action Required	

Effective: 01/02/2017 to 01/03/2018

Display Action Officer: Yes

Street: LONDON ROAD NORTHBOUND (9700023)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Section: 2,001,005.00		Road No. - Locn.: 2015/1 - GATWICK SUBWAY I Span: 1()		C/Way Type: ST:Subway Span		Area: CRAWLEY		
Batch: 20006675 - 28/01/2010		2015 I:DW Butler E:Ian Steel		Route: BCI:Principal Inspection		Officer: Structures Legacy		Date: 31/05/2017
20611561	.1 No Evidence Of Deformation	28/01/2010		M/BW/MC-Deformation	Internal		Action Required	
20611554	.1 No Evidence Of Deformation	31/05/2017		M/BW/MC-Deformation	Internal		Action Required	
20611578	.5 Minor Signs Of Wear	31/05/2017		EXPJ-Elstmc&Oth Missing Bolts	Internal		Action Required	
20611576	.1 No Visible Settlement Of Structure	28/01/2010		FOUND- Settlement	Internal		Action Required	
20611575	.5 Minor Signs Of Wear	28/01/2010		EXPJ-Elstmc&Oth Missing Bolts	Internal		Action Required	
20611574	.2 Minor Section Loss (Penetration Less Than 5% Of Section)	31/05/2017		METALWORK- Section Loss	Internal		Action Required	
20611572	.1 No Signs Of Rusting Or Damage	28/01/2010		METALWORK-Rust/Pitts/Corrosi	Internal		Action Required	
20611571	.1 No Visible Settlement Of Structure	31/05/2017		FOUND- Settlement	Internal		Action Required	
20611570	.1 Little To No Wear And Weathering	31/05/2017		SURF- Wear/Weathering	Internal		Action Required	
20611569	.1 Little To No Wear And Weathering	28/01/2010		SURF- Wear/Weathering	Internal		Action Required	
20611568	.1 Finishing Coat Sound; Slight Weathering	28/01/2010		PAINT/COAT-Finishing Coating	Internal		Action Required	
20611567	.1 Moderate Seepage Through Deck/Arch Etc. (Some Resistance To Seepage)	28/01/2010		WATERPROOFING-Seepage	Internal		Action Required	
20611573	.1 Sound. No Deformation	31/05/2017		EMBANKMENT- Slip/Settlement	Internal		Action Required	
20611566	.5 Moderate Cracks (Easily Visible; Crazeing) And Deep Localised Spalls	28/01/2010		M/BW/MC-Cracks/Spalling	Internal		Action Required	
20611565	.1 Little To No Wear And Weathering	28/01/2010		SURF- Wear/Weathering	Internal		Action Required	
20611564	.1 Minor Seepage Through Deck/Arch Etc. (Slow Dripping)	31/05/2017		WATERPROOFING-Seepage	Internal		Action Required	
20611577	.2 No Spalls	28/01/2010		RC/PC/FJ-Spalling	Internal		Action Required	
20611563	.1 All Coats Failed	31/05/2017		PAINT/COAT-Finishing Coating	Internal		Action Required	
20611562	.2 Major Localised Spalls Exposing Shear Links And Main Bars With General Corrosion	31/05/2017		RC/PC/FJ-Spalling	Internal		Action Required	

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Section: .50		Road No. - Locn.: A23/47006		C/Way Type: Dual 2-Lane or one-way 2-Lane		Area: CRAWLEY		
345021	make safe - X2 damaged & x2 missing legs in center reservation - TE already aware (Safety barriers of fences)	approaching terminal building underpass	Nigel Dewey	zz - Do not use old Cat 2-1	Job is part of wider scheme	13/06/2007	13/07/2007	Est.
346323	Carriageway resurfacing inc Safepave	Northbound. Gatwick Road to City Place	David Hoad (Str Mnt) [KD]	zzScheme Delivery	Passed to Contractor	28/06/2007	27/06/2008	Est.
Section: 2.50		Road No. - Locn.: A23/51090		C/Way Type: Single 2-Lane Carriageway		Area: CRAWLEY		
407880			Norman Perryman (Routine ZZZGNI		Z Works Incomplete	15/08/2002	11/02/2003	Est.
409429	do not inspect		Ron Witkowski (Routine M: ZZZGNI		Z No code allocated	16/09/2002	12/03/2003	Est.
410910	no comments		Steve Bicknell (HE-Crwy) [ZZZGNI		Z No code allocated	14/10/2002	10/04/2003	Est.
415149			Norman Perryman (Routine ZZZGNI		Z No code allocated	11/12/2002	09/06/2003	Est.
416080	should not be inspected		Ron Witkowski (Routine M: ZZZGNI		Z No code allocated	16/01/2003	16/07/2003	Est.

Effective: 01/02/2017 to 01/03/2018

Display Action Officer: Yes

Street: LONDON ROAD NORTHBOUND (9700023)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Section:	2.50	Road No. - Locn.: A23/51090			C/Way Type: Single 2-Lane Carriageway		Area: CRAWLEY	
417345 not inspected			Norman Perryman (Routine	ZZZGNI	Z No code allocated	17/02/2003	15/08/2003	Est.
419667			Norman Perryman (Routine	ZZZGNI	Z No code allocated	20/03/2003	15/09/2003	Est.
421628 not inspected			Ron Witkowski (Routine M	ZZZGNI	Z No code allocated	14/04/2003	14/10/2003	Est.
423987			Bob McKinnon	ZZZGNI	Z No code allocated	13/05/2003	07/11/2003	Est.
425823 not cmdr			Ron Witkowski (Routine M	ZZZGNI	Z No code allocated	12/06/2003	05/12/2003	Est.
430003 no comments		0	Steve Bicknell (HE-Crwly)	ZZZGNI	Z No code allocated	19/08/2003	16/02/2004	Est.
433144		0	Norman Perryman (Routine	ZZZGNI	Z No code allocated	15/10/2003	12/04/2004	Est.
434850 No new intervention defects		0	Paul Reynolds	ZZZGNI	Z No code allocated	12/11/2003	11/05/2004	Est.
436104 pothole fillwith dbm (No new intervention defects)		0	Paul Reynolds	ZZZGNI	Z No code allocated	11/12/2003	14/06/2004	Est.
Section:	1,111.00	Road No. - Locn.: *2015 - GATWICK SUBWAY I			C/Way Type: Subways		Area: CRAWLEY	
6007789 Visit site to clear flooding (IMPACT DAMAGE)		2015 Gatwick Subway	Mike Theobald (Structures)	2 Hours - BB	Passed To Contractor To Start	25/01/2016	25/01/2016	Est.
Section:	9,999.00	Road No. - Locn.:			C/Way Type: Whole Street Feature		Area: CRAWLEY	
64095 REFER TO O/N 64082 FOR PROGRESS OF SCHEME. A23 Route Management Scheme		Grid Ref : Easting: 525805 , Northing: 135689 to Easting: 527498 , Northing: 142453	Asset Management Team	2 Weeks Contractor Assessment	Job is part of wider scheme	28/06/2012	12/07/2012	Est.
65238 DUMMY ORDER - REFER TO O/N 64082 A23 Route Management Scheme		Grid Ref : Easting: 525805 , Northing: 135689 to Easting: 527498 , Northing: 142453	Asset Management Team	2 Weeks Contractor Assessment	Asset Mgmt Team only	12/10/2012	26/10/2012	Est.
65807 New Safety Barrier Installation & carriageway improvements		Gatwick Terminal Building	Asset Management Team	Planned Works - Forward Prog.	Asset Mgmt Team only	12/12/2012	11/12/2019	Est.
69751 Programme Year TBC Carriageway Resurfacing (Planned Carriageway Works)		Airport Roundabout to Airport Way Access Northbound EN:528319, 140143 TO 528110, 141936	Asset Management Team	Planned Works - Forward Prog.	Asset Mgmt Team only	28/10/2013		
COORDINATE: JN 69751 London Road NB (NSG: 9700023) JN 69741 London Road NB (NSG: 9700024)								
326865 clear/treat all self seeded shrubs/bushes/weeds including ragwort (Obstructions - Internal)		airport terminal to longbridge r/a	Nigel Dewey	zz - Do not use old Cat 2-1	Job is part of wider scheme	01/08/2006	31/08/2006	Est.
337214 resurface footway (FW Potholes)		airport r/a	Nigel Dewey	zz - Do not use old Cat 3	Job is part of wider scheme	26/02/2007	25/02/2009	Est.
337215 side up both sides of one footway (Obstructions - Internal)		airport r/a	Steve Bicknell (HE-Crwly)	zz- Do not use old Cat 2-6	Job is part of wider scheme	26/02/2007	23/08/2007	Est.
337216 side up one side of one footway (Obstructions - Internal)		groundsbar house to brookfield	Steve Bicknell (HE-Crwly)	zz- Do not use old Cat 2-6	Job is part of wider scheme	26/02/2007	23/08/2007	Est.
337217 slurry seal (FW Potholes)		groundsbar house to brookfield	Nigel Dewey	zz - Do not use old Cat 3	Job is part of wider scheme	26/02/2007	25/02/2009	Est.
337219 hot patch required hra 8mx1.5mx0.100 (CW - Potholes)		nr entry to lowfield heath r/a	John Bowyer [JB]	zz - Do not use old Cat 3	Job is part of wider scheme	26/02/2007	18/07/2009	Est.

Effective: 01/02/2017 to 01/03/2018

Display Action Officer: Yes

Street: LONDON ROAD NORTHBOUND (9700023)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Section:	9,999.00	Road No. - Locn.:	C/Way Type: Whole Street Feature			Area: CRAWLEY		
337220	hot patch required hra 4mx1mx0.100 (CW - Heave/Rutting)	nr river mole bridge	James Avery (NAO)	zz- Do not use old Cat 2-6	Job is part of wider scheme	26/02/2007	23/08/2007	Est.
337221	hot patch required hra 3mx1.5mx0.100 (CW - Potholes)	exit from airport r/a	James Avery (NAO)	zz- Do not use old Cat 2-6	Job is part of wider scheme	26/02/2007	23/08/2007	Est.
347680	replace upright (Safety barriers of fences)	opp lamp col 718	Nigel Dewey	zz - Do not use old Cat 3	Job is part of wider scheme	18/07/2007	18/07/2009	Est.
347681	replace 3x upright (Safety barriers of fences)	opp lamp coll 803	Nigel Dewey	zz - Do not use old Cat 3	Job is part of wider scheme	18/07/2007	18/07/2009	Est.
351459	damaged stanchions on centre reserve (Safety barriers of fences)	by Terminal Building	Nigel Dewey	zz - Do not use old Cat 2-1	Job is part of wider scheme	13/09/2007	13/10/2007	Est.
354827	2 broken uprights /barrier (Safety barriers of fences)	lamp col 803	Nigel Dewey	zz - Do not use old Cat 3	Job is part of wider scheme	14/11/2007	13/11/2009	Est.
354828	2 broken uprights (Safety barriers of fences)	lamp col no718	Nigel Dewey	zz - Do not use old Cat 3	Job is part of wider scheme	14/11/2007	13/11/2009	Est.
357224	remove sapling trees (3rd Party defect)	fRom lowfoeld heath rnd to gatwick rd rnd	John Bowyer [JB]	zz - Do not use old Cat 3	Job is part of wider scheme	17/01/2008	16/01/2010	Est.
357225	advisory sign damage (Signs/bollards)	lamp col 718	Nigel Dewey	zz - Do not use old Cat 3	Job is part of wider scheme	17/01/2008	16/01/2010	Est.
360042	restructure tarmac f/way 75m (FW Potholes)	old brighton rd to bus stop	John Bowyer [JB]	zz - Do not use old Cat 3	Job is part of wider scheme	06/03/2008	06/03/2010	Est.
393250	2xsigns [1 of large direction sign 1 information sign about turning around roundabout] (WS Obst flood,spill,tree,hedge)	just before longbridge roundabout [surrey border] 527509,142424	Charlie West (Routine Mair z Fix required within 3 months)		Job is part of wider scheme	08/10/2010	05/01/2011	Est.
403387			Ron Witkowski (Routine M: ZZZGNI		Z Works Incomplete	16/05/2002	12/11/2002	Est.
405483			Ron Witkowski (Routine M: ZZZGNI		Z Works Incomplete	18/06/2002	12/12/2002	Est.
406846	kill weeds in central reservation ADV aware and will program works	north of gatwick road r'about	Steve Bicknell (HE-Crwly) [ZZZZP3		Z Works Incomplete	17/07/2002	13/01/2003	Est.
407936			Norman Perryman (Routine ZZZGNI		Z Works Incomplete	15/08/2002	11/02/2003	Est.
409368			Ron Witkowski (Routine M: ZZZGNI		Z No code allocated	16/09/2002	12/03/2003	Est.
410952	no comments		Steve Bicknell (HE-Crwly) [ZZZGNI		Z No code allocated	14/10/2002	10/04/2003	Est.
415206			Norman Perryman (Routine ZZZGNI		Z No code allocated	11/12/2002	09/06/2003	Est.
415599	pole 21 green light out reported to microsense mike	ped xing at fleming way roundabout	Norman Perryman (Routine ZZZZE1		Z Works Incomplete	30/12/2002	31/12/2002	Est.
415603	clear gullies & or pipes	north of bus layby north of lowfield heath roundabout	Norman Perryman (Routine ZZZZN2		Z Works Incomplete	30/12/2002	23/05/2003	Est.
416007			Ron Witkowski (Routine M: ZZZGNI		Z No code allocated	15/01/2003	16/07/2003	Est.
417417			Norman Perryman (Routine ZZZGNI		Z No code allocated	17/02/2003	18/08/2003	Est.
419730			Norman Perryman (Routine ZZZGNI		Z No code allocated	20/03/2003	15/09/2003	Est.
421574			Ron Witkowski (Routine M: ZZZGNI		Z No code allocated	14/04/2003	14/10/2003	Est.
423970			Bob McKinnon ZZZGNI		Z No code allocated	13/05/2003	07/11/2003	Est.
425770	head missing - passed to s/l 24/6/03	L/col 590	Ron Witkowski (Routine M: ZZZZN2		Z Works Scheduled	12/06/2003	30/10/2003	Est.

Effective: 01/02/2017 to 01/03/2018

Display Action Officer: Yes

Street: LONDON ROAD NORTHBOUND (9700023)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Section:	9,999.00	Road No. - Locn.:	C/Way Type: Whole Street Feature			Area: CRAWLEY		
428685		0	Norman Perryman (Routine	ZZZGNI	Z No code allocated	21/07/2003	16/01/2004	Est.
430037	no comments	0	Steve Bicknell (HE-Crwly) [ZZZGNI	Z No code allocated	19/08/2003	16/02/2004	Est.
431634		0	Bob McKinnon	ZZZGNI	Z No code allocated	19/09/2003	09/03/2004	Est.
433230		0	Norman Perryman (Routine	ZZZGNI	Z No code allocated	15/10/2003	12/04/2004	Est.
434780	No new intervention defects	0	Paul Reynolds	ZZZGNI	Z No code allocated	12/11/2003	11/05/2004	Est.
436019	No new intervention defects	0	Paul Reynolds	ZZZGNI	Z No code allocated	11/12/2003	14/06/2004	Est.
737386	Clear and make safe - Rubbish and spillages - Police are reporting debris and mud on the road following an rtc. They said the car hit the crash barrier and the police said the crash barrier in tact and doesn't require repairs its just the mud and debris on the road. There is no fuel on the road. Police ref 36126/05/17. The carriageway is open #OVRD : Called by police #How large? : Across lane 2 car ended up in lane 1 going north bound #Issue Type : Other #Is it causing an obstruction? : No [REDACTED] WS Obst flood,spill,tree,hedge)	Under the Airport way link road	Crawley District	2 Hours - BB	Works Closed	26/05/2017	26/05/2017	Act. BB01/322104
900481	police request road closure	north of beehive rb	John Bowyer [JB]	zzEmergency Response Required	Passed to Contractor	30/06/2011	30/06/2011	Est.
925065	replace lid on side-entry gulley in verge alongside nearside northbound carriageway (Planned Carriageway for WCO)	immediately east of Airport Roundabout	Ian Brett (HS-Mid Sussex)	z Fix required within 3 months	Z: Job Raised	05/04/2013	03/07/2013	Est.
961511	cut square & patch 1.0 x 0.6m holed area in offside lane of dual lane northbound carriageway (Potholes)	Northbound approx 100m north of Gatwick South Terminal Underpass (between lamp column nos.809 & 810)	Ian Brett (HS-Mid Sussex)	28 Days - BB	Job Raised	06/04/2016	04/05/2016	Est.
967929	Ironwork - replace broken side-entry gulley frame in verge at edge of near side lane of dual lane northbound carriageway on approach to Traffic Signals by Gatwick Service Road [REDACTED]	Approx 150m North of Gatwick South Terminal Underpass	Steve Bicknell (HE-Crwly) [28 Days - BB	Works Closed	21/11/2016	02/02/2017	Act. BB05/10834
972115	Reset loose noisy rattling inspection cover and Cut out and patch pothole developing around cover .1m X .1m X 100mm estimated (Potholes)	At the beginning of the filter lane to gatwick and m23 by base of col 392/03	Eleanor Harries (HS-Crawley)	5 Days - BB	Job Cancelled - No action req.	19/04/2017	24/04/2017	Est. BB01/927375

Effective: 01/02/2017 to 01/03/2018

Display Action Officer: Yes

Street: LONDON ROAD NORTHBOUND (9700023)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Section:	9,999.00	Road No. - Locn.:	C/Way Type: Whole Street Feature			Area: CRAWLEY		
972116	Cut out and patch pothole .6 X .4m X 60mm estimated in lane 1 just by hatching (Potholes)	Adjacent to slip road to garlicky and m23 London Road, Gatwick, RH6 0 between col 392/06 and 392/07	Eleanor Harries (HS-Crawk	28 Days - BB	Works Closed	19/04/2017	04/05/2017	Act. BB01/927376
972160	Reset loose noisy rattling inspection cover and Cut out and patch pothole developing around cover .1m X .1m X 100mm estimated (Potholes)	At the beginning of the filter lane to gatwick and m23 by base of col 392/03	Eleanor Harries (HS-Crawk	5 Days - BB	Job Cancelled - No action req.	20/04/2017	25/04/2017	Est.
972651	Apply Tack Coat & patch 2.0 x 0.1m holed strip at edge of nearside lane of two lane northbound carriageway (Potholes)	By start of slip lane onto Airport Way Access Northbound (by lamp column no.392/01)	Ian Brett (HS-Mid Sussex)	28 Days - BB	Works Closed	04/05/2017	12/06/2017	Act. BB01/927810
976345	COSTS PLEASE R9 works. REMOVE 1x damaged sign & 2x damaged posts. INSTALL 2x new posts (89mm dia. x 5350mm long). ATTACH 1x new "2 Lanes merge into 1 Lane / 200 yds" Sign (diag. 872.1v) (2500mm high x 1250mm wide) to serve eastbound traffic. C/C = 900mm. Mount Height = 2.2m. (Signs / Bollards Planned)	North side verge approx. 60m east of Airport Roundabout. Grid Ref: 528389, 140157	John Cunningham (TE Cra	28 Days - BB	Works Closed	11/10/2017	29/01/2018	Act. BB05/11476
979473	Cut square & patch 1.2 x 0.8m by 80mm depth hole in offside lane of two lane westbound carriageway (n.b. Nearside lane is designated bus lane) (1 of 6) (Potholes)	By lamp column no.808 (75m north of Gatwick South Terminal underpass)	Ian Brett (HS-Mid Sussex)	28 Days - BB	Scheduled	05/02/2018	01/03/2018	Est. BB01/933755
979475	Cut square & patch 0.3 x 0.3m by 40mm depth hole in offside lane of two lane westbound carriageway (n.b. Nearside lane is designated bus lane) (1 of 6) (Potholes)	By lamp column no.808 (75m north of Gatwick South Terminal underpass)	Ian Brett (HS-Mid Sussex)	28 Days - BB	Scheduled	05/02/2018	01/03/2018	Est. BB01/933756
979476	Cut square & patch 0.8 x 0.6m by 60mm depth hole in offside lane of two lane westbound carriageway (n.b. Nearside lane is designated bus lane) (1 of 6) (Potholes)		Ian Brett (HS-Mid Sussex)	28 Days - BB	Scheduled	05/02/2018	01/03/2018	Est. BB01/933757

Effective: 01/02/2017 to 01/03/2018

Display Action Officer: Yes

Street: LONDON ROAD NORTHBOUND (9700023)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Section:	9,999.00	Road No. - Locn.:	C/Way Type: Whole Street Feature			Area: CRAWLEY		
979477	Cut square & patch 0.6 x 0.6m by 60mm depth hole in offside lane of two lane northbound carriageway (n.b. Nearside lane is designated bus lane) (1 of 6) (Potholes)	By lamp column no.808 (75m north of Gatwick South Terminal underpass)	Ian Brett (HS-Mid Sussex)	28 Days - BB	Scheduled	05/02/2018	01/03/2018	Est. BB01/933758
979478	Cut square & patch 0.4 x 0.2m by 40mm depth hole in offside lane of two lane northbound carriageway (n.b. Nearside lane is designated bus lane) (1 of 6) (Potholes)	Between lamp column no.809 & 810 (120m north of Gatwick South Terminal underpass)	Ian Brett (HS-Mid Sussex)	28 Days - BB	Scheduled	05/02/2018	01/03/2018	Est. BB01/933759
979479	Cut square & patch 0.4 x 0.3m by 40mm depth hole in offside lane of two lane northbound carriageway (n.b. Nearside lane is designated bus lane) (1 of 6) (Potholes)	Between lamp column no.809 & 810 (120m north of Gatwick South Terminal underpass)	Ian Brett (HS-Mid Sussex)	28 Days - BB	Scheduled	05/02/2018	01/03/2018	Est. BB01/933760
6009010	Programme Year TBC Footway Works TBC (Planned Footway Works)	subway entrance to just north of terminal building EN 528605, 141409 to 528536, 141549	Asset Management Team	Planned Works - Forward Prog.	Asset Mgmt Team only	26/01/2017		
60401525	REFURBISH all whitelining as highlighted on attached plan. Approx. 52m of Centre Line (diag.1004.1), 70m of Centre Line (diag.1005.1), 12m Stop Line (diag.1001), 40m Edge Cway (diag.1010)), 3no. Move Left Arrow (diag.1014), 4no. Arrows (diag.1038v), 260m Hatching (diag.1040), 190m Chevron Hatching (diag.1042), 56no. BUS LANE Markings (diag.1048), and 1110m of Bus Lane continuous lining (diag.1049), 1400m of solid edge line (diag.1012.1), & 105m BUS STOP marking (diag.1025.4). Lining / Studs Planned)	Between Beehive Ring Road and Perimeter Road North. Grid Ref: 528549, 140256 & 528489, 141599.	John Cunningham (TE Cra	28 Days - BB	PM Certified Final Account	17/01/2017	16/06/2017	Act. BB04/10242
Section:	2,000,001.00	Road No. - Locn.:	C/Way Type: ST:Bridge-Underpass/Subway:Pe			Area: CRAWLEY		
4000109	HAC testing and remediation	2015 Gatwick Subway I	Richard Hammond [KD]	6 Weeks Contractor Assessment	Job Raised	25/10/2017	06/12/2017	Est.

Effective: 01/02/2017 to 01/03/2018

Display Action Officer: Yes

Street: LONDON ROAD NORTHBOUND (9700023)

Street Works Notices

Organisation: Balfour Beatty | West Sussex Highways (3800010)

Works Ref: 976345

Notice Type: Works Stop

Work Status: Works Stopped

Work Type: EToN 4: Minor

Version: 4

Start: 29/01/2018 00:00:00

Issued: 29/01/2018 13:48:21

Est. End: 29/01/2018

Work Desc: R9 works. REMOVE 1x damaged sign & 2x damaged posts. INSTALL 2x new posts (89mm dia. x 5350mm long). ATTACH 1x new "2 Lanes merge into 1 Lane / 200 yds" Sign (diag. 872.1v) (2500mm high x 1250mm wide) to serve eastbound traffic. C/C = 900mm. Mount Height = 2.2m. (Signs / Bollards Planned)

Completion: 29/01/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	North side verge approx. 60m east of Airport Roundabout. Grid Ref: 528389, 140157	Carriageway	No Excavation	0.00	0.00	Site Closed	29/01/2018			29/01/2018