

Reference	Type	Received Date	Address	Nature of Complaint
	REPORT	<input type="checkbox"/> Mar-20	<input type="checkbox"/> County Place Perth PH2 8EE <input type="checkbox"/> Perth Street	Decorative masonry balustrade at front of building is partially dislodged.
	REPORT	<input type="checkbox"/> Mar-20	<input type="checkbox"/> Blairgowrie PH10 6DQ <input type="checkbox"/>	Falling Masonry Cladding
	REPORT	<input type="checkbox"/> Feb-20	<input type="checkbox"/> Union Street Coupar Angus Union Lane	Morta falling from the chimney breasts onto the public footpath and slates coming down the roof, not only from the front of the building but also at the side
	REPORT	<input type="checkbox"/> Feb-20	<input type="checkbox"/> Perth	Site visit and noted some small pieces of masonry on the pavement but no sign of loose masonry on the gale wall above so assume it must have been due to frost heave. No frost today at time of visit and windy which would have taken the frost out of the sandstone quickly.
	REPORT	<input type="checkbox"/> Jan-20	<input type="checkbox"/> Mill Wynd Perth PH1 5PE	Sand stone above the opening has been delaminating over a long period of time but no sign of any immediate stone ready to fall.
	REPORT	<input type="checkbox"/> Nov-19	<input type="checkbox"/> St John's Place Perth PH1 5SZ	Dislodged masonry to the gable / chimney at the rear.
	REPORT	<input type="checkbox"/> Nov-19	<input type="checkbox"/> Nelson Street PerthPH2 8LR	masonry spalling off the facade of flats at <input type="checkbox"/> Nelson Street, Perth PH2 8LR. Some masonry has already fallen from the building but there appears to be a large section ready to fall and it is located 2 or 3m above the <input type="checkbox"/> entrance door.
	REPORT	<input type="checkbox"/> Oct-19	<input type="checkbox"/> Crieff Road Perth	External wall <input type="checkbox"/> Wallace Place <input type="checkbox"/> <input type="checkbox"/> is clearly in a state of disrepair and requires attention to secure public safety. It is also apparent that sections of the timber post and board fencing have become detached and are hanging loose, a section of coping stone has become dislodged from the wall and the guttering <input type="checkbox"/> <input type="checkbox"/> has either become blocked or is no longer fit for purpose. As a result surface water has been seen to be regularly dripping onto the face of the wall, which may have contributed to the condition referred to previously.

REPORT



Oct-19 Perth
PH2 8NL

[Redacted address]

Tay Street

two areas of decorative stonework on eaves cornice which appeared damaged located on the East elevation of the building [Redacted]

REPORT



Oct-19 [Redacted] High StreetPerthPH1 5TH

Several pieces of masonry have fallen from property above

REPORT



Oct-19 Perth
PH1 5LA

[Redacted address]

George Street

Chimney in disrepair

REPORT



Aug-19 Perth
PH1 5PA

[Redacted address] High Street

Fallen masonry

REPORT



May-19 Perth
PH1 5JL

[Redacted address] George Street

Small piece of masonry has fallen from one of the buildings [Redacted]

REPORT



Apr-19 [Redacted] High
StreetPerthPH1 5PB

[Redacted address]

Police Service had contacted Duty Office to state that slates and metal objects had fallen from the building onto the adjacent pavement.

REPORT



Mar-19 [Redacted] cott Street And [Redacted] South
Street
Perth

[Redacted address]

Masonry falling from facade

REPORT



Feb-19 Perth

[Redacted address]

Mill Street

Red brick lying in car park. When you look up, there is a large section of masonry (maybe mortar) hanging.

REPORT



Feb-19 Perth
PH2 8LW

[Redacted address] Victoria Street

During the storm some masonry fell from the adjoining building damaging the roof [Redacted] concerned that the roof remains dangerous and needs urgent action.

REPORT



Feb-19 Perth
PH2 7HB

[Redacted address] Main Street

Falling cement render [Redacted] to the rear of the property.

	REPORT	<div></div> Feb-19 <div></div> High Street Perth	Report that they had attended a call out on Saturday (6th) following a report of some masonry falling. They say the loose masonry was removed.
	REPORT	<div></div> Sep-18 <div></div> <div></div> Balgowan Road Perth	Section of Wall Collapsed
	REPORT	<div></div> Sep-18 <div></div> Princes Street Perth PH2 8LJ	Falling Slates
	REPORT	<div></div> Sep-18 <div></div> <div></div> South Street Perth PH2 8NY	Loose Window on First Floor Level
	REPORT	<div></div> Sep-18 <div></div> Nelson Street <div></div> South William StreetPerth	Render fallen from gable end
	REPORT	<div></div> Sep-18 <div></div> Glenlochay Road Perth PH2 0AX	Unauthorised works
	REPORT	<div></div> Aug-18 <div></div> St Catherine's Road Perth PH1 5SA	Falling and Overhanging masonry from a chimney
	REPORT	<div></div> Aug-18 <div></div> <div></div> Market Street/New Row Perth	Concerns expressed regarding the condition of a wall <div></div> <div></div> accessed via Market Street. Perth, PH1 5QF.
	REPORT	<div></div> Aug-18 <div></div> High Street Perth PH1 5TH	Concerns expressed regarding a loose cope and bird spikes hanging over Kirk Close, <div></div>

REPORT

[redacted] ul-18

[redacted] Rose Terrace
Perth
PH1 5HA

[redacted] coping stone
overhanging the front entrance [redacted]

REPORT

[redacted] May-18

[redacted] nchaffray Street
Perth

A large piece of masonry has fallen off the building into the garden

REPORT

[redacted] Mar-18

[redacted] Tay Street
Perth
PH2 8NN

Haunching fallen from building

REPORT

[redacted] Jan-18

[redacted]
[redacted] George Street
Perth
PH1 5JR

Large piece of masonry reported to have fallen from the building.

REPORT

[redacted] Nov-17

[redacted]
Main Street
Kinrosswood
Kinross
KY13 9HN
[redacted] High Street And [redacted] King Edward

Fallen masonry

REPORT

[redacted] Aug-17

Street
Perth
PH1 5TH

Report received that a piece of masonry has fallen form the façade on to the pedestrianised area. No report that anyone was hurt.

REPORT

[redacted] Aug-17

[redacted]
[redacted] South Street
Perth
PH2 8PG

Complainant advised that slates had become dislodged from the roof above [redacted] and landed on the pavement.

REPORT

[redacted] Jun-17

[redacted]
Auchterarder Road
Dunning
Perth
PH2 0RJ

There is a loose coping stone [redacted] which is at risk of falling in to neighbours garden..

REPORT

[redacted] Jun-17

[redacted] George Street
Perth
PH1 5JL

Report of falling masonry from the external wall

REPORT

☐ May-17 ☐ St John Street
Perth
PH1 5SP
☐

Fallen masonry from tenement

REPORT

☐ Mar-17 Marshall Place
Perth
PH2 8NS
☐

Piece masonry fell from building.

REPORT

☐ Jan-17 ☐ High Street
Crieff
☐

Loose stone (spalling) noted by complainant on the pavement

REPORT

☐ Jan-17 ☐ Burnside
Scone
Perth
PH2 6LP
☐

Masonry has fallen and left a large hole

REPORT

☐ Dec-16 ☐ East High Street
Crieff

Loose render on footpath, possible loose stonework to the corner at higher level

REPORT

☐ Sep-16 Margaret Street
Stanley
☐

Stone wall bordering gardens is collapsing causing large stones to fall onto the pavement and road

REPORT

☐ Aug-16 Strathearn Terrace
Crieff
☐

Large area of bossed render and signs of smaller areas falling

REPORT

☐ Jul-16 ☐ St John Street
Perth
PH1 5SN
☐

Falling brickwork from building

REPORT

☐ Jun-16 ☐ Barossa Street
Perth
PH1 5NR
☐

Falling render from gable end of neighbouring building ☐

REPORT

☐ Apr-16 ☐ Coventry Place And Mill
Street
Kinross
☐

Falling render

REPORT

☐ Apr-16 ☐ South Street
Perth
PH2 8PA

Small piece of stone has fallen onto the pavement

[illegible]