PFI WORKS SURVEY R1 or R2 Inspection 1	
Date/time 18/08/2009 Address Name of occupant Telephone	
QUESTIONS TO OCCUPANTS for a score out of 10 Is the contractor: 1 keeping your home clean and tidy 2 keeping appointments 3 progressing the work properly 4 not caused any leaks, floodings or water penetration 5 looking after you generally in terms of customer care and communication	8.00 8.00 7.00 10.00 5.00
COMMENTS from the occupants	
Partners broke tile behind the cooker and did not fit a cooker chain.	
INSPECTING OFFICERS OBSERVATIONS - for a score out of 10 quality of works in progress quality of finished works health and safety	8 8 8
GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments Lofts are done	THE PERSON NAMED IN THE PE
	The state of the s

PFI WORKS SURVEY R1 or R2 Inspe	ction 1
Date / time 28/08/2009	i
Address	
Name of occupant	
Telephone	
QUESTIONS TO OCCUPANTS for a score out of 10	
Is the contractor:	
1 keeping your home clean and tidy	· 10.00
2 keeping appointments	5.00
3 progressing the work properly	5.00
4 not caused any leaks, floodings or water penetration	10.00
5 looking after you generally in terms of customer care and communicatio COMMENTS from the occupants	n 2.00
Work took too long	
Found operatives asleep on the sofa at 11.30am	
Bread missing from the kitchen	
No boiler instructions	
•	
INSPECTING OFFICERS OBSERVATIONS - for a score out of 10	
quality of works in progress	0
quality of works in progress quality of finished works	8
health and safety	8 8
nearly and salety	0
Lofts done GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comm	vente
GENERAL OBSERVATIONS BY THE INST ESTING STRICER COM	ients

PFI WORKS SURVEY R1 or R2 Inspection	1
Date / time 25/08/2009	
Address	
Name of occupant	
Telephone	
QUESTIONS TO OCCUPANTS for a score out of 10	
Is the contractor:	
1 keeping your home clean and tidy	2.00
2 keeping appointments	10.00
3 progressing the work properly 4 not caused any leaks, floodings or water penetration	7.00
5 looking after you generally in terms of customer care and communication	6.00 4.00
COMMENTS from the occupants	***
two operatives found asleep in the bedroom	
Other operatives were okay	
Fire alarms go off randamly and seem to set off the other alarms in the stree	t
INSPECTING OFFICERS OBSERVATIONS - for a score out of 10 quality of works in progress quality of finished works	7 6
health and safety	8
GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments	
Loft not done	

PFI WORKS SURVEY R1 or R2 Inspection 1 Date / time 24/08/2009 Address Name of occupant Telephone	
QUESTIONS TO OCCUPANTS for a score out of 10 Is the contractor: 1 keeping your home clean and tidy 2 keeping appointments 3 progressing the work properly 4 not caused any leaks, floodings or water penetration 5 looking after you generally in terms of customer care and communication	2.00 0.00 1.00 7.00 1.00
COMMENTS from the occupants Always hard to get hold of anyone. Messed up carpet	
Has mice infestation now Did not adhere to programme	
INSPECTING OFFICERS OBSERVATIONS - for a score out of 10 quality of works in progress quality of finished works health and safety	8 8 8
GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments Lofts done	

\$

PFI WORKS SURVEY R1 or R2 Inspec	ction 2
Date / time 28/08/2009	
Address	
Name of occupant	
Telephone	
QUESTIONS TO OCCUPANTS for a score out of 10	
Is the contractor:	
1 keeping your home clean and tidy	6.00
2 keeping appointments	6.00
3 progressing the work properly	5.00
4 not caused any leaks, floodings or water penetration	5.00
5 looking after you generally in terms of customer care and communication	5.00
COMMENTS from the occupants	
Residents complaining that they had painted the property two years prior to but Partners insisted on doing again. Scaffolding up a long time.	refurb
INSPECTING OFFICERS OBSERVATIONS - for a score out of 10	
quality of works in progress	8
quality of finished works	6
health and safety	8
GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments	
Lofts not done	

PFI WORKS SURVEY R1 or R2	Inspection 2
Date / time 18/08/2009	•
Address	
Name of occupant	
Telephone	
QUESTIONS TO OCCUPANTS for a score out of 10	
Is the contractor:	
1 keeping your home clean and tidy	5.00
2 keeping appointments	5.00
3 progressing the work properly4 not caused any leaks, floodings or water penetration	4.00 6.00
5 looking after you generally in terms of customer care and commi	
COMMENTS from the occupants	flot
Electicians brought their own microwave to cook food in the tenants Roof leak	nat
Hoorican	
•	
INSPECTING OFFICERS OBSERVATIONS - for a score out of 10	1
quality of works in progress	6
quality of finished works	6
health and safety	7
GENERAL OBSERVATIONS BY THE INSPECTING OFFICER con	<u>ıments</u>
Lofts not done	
Asbestos flues left	
Hole in cupboard ceiling	
	•

PFI WORKS SURVEY R1 or R2 In	spection 2
Date / time 25/08/2009	•
Address	
Name of occupant	
Telephone	
QUESTIONS TO OCCUPANTS for a score out of 10	
Is the contractor:	2
1 keeping your home clean and tidy	2.00
2 keeping appointments	2.00
3 progressing the work properly	0.00
4 not caused any leaks, floodings or water penetration	0.00
5 looking after you generally in terms of customer care and communic	ation
COMMENTS from the occupants	
Operatives sleeping on the stairs	
Braclet gone missing reported to the police	
Wardrobe broken - operatives used it to stand on for loft access	
Kit flooring ripped in two places	
Fire alarms go off randomly	
INSPECTING OFFICERS OBSERVATIONS - for a score out of 10	
quality of works in progress	8
quality of finished works	8
health and safety	8
GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comme	ente
The man between the comment of the c	51113
Lofts done	
	N.

PFI WORKS SURVEY	R1 or R2	Inspection	on 2
Date / time 28/08/2009	9	·	
Address			
Name of occupant			
Telephone			
QUESTIONS TO OCCUPANTS 1	or a score out of 10		
Is the contractor:			
1 keeping your home clear	n and tidy		10.00
2 keeping appointments			8.00
3 progressing the work pro	. •		9.00
4 not caused any leaks, flo			8.00
5 looking after you generally	in terms of customer care	e and communication	10.00
COMMENTS from the occupant	's		
oo manaa aa	<u> </u>		
•			
MODEOTINO OFFICERS OFFI			
INSPECTING OFFICERS OBSEI		re out of 10	
quality of works in progre	SS		8
quality of finished works			6
health and safety			8
GENERAL OBSERVATIONS BY	THE INSPECTING OF	FICER comments	
Loft not done		ė.	

PFI WORKS SURVEY R1 or R2	Inspection 3
Date / time 28/08/2009	·
Address	
Name of occupant	
Telephone	
QUESTIONS TO OCCUPANTS for a score out of 10	
Is the contractor:	
1 keeping your home clean and tidy	9.00
2 keeping appointments	10.00
3 progressing the work properly	9.00
4 not caused any leaks, floodings or water penetration	
5 looking after you generally in terms of customer care a	nd communication 10.00
COMMENTS from the occupants	
-	
INSPECTING OFFICERS OBSERVATIONS - for a sco	ero out of 10
quality of works in progress	
quality of finished works	8 8
health and safety	8
	Ç
GENERAL OBSERVATIONS BY THE INSPECTING OF	FFICER comments
Lofts done	
Lorts done	

PFI WORKS SURVEY	R1 or R2		Inspection 3	
Date / time 27/08/20	009		-	
Address				
Name of occupant				
Telephone				
QUESTIONS TO OCCUPAN	TS for a score ou	t of 10		
Is the contractor:				
1 keeping your home clea	n and tidy			7.00
2 keeping appointments				7.00
3 progressing the work pr	operly			6.00
4 not caused any leaks, fl		enetration		10.00
5 looking after you generally				6.00
Tenant complaining tha	t the radiator has t	peen moved in the	small bedroom)
INSPECTING OFFICERS OF	SERVATIONS - fe	or a score out of	10	
quality of works in progr				7
quality of finished works				5
health and safety				7
GENERAL OBSERVATIONS	BY THE INSPEC	TING OFFICER co	omments	
Loft not done				
Lott not done				
	•			

.

PFI WORKS SURVEY R1 or R2 R2 Ins	spection 3
Date / time 27/08/2009	
Address	
Name of occupant	
Telephone	
QUESTIONS TO OCCUPANTS for a score out of 10	
Is the contractor:	
1 keeping your home clean and tidy	6.00
2 keeping appointments	9.00
3 progressing the work properly	6.00
4 not caused any leaks, floodings or water penetration	0.00
5 looking after you generally in terms of customer care and communicati	ion 10.00
INSPECTING OFFICERS OBSERVATIONS - for a score out of 10	
quality of works in progress	7
quality of finished works	6
health and safety	8
, and the second	_
CENERAL ORSERVATIONS BY THE INSPECTING OFFICER	
GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comm	<u>ients</u>
Loft not done	

R1 or R2

Inspection 3

Date / time

28/08/2009

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	8.00
2 keeping appointments	10.00
3 progressing the work properly	5.00
4 not caused any leaks, floodings or water penetration	5.00
5 looking after you generally in terms of customer care and communication	4.00

COMMENTS from the occupants

Hot water off for three weeks when pregnant and has very young children

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	8
quality of finished works	8
health and safety	8

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

Loft done



R1 or R2

Inspection 1

Date/time

04/12/2009

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	8.00
2 keeping appointments	7.00
3 progressing the work properly	8.00
4 not caused any leaks, floodings or water penetration	4.00
5 looking after you generally in terms of customer care and communication	7.00

COMMENTS from the occupants

water pen from flat roof after completion of works David Heath and David Shadbolt were very good.

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	8
quality of finished works	7
health and safety	8

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

Resident complaining that some of the coping stones were renewed but others left - Cement pointing / jointing appears missing.

Holes at eaves of new roof has allowed squirrel infestation Loft is partially done

R1 or R2

Inspection 1

Date / time

03/12/2009

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	7.00
2 keeping appointments	10.00
3 progressing the work properly	5.00
4 not caused any leaks, floodings or water penetration	10.00
5 looking after you generally in terms of customer care and communication	1.00

COMMENTS from the occupants

leaseholder, made following comments

Not notified about the works - claims no section 20 sent.

Gave permission for the wood in the loft to be moved so insulation could be laid but did not happen.

Told Partners she did not require an intercom system but was fitted anyway.

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	5
quality of finished works	5
health and safety	8

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

Loft not done. The whole loft was signed off as a snagging item - Not acceptable John Venning emailed separately about this.

R1 or R2

Inspection 1

Date / time

27/10/2009

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	2.00
2 keeping appointments	9.00
3 progressing the work properly	7.00
4 not caused any leaks, floodings or water penetration	3.00
5 looking after you generally in terms of customer care and communication	5.00

COMMENTS from the occupants

Electricians and gas fitters good but plumber not so good.

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	8
quality of finished works	8
health and safety	8

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

No steps to check the loft

R1 or R2

Inspection 1

Date / time

15/12/2009

Address

Name of occupant

Telephone

7561 1723

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	8.00
2 keeping appointments	0.00
3 progressing the work properly	0.00
4 not caused any leaks, floodings or water penetration	10.00
5 looking after you generally in terms of customer care and communication	0.00

COMMENTS from the occupants

Antique plates stolen and other things. £50 compensation awarded for this.

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	8
quality of finished works	6
health and safety	7

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

Loft is partially done

R1 or R2

Inspection 2

Date / time

08/12/2009

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	8.00
2 keeping appointments	10.00
3 progressing the work properly	9.00
4 not caused any leaks, floodings or water penetration	10.00
5 looking after you generally in terms of customer care and communication	10.00

COMMENTS from the occupants

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	8
quality of finished works	7
health and safety	8

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

Half landing sash window - 6mm play - staff bead needs adjusting. Resident requested appointment by letter.

Loft is insulated but not hatch

R1 or R2

Inspection 2

Date / time

27/10/2009

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	1.00
2 keeping appointments	5.00
3 progressing the work properly	1.00
4 not caused any leaks, floodings or water penetration	7.00
5 looking after you generally in terms of customer care and communication	1.00

COMMENTS from the occupants

Resident claims to have made formal complaint to Partners about carpets and floorbrds not put back.

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	8
quality of finished works	8
health and safety	8

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

Lofts all done

R1 or R2

Inspection 2

Date / time

07/12/2009

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

ceeping your home clean and tidy ceeping appointments	3.00 4.00
4 not caused any leaks, floodings or water penetration	10.00
5 looking after you generally in terms of customer care and communication	1.00

COMMENTS from the occupants

Partners lost residents keys

Without hot water for three days because no instructions given how to operate boiler and hotwater cylinder.

The UH RLO and Partners emergency said it wasn't their problem to resolve.

Kit wall cupboard - shelf peg missing

Cooker and makeshift table left behind by Partners

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	8	
quality of finished works	6	
health and safety	8	

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

fix back internal flue collar and pipe boxing below boiler lots of paint on the bathroom light - needs to be cleaned or changed Made good hair line cracks in bedroom and hall walls? Insulate loft hatch Loft done

R1 or R2

Inspection 2

Date / time

21/12/2009

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	0.00
2 keeping appointments	5.00
3 progressing the work properly	4.00
4 not caused any leaks, floodings or water penetration	5.00
5 looking after you generally in terms of customer care and communication	3.00

COMMENTS from the occupants

Felt no respect from UH

Radiator fell off wall 1st fl frt bed in Feb 2009 - seven different people looked at but nothing Radiator in 1st floor rear bedroom too small 1000x400mm (very large bedroom) UH promised to change small radiator in bedroom but never did

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	8	
quality of finished works	5	
health and safety	7	

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

Main front loft is done Loft in rear addition not done pipes and MST not insulated

R1 or R2

Inspection 3

Date / time

04/11/2009

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	6.00
2 keeping appointments	6.00
3 progressing the work properly	5.00
4 not caused any leaks, floodings or water penetration	5.00
5 looking after you generally in terms of customer care and communication	6.00

COMMENTS from the occupants

boiler kept breaking down - okay now

possible damp to LR

Loose cupboard back in base unit - behind gas meter

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	8
quality of finished works	7
health and safety	8

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

Hole in ceiling to communal front hall 100x100mm

Loft done apart from hatch

R1 or R2

Inspection 3

Date / time

27/10/2009

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	9.00
2 keeping appointments	8.00
3 progressing the work properly	9.00
4 not caused any leaks, floodings or water penetration	10.00
5 looking after you generally in terms of customer care and communication	10.00

battery bell removed and mains bell fitted but has never worked

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	8
quality of finished works	8
health and safety	8

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

No steps to check the loft

R1 or R2 R2

Inspection 3

Date / time

08/12/2009

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	9.00
2 keeping appointments	9.00
3 progressing the work properly	9.00
4 not caused any leaks, floodings or water penetration	9.00
5 looking after you generally in terms of customer care and communication	7.00

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	8
quality of finished works	7
health and safety	8

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

Loft done but not hatch
Truncking to bathroom fan very untidy
fix back cables at low level if disturbed by building works
Washing machine and fridge should be levelled after reinstallation (OAP)
Cable for entry phone left in a taped up coil

R1 or R2 R2

Inspection 3

Date / time

21/12/2009

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	4.00
2 keeping appointments	2.00
3 progressing the work properly	6.00
4 not caused any leaks, floodings or water penetration	2.00
5 looking after you generally in terms of customer care and communication	6.00

COMMENTS from the occupants

Used toilet without permission and did not flush.

Four separate leaks

J don∈No communication

Used kitchen knives to open paint cans

Poor management

Operatives stole cans of beer from kitchen

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	·	9
quality of finished works		7
health and safety		8

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

Electrical spur not fixed back after damp works

Date/time

24/12/09 10am

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	8.00
2 keeping appointments	8.00
3 progressing the work properly	9.00
4 not caused any leaks, floodings or water penetration	6.00
5 looking after you generally in terms of customer care and commi	10.00

COMMENTS from the occupants

Silicone failing in bathroom

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	7
quality of finished works	6
health and safety	7

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

Loft not done (resident says she told partners the lumber could be removed) Sealant on bath failing check bathroom for roof leak

R1 or R2

Date / time

26/01/2010

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	1.00
2 keeping appointments	8.00
3 progressing the work properly	6.00
4 not caused any leaks, floodings or water penetration	0.00
5 looking after you generally in terms of customer care and commi	5.00

COMMENTS from the occupants

Flats B and C doors kicked in - police said the person had keys to communal front door.

FED locks loose - possibly fitted by Rydon

Leak from upstairs heating refurb caused extensive damage to flat a - whole room destroyed and residents decanted to hotel for 2 weeks.

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	7
quality of finished works	8
health and safety	8

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

sound insulation worse since refurbishment - from neighbours above needs invest damage to kit ceiling when fixing hardboard to floor in communal passage communal light switch faulty

R1 or R2

Date / time

22/01/2010

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	9.00
2 keeping appointments	9.00
3 progressing the work properly	7.00
4 not caused any leaks, floodings or water penetration	7.00
5 looking after you generally in terms of customer care and commi	6.00

COMMENTS from the occupants

Nice operatives

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	8
quality of finished works	8
health and safety	8

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

Loft done

R1 or R2

Date / time

15/02/2010

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	6.00
2 keeping appointments	8.00
3 progressing the work properly	5.00
4 not caused any leaks, floodings or water penetration	10.00
5 looking after you generally in terms of customer care and commi	6.00

COMMENTS from the occupants

Took a long time

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	8
quality of finished works	6
health and safety	7

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

Loft wasn't done as deemed available - loft finally done 4/2/10

Inspection 2

Date / time

09/02/2010

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	10.00
2 keeping appointments	10.00
3 progressing the work properly	10.00
4 not caused any leaks, floodings or water penetration	10.00
5 looking after you generally in terms of customer care and commi	10.00

COMMENTS from the occupants

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	7
quality of finished works	7
health and safety	8

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

Shadbolts on site fitting loft insulation - 9/2/10 witnerssed by Mchurch.

Damage to communal wall under lightswitch - reported to Rydons and Mchurch hachased Tom Deszo.

R1 or R2

Inspection 2

Date / time

26/01/2010

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	8.00
2 keeping appointments	8.00
3 progressing the work properly	7.00
4 not caused any leaks, floodings or water penetration	10.00
5 looking after you generally in terms of customer care and commi	7.00

COMMENTS from the occupants

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	7
quality of finished works	7
health and safety	8

<u>GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments</u> tigation

R1 or R2

Inspection 2

Date / time

12/01/2010

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	6.00
2 keeping appointments	9.00
3 progressing the work properly	6.00
4 not caused any leaks, floodings or water penetration	0.00
5 looking after you generally in terms of customer care and commi	2.00

COMMENTS from the occupants

Lots of problems with boiler
Toilet leaks - ie separate wc next to bathroom
Wall plastered but not decorated ie 1m2
WC in bathroom leaking
Lots of hairline cracks filled in but not decorated
Emersion cable not secured

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	7
quality of finished works	6
health and safety	6

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

loft area/access/ to eaves in attic room not insulated - MST not insulated. Lots of problems with boiler
Toilet leaks - ie separate wc next to bathroom
Wall plastered but not decorated ie 1m2
WC in bathroom leaking
Lots of hairline cracks filled in but not decorated

Emersion cable not secured

R1 or R2

Inspection 2

Date / time

19/01/2010

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	1.00
2 keeping appointments	4.00
3 progressing the work properly	1.00
4 not caused any leaks, floodings or water penetration	1.00
5 looking after you generally in terms of customer care and commi	0.00

COMMENTS from the occupants

Poor finished to bathroom

Roof has continued to leak pre and post refurbishment - now damaging new ward Alleges leg of lamb stolen from freezer

Electrical shower fitted but broke down after 3 months and has paid £67 to repair

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress quality of finished works health and safety

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

Damp reading to ceiling below roof leak is 100% Hot water to bath is very slow

Loft is done

R1 or R2

Date / time

26/02/2010

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	5.00
2 keeping appointments	7.00
3 progressing the work properly	2.00
4 not caused any leaks, floodings or water penetration	0.00
5 looking after you generally in terms of customer care and commu	1.00

COMMENTS from the occupants

would like redundant bell push removed

Roof has been leaking 2 years prior to refurbishment and is still leaking

Roof left exposed for 3 weeks during refurbishment and caused damage to whole UH repaired now.

Poor finish to new path

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	7
quality of finished works	7
health and safety	8

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

Very poor finish to new cast in situ front path Roof leaking for years and still not resolved Remove redundant bell push as

R1 or R2

Date / time

22/01/2010

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	5.00
2 keeping appointments	2.00
3 progressing the work properly	1.00
4 not caused any leaks, floodings or water penetration	4.00
5 looking after you generally in terms of customer care and commu	1.00

comments from residents

Roof leak

Workers don't speak English

Low energy light bulbs removed and replaced with tungsten bulbs

Smoking outside

scaffolding up too long

Pointing to brickwork unnecesary

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	7	
quality of finished works	6	
health and safety	7	

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

Roof leak - tested with Protimeter 100% and staining Loft not insulated communal light switch sticks

R1 or R2 R2

Date / time

15/01/2010

Address

Name of occupant

Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	9.00
2 keeping appointments	10.00
3 progressing the work properly	8.00
4 not caused any leaks, floodings or water penetration	10.00
5 looking after you generally in terms of customer care and commu	10.00

Operatives were polite

Radiators not working properly (resident called UH out twice but still not working)

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	8
quality of finished works	7
health and safety	7

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments

Cracking to kitchen firebreast and hall

Radiators not working in hall, dining room, 1st floor front room, 2nd floor front room

No loft here.

R1 or R2 R2

Date / time Address Name of occupant Telephone

QUESTIONS TO OCCUPANTS for a score out of 10

Is the contractor:

1 keeping your home clean and tidy	1.00
2 keeping appointments	10.00
3 progressing the work properly	6.00
4 not caused any leaks, floodings or water penetration	5.00
5 looking after you generally in terms of customer care and commu	2.00

COMMENTS from the occupants

Sarah RLO was very good

Resident said that she gave UH a list of her concerns and issues but not resolved. UH removed good quality brass fasteners and replaced with zinc fasteners

INSPECTING OFFICERS OBSERVATIONS - for a score out of 10

quality of works in progress	8
quality of finished works	8
health and safety	8

GENERAL OBSERVATIONS BY THE INSPECTING OFFICER comments