

**Fault History**

Serial Number:	LN90AA
NSN:	2320998939741

Criteria:	
Repair Level:	ALL
Work Object Status:	Closed
Mission Impact:	ALL
Fault State:	ALL
Escalate Work:	ALL
Work Request ID:	
Assigned Work Status:	ALL
Working Organisation:	
Repair Section:	

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Estimated Repair Time
000000-00B1F161		SNvE 377 - SWIVEL HOUSING	Closed	Non-Taskworthy	No	Level 1	000000-0000697A	29 Mar 2019	N/A	Inspection	TUL HS GS SOFT TOP	001:00
000000-00B068B8		AUTO - RENEW COOLANT SENSOR TOP OF ENGINE	Closed	Fully Fit	No	Level 2		22 Jan 2019	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00B068AB		AUTO - RENEW ALTERNATOR BELT	Closed	Fully Fit	No	Level 2		22 Jan 2019	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A8256C		AUTO - MOD 46 WHEEL NUT POINTERS NOT EMBODIED AS PER MI 2320-D-128-811	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A825AD		AUTO - QTY 4 TYRE SIDEWALLS STARTING TO PERISH	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A82548		AUTO -NYLOC NUTS ON STEERING BALL JOINTS REQUIRE TORQUE CHECK	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A41343		Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Limited Role	No	Level 2	000000-00004519	28 Jul 2017	N/A	Closed No Action	TUL HS GS SOFT TOP	001:00
000000-00962071		Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Non-Taskworthy	No	Level 2	000000-00003209	20 Jan 2016	N/A	Inspection	TUL HS GS SOFT TOP	000:00
000000-00A825B9		AUTO - DRIVERS WIPER BLADE SPLIT	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15

000000-00A825B5		AUTO - FUEL RETURN HOSE BETWEEN NO 3 AND NO 4 INJECTORS LEAKING	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A825B0		AUTO - HAZARD LAMPS INOPERATIVE	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A825AB		AUTO - OOPS 5 YEARLY TASKS DUE MAY 2018	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A825A9		AUTO - QTY 5 TYRE VALVE DUST CAPS MISSING	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A825A6		AUTO - LH DOOR IS A POOR FIT AND NUT SEALING AT TOP	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A825A3		AUTO - OVERFLOW TUBE MISSING FROM POWER STEERING RESERVOIR	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A825A2		AUTO - OOPS 2 YEARLY ENGINE OIL/FILTER DUE	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A8258A		AUTO - OOPS 2 YEARLY AIR CLEANER DUE	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A82578		AUTO - 2 YEARLY SERVICE REQUIRED	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A82576		AUTO - 1 YEARLY SERVICE REQUIRED	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A82574		AUTO - TABLE 7 6 MONTHLY REQUIRED	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A82569		AUTO - MOD 41 NEGATIVE ISOLATOR SWITCH NOT EMBODIED AS PER MI 2320-D-128-811	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A8255F		AUTO - REAR CANOPY SHEET LH LOWER BUNGEE FASTENER MISSING	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A82559		AUTO - DIFF LOCK SAFETY/WARNING DECAL MISSING FROM DASH	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A8254A		AUTO - CLUTCH PEDAL STIFF AND STICKING	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-00A82543		AUTO - INTERMITTENT TAPPET NOISE FROM ENGINE	Closed	Fully Fit	No	Level 2		20 Dec 2017	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-0084C1CA		MODS HXP13-001	Closed	Fully Fit	No	Level 2		04 Aug 2014	N/A	Refurbishment	TUL HS GS SOFT TOP	000:15
000000-0084C1C6		COOLING SYSTEMS HXP13-001	Closed	Fully Fit	No	Level 2		04 Aug 2014	N/A	Refurbishment	TUL HS GS SOFT TOP	000:00
000000-0084C1C4		TRANSMISSION REPAIRS HXP13-001	Closed	Fully Fit	No	Level 2		04 Aug 2014	N/A	Refurbishment	TUL HS GS SOFT TOP	000:00
000000-0084C1BB		BRAKE REPAIRS HXP13-001	Closed	Fully Fit	No	Level 2		04 Aug 2014	N/A	Refurbishment	TUL HS GS SOFT TOP	000:00
000000-0084C1B0		BODY REPAIRS HXP13-001	Closed	Fully Fit	No	Level 2		04 Aug 2014	N/A	Refurbishment	TUL HS GS SOFT TOP	000:00
000000-0084C1A7		STEERING/SUSPENSION REPAIRS HXP13-001	Closed	Fully Fit	No	Level 2		04 Aug 2014	N/A	Refurbishment	TUL HS GS SOFT TOP	000:00

000000-0084C199		ELECTRICAL REPAIRS HXP13-001	Closed	Fully Fit	No	Level 2		04 Aug 2014	N/A	Refurbishment	TUL HS GS SOFT TOP	000:00
000000-0084C187		CAB INTERIOR REPAIRS HXP13-001	Closed	Fully Fit	No	Level 2		04 Aug 2014	N/A	Refurbishment	TUL HS GS SOFT TOP	000:00
000000-007C23DA		CES NOT PRESENTED FOR INSPECTION	Closed	Fully Fit	No	Level 1		19 Oct 2013	N/A	Closed No Action	TUL HS GS SOFT TOP	
000000-007B9D31		RENEW PADDING @ WEAPON RACK.	Closed	Fully Fit	No	Level 1		25 Sep 2013	N/A	Inspection	TUL HS GS SOFT TOP	000:30
000000-007B9D2F		RENEW SPARE WHEEL SLING.	Closed	Fully Fit	No	Level 1		25 Sep 2013	N/A	Closed No Action	TUL HS GS SOFT TOP	
000000-007B9D2D		COMD SEAT FAILS TO ADJUST.	Closed	Fully Fit	No	Level 2		25 Sep 2013	N/A	Closed No Action	TUL HS GS SOFT TOP	
000000-007B9D29		CAP MISSING @ ALTERNATOR EXHAUST.	Closed	Fully Fit	No	Level 1		25 Sep 2013	N/A	Inspection	TUL HS GS SOFT TOP	001:00
000000-007B9D28		RENEW HANDBRAKE GAITOR.	Closed	Fully Fit	No	Level 1		25 Sep 2013	N/A	Closed No Action	TUL HS GS SOFT TOP	
000000-007B9D27		RECERTIFY BY 25/10/13 OR REINSPECT.	Closed	Non-Taskworthy	No	Level 2		25 Sep 2013	N/A	Closed No Action	TUL HS GS SOFT TOP	
000000-007B9D13		INVESTIGATE ENGINE FAULT @ No4 CYLINDER CAM FOLLOWER.	Closed	Non-Taskworthy	No	Level 2		25 Sep 2013	N/A	Closed No Action	TUL HS GS SOFT TOP	000:15
000000-007B9D12		DVR SEATBELT U/S.	Closed	Non-Taskworthy	No	Level 2		25 Sep 2013	N/A	Closed No Action	TUL HS GS SOFT TOP	
000000-007B9D0E		No1 BALLJOINT GAITOR SPLIT.	Closed	Non-Taskworthy	No	Level 2		25 Sep 2013	N/A	Closed No Action	TUL HS GS SOFT TOP	
000000-007B2CD1		replace bonnet stay grommet	Closed	Fully Fit	No	Level 2		30 Aug 2013	N/A	Closed No Action	TUL HS GS SOFT TOP	
000000-007B2B6D		windscreen washer pump inoperable	Closed	Non-Taskworthy	No	Level 2		29 Aug 2013	N/A	Inspection	TUL HS GS SOFT TOP	002:00
000000-007B2B6B		nearside tracta joint seal seeping	Closed	Non-Taskworthy	No	Level 2		30 Aug 2013	N/A	Closed No Action	TUL HS GS SOFT TOP	
000000-007B0E79		Refit mod30 seat belt protection	Closed	Fully Fit	No	Level 1		30 Aug 2013	N/A	Closed No Action	TUL HS GS SOFT TOP	
000000-00843A26		Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58	09 Oct 2014	Degraded	Inspection	TUL HS GS SOFT TOP	000:30
000000-007B897E	000000-002EBBDE	REPAIR TO TH EXIT STANDARDS, IAW BRITFOR SOI 207	Closed	Non-Taskworthy	No	Level 2		24 Sep 2013	N/A	Inspection	TUL HS GS SOFT TOP	000:30
000000-007AF69A		REPLACE ENGINE	Closed	Non-Taskworthy	No	Level 3		13 Aug 2013	N/A	Closed No Action	TUL HS GS SOFT TOP	

000000-007B9D2A	000000-002EBBDE	AIR FILTER BOX INSECURE.	Closed	Fully Fit	No	Level 1		25 Sep 2013	N/A	Inspection	TUL HS GS SOFT TOP	000:30
000000-007B2B68		Replace drivers seat back	Closed	Limited Role	No	Level 2		30 Aug 2013	N/A	Inspection	TUL HS GS SOFT TOP	001:15
000000-007B2CBA		replace steering upper UJ and breakable linkage	Closed	Non-Taskworthy	Yes	Level 2		30 Aug 2013	N/A	Inspection	TUL HS GS SOFT TOP	002:00
000000-007B0E6D		Replace front l/h tyre	Closed	Fully Fit	No	Level 2		30 Aug 2013	N/A	Inspection	TUL HS GS SOFT TOP	001:00
000000-007AF69B		REPLACE VEHICLE TILT	Closed	Limited Role	Yes	Level 2		13 Aug 2013	N/A	Inspection	TUL HS GS SOFT TOP	001:30
000000-006B04D4		Insp Steering Drop Arm Tab Washer	Closed	Fully Fit	No	Level 2	000000-00000310	22 Jun 2011	N/A	Inspection	TUL HS GS SOFT TOP	000:15
000000-0079B0AB		Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00000835	25 Jun 2013	N/A	Inspection	TUL HS GS SOFT TOP	000:30
000000-0079808B		GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Fully Fit	No	Level 1	000000-0000081A	24 Jun 2013	N/A	Failure	TUL HS GS SOFT TOP	000:15
000000-004044F9		Initial Maintenance	Closed	Fully Fit	No	Level 1		29 Mar 2009			TUL HS GS SOFT TOP	
000000-004044F2		Initial Usage	Closed	Fully Fit	No	Level 1		29 Mar 2009			TUL HS GS SOFT TOP	