Location of tree		Species	Reason for removal	Height (m)	Spread (m)	Dbh (cm)	Age	Location of replacement trees(s)	Species of replacement tree(s)	Planned date of removal	CAVAT Valuation
sd 105	Warde Avenue, Balby	Acer pseudoplatanus	Decayed / diseased	Not recorded	Not recorded	Not recorded	70	Same location	Acer pseudoplatanus	Notset	None
o/s 5	Warde Avenue, Balby	Acer pseudoplatanus	Decayed / diseased	Not recorded	Not recorded	Not recorded	70	Same location	Acer pseudoplatanus	Not set	None
Cent res opp former blood stock	Carr House Road, Belle Vue	Ulmus x Regal	Weak fork structures	12	7	40	40	Same location	Ulmus x Lobel	Not set	None
Cent res opp former blood stock	Carr House Road, Belle Vue	Ulmus x Regal	Weak fork structures	12	8	40	40	Same location	Ulmus x Lobel	Not set	None
Cent res opp former blood stock	Carr House Road, Belle Vue	Ulmus x Regal	Weak fork structures	11	7	35	40	Same location	Ulmus x Lobel	Not set	None
Cent res opp former blood stock	Carr House Road, Belle Vue	Ulmus x Regal	Weak fork structures	13	7	45	40	Same location	Ulmus x Lobel	Not set	None
Fr/0 26	26 Amersall Crescent, Scawthorpe	Crataegus monogyna	Decayed / diseased	10	7	40	73	Same location	Not yet decided	Notset	None
Fr/0 108	108 Stonehill Rise, Scawthorpe	Acer saccharinum	Decayed / diseased	11	12	45	53	Same location	Not yet decided	Not set	None
Fr/O 5	5 Rose Crescent, Scawthorpe	Crataegus monogyna	Decayed / diseased	7	7	30	73	Same location	Not yet decided	Notset	None
Fr/0 134	134 Amersall Road, Scawthorpe	Sorbus aucuparia	Dead	10	8	35	38	Same location	Not yet decided	Not set	None
Sd/O 2	2 Grange Avenue, Balby	Acer platanoides	Weak fork structures	11	8	15	40	Same location	Not yet decided	Not set	None
fr/o 26	Middlefield Road, Bessacarr	Tilia spp.	The duty to maintain the public highway as set out in section 41 of the Highways Act 1980	14	7	40	36	Same location	Acer campestre 'Lienco'	Not set	None
fr/o 24	Middlefield Road, Bessacarr	Tilia spp.	The duty to maintain the public highway as set out in section 41 of the Highways Act 1980	14	8	40	36	Same location	Acer campestre 'Lienco'	Not set	None
			-								

Location of tree		Species	Reason for removal	Height (m)	Spread (m)	Dbh (cm)	Age	Location of replacement trees(s)	Species of replacement tree(s)	Planned date of removal	CAVAT Valuation
fr/o 22	Middlefield Road, Bessacarr	Tilia spp.	The duty to maintain the public highway as set out in section 41 of the Highways Act 1980	14	7	40	36	Same location	Acer campestre 'Lienco'	Not set	None
fr/o 16	Middlefield Road, Bessacarr	Tilia spp.	The duty to maintain the public highway as set out in section 41 of the Highways Act 1980	14	8	40	36	Same location	Acer campestre 'Lienco'	Not set	None
fr/o 14	Middlefield Road, Bessacarr	Tilia spp.	The duty to maintain the public highway as set out in section 41 of the Highways Act 1980	14	9	40	36	Same location	Acer campestre 'Lienco'	Not set	None
fr/o 12	Middlefield Road, Bessacarr	Tilia spp.	The duty to maintain the public highway as set out in section 41 of the Highways Act 1980	14	8	40	36	Same location	Acer campestre 'Lienco'	Not set	None
fr/o 10	Middlefield Road, Bessacarr	Tilia spp.	The duty to maintain the public highway as set out in section 41 of the Highways Act 1980	14	8	40	36	Same location	Acer campestre 'Lienco'	Not set	None
fr/o 8	Middlefield Road, Bessacarr	Tilia spp.	The duty to maintain the public highway as set out in section 41 of the Highways Act 1980	14	8	40	36	Same location	Acer campestre 'Lienco'	Notset	None
fr/o 6	Middlefield Road, Bessacarr	Tilia spp.	The duty to maintain the public highway as set out in section 41 of the Highways Act 1980	14	16	40	36	Same location	Acer campestre 'Lienco'	Not set	None