Vork Objects														
erial Number:	KA26AA				-				-	-			-	
ISN:	2320998939741													
itait.	2320330333741													
riteria:						_								
epair Level:	ALL				_	_								
	Closed													
Aission Impact:	ALL				_	_								
ault State:	ALL													
scalate Work:	ALL				_	_								
Vork Request ID:	rec													
ssigned Work Status:	ALL													
Vorking Organisation:														
epair Section:														
.,														
ault ID	Work Request ID	Fault Description	Work Stati	us Fault State	Escalate Wo	rk Renair Lev	el Batch Fault Group ID Number	Fault Occurrence Dat	e Mission Imna	t Reason For Work	Level 3 Description	Working Organisation	Renair Section Fo	stimated Renair Tir
00000-00B64E45		L/H WIPER BLADE SPLIT	Closed	Fully Fit	No	Level 1		17 Sep 2019	N/A	Failure	TUL HS GS SOFT TOP			00:00
00000-00B64E44		REAR BRAKE PADS	Closed	Fully Fit	No	Level 2		17 Sep 2019	N/A	Servicing	TUL HS GS SOFT TOP			00:00
00000-00B64E42		FRONT BRAKE PADS	Closed	Fully Fit	No	Level 2		17 Sep 2019	N/A		TUL HS GS SOFT TOP			00:00
00000-008A9A84		OBSERVE FREEPLAY AT STEERING SHAFT	Closed	Fully Fit	No	Level 2		09 Jul 2015	N/A		TUL HS GS SOFT TOP			000:30
00000-008A9A89		OBSERVE FREEPLAY AT VISCOUS FAN	Closed	Fully Fit	No	Level 2		09 Jul 2015	N/A		TUL HS GS SOFT TOP			000:30
00000-00B183FC		Left Rear Axle aligning rod rear bush slight play.	Closed	Fully Fit	No	Level 2		12 Mar 2019	N/A	Inspection	TUL HS GS SOFT TOP		Or	00:00
00000-00B2C32F		Starter Motor Fault	Closed	Non-Taskworth		Level 2		25 Apr 2019	N/A		TUL HS GS SOFT TOP			00:00
00000-00B21D46		SNvE377 - SWIVEL HOUSING	Closed	Fully Fit	No	Level 1	000000-0000697B	29 Mar 2019	N/A		TUL HS GS SOFT TOP			01:00
00000-00B1F142		SNvE 377 - SWIVEL HOUSING	Closed	Non-Taskworth		Level 1	000000-0000697A	29 Mar 2019	N/A	Inspection	TUL HS GS SOFT TOP			001:00
00000-00AE3E3B		Wiper blade U/S	Closed	Non-Taskworth		Level 1		02 Oct 2018	N/A	Failure	TUL HS GS SOFT TOP			00:00
00000-00AC8F54		N/S MIRROR LOOSE	Closed	Fully Fit	No	Level 2		16 Jul 2018	N/A	Failure	TUL HS GS SOFT TOP			00:00
00000-00AB78D7		FRONT STEERING GUARD BENT	Closed	Fully Fit	No	Level 2		31 May 2018	N/A	Damage	TUL HS GS SOFT TOP			00:00
00000-00A7852D		SUN VISORS	Closed	Fully Fit	No	Level 2		22 Nov 2017	N/A	Failure	TUL HS GS SOFT TOP			00:00
00000-00A78785		ENGINE BREATHER PIPE SPLIT	Closed	Fully Fit	No	Level 2		22 Nov 2017	N/A		TUL HS GS SOFT TOP			00:00
00000-00A77F76		SPEEDO CABLE SNAPPED	Closed	Fully Fit	No	Level 2		21 Nov 2017	N/A		TUL HS GS SOFT TOP			00:00
00000-00A71F9B		SCREEN WASHERS INOP	Closed	Fully Fit	No	Level 2		14 Nov 2017	N/A		TUL HS GS SOFT TOP		Or	00:00
00000-00A71D45		INSTRUMENT CLUSTER SURROUND DAMAGED	Closed	Fully Fit	No	Level 2		01 Nov 2017	N/A		TUL HS GS SOFT TOP			00:00
00000-00A6F43D		O/s/R REFLECTOR MISSING	Closed	Non-Taskworth	IV No	Level 2		06 Nov 2017	N/A	Damage	TUL HS GS SOFT TOP		Or	00:00
00000-00A6E40D		DRIVERS DOOR POCKET	Closed	Limited Role	No	Level 2		06 Nov 2017	N/A		TUL HS GS SOFT TOP			00:00
00000-00A6E40B		DRIVERS WIPER ARM	Closed	Non-Taskworth	IV No	Level 2		06 Nov 2017	N/A	Failure	TUL HS GS SOFT TOP		Or	00:00
00000-00A41388		Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Limited Role	No	Level 2	000000-00004519	28 Jul 2017	N/A		TUL HS GS SOFT TOP			01:00
00000-008A9A80		RENEW ENGINE BLAST PLATE	Closed	Fully Fit	No	Level 2		09 Jul 2015	N/A		TUL HS GS SOFT TOP			000:30
00000-008A9A7A		RENEW THERMOSTAT	Closed	Fully Fit	No	Level 2		08 Jul 2015	N/A		TUL HS GS SOFT TOP			000:30
00000-009620A8		Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Fully Fit	No	Level 2	000000-0000320A	20 Jan 2016	N/A	Inspection	TUL HS GS SOFT TOP			000:30
00000-009EDB52		EMERGENT WORK	Closed	Fully Fit	No	Level 1		12 Dec 2016	N/A		TUL HS GS SOFT TOP			002:30
00000-008A99FA		RENEW THERMOSTAT	Closed	Fully Fit	No	Level 2		08 Jul 2015	N/A	Inspection	TUL HS GS SOFT TOP		00	001:00
00000-008A4C5A		RENEW VACUUM PUMP	Closed	Non-Taskworth	y No	Level 2		26 Jun 2015	N/A	Failure	TUL HS GS SOFT TOP			001:00
00000-008A2D38		CARRY OUT MEI	Closed	Fully Fit	No	Level 2		22 Jun 2015	N/A	Inspection	TUL HS GS SOFT TOP		00	002:00
00000-008A2D3C		CARRY OUT 6 MONTHLY SERVICING IAW RELEVANT AESP	Closed	Non-Taskworth	y No	Level 2		22 Jun 2015	N/A	Servicing	TUL HS GS SOFT TOP		00	001:00
00000-008904C4		RENEW THERMOSTAT	Closed	Fully Fit	No	Level 1		29 Apr 2015	N/A	Failure	TUL HS GS SOFT TOP		or	001:00
00000-0089E134		INVESTIVAGE HUBS OVERHEATING	Closed	Non-Taskworth	ıy No	Level 2		04 Jun 2015	N/A		TUL HS GS SOFT TOP			002:00
00000-0088EF05		RENEW REAR BRAKE PADS	Closed	Non-Taskworth	y No	Level 2		29 Apr 2015	N/A	Failure	TUL HS GS SOFT TOP		or	001:00
00000-00843A01		Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58	09 Oct 2014	Degraded		TUL HS GS SOFT TOP			000:30
00000-0080D13C		REMUS PROGRAMME	Closed	Fully Fit	No	Level 2		29 Apr 2014	N/A	Refurbishment	TUL HS GS SOFT TOP		or	00:00
00000-006B0506		Insp Steering Drop Arm Tab Washer	Closed	Non-Taskworth	y No	Level 2	000000-00000310	22 Jun 2011	N/A	Inspection	TUL HS GS SOFT TOP		or	000:30
00000-0079B08C		Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00000835	25 Jun 2013	N/A		TUL HS GS SOFT TOP		00	000:15
00000-0079806B		GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non-Taskworth	y No	Level 1	000000-0000081A	24 Jun 2013	N/A	Failure	TUL HS GS SOFT TOP		00	000:15
00000-0079806B 00000-00404015			Closed	Non-Taskworth Fully Fit	No No	Level 1 Level 1	000000-0000081A	24 Jun 2013 29 Mar 2009	N/A	Failure	TUL HS GS SOFT TOP		0.	000:15