

Wendy Hallam

From: Karen Nurse
Sent: 19 May 2015 16:25
To: [REDACTED]@vinciconstruction.co.uk'
Subject: C03 Barriers
Attachments: 20150513071057051.jpg; 20150513071116208.jpg; Acorn Bank.docx; Barrier C03.docx; Barrier C03A.docx

[REDACTED]

I have received comments and photos showing barriers at a few locations where I would question what is trying to be achieved and whether what has been installed is fit for purpose:

Acorn Bank.docx – There is no overlap with plenty of space either side of the path to avoid them. Are they necessary.

Barrier C03.docx – Space either side of path to avoid them.

Barrier C03A.docx – evidence of off path avoidance. Are they necessary.

A few other items to note that may or may not come up in RSA3:

Wilford Lane 7051 – guard railing at kerb line to deter cyclists carrying straight on into carriageway.

Wilford Lane 6208 – Could this obstacle within tactile area have been avoided.

I was going to raise the issue with the barriers at next week's IRM meeting however, I won't be able to make it as I will be on leave all week. Rather than wait until the next one could you please raise my concerns.

Many Thanks Karen

Karen Nurse

Principal Project Manager, Major Projects
Environment & Resources Dept, Nottinghamshire County Council

Trent Bridge House, Fox Road, West Bridgford, Nottingham, NG2 6BJ

D 0115 977 3164

[REDACTED]
E karen.nurse@nottscc.gov.uk