| | FRI - AM | FRI - PM | SAT - AM | SAT - PM | SUN - AM | SUN - PM | MON - AM | MON - PM |
|--|----------|----------|----------|----------|----------|----------|----------|----------|
| Site Activity and key dates | 24th | 24th | 25th | 25th | 26th | 26th | 27th | 27th |
| 0800hrs - RIS onsite and set up DCU. | | | | | | | | |
| 0830hrs - Scaffolding contractor on site to erect fixed scaffolding/working platform. | | | | | | | | |
| 1200hrs - 1700hrs - RIS to construct enclosure to the Clock Tower. | | | | | | | | |
| 0800hrs - 1700hrs Smoke test (AM) the enclosure and commence removals and environmental cleaning. | | | | | | | | |
| 0800hrs - 1700hrs Complete environmental cleaning ready for the 4 stage clearance test to be carried out | | | | | | | | |
| 0800hrs - Independent analyst to attend site and carry out 4 stage clearance test | | | | | | | | |
| 0930hrs - RIS to remove 2 strips of AIB (SCC) from the back stage area – independent analyst to carry out personal, back ground and reassurance air monitoring during this element of the project | | | | | | | | |
| 1130hrs - Following satisfactory results being obtained from the analyst the enclosure is to be removed from the clock tower - ready for the scaffolding to be dismantled | | | | | | | | |
| 1330hrs – scaffolding contractor to remove fixed scaffolding/working platform | | | | | | | | |
| 1600hrs – RIS to check all areas of work prior to contacting the client to attend site and carry out a visual inspection of all the areas of work - Job completion certificate to be signed by all parties – i.e. BGCBC and RIS | | | | | | | | |
| 1700hrs RIS off site | | | | | | | | |