Cycle Highways

Borough Cycling Team - Document/Work Package Review Form

Document Number:	70005333	
Document title:	Southbank to Bloomsbury	
Revision:	B/C	
Date of Review:	14-Jul-15	

Key to Reviewers

Initial	Name	Position	Organisation
			TfL
Bearing .			TfL

Note: There are a number of issues with the wayfinding adopted within these designs;

- Too many symbols throughout the routes
 Symbols are badly posistioned poor primary and secondary posisitioning
 There are no signs

- 4. Unnecessary use of straight on arrows5. Non quietway routes have been signed this should not be incorporated

PLEASE REFER TO LATEST WAYFINDING GUIDENCE

Detailed Comments

Ref	Report section	Comment by	Comment	Summary of recommended actions	Designer Response
GA	- 01			Wayfinding guidence not followed - please follow and apply	
GA -	02		Fully supportive of the Wellington Street proposals	Wayfinding guidence not followed - please follow and apply	