



DESSec-FOI@mod.gov.uk



Defence Equipment & Support Maple 0a #2043 MOD Abbey Wood Bristol BS34 8JH



Our Reference: FOI2018/10382

Date: 04/09/2018

Dear Mr Jones,

Mr James Jones

request-444054-6cea4358@whatdotheyknow.com

Thank you for your email of 3 August 2018 which requested the following information:

Many thanks for your reply. The highlighted sections of the worksheets are of great help. Can you advise me as to the revision date of the worksheets?

I note the emphasis is on the BTTDFU but it was my understanding that this unit was replaced by the Gas Fired Time Delay Unit (GFTDU) under Mod 02198. Can you advise? Also, are there diagrams to go with the worksheets? There is constant references to item numbers which I assume relates to a drawing(s).

All the worksheets relate to bay servicing, is it possible to be provided with aircraft servicing documentation covering seat fitment including cartridges?

I am treating your email as a request for information under the Freedom of Information(FOI) Act 2000. A search has now been completed within the Ministry of Defence, and I can confirm that information in the scope of your request is held.

In answer to your first question, the worksheets we provided were the bay maintenance schedule for the ejection seat type 10A which was last revised in October 2017, and the bay maintenance schedule for the BTTDFU which was last revised in November 2016.

Secondly, the BTTDFU was not replaced with a different item under Mod 02198. Instead, it was modified to become a gas operated unit, rather than a mechanically operated unit.

Regarding your third question, there are no diagrams to go with these worksheets. The item numbers mentioned refer to other maintenance steps within the worksheet.

Finally, you will find alongside this letter a copy of the Ejection Seat and Cartridge Installation Maintenance Procedures as at January 2012. Under Section 16 of the Act (advice and assistance), the parts pertinent to pre and post Mod 02198 have been highlighted. Please also note that Fig 1 and Fig 2 are missing from the document and are labelled 'graphic not found'. You will however find these on pages 50 and 51 respectively. You will also find alongside this letter a copy of the current document, dated April 2018.

If you are not satisfied with this response or you wish to complain about any aspect of the handling of your request, then you should contact me in the first instance. If informal resolution is not possible and you are still dissatisfied then you may apply for an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail <u>CIO-FOI-IR@mod.uk</u>). Please note that any request for an internal review must be made within 40 working days of the date on which the attempt to reach informal resolution has come to an end.

If you remain dissatisfied following an internal review, you may take your complaint to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not investigate your case until the MOD internal review process has been completed. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website, <a href="http://www.ico.org.uk">http://www.ico.org.uk</a>.

Yours sincerely,

DE&S Secretariat Parliamentary