

CDM Process/Site Survey Report A0

This form is mandatory for any LTS/RTS build subject to CDM 2015

Internal Use only			
Project No.			
Date of issue			

PART 1 (Key details)

TITLE & DESCRIPTION of project

Site Survey LTS693 Ramsay Croft Car Park, Old Edinburgh Road, Dalkeith, EH22 1JD on 13th May 2021

	SMP Mobilisation Team		Infrastructure Provider	
Company	Mitie	Company	Premier Modular	
Main Contact		Main Contact		
Telephone No.		Telephone No.		
<u>v.uk</u> Email	@mitie.com	Email	@saintsconstruction.co.uk	
	Council		Council	
Company	Midlothian Council	Company	Midlothian Council	
Main Contact		Main Contact		
Telephone No.		Telephone No.		
Email	@midlothian.gov. uk	Email	@midlothian.gov.uk	
.g. designers, cont	tractors) - please add as required.	Contact details	held by PD and PC.	
	Telephone No. Company Main Contact Telephone No. Email	Telephone No. Council Company Midlothian Council Telephone No. Email @mitie.com @mitie.com @mitie.com @mitie.com @mitie.com @mitie.com @mitie.com @mitie.com	Telephone No. Council Company Midlothian Council Telephone No. Main Contact Telephone No. Telephone No. Email @midlothian.gov. Uk @midlothian.gov. Uk Contact Contact details	

@midlothian.gov.uk

@midlothian.gov.uk (email only)				
Survey Findings				
Considerations	Site Findings	Actions		
Boundaries and access, including temporary access:	No access difficulties for build or day to day operations.			
Any restrictions on deliveries or waste collection?	No	N/A		
Any key permit requirements? • airports and crane permits	None	N/A		
Adjacent Land usage and considerations	Adjacent to the site there is a supermarket with own car park, a converted church now used as a workshop, an indoor bowling club, a Royal Mail Delivery Office and some residential buildings. Only the residential buildings are likely to be affected by noise/lights etc	Site to be situated as far as possible from the private residences. Sound reduction planned for generator and lighting planned to shine away from housing.		
Are there any risks associated with neighbouring land use?	None observed	N/A		
Underground / Overhead services: • Water • Gas • Electricity – underground • Electricity – overhead lines • Communications Will these affect the build? Is there safe access to services?	Overhead phone lines but very high. Mitie and Premier agreed they would not affect access.	N/A		
Ground Conditions: Stable conditions – car park, hard standing, prepared ground Are underground structures present? Are there water courses nearby that could affect the safe use of plant, i.e. cranes?	The ground requires some work on potholes. Council have agreed to repair these early next week. They will also clean the existing drains.	Potholes to be repaired and drains to be cleaned by council prior to build		

Version 1 - 10/2020 Site Survey Report A0

Are existing structures present on site? What information is available? stability, structural form, fragile or hazardous materials, fire damage Ground shrinkage or movement Poor maintenance adversely affecting the structure Made from hazardous materials e.g. asbestos	No structures except raised beds forming boundary of car park. All in good condition.	N/A
Any difficulties relating to plant and equipment in the premises, such as overhead gantries/lines/bridges whose height restricts access or safe use?	None	N/A
Are there any environmental hazards? • Flooding/drainage issues • Trees – tree survey provided?	No apparent flood issues. Drains will be cleaned prior to build. Most trees are quite small, one larger one may overhang site but not in an area likely to cause difficulties with access. Likely to be above staff parking area	N/A
Site use: Will hoarding or fencing be required and is the site suitable for this? Are there site transport or vehicle movement restrictions? Can emergency response services safely access the site? Can fire precautions be put in place? Is there space for emergency muster and means of escape? Are there any restricted areas, designated by the landlord or tenant? Can smoking areas be safely accommodated? Will site activities adversely affect existing use?	Fencing will be used to separate test site from other parts of car park not being used. Site is suitable. No vehicle restrctions. Good emergency access. No difficulties for fire precautions and access as is modular build. No restricted areas. Smoking area can be incorporated into site. Car parking spaces will be fewer but there should still be adequate provision in the area.	Council will communicate closer of section of the car park to local businesses who may be affected. Mail delivery office staff do use the car park as well as members of the bowling club. Signs will be put up tomorrow 14/5 to advise public of suspension of parking bays in test site area.
Can appropriate welfare provisions/arrangements be developed and maintained on site?	Yes	Mitie to confirm suitable welfare provision is agreed with Premier

The regional lead discussed any changes to the existing LTS infrastructure list with the site management partner. It was agreed that the additional infrastructure detailed in their report is required to ensure that the site is able to open safely and on time.

Please details any other discussions, agreements, requirements or enabling works

Site Survey Report A0 Version 1 - 10/2020

Site Survey Report A0 Version 1 - 10/2020