

Action No.	Priory Park - Actions	Proposed Actions	Timeframe
1	The ball court needs attention and basketball nets replaced	We will address the weeds in the tarmac and replace the basketball nets	Prior to Christmas
2	A new use is needed for the abandoned bowling green as it looks forgotten.	The pavilion is leased as part of the café and is used as a childrens part and function space. The green area is actively used throughout the summer as an events space. This is its purpose it is not forgotten?	
3	The bark surfacing by the zip wire needs topping up.	This will be topped up.	Next two weeks
4	Weeds need removing from the wetpour	These will be removed	Next week.
5	The wooden mushroom seats need replacing or removing	Mushroom seats will be removed	Next two weeks
6	Bins need replacing with a different design.	These bins are a standard design across Haringey, as long as they remain servicable they will not be replaced. However there is a wider piece of work with the Friends Forum to produce a new style guide for Haringey this may result in new bin types being selected. This work is scheduled to be concluded by next April / May.	No immediate action Note: 5 Bins were replaced in Priory in September
7	Benches need some maintenance	The benches in the park will be reviewed and where required maintenance will be undertaken.	Prior to Christmas
8	There needs to be a drastic increase in horticultural standards	These will be addressed.	Next two weeks.
9	A plan is needed to restore the historic elements of the park	The Friends of the Park have been working on a project to restore the St Pauls Fountain for the last couple of years. They have been working with St Pauls Cathedral and local artists. Detailed investigations have been undertaken and a HLF bid is being planned. They need to raise £250k to undertake the restoration.	Being progressed by Friends

Action No.	Albert Recreation Ground - Actions	Proposed Actions	Timeframe
	1 Sunshine Garden Centre Gate - litter and untidy state of entrance near pyracanthus	Entrance to be tidied and shrubs trimmed back where necessary	Next two weeks
	Information on notice board including greenflag certificate but out of date events advertised ie. Christmas fair 25 th /26 th November 2017. Some small graffiti on entrance board	Notice board to be cleaned and out of date notices removed	Next two weeks
	3 Some severe disruption to path surfaces could cause trip hazards	Patching repairs to be undertaken	January for patching works. However if more substantial reconstruction works are identified this work will extend into February.
	4 Condition of play area was very poor. Dangerous screw head exposed on slide platform, dog faeces on hard surface, holes in play surface. Seats need repainting Litter bin untidy surround. Basket ball nets torn.	Timber to be replaced, dog faeces to be removed if still present, holes in safety surfacing to be addressed, seat to be painted, litter bin to be tidied around, basketball nets to be replaced.	Next week for timber to be replaced, other issues to be resolved next week or prior to Christmas
	5 Mainly ok but one dead tree adjacent to a main footpath was almost dead and had a litter item hanging from it.	Dead tree to be felled and removed	Prior to Christmas

Action No.	Bruce Castle - Actions	Proposed Actions	Timeframe
1	The entrances had litter and weeds present	Areas to be cleaned and any litter present removed	Next Two Weeks
	There are random signs that have been ripped out of the ground and poles that I assume used to contain signs	Any redundant poles to be removed and the vandliased way marker to be reinstalled.	Next Two Weeks
	3 The footpaths are in need repairing, a plan needs developing	Patching repairs to be undertaken	January/Feb
	4 The café was closed and the area looked forgotten and uncared for.	The café is leased and operates reduced hours during the Autumn / Winter Period. The old bowling green is part of the demise and therefore not under the control of the council.	No immediate action
	5 The ball court was in poor condition with netting missing and basketball post leaning and the MUGA basket ball end was missing altogether.	Nets to be replaced, basketball post to be striaghtend or replaced. Basketball hoop will not be replaced as other basketball provision available in close proximity.	Prior to Christmas
6	Concrete is exposed in the children's play bark safety surface and needs topping up Broken play equipment left exposed Gate to play area is missing Weeds lifting the wetpour safety surfacing	Barked to be topped up, broken equipment to be repaired or removed, new gate to be provided. Weeds to be removed from wet pour.	Barked to be topped up and damaged equipment to be removed if not able to be made safe. New gate to be ordered and installed when delivered. Weeds to be removed in next two weeks.
7	Benches are in poor condition	The benches in the park will be reviwed and where required maintenance will be undertaken.	Prior to Christmas
8	Horticultural standards were poor around the locked remembrance garden	Remberance garden is kept locked due to anti semitic vandalisum and now opened for events and occasions. Any low horticultrual standards to be addressed in next two weeks.	Next Two Weeks

Action No.	Markefield Park - Actions	Proposed Actions	Timeframe
1	The entrance had a lot of graffiti	Remove Graffiti	Next two weeks
	2 The notice board is difficult to read due to poor cleaning.	Clean notice board	Next two weeks
	3 The footpaths are mixed across the site.	Not sure what this comment means	No immediate action
	The ball court was in poor condition with holes in the surface and nets missing.	Patch repairs to be organised where required and missing net replaced	January
	There is broken and loose elements on the Kompan multi play unit.	Broken element has been made safe and childrens cradle seat to be replaced.	Next two weeks
	5 Children's cradle seats in very poor / dangerous condition		
	Benches and bins covered in graffiti. Some in poor condition. Picnic tables have burn marks from BBQs	Graffiti to be removed, benches to be maintained and burnt timber replaced.	Prior to Christmas
7	Lighting was present and looked OK, but some floodlighting on the ballcourt was missing.	Ball court lighting will be replaced with LED lamps as part of number 9 below.	as part of wider scheme
8		The area in the photgrpah is a nature conservation area of the park within the old filter bed structures it is not an area of high mainteance horticulture	No immediate action other than regualr volunteer work with The Conservation Volunteers
	8 Horticultural standard poor in some areas of the park.		
9		The area is part of a project to build a new floodlit MUGA and an new outdoor gym for which we have recieved £200k from LMCT and Sport England. The scheme has planning permission and is about to go out tender. Lighting on the existing MUGA will be addressed as part of this project.	
	9 A new use needs to be identified for the abandoned bowling green		Plan to open by Summer 2019.

Action No.	Woodside Park - Actions	Proposed Actions	Timeframe
1	Footpaths are very poor. The tarmac footpaths are cracking badly and some areas need replacing and the breedon gravel path top the second play area is also in poor condition.	breedon gravel path to be raked and relevelled. Patch repairs to be undertaken on paths.	Breedon path in next two weeks. Tarmacking repairs to be completed in January.
2	There were holes in the floor where something had been removed leaving exposed holes.	Holes to be filled and area reseeded	Two Weeks
3	The toddler childrens play area was in an a terrible condition and despite a sign children were still using the equipment . Weeds are present around the wetpour which is lifting the safety surface.	This area is closed and has been rescured to prevent children accessing it. Funding is being sort for its replacement.	Spring/ Summer 2019
4	Benches look tired and bins are in poor condition	Bench to be removed and replaced with new bench	Prior to Christmas
5	Horticultural standards were poor. Path edges need cutting back.	Grass edging to path to be undertaken.	Prior to Christmas