Activity:

HIGHWAYS SAFETY INSPECTION

Inspection no: 4030

Started:

22-SEP-08

Inspector:

Dry Conditions

Completed:

22-SEP-08

Conditions:

Comments:

Inspection Interval: 364

Repair no	Street	Area	Repair type	Priority	Repair completion / referred on date	Additional info
					referred on date	

Activity:

HIGHWAYS SAFETY INSPECTION

Inspection no: 75738

Started:

22-SEP-09 22-SEP-09 Inspector:

Conditions:

Dry Conditions

Completed: Comments:

Inspection Interval:

364

Repair no	Street	Area	Repair type	Priority	Repair completion /	Additional info
					referred on date	

Activity:

HIGHWAYS SAFETY INSPECTION

Inspection no: 163548

Started:

21-SEP-10

Inspector:

Completed:

21-SEP-10

Conditions:

Dry Conditions

Comments:

Inspection Interval:

364

Repair no	Street	Area	Repair type	Priority	Repair completion /	Additional info
					referred on date	

Activity:

Walked safety inspections for area inspectors

Inspection no: 248071

Started:

26-JUL-11

Inspector:

Completed:

26-JUL-11

Conditions:

Dry Conditions

Comments:

Complete - No Defects

Inspection Interval:

364

Repair no	Street	Area	Repair type	Priority	Repair completion /	Additional info
					referred on date	

Activity:

Walked safety inspections for area inspectors

Inspection no: 308815

Started:

20-JUL-12

Inspector:

Completed:

20-JUL-12

Conditions:

Dry Conditions

Comments:

Inspection Interval:

364

Repair no	Street	Area	Repair type	Priority	Repair completion / referred on date	Additional info
WO309910	BACK NORRIS STREET LITTLE LEVER - JUNCTION OF KAY ST MARKED	Area 04	C/W - BITMAC DEFECT 2.5M2 UP TO 3M2	C - URGENT REPAIRS 20 DAYS	Complete - 06-AUG-12	rain

Activity: V

Walked safety inspections for area inspectors

Inspection no: 363143

Started: 26-JUL-13

Inspector:

Completed:

26-JUL-13

Conditions:

Dry Conditions

Comments:

Inspection Interval: 364

Repair no	Street	Area	Repair type	Priority	Repair completion / referred on date	Additional info
WO365621	BACK NORRIS STREET LITTLE LEVER - OPPOSITE REAR 7 CHURCH ST JUNCTION KAY ST.	Area 04	Pass to Minor Works Footway	C - URGENT REPAIRS 20 DAYS	Complete - 26-JUL-13	FOOTWAY IN VERY UNEVEN STATE.ABOUT 30M X 0.8
WO365623	BACK NORRIS STREET LITTLE LEVER - REAR OF 45 NORRIS STREET	Area 04	UNITED UTILITIES	C - URGENT REPAIRS 20 DAYS	Complete - 26-JUL-13	WATER BOX LID MISSING.

Activity:

Walked safety inspections for area inspectors

Inspection no: 428523

24-JUL-14

Inspector:

Completed:

24-JUL-14

Conditions:

Dry Conditions

Comments:

Started:

Inspection Interval: 364

Repair no	Street	Area	Repair type	Priority	Repair completion / referred on date	Additional info
WO430384	BACK NORRIS STREET LITTLE LEVER - FULL LENGTH		Pass to Major Works Footway	C - URGENT REPAIRS 20 DAYS	Complete - 24-JUL-14	FOOTWAYS ARE VERY POOR,LARGE AREAS OF SUNKEN/DAMAGED FLAGS,ETC. NEAR A SCHOOL,DEFECT SCORE 4.
WO430387	BACK NORRIS STREET LITTLE LEVER - OPPOSITE REAR 39 CHURCH STREET MARKED	Area 04	CH - BITMAC DEFECT 0.5M2 UP TO 1M2	C - URGENT REPAIRS 20 DAYS	Complete - 29-JAN-14	
WO430388	BACK NORRIS STREET LITTLE LEVER - REAR OF 27 CHURCH STREET AROUND MANHOLE	Area 04	C/W - BITMAC DEFECT 0.5M2 UP TO 1M2	C - URGENT REPAIRS 20 DAYS	Complete - 29-JAN-14	MARKED.

Activity: Walked safety inspections for area inspectors

Inspection no: 488084 Started: 21-JUL-15 Inspector:

Completed: 21-JUL-15 Conditions: Dry Conditions

Comments: Inspection Interval: 364

Repair no	Street	Area	Repair type	Priority	Repair completion / referred on date	Additional info
WO489822	BACK NORRIS STREET LITTLE LEVER - FULL LENGTH -	Area 04	Pass to Major Works Footway	C - URGENT REPAIRS 20 DAYS	Complete - 21-JUL-15	VERY UNEVEN AND SUNKEN FOOTWAY.SEE PHOTO. PASS TO
WO489823	BACK NORRIS STREET LITTLE LEVER - REAR OF 25 **2" EASY LIFT ON 1?". SB/JM 12/08/15 SAFETY VAN. REMOVED 1" EASY LIFT. REPLACED WITH 2" EASY LIFT**	Area 04	DRAINAGE	C - URGENT REPAIRS 20 DAYS	Complete - 21-JUL-15	GULLY LID SAT LOW IN FRAME
WO489825	BACK NORRIS STREET LITTLE LEVER - OPPOSITE REAR 3 CHURCH STREET **SB/JM 12/08/15 SAFETY VAN. REMOVED 1" EASY LIFT - REPLACED WITH 2" EASY LIFT**	Area 04	DRAINAGE	C - URGENT REPAIRS 20 DAYS	Complete - 21-JUL-15	GULLY FRAME IS DAMAGED,AND TOP IS SAT LOW IN FRAME.SEE PHOTO.
WO489826	BACK NORRIS STREET LITTLE LEVER - REAR OF 5 -	Area 04	CH - BITMAC DEFECT 1M2 UP TO 1.5M2	C - URGENT REPAIRS 20 DAYS	Complete - 03-AUG-15	
WO489827	BACK NORRIS STREET LITTLE LEVER - REAR OF 15-17 -	Area 04	CH - BITMAC DEFECT 2.5M2 UP TO 3M2	C - URGENT REPAIRS 20 DAYS	Complete - 03-AUG-15	
WO489828	BACK NORRIS STREET LITTLE LEVER - REAR OF 23 AROUND GULLY	Area 04	CH - BITMAC DEFECT 2M2 UP TO 2.5M2	C - URGENT REPAIRS 20 DAYS	Complete - 03-AUG-15	
WO489829	BACK NORRIS STREET LITTLE LEVER - REAR OF 31-33 -	Area 04	F/W - BITMAC DEFECT 4.5M2 UP TO 5M2	C - URGENT REPAIRS 20 DAYS	Complete - 03-AUG-15	

Activity:

Walked safety inspections for area inspectors

Inspection no: 701653

Started:

21-JUL-16

Inspector:

Completed:

21-JUL-16

Conditions:

Dry Conditions

Comments:

Inspection Interval: 364

Repair no	Street	Area	Repair type	Priority	Repair completion / referred on date	Additional info
WO704109	BACK NORRIS STREET LITTLE LEVER - REAR OF 31 -	Area 04	F/W - BITMAC DEFECT 2M2 UP TO 2.5M2	C - URGENT REPAIRS 20 DAYS	Complete - 30-AUG-16	DEPRESSION
WO704110	BACK NORRIS STREET LITTLE LEVER - REAR OF 37 -	Area 04	F/W - BITMAC DEFECT 1M2 UP TO 1.5M2	C - URGENT REPAIRS 20 DAYS	Complete - 30-AUG-16	DEPRESSION
WO704111	BACK NORRIS STREET LITTLE LEVER - REAR OF 7 CHURCH ST. AROUND GULLY	Area 04	CH - BITMAC DEFECT UP TO 0.5M2	C - URGENT REPAIRS 20 DAYS	Complete - 30-AUG-16	
WO704116	BACK NORRIS STREET LITTLE LEVER - REAR OF 21 -	Area 04	F/W - BITMAC DEFECT 1M2 UP TO 1.5M2	C - URGENT REPAIRS 20 DAYS	Complete - 30-AUG-16	DEPRESSION

Repairs resulting from Enquiries and adhoc repairs

Repair no	Reported via	Street	Area	Repair type	Priority	Repair completion / referred on date	Additional info
WO223137	CRM	BACK NORRIS STREET LITTLE LEVER - REAR OF 15	Area 04	C/W - BITMAC DEFECT 0.5M2 UP TO 1M2	C - URGENT REPAIRS 20 DAYS	Complete - 27-JUN-11	
WO467425	CRM	BACK NORRIS STREET LITTLE LEVER - BETWEEN ALLEN STREET & SLANDER STREET PREVIOUSLY REPORTED PASSED TO MAJOR WORKS	Area 04	Pass to Minor Works Footway	C - URGENT REPAIRS 20 DAYS		FOOTWAY IN VERY POOR STATE,ADJACENT TO SCHOOL.
WO467426	CRM	BACK NORRIS STREET LITTLE LEVER - OPPOSITE REAR 7/9 CHURCH STREET -	Area 04	F/W - 4M2 - FLAG TAKEUP BROKEN & LAY BITMAC	C - URGENT REPAIRS 20 DAYS	Complete - 13-APR-15	
WO467427	CRM	BACK NORRIS STREET LITTLE LEVER - OPPOSITE REAR 11 CHURCH STREET -	Area 04	F/W - 2M2 - FLAG TAKEUP BROKEN & LAY BITMAC	C - URGENT REPAIRS 20 DAYS	Complete - 13-APR-15	
WO467428	CRM	BACK NORRIS STREET LITTLE LEVER - OPPOSITE REAR 13-15 CHURCH STREET -	Area 04	F/W - BITMAC DEFECT 4M2 UP TO 4.5M2	C - URGENT REPAIRS 20 DAYS		VARIOUS LOCATIONS
WO467429	CRM	BACK NORRIS STREET LITTLE LEVER - OPPOSITE 17 CHURCH STREET -	Area 04	F/W - BITMAC DEFECT 1M2 UP TO 1.5M2	C - URGENT REPAIRS 20 DAYS		
WO467430	CRM	BACK NORRIS STREET LITTLE LEVER - OPPOSITE REAR 19/21 CHURCH STREET -	Area 04	DEFECT 3M2 UP TO 3.5M2	C - URGENT REPAIRS 20 DAYS		
WO622511	CRM	BACK NORRIS STREET LITTLE LEVER - OPPOSITE REAR 3 CHURCH ST. MARKED	Area 04	DEFECT 2M2 UP TO 2.5M2	C - URGENT REPAIRS 20 DAYS		
WO622512	CRM	BACK NORRIS STREET	Area 04	F/W - BITMAC	C - URGENT REPAIRS	Complete - 27-APR-16	2 X DEFECTS

Repair no	Reported via	Street	Area	Repair type	Priority	Repair completion / referred on date	Additional info
		LITTLE LEVER - OPPOSITE REAR 5 & 7 CHURCH ST. MARKED		DEFECT 2M2 UP TO 2.5M2	20 DAYS		
WO622513	CRM	BACK NORRIS STREET LITTLE LEVER - OPPOSITE 9 CHURCH ST. MARKED	Area 04	F/W - BITMAC DEFECT 1M2 UP TO 1.5M2	C - URGENT REPAIRS 20 DAYS		
WO622514	CRM	BACK NORRIS STREET LITTLE LEVER - OPPOSITE 9 CHURCH ST. AROUND GULLY	Area 04	DEFECT 0.5M2 UP TO 1M2	C - URGENT REPAIRS 20 DAYS		MARKED
WO622515	CRM	BACK NORRIS STREET LITTLE LEVER - OPPOSITE 11 & 17 MARKED	Area 04	F/W - BITMAC DEFECT 3.5M2 UP TO 4M2	C - URGENT REPAIRS 20 DAYS	Complete - 27-APR-16	2 X DEFECTS
WO622516	CRM	BACK NORRIS STREET LITTLE LEVER - OPPOSITE 19 CHURCH ST. MARKED	Area 04	F/W - BITMAC DEFECT 1M2 UP TO 1.5M2	C - URGENT REPAIRS 20 DAYS	Complete 277th Reference	
WO622517	CRM	BACK NORRIS STREET LITTLE LEVER - OPPOSITE 23 MARKED	Area 04	CH - BITMAC DEFECT 1.5M2 UP TO 2M2	C - URGENT REPAIRS 20 DAYS	2771176.10	IN FOOTWAY / CHANNEL
WO622518	CRM	BACK NORRIS STREET LITTLE LEVER - REAR OF 35 NORRIS ST	Area 04	DEFECT 1.5M2 UP TO 2M2	C - URGENT REPAIRS 20 DAYS	2771176.10	
WO622519	CRM	BACK NORRIS STREET LITTLE LEVER - REAR OF 35 NORRIS ST	Area 04	DEFECT 1M2 UP TO 1.5M2	C - URGENT REPAIRS 20 DAYS	2771176.10	
WO622520	CRM	BACK NORRIS STREET LITTLE LEVER - REAR OF 23 NORRIS ST	Area 04	CH - BITMAC DEFECT 1.5M2 UP TO 2M2	C - URGENT REPAIRS 20 DAYS	Complete - 27-APR-16	