



St Margaret Mary's Gas Report

Event 121511

Introduction

- Event raised by the Janitor 12th January for reported gas leak in the home economics department on the first floor at 08.10hrs by the teaching staff.
- Janitor isolates Gas at 08.15.
- G S Halls Gas Engineer at school at 08:30
- Engineer carry's out tests by 09.30 and confirms no leaks evident on system.
- Pupils sent home 09.45
- Transco inspect system and concur with G S Hall's diagnoses.
- 3ED, Amey and GCC H&S and School Management team attend meeting in Head Teachers office at 11.00.
- Further investigation carried out by G S Hall's and Amey.

Actions

1. **Gas Cooker** - All gas cookers in home economic classrooms have been fitted with physical barrier to prevent cookers striking gas pipes at rear. (Completed 14.1.06.)
2. **Gas Isolation valves**- All valves have been made accessible for janitor in home economics and science classrooms. (Complete 12.1.06) Further works are on going to make these manual valves available for the teachers to use on a daily bases.
3. **Gas Proving System**- Instruction and training to teaching staff in Home Economics and Science was carried out on 12.1.06 and staff informed not to operate this system except in an emergency. This was carried out by ABS Regional & Facilities Managers