

Work Objects														
Serial Number:	14KF03													
NSN:	2320998937008													
Criteria:														
Repair Level:	ALL													
Work Object Status:	Closed													
Mission Impact:	ALL													
Fault State:	ALL													
Escalate Work:	ALL													
Work Request ID:														
Assigned Work Status:	ALL													
Working Organisation:														
Repair Section:														
Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-007163D5		REPAIR EXHAUST	Closed	Non-Taskworthy	No	Level 2		22 May 2012	N/A	Failure	TUM FFR HARD TOP			
000000-006F8C6E		REPLACE U/S GEARBOX	Closed	Non-Taskworthy	No	Level 2		01 Mar 2012	N/A	Failure	TUM FFR HARD TOP			
000000-006F8C88		HANDBRAKE U/S	Closed	Non-Taskworthy	No	Level 2		01 Mar 2012	N/A	Failure	TUM FFR HARD TOP			
000000-00706250		BRAKE SHOES U/S	Closed	Non-Taskworthy	No	Level 2		20 Mar 2012	N/A	Failure	TUM FFR HARD TOP			
000000-006E6B11		RENEW HEADLAMPS	Closed	Fully Fit	No	Level 2		13 Dec 2011	N/A	Damage	TUM FFR HARD TOP			
000000-006E50ED		INVESTIGATE LIGHTS FAULT	Closed	Fully Fit	No	Level 2		06 Dec 2011	N/A	Inspection	TUM FFR HARD TOP			
000000-006B8720		ADJUST HANDBRAKE	Closed	Limited Role	No	Level 2		21 Jul 2011	N/A	Failure	TUM FFR HARD TOP			
000000-006B871C		REPLACE U/S WIPER STORK	Closed	Limited Role	No	Level 2		21 Jul 2011	N/A	Failure	TUM FFR HARD TOP			
000000-006AE414		Insp Steering Drop Arm Tab Washer	Closed	Non-Taskworthy	No	Level 2	000000-000002B8	22 Jun 2011	N/A	Inspection	TUM FFR HARD TOP			
000000-005F0F48		Replace Component	Closed		No	Level 1		12 Apr 2011	N/A	Modification	TUM FFR HARD TOP			
000000-005F0022		REPLACE U/S STEERING BOX	Closed	Limited Role	No	Level 2		08 Apr 2011	N/A	Failure	TUM FFR HARD TOP			
000000-005F0020		FUNCTIONAL TEST	Closed	Limited Role	No	Level 2		08 Apr 2011	N/A	Servicing	TUM FFR HARD TOP			
000000-005F001D		REPLACE SPEEDO HEAD	Closed	Limited Role	No	Level 2		08 Apr 2011	N/A	Damage	TUM FFR HARD TOP			
000000-005F001B		REPLACE HORN	Closed	Limited Role	No	Level 2		08 Apr 2011	N/A	Failure	TUM FFR HARD TOP			
000000-005F0017		REPLACE SPEEDO DRIVE GEAR	Closed	Limited Role	No	Level 2		08 Apr 2011	N/A	Damage	TUM FFR HARD TOP			
000000-005F0015		REPLACE STEERING BALL JOINT	Closed	Limited Role	No	Level 2		08 Apr 2011	N/A	Failure	TUM FFR HARD TOP			
000000-005F0013		REPLACE R/H DOOR LOCK	Closed	Limited Role	No	Level 2		08 Apr 2011	N/A	Damage	TUM FFR HARD TOP			
000000-005F0011		REPLACE ROCKER GASKET	Closed	Limited Role	No	Level 2		08 Apr 2011	N/A	Damage	TUM FFR HARD TOP			
000000-005D3A83		REPLACE WIPERS	Closed	Non-Taskworthy	No	Level 2		20 Jan 2011	N/A	Failure	TUM FFR HARD TOP			
000000-005D3A8F		REPLACE WIPER MOTOR	Closed	Non-Taskworthy	No	Level 2		20 Jan 2011	N/A	Failure	TUM FFR HARD TOP			
000000-00562D81	000000-002C176E	YEARLY SERVICE MEC	Closed	Fully Fit	No	Level 2		25 Aug 2010			TUM FFR HARD TOP			
000000-00562D7B	000000-002C176E	YEARLY SERVICE MEC	Closed	Fully Fit	No	Level 2		25 Aug 2010			TUM FFR HARD TOP			
000000-00562D74	000000-002C176E	YEARLY SERVICE LEC	Closed	Fully Fit	No	Level 2		25 Aug 2010			TUM FFR HARD TOP			
000000-004F144F	000000-002AEA16	U/S ENGINE MOUNT WORN	Closed	Non-Taskworthy	No	Level 2		07 Apr 2010			TUM FFR HARD TOP			
000000-004F144B	000000-002AEA16	SUMP LEAKING	Closed	Non-Taskworthy	No	Level 2		07 Apr 2010			TUM FFR HARD TOP			
000000-004F144A	000000-002AEA16	DROP ARM BALL JOINT WORN	Closed	Non-Taskworthy	No	Level 2		07 Apr 2010			TUM FFR HARD TOP			
000000-004F1449	000000-002AEA16	TRANSFER BOX OUTPUT SEAL	Closed	Non-Taskworthy	No	Level 2		07 Apr 2010			TUM FFR HARD TOP			
000000-004F1448	000000-002AEA16	REAR AXLE INPUT SEAL LEAKING	Closed	Non-Taskworthy	No	Level 2		07 Apr 2010			TUM FFR HARD TOP			
000000-004F143B	000000-002AEA16	WATER PUMP LEAKING	Closed	Non-Taskworthy	No	Level 2		07 Apr 2010			TUM FFR HARD TOP			
000000-004F143A	000000-002AEA16	WINDOW WASHER MOTOR U/S	Closed	Non-Taskworthy	No	Level 2		07 Apr 2010			TUM FFR HARD TOP			
000000-004F1438	000000-002AEA16	ROCKER COVER GASKET LEAKING	Closed	Non-Taskworthy	No	Level 2		07 Apr 2010			TUM FFR HARD TOP			
000000-004F1437	000000-002AEA16	REPLACE DOOR HINGES	Closed	Non-Taskworthy	No	Level 2		07 Apr 2010			TUM FFR HARD TOP			
000000-004EEE46	000000-002AEA16	6 MONTHLY MEC SERVICE	Closed	Non-Taskworthy	No	Level 2		31 Mar 2010			TUM FFR HARD TOP			
000000-004EEE45	000000-002AEA16	6 MONTHLY LEC SERVICE	Closed	Non-Taskworthy	No	Level 2		31 Mar 2010			TUM FFR HARD TOP			
000000-0026E6BF	000000-002AEA16	REPAIR RADIO BATTERY BOX AND FITTING	Closed	Fully Fit	No	Level 2		19 Aug 2008			TUM FFR HARD TOP			
000000-0026E698	000000-002AEA16	RENEW STEERING BOX FILLER PLUG	Closed	Fully Fit	No	Level 2		19 Aug 2008			TUM FFR HARD TOP			
000000-0026E66F	000000-002AEA16	RENEW 90 AMP GENERATOR LUBRICATOR	Closed	Fully Fit	No	Level 2		19 Aug 2008			TUM FFR HARD TOP			
000000-004CEEE8	000000-002A80BF	OIL LEAK	Closed	Fully Fit	No	Level 2		16 Feb 2010			TUM FFR HARD TOP			
000000-0044EAAD		Insufficient Data	Closed	Non-Taskworthy	No	Level 1		30 Jun 2009			TUM FFR HARD TOP			
000000-0026E52F	000000-0028078B	CARRY OUT MEI	Closed	Fully Fit	No	Level 2		19 Aug 2008			TUM FFR HARD TOP			
000000-0026E532	000000-0028078B	CARRY OUT 1Y SERVICE	Closed	Fully Fit	No	Level 2		19 Aug 2008			TUM FFR HARD TOP			
000000-0026E6D3	000000-002807A9	LH INDICATOR INOP	Closed	Non-Taskworthy	No	Level 2		19 Aug 2008			TUM FFR HARD TOP			
000000-00224364		Initial Usage	Closed	Fully Fit	No	Level 1		24 Jul 2008			TUM FFR HARD TOP			
000000-0022437E		Initial Maintenance	Closed	Fully Fit	No	Level 1		24 Jul 2008			TUM FFR HARD TOP			