



STAFFORDSHIRE COUNTY COUNCIL ROMIS SYSTEM
SAFETY INSPECTION SUMMARY

Report Name : RominspectionV2

Run By : MIKEWE

Start Date : 01-FEB-2008 End Date : 23-FEB-2010

Run Date : 23 FEB 2010

Road No : D4371 NSG Ref : 36701335

Page No : 1

Inspection Date	Id	Road Condition	Weather Condition	Initiation Type	Inspector	Defect
17-MAR-2008	730219	DRY	FIN	NRM	HEARD1SC	Y