

Safety Inspection Record of Repairable Defects and Minor Works



Highway Unit: MAIDSTONE

Inspectors Initials AP – ALAN PURVIS- EARL BOURNER

Inspection Frequency (*delete as necessary)	Carriageway Inspection	Weekly/Monthly/Six Monthly *
	Footway walked Inspection	Monthly/Y early*
	Cycle Track Inspection	Monthly/Six monthly/Y early*

Inspection Route Number AREA A20	BEARSTED/HARRIETSHAM/LENHAM	Inspection Date: 19-1-2010
-------------------------------------	------------------------------------	-------------------------------

Road Name	NSG Ref	Inspection Method (W/D/C)	Nature of Repairable Defects/ Minor Works and their Specific Location	Repair Response Time (2hr/3 day /Prog/E)	No Repairs ?	Works Order No
ASHFORD ROAD	24200038	D/BEAR	NO DEFECTS			
ASHFORD ROAD	24200040	D/HARR	NO DEFECTS			
ASHFORD ROAD	24200042	D/LEN	NO DEFECTS			
ASHFORD ROAD	24200041	D/HOLL	NO DEFECTS			
ASHFORD ROAD	24200043	D/MAID	1 SQM SEE WAMS 41001614			

Safety Inspection Record of Repairable Defects and Minor Works



Highway Unit: MAIDSTONE

Inspectors Initials AP – ALAN PURVIS- J. CUNNINGHAM

Inspection Frequency (*delete as necessary)	Carriageway Inspection	Footway walked Inspection	Cycle Track Inspection	Weekly/Monthly/Six Monthly *	Monthly/Yearly*	Monthly/Six monthly/Yearly*
Inspection Route Number AREA A20 BEARSTED/HARRIETSHAM/LENHAM						
Inspection Date: 1-12-2009						
Road Name	NSG Ref	Inspection Method (W/D/C)	Nature of Repairable Defects/ Minor Works and their Specific Location	Repair Response Time (2hr/3 day /Prog/E)	No Repairs ?	Works Order No
ASHFORD ROAD	24200038	D/BEAR			NO DEFECTS	
ASHFORD ROAD	24200040	D/HARR	OPP HOLM MILL LANE ISQM SEE WAMS	PROG		
ASHFORD ROAD	24200042	D/LEN	41000880		NO DEFECTS	
ASHFORD ROAD	24200041	D/HOLL	ISQM DUAL CARRIAGEWAY SEE WAMS	3 DAY		

Safety Inspection Record of Repairable Defects and Minor Works



Highway Unit: MAIDSTONE

Inspectors Initials AP - ALAN PURVIS

Inspection Frequency (*delete as necessary) Carriageway Inspection ~~Weekly/Monthly/Six Monthly *~~

Footway walked Inspection ~~Monthly/Yearly*~~

Cycle Track Inspection ~~Monthly/Six-monthly/Yearly*~~

Inspection Route Number AREA **ROSEACRE** 48 Inspection Date: 20-10-2009

Road Name	NSG Ref	Inspection Method (W/D/C)	Nature of Repairable Defects/ Minor Works and their Specific Location	Repair Response Time (2hr/3 day /Prog/E)	No Repairs ?	Works Order No
WARE STREET	24201605	D			N/D	
SHARSTED WAY	24201339	D			N/D	
SANDY MOUNT	24201324	D			N/D	
HOG HILL	24200765	D			N/D	
SANDY LANE	24201322	D			N/D	
ROSEACRE LANE	24201291	D	3 SQM JUN A20-O/S 24 1SQM	PROG		
TOWER LANE	24201555	D			N/D	
CLARENDON CLOSE	24200350	D			N/D	
PLANTATION LANE	24201210	D			N/D	
THE GROVE	24201505	D			N/D	

Road Name	NSG Ref	In. Method (W/D/C)	Nature of Repairable Defects Minor Works and their Specific Location	Repair Response Time (2hr/3 day /Prog/E)	No Repairs ?	Works Order No
WARE STREET	24201605	D	20-10-09		N/D	
SHARSTED WAY	24201339	D			N/D	
SANDY MOUNT	24201324	D			N/D	
HOG HILL	24200765	D			N/D	
SANDY LANE	24201322	D			N/D	
ROSEACRE LANE	24201291	D	3 SQM JUN A20-O/S 24 ISQM WAMS 41000302 AND 41000303	PROG		
TOWER LANE	24201555	D			N/D	
CLARENDON CLOSE	24200350	D			N/D	
PLANTATION LANE	24201210	D			N/D	
THE GROVE	24201505	D			N/D	

Safety Inspection Record of Repairable Defects and Minor Works



Highway Unit: MAIDSTONE

Inspectors Initials DB DAVE BARNES

Inspection Frequency (* delete as necessary)	Carriageway Inspection	Weekly/Monthly/Six Monthly *	Footway walked Inspection	Monthly/Yearly*	Cycle Track Inspection	Monthly/Six monthly/Yearly*		
Inspection Route Number	ROSEACRE		48		Inspection Date:	16/03/2009-21/03/2009		
Road Name	NSSG Ref	Inspection Method (W/D/C)	Nature of Repairable Defects/ Minor Works and their Specific Location			Repair Response Time (2hr/3 day /Prog/E)	No Repairs ?	Works Order No
WARE STREET	24201605	W					X	
SHARSTED WAY	24201339	W					X	
SANDY MOUNT	24201324	W					X	
HOG HILL	24200765	W					X	
SANDY LANE	24201322	W					X	
ROSEACRE LANE	24201291	W					X	
TOWER LANE	24201555	W					X	
CLARENDON CLOSE	24200350	W					X	
PLANTATION LANE	24201210	W	Scabby in places some minor kerb damage				X	
THE GROVE	24201505	W	Scabby in places some minor kerb damage				X	

