

Effective: 16/02/2008 to 18/02/2010
 Street: MEGGRIMS HILL (41100643)

Display Action Officer: Yes

Street: MEGGRIMS HILL (41100643)

Locality: SANDHURST KENT

Area: Tunbridge Wells

Condition Survey

Defect No.	Description	Log Date	Location	Defect Type	Class	Organisation	Status	Job No.
Feat. No.: 10.000.00	Feature Id - Locn.:			Feature Type: Whole Site Tree Feature			Area: Tunbridge Wells	
Batch: 1502887 - Ad Hoc Inspection Batch								
1513373	caller reports that this vegetation is more overgrown than ever before and he has to call every year he wonders if it is on the schedule	17/09/2009	outside megrims and its land esp by the gateway Megrims House Also called Rye Road	T Other	Internal	WMI Sawett	Uncommite	1730952
Batch: 1502723 - Ad Hoc Inspection Batch								
1512824	caller reports that this vegetation is more overgrown than ever before and he has to call every year he wonders if it is on the schedule	27/08/2009	Existing Megrims House stone way onto Megrims Hill (A269). The offending vegetation is on the left, immediately after the white picket fence for 20m, to just beyond the road sign	T Other	Internal	Chris Keele	Unactioned	
Batch: 1501828 - Data Logger Inspections								
No noticeable defects found								
Feat. No.: 10.001.00	Feature Id - Locn.:			Feature Type: Oak spp.			Area: Tunbridge Wells	
Batch: 1501829 - Data Logger Inspections								
1509518	TN184 NL	16/04/2009	In grounds of field Green House, Megrims Hill	T S Dead stems	Internal	Chris Keele	Unactioned	16/04/2009
Feat. No.: 999.999.00 Feature Id - Locn.:								
Batch: 41400640 - Ad Hoc Inspection Batch								
41401389	POT HOLES/PATCHING- 4 NUMBER 12X12x50mm + 3x1x50mm + 5x12x50mm TRAFFIC LIGHTS REQUIRED COST TO 1541185	17/02/2010	A262 just down from junction Shroden Lane-SANDHURST BOUND	CW Pothole	Internal	Cliff Wilson	Committed	41401020
Batch: 41400492 - Inspection Batch								
41401102	REACTIVE WORKS ROUTINE GANG C way POTHOLE 15qm X 30MM DEEP X 8 OFF ALL COSTS TO BE APPLIED TO 1541181	01/02/2010	BELOW JUNCTION WITH SILVERDEN LANE	CW Pothole	Internal	Richard Kaupert	Committed	41400771
Batch: 41400255 - Ad Hoc Inspection Batch								
41400504	REACTIVE WORKS FIND & FIX C/WAY P/HOLES 0.5 SQM X 50MM DEEP X 5 OFF ALL COSTS TO BE APPLIED TO 1541185	18/01/2010	ADJACENT TO DOWNGATE COTTAGE	CW Pothole	Internal	Richard Kaupert	Committed	41400396
Batch: 41400175 - Ad Hoc Inspection Batch								
41400403	REACTIVE WORKS 2 MAN GANG C/W P/HOLES 0.5 SQM X 50MM DEEP ALL COSTS TO BE APPLIED TO 15414003	08/01/2010	ONE EACH SIDE OF JUNCTION WITH SILVERDEN LANE	CW Pothole	Internal	Richard Kaupert	Committed	41400289
Batch: 41400067 - Inspection Batch								
41400197		17/12/2009		No Defect Found	Internal	Richard Kaupert	Unactioned	17/12/2009

02/03/2010

Street History Report

Page 2 of 6

Effective: 10/03/2009 15:06:00
Street: MECRIMS HILL 1411006431

Display Action Officer: Yes

Condition Survey

Defect No: Description	Feature Id - Locn:	Log Date	Location	Defect Type	Feature Type: Wings Street Feature	Class - Organisation	Status	Job No.
102154302	Batch: 102154318 - Inspection Batch	23/09/2009	Weymans Hill, sandhurst On sng bend 992001	No Defect Found	CW Pothole	Internal	Completed	10224635
102249909	Batch: 102151505 - Inspection Batch	26/11/2009	SW DRIVER	No Defect Found		Internal	Unactioned	Date: 26/11/2009
10224025	Batch: 10214735 - Inspection Batch	29/10/2009	SW DRIVER	No Defect Found		Internal	Unactioned	Date: 29/10/2009
102230595	Batch: 10214318 - Inspection Batch	23/09/2009		No Defect Found		Internal	Unactioned	Date: 23/09/2009
102215779	Batch: 10213761 - Inspection Batch	27/08/2009		No Defect Found		Internal	Unactioned	Date: 27/08/2009
102154312	Batch: 10212831 - Inspection Batch	27/07/2009		No Defect Found		Internal	Unactioned	Date: 27/07/2009
10217721	Batch: 10210894 - Inspection Batch	26/06/2009		No Defect Found		Internal	Unactioned	Date: 26/06/2009
102160957	Batch: 10211753 - Inspection Batch	01/06/2009		No Defect Found		Internal	Unactioned	Date: 01/06/2009
102158277	Batch: 10210794 - Inspection Batch	27/05/2009		No Defect Found		Internal	Unactioned	Date: 27/05/2009
10214546	Batch: 10209804 - Inspection Batch	27/04/2009		No Defect Found		Internal	Unactioned	Date: 27/04/2009
10210657	Batch: 10207220 - Ad Hoc Inspection Batch	18/02/2009	AZ68 East of junction Silverdun Lane	CW Surface Erosion		Internal	Completed	10210049
10209805	Batch: 10206561 - Inspection Batch	05/02/2009		No Defect Found		Internal	Unactioned	Date: 05/02/2009
10209137	Batch: 10206006 - Inspection Batch	26/01/2009		No Defect Found		Internal	Unactioned	Date: 26/01/2009
10208071	Batch: 10205955 - Inspection Batch	05/01/2009		No Defect Found		Internal	Unactioned	Date: 05/01/2009
10206677	Batch: 10204312 - Inspection Batch	28/11/2008		No Defect Found		Internal	Unactioned	Date: 28/11/2008

Report generated by : Richard Kauper

11:12:33

Effective: 18/02/2008 to 18/02/2010
 Street: MEGRAMS HILL (41100643)

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Feature Id - Locn:	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat. No.:	999 999 000				Feature Type: Whole Street Feature				
Batch:	10203951 - Inspection Batch				Route: Ad-Hoc Community Delivery 2	Officer: John Gauge			Date: 14/11/2008
10206182	vegetation obscuring left hand ahead sign - cut back by inspector 12/11/2008		14/11/2008	North west bound at approach to junction of AM Sign Obscured by Vegetation Silverdale Lane	Internal		Uncomplete		10206820
Batch:	10203832 - Inspection Batch				Route: Ad-Hoc Community Delivery 2	Officer: Cliff Wilson			Date: 30/10/2008
10205780	INSPECTED 29 10 08		30/10/2008		No Defect Found		Unactioned		
Batch:	10203852 - Inspection Batch				Route: Turbridge Wells-Sandhurst 11E	Officer: Richard Kaupert			Date: 30/10/2008
No actionable defects found									

Customer Services

Enquiry No:	17501730	Logged by:	Clair Whitehead	on:	18/02/2010 09:39	Officer:	G.Turbridge Wells Ringway
Service:	Potholes	Subject:	Pothole On The Road	Classification:	Faults		
Desc: caller has hit a pothole and also a drain cover hole is approx 16inch x 16 inches 6/7 inches deep which is on the edge of a manhole cover which is exposed and raised 2 acoys and 2 tyres damaged on N15							
Location:	Megrims Hill sandhurst On blind bend section	Contact:					
Plot Number:	999 999 000	Feature id - Location:		Feature Type:	Whole Street Feature		
Job Number:	10224836	Defect Number:	10225950				
Enquiry No:	18600684	Logged by:	Esther Smith	on:	15/01/2010 16:19	Officer:	Alan Riley
Service:	Trees	Subject:	Information On Trees	Classification:	Faults		
Desc: Copy of Land registry plan enclosed Customer asking for confirmation that KHS will still maintain trees and foliage on embankment inc grass each year.							
Location:		Contact:					
Enquiry No:	16318288	Logged by:	Jennifer Pow	on:	14/11/2009 11:12	Officer:	Graham White
Service:	Trees	Subject:	Tree or Branch Fallen	Classification:	Faults		
Desc: A tree has fallen across the road and is being held up by trees on other side of the road. its a dead tree, about 18 inches round could fall on a car.							
Location:	The top of the lane, between sandhurst and hawkhurst going towards sandhurst its on the right hand side.	Contact:					
Enquiry No:	16345551	Logged by:	Lisa Thompson	on:	15/09/2009 16:15	Officer:	Michelle Ticknell-Smith
Service:	Trees	Subject:	Tree or Branch Fallen	Classification:	Faults		
Desc: Very big tree 30-40 feet and at a 30 degree angle and look like it will fall over. health tree but its in falling position							
Location:	right hand side bottom of the hill by the nursery.	Contact:					
Plot Number:	999 999 000	Feature Id - Location:		Feature Type:	Whole Street Feature		
Enquiry No:	16295897	Logged by:	Diana Simmonds	on:	27/07/2009 15:51	Officer:	Alan Riley
Service:	Vegetation (see also Trees)	Subject:	Obstructing Visibility	Classification:	Faults		
Desc: caller reports that this vegetation is more overgrown than ever before and he has to call every year he wonders if its on the schedule							
Location:	outside megrims and its land esp by the gateway Megrims House Also called Rye Road	Contact:					
Plot Number:	999 999 000	Feature Id - Location:		Feature Type:	Whole Street Feature		
Job Number:	425091	Defect Number:	1513373				

02/03/2010

Street History Report

Effective: 18/02/2009 to 18/02/2010
Street: MEGGINS HILL (A1100242)

Display Action Officer: You

Customer Services

Enquiry No: 18247976

Service: Potholes

Desc: 4 potholes in the centre of the road about 3meters deep all quite close to each other
Location: Swarden Lane junction with A268 Meggins Hill Sandhurst near Hawkhurst Rd
Contact:

Logged by: Harvey Ball

Subject: Pothole On The Road

Classification: Faults

Officer: G Cam Del 2, Raby

on: 18/02/2009 11:27

Feature Id - Location:

Defect Number: 102100657

Feature Type: Whole Street Feature

Plot Number: 995/995/33

Job Number: 10210065

Service: Potholes

Desc: A pothole in the road approx 4meters deep
Location: Close to F405 green by the 1st on the left hand side

Logged by: Harvey Ball

Subject: Pothole On The Road

Classification: Faults

Officer: John Gough

on: 18/02/2009 11:26

Enquiry No: 16240877

Service: Draining and Flooding

Desc: Meggins Hill water tap cover - This about 100 yards from the junction with Swarden Lane on the Hawkhurst side of the junction. It's opposite the water marker no 250
Location: 100 yards from the junction with Swarden Lane

Logged by: Hilary Johnson

Subject: Manhole/Drain Cover Problem

Classification: Faults

Officer: John Gough

on: 17/12/2008 16:40

Enquiry No: 14401096

Service: Information Requested

Desc: enquiry with plan
Location:

Logged by: Christine Jacques

Subject: Land Boundary/Definition

Classification: Request for Information

Officer: Will Salwell

on: 08/08/2009 10:13

Maintenance Management

Job No: Description

Location

Officer

Priority

Job Status

Entered

Completion

Works Order

Feat. No.: 10,000 00

Feature Id - Locn:

1730687 ADDED ON ORDER 4460300

NOW CLOSED- caller reports that this vegetation is more overgrown than ever before and he has to call every year he wonders if its on the schedule (T Other)

Feat. Type: Waste Site Tree Feature

WAMS- App No action required

Defect non-actionable

17/09/2006

15/10/2009

Est

Feat. No.: 999/999/00

Feature Id - Locn:

421807 clean & jet gutters (44)

4088 Meggins Hill Swarden Lane Sandhurst to 0257 Swarden Lane Sandhurst Sun wells

Feat. Type: Waste Street Feature

WAMS - Programmed

Resource Works Complete

12/10/2007

25/09/2008

Act KR2421432

425081 Extended double white lining at brow of hill, via Meggins Cottage for a distance of approx 30m west towards Hawkhurst, marked on site, refresh adjoining hmg, edge of car kerbs and adj junction lining

Barrie Kelson aware of the works, and has copies of location plan.
480291 Please carry out Thin Surfacing works as agreed on site with Steve Clark and Wayne Lamer

Feat. Type: Waste Street Feature

WAMS - Programmed

Financial Completion Submitted

31/01/2008

11/03/2009

Act KR0424027

Between Sponder Lane and Swarden Lane

WAMS - Programmed

Financial Completion Submitted

07/04/2007

17/02/2009

Act KR0480138

Effective: 18/02/2009 to 18/02/2010
 Street: MCGRIMS HILL (d1100943)

Display Action Officer: Yes

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
10205820	vegetation obscuring left turn ahead sign - cut back by inspector	North west bound at approach to junction of Silverdale Lane	John George	WAMS - App No action required	Defect non-Actionable	13/11/2009		
102112008	Sign Obscured by Vegetation)							
10210046	3 man gang works - cut out and carry out permanent reinstatement to c/w patches - 2.0m x 8.1.3m x 4.3.0m x 4.1.0m x 5.4.0m x 9.1.2m x 2.2 way lights after 9.30am (CW Surface Erosion)	A269 East of Junction Swindon Lane	John George	WAMS - Programmed	Financial Completion Submitted	18/02/2009	09/03/2009	Act. KR/1020857
10224330	patch 1 x pothole back at costs to 1541181	Mogrim's Hill near some sort of access panel on the bank	Hub West Turbridge Wells	WAMS - 1/2 Man	Job Accepted	09/02/2010	09/03/2010	Est. KR/10225118
10224531	patch 1 x pothole back at costs to 1541181	near silverdale lane	Hub West Turbridge Wells	WAMS - 3 Day Urgent	Works Programmed	16/02/2010	09/02/2010	Est. KR/10225836
10224546	patch 1 x pothole back at costs to 1541181	near in with Silverdale lane	Hub West Turbridge Wells	WAMS - 3 Day Urgent	Works Programmed	16/02/2010	09/02/2010	Est. KR/10225935
10224636	RHSX 68x91 FILL LARGE C/W POTHOLE (CW Pothole)	Mogrim's Hill sandhurst On blind bend section	Mark Osborne	WAMS - 2 Hour Emergency	Financials Complete	18/02/2010	18/02/2010	Act. KR/10226111
41402266	REACTIVE WORKS 2 MAN GANG C/W PHOLES 0.5 SQM X 50 MM DEEP ALL COSTS TO BE APPLIED TO 1541185 (CW Pothole)	ONE EACH SIDE OF JUNCTION WITH SILVERDALE LANE	Richard Kaupert	WAMS - 3 Day Urgent	Relative Works Complete	05/01/2010	17/01/2010	Act. KR/10222402
41402389	REACTIVE WORKS FIND & FIX C/WAY PHOLES 0.5 SQM X 50MM DEEP X 4 OFF ALL COSTS TO BE APPLIED TO 1541185 (CW Pothole)	ADJACENT TO DOWNGATE COTTAGE	Richard Kaupert	WAMS - 3 Day Urgent	Relative Works Complete	10/01/2010	18/01/2010	Act. KR/10223094
41400771	REACTIVE WORKS ROUTINE GANG C/WAY POTHOLE 15qm X 30MM DEEP X 8 OFF ALL COSTS TO BE APPLIED TO 1541185 (CW Pothole)	BELOW JUNCTION WITH SILVERDALE LANE	Richard Kaupert	WAMS - 3 Day Urgent	Relative Works Complete	01/02/2010	09/02/2010	Act. KR/10224471
41401020	POT HOLES/PATCHING - 4 NUMBERS 12x1/2x50mm + 3x1x50mm + 5x1/2x50mm + 5x1/2x50mm TRAFFIC LIGHTS REQUIRED COST TO 1541185 (CW Pothole)	A262 just down from junction Swindon Lane-SANDHURST BOUND	Cliff Wilson	WAMS - 1/2 Man	Job Accepted	17/02/2010	17/03/2010	Est. KR/10225932

Effective: 18/02/2009 to 18/02/2010
 Street: MEGRIMS HILL (41100643)

Display Action Officer: Yes

Street Works Notices

Organisation: K+S Alliance Partner - Rangway (KR)

Works Ref: 10210049
 Notice Type: Works Stop
 Work Status: Works Stopped
 Work Type: ETON 4+ Standard

Version: 3
 Start: 05/03/2009 09:25:00
 Issued: 11/03/2009 09:36:28
 Est. End: 18/03/2009

Work Desc: 3 man gang works - cut out and carry out permanent reinstatement to c/w patches - 2.0x0.8
 1.3x0.4, 3.0x0.4, 1.0x0.5, 4.0x0.9, 1.2x1.2 - 2 way lights after 9:30am (CW Surface Erosion)

Site No. Location

1 A258 East of junction Silverden Lane
 Carriageway

Position
 Carriageway

Depth
 Not Known (Depth)

Length
 0.00

Width Status
 0.00 A Site of a Proposed Street

Site Date
 03/03/2009

Interim
 Perm.
 Prop. End
 08/03/2009

Works Ref: 41400395
 Notice Type: Registration of Reinstatement - Full
 Work Status: Works Stopped
 Work Type: ETON 4+ Immediate - Urgent

Version: 4
 Start: 27/01/2010 00:00:00
 Issued: 03/02/2010 09:24:32
 Est. End: 28/01/2010

Work Desc: REACTIVE WORKS FIND & FIX C/WAY PHOLES 0.5 SQM X 50MM DEEP X 5 OFF ALL
 COSTS TO BE APPLIED TO 1541185 (CW Pothole)

Site No. Location

1 ADJACENT TO DOWNGATE COTTAGE
 Carriageway

Position
 Carriageway

Depth
 Up to 1.5 Metres of Cover

Length
 1.00

Width Status
 1.00 A Permanent Reinstatement

Site Date
 29/01/2010

Interim
 Perm.
 Prop. End
 29/01/2010

Works Ref: 41400771
 Notice Type: Cancellation
 Work Status: Abandoned Works
 Work Type: ETON 4+ Immediate - Urgent

Version: 3
 Start: 05/02/2010 00:00:00
 Issued: 10/02/2010 14:20:45
 Est. End: 05/02/2010

Work Desc: REACTIVE WORKS ROUTINE GANG C/WAY POTHOLE 1.9m X 30MM DEEP X 8 OFF ALL
 COSTS TO BE APPLIED TO 1541185 (CW Pothole)

Site No. Location

1 BELOW JUNCTION WITH SILVERDEN LANE
 Carriageway

Position
 Carriageway

Depth
 Not Known (Depth)

Length
 0.00

Width Status
 0.00 A Site of a Proposed Street

Site Date
 05/02/2010

Interim
 Perm.
 Prop. End
 05/02/2010