

Safety Inspection Record of Repairable Defects and Minor Works



Highway Unit: Tunbridge Wells

Inspector: AB

Driver: RJK

Inspection Frequency:

Carriageway Inspection: Monthly

Footway Walked Inspection:

Monthly / Three-Monthly / Annual (N/A)

Inspection Route Number:

Sandhurst 11E - CW6

Inspection Date: 29-02-2008

Road Name	NSG Ref	Inspection Method (W/D/C)	Nature of Repairable Defects/ Minor Works and their Specific Location	Repair Response Time (2hr/3 day/ Prog/E)	No Repairs	Works Order No
A288 Rye Road	41100864	D	30-40yds past Tibbrook cottage repair 1 small pothole adj to gully. 1250m ²	prog		nomu
Queen Street	41100816	D			X	
Magrims Hill	41100843	D			X	

Safety Inspection Record of Repairable Defects and Minor Works



Highway Unit: Tunbridge Wells

Inspector AB

Drive RJK

Inspection Frequency

Carrageway Inspection: Monthly

Footway Walked Inspection:

Monthly / Three-Monthly / Annual (N/A)

Inspection Route Number:

Sandhurst 11E - CW6

Inspection Date: 18-03-2008

Road Name	NSG Ref	Inspection Method (W/D/C)	Nature of Repairable Defects/ Minor Works and their Specific Location	Repair Response Time (2hr/3 day/ Prog/E)	No Repairs	Works Order No
A288 Ryd Road	41100864	D	jw stonepit lane patch 1 small pothole dbm. 1250m2	prog		norm
Queen Street	41100816	D			X	
Megrims Hill	41100843	D			X	

Safety Inspection Record of Repairable Defects and Minor Works



Highway Unit: Tunbridge Wells

Inspector CW

Drive RJK

Inspection Frequency

Carriageway Inspection: Monthly

Footway Walked Inspection:

Monthly / Three-Monthly / Annual (N/A)

Inspection Route Number:

Sandhurst 11E - CW6

Inspection Date: 28-04-2008

Road Name	NSG Ref	Inspection Method (W/D/C)	Nature of Repairable Defects/ Minor Works and their Specific Location	Repair Response Time (2hr/3 day/ Prog/E)	No Repairs	Works Order No
A288 Rye Road	41100864	D	No repairs			
Queen Street	41100816	D	No repairs			
Megrims Hill	41100643	D	No repairs			

Safety Inspection Record of Repairable Defects and Minor Works



Highway Unit: Tunbridge Wells

Inspector: cliff wilson

Drive R. Kaupert

Inspection Frequency:

Carriageway Inspection: Monthly

Footway Walked Inspection:

Monthly / Three-Monthly / Annual (N/A)

Inspection Route Number:

Sandhurst 11E - CW6

Inspection Date: 27 May 2008

Road Name	NSG Ref	Inspection Method (W/D/C)	Nature of Repairable Defects/ Minor Works and their Specific Location	Repair Response Time (2hr/3 day/ Prog/E)	No Repairs ?	Works Order No
A268 Rye Road	41100864	D			X	
Queen Street	41100816	D			X	Normu
McGrims Hill	41100843	D			X	

Safety Inspection Record of Repairable Defects and Minor Works



Highway Unit: Tunbridge Wells

Inspector R KAUPERT

Drive RAY LEADBETATER

Inspection Frequency

Carriageway Inspection: Monthly

Footway Walked Inspection:

Monthly / Three-Monthly / Annual (N/A)

Inspection Route Number:

Sandhurst 11E - CW6

Inspection Date: 26-06-2008

Road Name	NSSG Ref	Inspection Method (M/D/C)	Nature of Repairable Defects/ Minor Works and their Specific Location	Repair Response Time (2hr/3 day/ Progre)	No Repairs ?	Works Order No
A268 Rye Road	41100864	D			X	
Queen Street	41100816	D			X	
Megrims Hill	41100643	D			X	

Safety Inspection Record of Repairable Defects and Minor Works



Highway Unit: Tunbridge Wells Inspector: CLIFF WILSON Drive: RAY LEADBEATER


Inspection Frequency: Carriageway Inspection: Monthly

Footway Walked Inspection: Monthly / Three-Monthly / Annual (N/A)

Inspection Route Number: Sandhurst 11E - CW6 Inspection Date: 29-07-2008

Road Name	NSSG Ref	Inspection Method (W/D/C)	Nature of Repairable Defects/ Minor Works and their Specific Location	Repair Response Time (2hr/3 day/ Prog/E)	No Repairs ?	Works Order No
A268 Rye Road	41100864	D			X	
Queen Street	41100816	D			X	
Magrims Hill	41100843	D			X	

Safety Inspection Record of Repairable Defects and Minor Works



Highway Unit: Tunbridge Wells Inspector: CLIFF WILSON Drive: RAY LEADBEATER

Inspection Frequency: Carriageway Inspection: Monthly

Footway Walked Inspection: Monthly / Three-Monthly / Annual (N/A)

Inspection Route Number: Sandhurst 11E - CW6 Inspection Date: 23-08-2007

Road Name	NSG Ref	Inspection Method (W/D/C)	Nature of Repairable Defects/ Minor Works and their Specific Location	Repair Response Time (2hr/3 day/ Prog/E)	No Repairs ?	Works Order No
A268 Rye Road	41100864	D	REMOVED PIECE OF PLY FROM ROAD NEARLAMBERDEN FARM		X	
Queen Street	41100816	D			X	
Megrim's Hill	41100843	D			X	

Safety Inspection Record of Repairable Defects and Minor Works



Highway Unit: Tunbridge Wells

Inspector CLIFF WILSON

Drive DAVID HOLDEN

Inspection Frequency

Carriageway Inspection: Monthly

Footway Walked Inspection:

Monthly / Three-Monthly / Annual (N/A)

Inspection Route Number:

Sandhurst 11E - CW6

Inspection Date: 30-09-2008

Road Name	NSG Ref	Inspection Method (M/D/C)	Nature of Repairable Defects/ Minor Works and their Specific Location	Repair Response Time (2hr/3 day/ Prog/E)	No Repairs ?	WORKS Order No
A268 Rye Road	41100864	D	POT HOLE BY BT COVER OPP CROUCH LANE	P		KR10203821
Queen Street	41100816	D			X	
Megrims Hill	41100843	D			X	