

Inspected: 03/03/2008 to 03/03/2010
 Street: CLAPHAM HILL (5600291)
 Report Type: Assessment

Street: CLAPHAM HILL (5600291)

Area: Canterbury

Feature No.: 999,999.00

Feature Id - Location:

Feature Type: Whole Street Feature

Contract Area: Highways

Batch: 42200938 - Inspection Batch

Route: Canterbury 2(Area A)

Officer: Ian Young

Date: 16/02/2010

Defect No.	Description	Log Date	Location	Type	Organisation	Status
42202229	no recordable defects	16/02/2010		NDF		Unactioned

Batch: 42200523 - Inspection Batch

Route: Canterbury 2(Area A)

Officer: Ian Young

Date: 14/01/2010

Defect No.	Description	Log Date	Location	Type	Organisation	Status
42200952	dbm 2 x cpos stop/go	14/01/2010	bottom of hill just before bogshole	CPO		Committed

Batch: 42200434 - Ad Hoc Inspection Batch

Route: Adhoc CD3 Canterbury

Officer: Ralph Simpson

Date: 12/01/2010

Defect No.	Description	Log Date	Location	Type	Organisation	Status
42200839	pothole .300 x .300 x .040mm.	12/01/2010	50m on the Whitstable side of Bogsole.	CPO		Committed

Batch: 42200410 - Ad Hoc Inspection Batch

Route: Adhoc CD3 Canterbury

Officer: Peter Shirley

Date: 11/01/2010

Defect No.	Description	Log Date	Location	Type	Organisation	Status
42200815	carriageway pothole	11/01/2010	between two rounabouts over A299 near busstop.	CPO		Committed

Batch: 42200150 - Inspection Batch

Route: Canterbury 2(Area A)

Officer: Ian Young

Date: 15/12/2009

Defect No.	Description	Log Date	Location	Type	Organisation	Status
42200296	no recordable defects	15/12/2009		NDF		Unactioned

Batch: 42200001 - Ad Hoc Inspection Batch

Route: Adhoc CD3 Canterbury

Officer: Ian Young

Date: 22/09/2009

Defect No.	Description	Log Date	Location	Type	Organisation	Status
42200001	a directions sign is blocked by an overgrowing tree.	22/09/2009	A290, bewteen old thanet way and new thanet way, whitstable side of the pub	VVS		Committed

Batch: 10408954 - Inspection Batch

Route: Canterbury 2(Area A)

Officer: Ian Young

Date: 17/11/2009

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10422124	no recordable defects	17/11/2009		NDF		Unactioned

Batch: 10408551 - Inspection Batch

Route: Canterbury 2(Area A)

Officer: Ian Young

Date: 12/10/2009

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10421244	no recordable defects	12/10/2009		NDF		Unactioned

Batch: 10408367 - Inspection Batch

Route: Canterbury 2(Area A)

Officer: Ian Young

Date: 16/09/2009

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10420708	no recordable defects	16/09/2009		NDF		Unactioned

Batch: 10407941 - Inspection Batch

Route: Canterbury 2(Area A)

Officer: Ian Young

Date: 17/08/2009

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10419303	no recordable defects	17/08/2009		NDF		Unactioned

Inspected: 03/03/2008 to 03/03/2010
 Street: CLAPHAM HILL (5600291)
 Report Type: Assessment

Street: CLAPHAM HILL (5600291)

Area: Canterbury

Feature No.: 999,999.00

Feature Id - Location:

Feature Type: Whole Street Feature

Contract Area: Highways

Batch: 10407184 - Inspection Batch

Route: Canterbury 2(Area A)

Officer: Ian Young

Date: 07/07/2009

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10417028	no recordable defects	07/07/2009		NDF		Unactioned

Batch: 10406784 - Inspection Batch

Route: Canterbury 2(Area A)

Officer: Ian Young

Date: 17/06/2009

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10415998	no recordable defects	17/06/2009		NDF		Unactioned

Batch: 10405966 - Inspection Batch

Route: Canterbury 2(Area A)

Officer: Ian Young

Date: 11/05/2009

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10413651	no new defects	11/05/2009		NDF		Unactioned

Batch: 10405810 - Inspection Batch

Route: Canterbury 2(Area A)

Officer: Ian Young

Date: 29/04/2009

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10412963	no new defects	29/04/2009		NDF		Unactioned

Batch: 10405513 - Inspection Batch

Route: Canterbury 2(Area A)

Officer: Ian Young

Date: 16/04/2009

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10412161	reset iron cover //lights	16/04/2009	house called flower pot	CIS		Committed
10412160	dbm 4mt of eroded area	16/04/2009	sea map	CSE		Committed
10412159	reset cover//lights	16/04/2009	100mt passed pye ally	CIS		Committed
10412158	dbm10mt of foot path	16/04/2009	top of hill see map	FTD		Committed

Batch: 10404738 - Inspection Batch

Route: Canterbury 2(Area A)

Officer: Ian Young

Date: 09/03/2009

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10409904	no new defects	09/03/2009		NDF		Unactioned

Batch: 10404546 - Inspection Batch

Route: Ad-Hoc Community Delivery 3

Officer: Ian Young

Date: 26/02/2009

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10409195	reset cover t/lights	26/02/2009	50mt past pye alley	CIW		Committed

Batch: 10404186 - Ad Hoc Inspection Batch

Route: Ad-Hoc Community Delivery 3

Officer: Craig Marsh

Date: 13/02/2009

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10408381	dislodged manhole cover. Reset or make safe with traffic lights if required. Confirmation of call out 65822	13/02/2009	Whitstable bound carriage way, between j/w Pye Alley Lane and roundabout	CYR		Committed

Batch: 10404160 - Inspection Batch

Route: Canterbury 2(Area A)

Officer: Ian Young

Date: 12/02/2009

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10408285	dbm cpo	12/02/2009	50mt past pyeally going to whits	CPO		Committed

Batch: 10403549 - Inspection Batch

Route: Canterbury 2(Area A)

Officer: Ian Young

Date: 13/01/2009

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10406696	no recordable defects	13/01/2009		NDF		Unactioned

Inspected: 03/03/2008 to 03/03/2010

Street: CLAPHAM HILL (5600291)

Report Type: Assessment

Street: CLAPHAM HILL (5600291)

Area: Canterbury

Feature No.: 999,999.00

Feature Id - Location:

Feature Type: Whole Street Feature

Contract Area: Highways

Batch: 10403092 - Inspection Batch

Route: Canterbury 2(Area A)

Officer: Ian Young

Date: 11/12/2008

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10405486	dm 2 x pots 1by iron cover	11/12/2008	botton of hill 20 up from bogshole	CPO		Committed

Batch: 10402562 - Inspection Batch

Route: Canterbury 2(Area A)

Officer: Ian Young

Date: 05/11/2008

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10403869	dbm 2 x pot holes	05/11/2008	bottom of hill close to pie alley	CPO		Committed
10403868	STRIM back footway	05/11/2008	from pie alley to fallen tree	VVS		Committed
10403867	fallen tree	05/11/2008	halfway down hill	VVS		Committed

Batch: 10402084 - Inspection Batch

Route: Canterbury 2(Area A)

Officer: Ian Young

Date: 13/10/2008

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10402906		13/10/2008		NDF		Unactioned

Batch: 10401837 - Ad Hoc Inspection Batch

Route: Ad-Hoc Community Delivery 3

Officer: Ian Young

Date: 26/09/2008

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10402377	REMOVE DROP KERBS AND RAISE UP TO SAME AS F/WAY /FIT 6X NEW KERBS	26/09/2008	20 MT PASSED PIE ALLY SIDE OF FENCE	KDI		Committed

Batch: 10401692 - Inspection Batch

Route: Ad-Hoc Community Delivery 3

Officer: Ian Young

Date: 18/09/2008

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10402123		18/09/2008	clapham hill/ on left passed pye ally	VVS		Committed
10402122	CUT BACK BUSHES	18/09/2008	ON LEFT PASSED PYE ALLEY	VTV		Archived

Batch: 10401554 - Ad Hoc Inspection Batch

Route: Ad-Hoc Community Delivery 3

Officer: Ian Young

Date: 11/09/2008

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10401956	DBM EDGE OF DRIVES	11/09/2008	CEDERWOOD/SEVILA/SEE MAP	CED		Committed

Batch: 10401495 - Ad Hoc Inspection Batch

Route: Ad-Hoc Community Delivery 3

Officer: Craig Marsh

Date: 10/09/2008

Defect No.	Description	Log Date	Location	Type	Organisation	Status
10401896	Clear debris and small spillage following rtc. Confirmation of call out 60805 issued 10/9/08	10/09/2008	at roundabout j/w A299 off slip	OMD		Committed

Batch: 505057 - Ad Hoc Inspection Batch

Route: WAMS Ad-Hoc Canterbury

Officer: Ian Young

Date: 17/03/2008

Defect No.	Description	Log Date	Location	Type	Organisation	Status
505664	remove drop kerbs and dbm up to same as the rest of footpath	17/03/2008	20 mt passed pie ally	KDI		Archived