



## Project-information

Project name:  
**MEY GREEN**

Contract number:  
**B0718810**

Contact:  
**BILL LIDDELL**

Date:  
**23/07/2010**

Client **Fife Council ~ Roads DLO Service**  
 Contact: **Bill Liddell**  
 Position: **Roths Depot**  
 Road **Strathore Road**  
 Town **Thornton KY1 4DF**  
 County  
 Telephone: **08451 555555 EXT 444**  
 Fax:  
 Mobile: **07809 782761**  
 E-Mail:

Site  
 Contact:  
 Position:  
 Road **MEY GREEN**  
 Town **STENTON, GLENROTHES**  
 County  
 Telephone:  
 Fax:  
 Mobile:  
 E-Mail:

Contractor **Euro Environmental Contracts Ltd**  
 Contact: **John Bunting**  
 Position: **CCTV Manager**  
 Road **2 Whitestone Place**  
 Town **Whitehill Industrial Estate**  
 County **Bathgate EH48 2EW**  
 Telephone: **01506 654200**  
 Fax: **01506 652525**  
 Mobile: **07775 594273**  
 E-Mail: **j@xx**




## Inspection report

Date: <b>23/07/2010</b>	Job N°: <b>B07-188-10</b>	Weather: <b>Dry</b>	Operator: <b>JOHN BUNTING</b>	section number: <b>1</b>	PLR: <b>7802 X</b>
Present:	Vehicle: <b>MX08 HTP</b>	Camera: <b>P494</b>	Preset:	Cleaned: <b>Yes</b>	Grade:

Road: <b>MEY GREEN</b>	Division:	start MH: <b>8901</b>
Place: <b>STENTON</b>	District:	end MH: <b>7802</b>
Location: <b>Footpath or verge</b>	Tape No.:	Total length: <b>37.9 m</b>

Purpose: <b>Asset condition</b>	Size/Shape: <b>Circular 525</b>
Use: <b>Surface water</b>	Material: <b>Concrete</b> Pipe length: <b>2.5m</b>
Catchment:	Lining:
	Category:

Comment:  
 Location details: **REAR OF NO.4**



<b>Structural Defects</b>	<b>Constructional Features</b>
<b>Service Defects</b>	<b>Miscellaneous Features</b>




## Inspection report

Date: <b>23/07/2010</b>	Job N°: <b>B07-188-10</b>	Weather: <b>Dry</b>	Operator: <b>JOHN BUNTING</b>	section number: <b>2</b>	PLR: <b>7801 X</b>
Present:	Vehicle: <b>MX08 HTP</b>	Camera: <b>P494</b>	Preset:	Cleaned: <b>No</b>	Grade:

Road: <b>MEY GREEN</b>	Division:	start MH: <b>7802</b>
Place: <b>STENTON</b>	District:	end MH: <b>7801</b>
Location: <b>Footpath or verge</b>	Tape No.:	Total length: <b>75.7 m</b>

Purpose: <b>Asset condition</b>	Size/Shape: <b>Circular 525</b>
Use: <b>Surface water</b>	Material: <b>Concrete</b> Pipe length: <b>2.5m</b>
Catchment:	Lining:
	Category:

Comment:  
 Location details: **TREES OPP REAR OF NO.8**



<b>Structural Defects</b>	<b>Constructional Features</b>
<b>Service Defects</b>	<b>Miscellaneous Features</b>