

Inspection Type(s)

Annual Safety Inspection
safety inspections

Site: SHORE LANE (39901649)

Area: Bradfield

Asset No: 1,000.00

Asset Id - Location 00011196 - ZU190 //

Feature Type: Local Road

Contract Area: Tendring

Inspection	Date	Route	Type	Officer
1735918	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735917	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735916	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735915	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735914	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735913	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735912	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735911	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735910	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735909	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735908	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735907	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735906	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735905	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735904	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735903	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735902	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735901	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735900	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735899	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff
1735898	17/04/2013	Adhoc Inspections	adhoc inspections	Sean Roff

Defect Details

Defect	Description	Log Date	Location	Organise./Job	Priority
1778616	RA4=2x2 CWPH 0.6x0.6x85mm HRA	17/04/2013	Just before beach/bridle way on lhs		
1778615	RA4=2x2 CWPH 0.9x0.5x70mm HRA	17/04/2013	Just before beach/bridle way on lhs		
1778614	RA6=3x2 CWPH 1.1x0.8x100mm HRA	17/04/2013	Just before beach/bridle way on lhs		
1778613	RA6=3x2 CWPH 1.6x1.2x100mm HRA	17/04/2013	Just before beach/bridle way on rhs		
1778612	RA6=3x2 CWPH HRA 1.1x0.6x70mm HRA	17/04/2013	After bridge twd beach on rhs		
1778611	RA6=3x2 CWPH 1.5x1.5x90mm HRA	17/04/2013	After bridge twd beach on rhs		
1778610	RA6=3x2 CWPH 2.0x1.6x100mm HRA	17/04/2013	After bridge twd beach on rhs		
1778609	RA6=3x2 CWPH 1.6x1.4x90mm HRA	17/04/2013	Just after bridge twd beach on rhs		
1778608	RA4=4x1 CWPH 1.5x1.5x100mm HRA	17/04/2013	Just after bridge twd beach on lhs		
1778607	RA6=3x2 CWPH 2.6x1.5x100mm HRA	17/04/2013	Under railway bridge		
1778606	RA6=3x2 CWPH 1.3x1.2x120mm HRA	17/04/2013	On rhs just before railway bridge	1533884	HW: P3 upto 28 days
1778605	RA6=3x2 CWPH 1.3x1.1x100mm HRA	17/04/2013	On lhs just before railway bridge		
1778604	RA6=3x2 CW edge erosion 26.0x1.0x200mm HRA	17/04/2013	On lhs heading twd railway bridge		
1778603	RA6=3x2 CWPH 1.2x1.1x140mm HRA	17/04/2013	On rhs heading twd railway bridge		
1778602	RA4=4x1 CWPH 0.6x0.5x60mm HRA	17/04/2013	On rhs heading twd railway bridge		
1778601	RA6=3x2 CWPH 4.6x1.0x200mm HRA	17/04/2013	On lhs heading twd railway bridge		
1778600	RA4=2x2 CWPH 2.0x0.9x120mm HRA	17/04/2013	On lhs heading twd railway bridge		
1778599	RA4=4x1 CWPH 0.5x0.4x55mm HRA	17/04/2013	On rhs by field entrance heading twd railway bridge		
1778598	RA6=3x2 CWPH 1.1x1.2x110mm HRA	17/04/2013	On lhs opposite field entrance heading twd railway bridge		
1778597	RA4=4x1 CWPH 0.6x0.4x60mm HRA	17/04/2013	On lhs heading twd railway bridge		

Defect Details

Defect	Description	Log Date	Location	Organise./Job	Priority
1778596	RA6=3x2 CWP HRA	17/04/2013	On rhs heading twd railway bridge		