

insight - Microsoft Internet Explorer provided by North Tyneside Council

SymMap

File Export to Zoom to Create Search Advanced Help

Layers

- ☒ Customer Services
- ☒ General Maintenance
- ☐ Licences
- ☒ Streetworks Layers
  - ☐ Co-Ordination Due
  - ☐ Daily Whereabouts We
- ☐ Restrictions
  - ☐ PROPOSED RESTRIC
  - ☐ RESTRICTION IN FC
- ☐ Daily Whereabouts
- ☐ Street Works
- ☐ Pinch Point
- ☒ Asset Layers
  - ☐ ITN
- ☒ Streets
- ☐ ASD Layers
- ☒ Index Groups
- ☒ Maintenance Network
- ☒ Other Layers
- ☒ OS MasterMap
- ☒ OS Raster Data

Activity Done Details

File Reports Shortcuts Tools Go to Help

Exit Desktop Map Options Functions Previous Next Create Amend Confirm Cancel

Details Observations L.A. Codes Observation Objects Activity Objects

Activity Type SF1 Safety Inspection (Driven) Survey 013032

Address BUDDLE STREET WALLSEND

Date Due 02/04/2018

Frequency 1 Months Standard Frequency 1 Months

Done Date/Time 16/03/2018 11:37 (Blank = Now) ☒ Mark Activity as Complete?

Inspector STEVE D Steve Dodds (Highway Maintenance)

Next Due Date 16/04/2018 (Blank = Calculated) Next Done Date 13/04/2018

Highway Ins Action Required Gully/Drainage No Action

Signage No Action Lines No Action

Description

Last updated by STEVE D at 13:47 on 16/03/2018

Prev Version Next Version Hand-held

North Tyneside Live 10/05/18

© Crown copyright and database rights 2017. OS data supplied by Ordnance Survey

insight - Microsoft Internet Explorer provided by North Tyneside Council

SymMap

File Export to Zoom to Create Search Advanced Help

Layers

- ☒ Customer Services
- ☒ General Maintenance
- ☐ Licences
- ☒ Streetworks Layers
  - ☐ Co-Ordination Due
  - ☐ Daily Whereabouts We
- ☐ Restrictions
  - ☐ PROPOSED RESTRIC
  - ☐ RESTRICTION IN FC
- ☐ Daily Whereabouts
- ☐ Street Works
- ☐ Pinch Point
- ☒ Asset Layers
- ☐ ITN
- ☒ Streets
- ☐ ASD Layers
- ☒ Index Groups
- ☒ Maintenance Network
- ☒ Other Layers
- ☒ OS MasterMap
- ☒ OS Raster Data

Activity Done Details

File Reports Shortcuts Tools Go to Help

Exit Desktop Map Options Functions Previous Next Create Amend Delete Confirm Cancel

Details Observations L.A. Codes Observation Objects Activity Objects

Activity Type SF1 Safety Inspection (Driven) Date/Time Done 16/03/2018 11:37 Survey 013032

Address BUDDLE STREET WALLSEND Chainage Display Address

Originated	L.A. Code	Stage Desc.	Action	Defect	Ordered	Completed	Latest Cost	Description
16/03/2018 11:37	00304683	COMPLETED	DEF	RM01	16/03/2018	27/03/2018	170.52	NO PERMIT REQUIRED Traffic

North Tyneside Live 10/05/18

© Crown copyright and database rights 2017. OS data not to be re-used

