

RMS



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period from to , and defects raised outside of inspections on the same Street during this period.

Usrn = Palacecraig Street, Kirkshaws, Coatbridge, North Lanarkshire
 Defect Or Inspection Date Between 01/january/2017 And 31/december/2017
 Item Category Uid = Maintenance

Instruction Reference	Item Type	Item Detail	Item Identity Code	Required Completion Date	Current Status	Actual Completion Date	Location Description
48405966: PALACECRAIG STREET							
Date Recorded 17/01/2017 N17203305	Carriageway	Pothole		18/01/2017 23:59:00	No Further Action	01/01/9999 00:00:00	The road is full of pot holes and uneven surface because of the Lorries using Palacecraig St as a short cut.Nearly all of Palacecraig Street but mainly at the entrance of the School
Enquiry Comments: Checked location 18/01/17 road is unsightly / uneven and requires resurfaced has been potholed numerous times to make safe Nothing hazardous at time of inspection , will continue to monitor on a routine basis...							
Work Instruction Comments: [REDACTED]							
Customer Details: [REDACTED]							
Date Recorded 15/02/2017 N17205755	Carriageway	Pothole		06/04/2017 23:59:00	Completed	27/03/2017 12:05:00	Make safe / SCREED ALL C/Way defects full length of Palacecraig Street Coatbridge Grid Ref (273057,663306) 2 Ton SAND CARPET
Enquiry Comments: Make safe / SCREED ALL C/Way defects full length of Palacecraig Street Coatbridge Grid Ref (273057,663306) 2 Ton SAND CARPET							
Work Instruction Comments: Make safe / SCREED ALL C/Way defects full length of Palacecraig Street Coatbridge Grid Ref (273057,663306) 2 Ton SAND CARPET							
Customer Details: [REDACTED]							
Date Recorded 16/03/2017							



Instruction Reference	Item Type	Item Detail	Item Identity Code	Required Completion Date	Current Status	Actual Completion Date	Location Description
N17208482	Carriageway	Pothole		17/03/2017 23:59:00	No Further Action	01/01/9999 00:00:00	The road is completely torn up with large holes causing dangerous driving conditions for through traffic. Palace Craig street, Coatbridge, ML5 4RY

Half way along the road just as you would turn right to drive down to Scotcast.

Outside of CEM and BN Medical premises.

Enquiry Comments: Already with contractor (APS) for repair
Refer To N17205755

Work Instruction Comments:

Customer Details:

Date Recorded 03/04/2017



Instruction Reference	Item Type	Item Detail	Item Identity Code	Required Completion Date	Current Status	Actual Completion Date	Location Description
N17209840	Carriageway	Pothole		04/04/2017 23:59:00	No Further Action	01/01/9999 00:00:00	Palacecraig Street, Coatbridge. This road is in a terrible state with potholes, particularly at the bend as you go right past St Andrews school entrance. From there up to the top of the road past Scotcast. Also the burger van that sits at this bend during the week is an accident waiting to happen. The bend is completely cut off by the van, surely the school children can walk another 20 or so yards down the road to get to it. Is the problem creating a hazard? Yes If so, what kind of hazard? (400 words max.) Damage to vehicles caused but the amount of potholes. The siting of the burger van, too close to the bend, obstructing motorists and Heavy Goods vehicles, an accident waiting to happen. Have you reported this before? NoPalacecraig Street Coatbridge. Past the Tannoy factory entrance up to and past the Scotcast entrance
<p>Enquiry Comments: C/Way surface at Palacecraig St is unsightly , uneven and in a poor condition , but regular potholing/screeding works are carried out and NOTHING HAZARDOUS at location Recent potholing ticket refer to N17205755</p> <p>Work Instruction Comments: [REDACTED]</p> <p>Customer Details: [REDACTED]</p>							
Date Recorded N17215070	31/05/2017 Carriageway	Pothole		07/06/2017 23:59:00	Completed	11/06/2017 12:00:00	Palacecraig Street - the full length of the street as it is very dangerous.
<p>Enquiry Comments: Infill / Scream /Make safe with Hot Material ALL C/Way defects located full length of Palacecraig Street Coatbridge Grid Ref (273071,663153) 3 Ton HRA</p> <p>Work Instruction Comments: Infill / Scream /Make safe with Hot Material ALL C/Way defects located full length of Palacecraig Street Coatbridge Grid Ref (273071,663153) 3 Ton HRA</p>							



Instruction Reference	Item Type	Item Detail	Item Identity Code	Required Completion Date	Current Status	Actual Completion Date	Location Description
-----------------------	-----------	-------------	--------------------	--------------------------	----------------	------------------------	----------------------

Customer Details:

Date Recorded 18/09/2017	Carriageway	Pothole		23/10/2017 23:59:00	Completed	13/10/2017 14:00:00	Customer has damaged car due to pot holes in street Palacecraig Street - the full length of the street as it is very dangerous.
---------------------------------	-------------	---------	--	---------------------	-----------	---------------------	---

Enquiry Comments: Brush out any water / loose material , tack coat and infill with hot material ALL C/Way defects located full length of Palacecraig Street Coatbridge
Grid Ref (273071,663156) 2 TON HRA

Work Instruction Comments: Brush out any water / loose material , tack coat and infill with hot material ALL C/Way defects located full length of Palacecraig Street Coatbridge
Grid Ref (273071,663156) 2 TON HRA

Customer Details:

Date Recorded 19/12/2017	Carriageway	Pothole		04/01/2018 23:59:00	Completed	09/01/2018 16:30:00	Brush out any water / loose material / Tack Coat and infill with HOT Material ALL C/Way potholes located full length of Palacecraig Street Coatbridge from its junction of Kirkshaws Road to its termination (4ton HRA) Grid Ref. (273048,663060)
---------------------------------	-------------	---------	--	---------------------	-----------	---------------------	---

Enquiry Comments: Brush out any water / loose material / Tack Coat and infill with HOT Material ALL C/Way potholes located full length of Palacecraig Street Coatbridge from its junction of Kirkshaws Road to its termination
(4ton HRA) Grid Ref. (273048,663060)

Work Instruction Comments: Brush out any water / loose material / Tack Coat and infill with HOT Material ALL C/Way potholes located full length of Palacecraig Street Coatbridge from its junction of Kirkshaws Road to its termination
(4ton HRA) Grid Ref. (273048,663060)

Customer Details:

