

FIDP/010128-17 M32 J1
Accident Date BETWEEN '01-Jan-2015' AND '05-Nov-2017'

151501839 SERIOUS 363410/178542 01/03/2015 03:50
LOCATION M32 J1 at Junction with A4174, Hambrook
DESCRIPTION V1 LEFT THE M32 N/B AT JUNCTION 1 TOWARDS THE A4174 WHEN FOR WHATEVER REASON D1 L/C AND COLLIDED WITH ROADSIDE FURNITURE AND ROLLED, COMING TO A STOP IN THE VERGE.

VEHICLES	DRIVER	CASUALTIES	VEH	SEX	AGE
1 Car	Male	31 1 Driver/Rider	SERIOUS	1 Male	31

151502715 SERIOUS 363602/178579 23/02/2015 07:40
LOCATION A4174, Hambrook
DESCRIPTION VEHS LEFT THE M32 J1 ONTO THE A4174 E/B TOWARDS BROMLEY HEATH. V2 MOVED FROM LANE 2 TO LANE 1, BUT COLLIDED WITH V1 (M/C) WHICH WAS ALREADY TRAVELLING IN LANE 1.

VEHICLES	DRIVER	CASUALTIES	VEH	SEX	AGE
1 M/cycle 125 - 500cc	Male	50 1 Driver/Rider	SERIOUS	1 Male	50
2 Car	Male	31			

151504237 SLIGHT 363416/178558 26/05/2015 09:50
LOCATION M32 J1 with A4174
DESCRIPTION V2 WAS STOPPED AT T/SIG WAITING TO ENTER THE ROUNDABOUT FROM THE M32 WHEN V1 FTS AND HIT THE R/O V2.

VEHICLES	DRIVER	CASUALTIES	VEH	SEX	AGE
1 Car	Not known	40 1 Driver/Rider	SLIGHT	2 Male	23
2 Car	Male	23			

151506079 SLIGHT 363545/178647 27/08/2015 17:54
LOCATION A4174, at its Junction with M32. Frenchay
DESCRIPTION V1 IS A TAXI WHO WAS TRANSPORTING C1 WHO HAD BEEN PICKED UP FROM PARKWAY STATION. V2 COLLIDED INTO THE BACK OF V1 WHILE NEGOTIATING THE A4174 ROUNDABOUT WITH THE M32 CAUSING C1 TO SUFFER WHIPLASH (ACCIDENT REPORTED BY C1)

VEHICLES	DRIVER	CASUALTIES	VEH	SEX	AGE
1 Taxi	Male	40 1 Passenger	SLIGHT	1 Male	47
2 Car	Female	30			

151506200 SLIGHT 363554/178662 27/08/2015 16:40
LOCATION M32 J1 with A4174, Frenchay
DESCRIPTION V1 HAD DRIVEN FROM THE M4 AND M32 AND WAS STATIONARY WAITING TO ENTER THE ROUNDABOUT WITH THE A4174 TO TRAVEL TOWARDS FRENCHAY WHEN V2 APPROACHED FROM BEHIND, FAILED TO STOP AND COLLIDED WITH THE REAR OF V1.

VEHICLES	DRIVER	CASUALTIES	VEH	SEX	AGE
1 Car	Female	48 1 Driver/Rider	SLIGHT	1 Female	48
2 Car	Male	30			

151506894 SERIOUS 363389/178403 29/08/2015 22:40
LOCATION M32 J1 Northbound Exit Slip, Hambrook
DESCRIPTION V1 Excited M32 at Northbound Exit Slip Road at Junction 1 left Carraigeway in Slip Road to the Nearside V1 Strucj Roadsign and a Large Tree of Carraigeway and Ended up Against Andother Tree down the Verge of the Carriageway 2 Other Vehicles Were Damaged by Flying Debris from V1

VEHICLES	DRIVER	CASUALTIES	VEH	SEX	AGE
1 Car	Male	27 1 Driver/Rider	SERIOUS	1 Male	27
2 Car	Female	30			
3 Car	Female	17			

FIDP/010128-17 M32 J1
Accident Date BETWEEN '01-Jan-2015' AND '05-Nov-2017'

151507105 SLIGHT 363559/178664 07/10/2015 08:10
LOCATION M32 J1 with A4174, Hambrook
DESCRIPTION V1 WAS STATIONARY IN THE MIDDLE LANE TRAVELLING S/B ON THE SLIP ROAD WHEN V2 BEHIND EXCELOATED, DIDN'T STOP AND HIT THE REAR OF V1.

VEHICLES	DRIVER	CASUALTIES	VEH	SEX	AGE
1 Car	Female	31 1 Driver/Rider	SLIGHT	1 Female	31
2 Car	Male	50			

161603191 SLIGHT 363581/178560 30/04/2016 16:20
LOCATION A4174 junction with M32, Hambrook
DESCRIPTION VEHS WERE W/B ONT HE A4174 TOWARDS THE ROUNDABOUT WITH THE M32, HEADING TOWARDS THE M5 IN THE RIGHT HAND LANE. V1 WAS WAITING AT THE T/SIGNALS WHEN V2 APPROACHED FROM BEHIND AND HIT THE REAR OF V1. D2 DROVE OFF.

VEHICLES	DRIVER	CASUALTIES	VEH	SEX	AGE
1 Car	Male	37 1 Passenger	SLIGHT	1 Female	33
2 Car	Female	46 2 Passenger	SLIGHT	1 Female	5

161604135 SLIGHT 363432/178673 24/05/2016 19:15
LOCATION A4174 Roundabout at Junction with M32
DESCRIPTION V1 LEFT THE M32 AT J1 TRAVELLING N/B, FAILED TO ABIDE BY THE T/SIGNALS ON THE RAB AND CONTINUED DRIVING STRAIGHT AHEAD. V2 ENTERED THE RAB FROM THE A4174 WHEN GIVEN A GREEN T/SIGNAL, BUT WAS HIT BY V1.

VEHICLES	DRIVER	CASUALTIES	VEH	SEX	AGE
1 Car	Male	49 1 Driver/Rider	SLIGHT	2 Female	47
2 Car	Female	47			

161606835 SLIGHT 363412/178562 05/09/2016 22:15
LOCATION M32 Slip Road at J1 with A4174, Hambrook
DESCRIPTION V2 STOPPED AT RED TRAFFIC LIGHTS ON EXIT OF M32 J1 WHEN V1 APPROACHED FROM BEHIND AND COLLIDED WITH THE R/O V2. D1 RAN FROM THE SCENE PRESUMABLE DRUNK.

VEHICLES	DRIVER	CASUALTIES	VEH	SEX	AGE
1 Car	Not known	Unk 1 Driver/Rider	SLIGHT	3 Male	44
2 Car	Male	29 2 Passenger	SLIGHT	2 Female	54
3 Car	Male	44 3 Passenger	SLIGHT	3 Female	46
		4 Passenger	SLIGHT	3 Female	42
		5 Passenger	SLIGHT	3 Female	44

161609535 SLIGHT 363559/178527 18/12/2016 17:30
LOCATION A4174 at Junction with M32, Frenchay
DESCRIPTION V1 WAS STATIONARY AT THE JUNCTION WHILE TRAV W/B ON THE A4174 TOWARDS THE M32 WHEN V2 APPROACHED FROM BEHIND AT SPEED AND HIT THE REAR OF V1.

VEHICLES	DRIVER	CASUALTIES	VEH	SEX	AGE
1 Car	Female	39 1 Driver/Rider	SLIGHT	1 Female	39
2 Taxi	Male	39 2 Passenger	SLIGHT	1 Female	45

FIDP/010128-17 M32 J1
Accident Date BETWEEN '01-Jan-2015' AND '05-Nov-2017'

171700841 SLIGHT 363567/178706 26/01/2017 15:10
LOCATION M32 J1 at Junction with A4174, Hambrook
DESCRIPTION V2 ENTERED THE SLIP ROAD TO LEAVE THE M32 S/B ONTO THE A4174. AS D2 WAS TRAV DOWN THE SLIP ROAD, THEY FAILED TO STOP FOR STATIONARY VEHICLES AHEAD AND COLLIDED WITH THE REAR OF V1.

VEHICLES	DRIVER	CASUALTIES	VEH	SEX	AGE
1 Car	Male	32 1 Driver/Rider SLIGHT	1	Male	32
2 Taxi	Male	63 2 Driver/Rider SLIGHT	2	Male	63
		3 Passenger SLIGHT	1	Male	30
		4 Passenger SLIGHT	2	Male	68

171702268 SLIGHT 363672/179005 13/03/2017 09:12
LOCATION M32 J1, Hambrook
DESCRIPTION VEHICLES TRAVEL S/B ON M32 TOWARDS BRISTOL. V2 MOVED FROM L2 INTO L1, FORCING V1 TO MOVE ONTO THE HARD SHOULDER TO AVOID COLLISION. D1 UNDERTOOK V2, BEFORE RE-ENTERING L1 IN FRONT OF V2, BEFORE BRAKING CAUSING V2 TO COLLIDE WITH THE REAR OF V1. D1 L/C AND COLLIDED WITH V3 WHICH WAS TRAVELLING IN L3.

VEHICLES	DRIVER	CASUALTIES	VEH	SEX	AGE
1 Car	Male	55 1 Passenger SLIGHT	1	Male	26
2 Goods > 7.5t	Male	30			
3 Car	Male	50			

171703723 SLIGHT 363587/178558 25/04/2017 05:41
LOCATION A4174 at junction with M32 J1, Hambrook
DESCRIPTION D1 STATES THAT V2 IN FRONT BROKE SUDDENLY AND CAUSED THEM TO GO INTO THE REAR OF V2. SUBSEQUENTLY V2 THEN WENT INTO V3. IT IS POSSIBLE THAT D1 WAS DRIVING TOO CLOSE TO V2.

VEHICLES	DRIVER	CASUALTIES	VEH	SEX	AGE
1 Car	Male	47 1 Driver/Rider SLIGHT	2	Male	47
2 Car	Male	47			
3 Car	Female	30			

171704441 SERIOUS 363353/178654 01/06/2017 16:30
LOCATION A4174 at Junction with M32, Frenchay
DESCRIPTION VEHICLES WERE TRAVELLING ON THE ROUNDABOUT TOWARDS FRENCHAY IN L2 WHEN V1 AND V2 COLLIDED. IT IS UNCLEAR WHO WAS AT FAULT BUT IT APPEARS THAT ONE OF THE DRIVERS MOVED BETWEEN LANES.

VEHICLES	DRIVER	CASUALTIES	VEH	SEX	AGE
1 Car	Male	58 1 Driver/Rider SERIOUS	1	Male	58
2 Car	Male	54			