

Inspected: 01/01/2013 to 18/08/2014
 Site: DAIRYHOUSE LANE (39900506)
 Report Type: Assessment

Site: DAIRYHOUSE LANE (39900506)		Area: Bradfield				
Asset No: 1,000.00		Asset Id - Location: 00010053 - ZU197 //				
Feature Type: Local Road		District: Tending				
Batch: 1732544 - Ad Hoc Inspection Batch						
Route: Adhoc Inspections		Officer: [REDACTED]	Date: 22/01/2013			
Defect No.	Description	Log Date	Location	Type	Organisation	Status
1773853	RA 2 = 1x2 Blocked Gully & System	22/01/2013	JW Heath Road	BGUL		Archived
Batch: 1597402 - Inspection Batch						
Route: adhoc route		Officer: [REDACTED]	Date: 30/04/2014			
Defect No.	Description	Log Date	Location	Type	Organisation	Status
20118009	RA4=2x2 CWPH 0.55x0.45x50mm HRA	30/04/2014	Outside Castle Garden opp Whitfield CWSF Lodge			Unactioned
Batch: 1597400 - Inspection Batch						
Route: adhoc route		Officer: [REDACTED]	Date: 30/04/2014			
Defect No.	Description	Log Date	Location	Type	Organisation	Status
20118007	RA4=4x1 300x400 fire hydrant mains cover misaligned	30/04/2014	Outside 1 in verge area	NRSW	9133041	Actioned
Batch: 1597397 - Inspection Batch						
Route: adhoc route		Officer: [REDACTED]	Date: 30/04/2014			
Defect No.	Description	Log Date	Location	Type	Organisation	Status
20118004	RA1=1x1 CWPH 0.3x0.3x40mm HRA	30/04/2014	Turning left into Dairyhouse Lane on CWSF jct			Unactioned
Batch: 1597396 - Inspection Batch						
Route: adhoc route		Officer: [REDACTED]	Date: 30/04/2014			
Defect No.	Description	Log Date	Location	Type	Organisation	Status
20118003	RA2=2x1 CWPH 0.6x0.55x43mm HRA	30/04/2014	On jct turning left into Dairyhouse Lane	CWSF		Unactioned
Batch: 1597395 - Inspection Batch						
Route: adhoc route		Officer: [REDACTED]	Date: 30/04/2014			
Defect No.	Description	Log Date	Location	Type	Organisation	Status
20118002	RA2=2x1 0.5x0.4x40mm HRA	30/04/2014	On jct turning left into Dairyhouse Lane	CWSF		Unactioned
Batch: 1573772 - Inspection Batch						
Route: adhoc route		Officer: [REDACTED]	Date: 08/01/2014			
Defect No.	Description	Log Date	Location	Type	Organisation	Status
1589736	RA4=2x2 CWPH 1.2x0.9x60mm HRA	08/01/2014	Outside 4	CWSF		Unactioned
Batch: 1573769 - Inspection Batch						
Route: adhoc route		Officer: [REDACTED]	Date: 08/01/2014			
Defect No.	Description	Log Date	Location	Type	Organisation	Status
1589728	RA3=3x1CWPH 0.25x0.3x40mm HRA	08/01/2014	Outside 2	CWSF		Unactioned
Batch: 1573762 - Inspection Batch						
Route: adhoc route		Officer: [REDACTED]	Date: 08/01/2014			
Defect No.	Description	Log Date	Location	Type	Organisation	Status
1589723	RA4=2x2 CWPH 0.8x0.6x65mm HRA - REGRADE from defect no 1564003	08/01/2014	Just past No 1	CWSF		Unactioned

Inspected: 01/01/2013 to 18/08/2014
 Site: DAIRYHOUSE LANE (39900506)
 Report Type: Assessment

Site: DAIRYHOUSE LANE (39900506)

Area: Bradfield

Asset No: 1,000.00

Asset Id - Location: 00010053 - ZU197 //

Feature Type: Local Road

District: Tendring

Batch: 1573761 - Inspection Batch

Route: adhoc route

Officer: [REDACTED]

Date: 08/01/2014

Defect No.	Description	Log Date	Location	Type	Organisation	Status
1589722	RA4=2x2 CWPH 1.0x0.6x60mm HRA - REGRADE from defect no 1564018	08/01/2014	Just past No 1	CWSF		Unactioned

Batch: 1573760 - Inspection Batch

Route: adhoc route

Officer: [REDACTED]

Date: 08/01/2014

Defect No.	Description	Log Date	Location	Type	Organisation	Status
1589721	RA4=2x2 CWPH 1.0x0.6x60mm HRA - REGRADE from defect no 1564016	08/01/2014	Opposite 2	CWSF		Unactioned

Batch: 1573759 - Inspection Batch

Route: adhoc route

Officer: [REDACTED]

Date: 08/01/2014

Defect No.	Description	Log Date	Location	Type	Organisation	Status
1589720	RA4=2x2 CWPH 0.5x0.4x60mm HRA - REGRADE from defect no 1564017	08/01/2014	Opposite 2	CWSF		Unactioned

Batch: 1569291 - Inspection Batch

Route: adhoc route

Officer: [REDACTED]

Date: 10/12/2013

Defect No.	Description	Log Date	Location	Type	Organisation	Status
1584090	RA1=1x1 blocked ditch/gully required jetting/clearing	10/12/2013	Ditch on side of house called Whitfield Lodge on dairyhouse lane.	BDCH		Unactioned

Inspected: 01/01/2013 to 18/08/2014
 Site: DAIRYHOUSE LANE (39900506)
 Report Type: Assessment

Site: DAIRYHOUSE LANE (39900506)

Area: Bradfield

Asset No: 1,000.00

Asset Id - Location: 00010053 - ZU197 //

Feature Type: Local Road

District: Tendring

Batch: 1553146 - Inspection Batch

Route: Area 01 Annual September

Officer: [REDACTED]

Date: 24/09/2013

Observation Type	Code	Grade	Score	Notes
carriageway condition	CWCN	poor condition	.0000	
cycleway condition	CYCN	Not Assessed	.0000	
footway condition	FWCN	Not Assessed	.0000	
surface slate	SSTT	dry	.0000	
Footway Presence	FWPC	not surveyed	.0000	
FW % as new	FWAN	not applicable	.0000	
FW % aesthetically impaired	FWAI	not applicable	.0000	
FW % functionally impaired	FWFI	not applicable	.0000	
FW % structurally unsound	FWSU	not applicable	.0000	

Defect No.	Description	Log Date	Location	Type	Organisation	Status
1564018	RA2=2x1 CWPH 0.8x0.45x35mm HRA	24/09/2013	Just past no 1 on rhs	CWSF		Unactioned
1564017	RA3=3x1 CWPH 0.5x0.45x47mm HRA	24/09/2013	Opposite 2	CWSF		Unactioned
1564016	RA3=3x1 CWPH 0.3x0.4x46mm HRA	24/09/2013	Opposite no 2	CWSF		Unactioned
1564015	RA2=2x1 CWPH 0.9x0.55x30mm HRA	24/09/2013	Approx 40m from Dairyhouse Farm	CWSF		Unactioned
1564014	RA1=1x1 CWPH 0.45x0.45x30mm HRA	24/09/2013	Approx 60m from Dairyhouse Farm	CWSF		Unactioned
1564013	RA2=2x1 CWPH 0.7x0.45x34mm HRA	24/09/2013	Approx 60m from Dairyhouse Farm	CWSF		Unactioned
1564012	RA2=2x1 CWPH 0.8x0.7x35mm HRA	24/09/2013	Approx 65m from Dairyhouse Farm	CWSF		Unactioned
1564011	RA2=2x1 CWPH 0.6x0.4x33mm HRA	24/09/2013	Approx 70m from Dairyhouse Farm	CWSF		Unactioned
1564010	RA2=2x1 CWPH 0.45x0.3x32mm HRA	24/09/2013	Approx 85m from Dairyhouse Farm	CWSF		Unactioned
1564009	RA2=2x1 CWPH 0.4x0.45x30mm HRA	24/09/2013	Approx 90m from Dairyhouse Farm	CWSF		Unactioned
1564008	RA1=1x1 CWPH 0.35x0.2x28mm HRA	24/09/2013	Approx 100m from Dairyhouse Farm	CWSF		Unactioned
1564007	RA2=2x1 CWPH 0.6x0.5x37mm HRA	24/09/2013	Approx 100m from Dairyhouse Farm	CWSF		Unactioned
1564006	RA3=3x1 CWPH 0.45x0.45x34mm HRA	24/09/2013	Approx 100m from Dairyhouse Farm	CWSF		Unactioned
1564005	RA2=2x1 CWPH 0.45x0.4x34mm HRA	24/09/2013	Approx 150m from Dairyhouse Farm	CWSF		Unactioned
1564004	RA3=3x1 CWPH 0.8x0.3x37mm HRA	24/09/2013	Approx 200m past Willow Cottage on rhs	CWSF		Unactioned
1564003	RA3=3x1 CWPH 0.55x0.5x43mm HRA	24/09/2013	Just past no 1 on rhs	CWSF		Unactioned

