

Site Asbestos Compendium Summary

This compendium report is based on Site id: **139429**, Client Ref: , Account Ref No: **3074**

South Gosforth Metro Station, Newcastle upon Tyne, NE3 1YT

This Site Asbestos Compendium Summary report has been produced at the request of Tyne and Wear Metro T/a Nexus it is a summary of asbestos survey findings. Not all of this buildings or items within may have been surveyed for asbestos containing materials - check for exceptions below. Information in this report should not be regarded as an exhaustive inventory of all asbestos containing materials on these premises. Any proposed work of an intrusive nature in the vicinity of asbestos containing material as identified in this summary MUST in the first instance be referred to Tyne and Wear Metro T/a Nexus building and civil section.

This Compendium Asbestos report aims to be concise, yet comprehensive compilation of asbestos records relating to *South Gosforth Metro Station, Newcastle upon Tyne, NE3 1YT*. This compendium will summarize larger work shown in individual reports undertaken for jobs carried out on this site.

The full Site Asbestos Compendium report can be found at:
<https://web.lucion.co.uk/print/compendium/139429?s=f1886f3d4493eaa03f1e0e8b98885823>

Cover Photo



Overview of Jobs carried out at this Site

Job ID	Job-Type	Start Date	Due Date
187930	Survey, Management		
172023	Air Test, Reassurance		
281089	Bulk ID	Sunday, 29th July, 2018	Thursday, 16th August, 2018

Breakdown of Asbestos findings


⊖ Asbestos should be presumed to be present within Locations and Items not accessed until further assessment. Additional surveyor comments.

↓ Previous Asbestos Records

Most Recent Asbestos Records ↓

Building: South Gosforth Metro Station		Level: -1	Location: 001/Station platform 2 - Void				
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record
	Whole location	No Access Gained	--	--	--		

table continued from previous page...

Building: South Gosforth Metro Station								Level: -1		Location: 001/Station platform 2 - Void	
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record				
	 Limited Access:  (inspected during Survey, Survey, Management)										
Building: South Gosforth Metro Station								Level: 0		Location: 001/Station platform 1	
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record				
	Panels to rear of bus stop signs	No Asbestos Identified	NAD	--	--		 NAD				
	 (inspected during Survey, Survey, Management)										
	VE panels	Asbestos Insulating Board	--	--	--	--	 PRESUME				
	 (inspected during Survey, Survey, Management)										
Building: South Gosforth Metro Station								Level: 0		Location: 002/Station platform 2	
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record				
	Panels to rear of bus stop signs	No Asbestos Identified	NAD	--	--		 NAD				
	 (inspected during Survey, Survey, Management)										
	VE panels	Asbestos Insulating Board	--	--	--	--	 PRESUME				
	 (inspected during Survey, Survey, Management)										
Building: South Gosforth Metro Station								Level: 0		Location: 002/Station platform 2 - Canopy	
No reportable Items and Materials recorded at this Location											
Building: South Gosforth Metro Station								Level: 0		Location: 003/Gas meter cupboard	
No reportable Items and Materials recorded at this Location											
Building: South Gosforth Metro Station								Level: 1		Location: 001/Ticket concourse	
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record				
	VE panels	Asbestos Insulating Board	--	--	--	--	 PRESUME				
	 (inspected during Survey, Survey, Management)										
Building: South Gosforth Metro Station								Level: 1		Location: 002/control room	
First Record	Item	Material	Fibre-Type	Score	Extent	Recommend	Latest Record				
	board material with the floor void	supalux	NAD	--	--		 NAD				