

Certificate of Analysis for Bulk Identification


Job No. 12WS 219/11

Customer Address

Blaenau Gwent County Borough
Council, Technical Services Division,
Baldwin House, Festival Park, Ebbw Vale,
NP23 8ED

Site Address

Brynmawr Market Hall (Cinema), Market
Square, Brynmawr, NP23 4AJ

Customer Order No	
Samples Submitted By	DDE
Sampled By	DDE
No. of Samples Submitted	2
Date Samples Submitted	23/03/2012
Date Samples Analysed	28/08/2012
Samples Analysed In	Margam
Samples Analysed By	D Davies-Evans
Analyst / Authorised Signature	

REC (Asbestos) Ltd. accepts no responsibility for sampling activities undertaken by the client. Analysis is conducted in accordance with HSG 248 / RECASB01. Where soil analysis requires the taking of representative sub samples, the cone and quarter technique is used as described in RECASB01. The material description shall be regarded as tentative and is not included in the UKAS Accreditation for this laboratory. Opinions and interpretations expressed herein are outside the scope of UKAS Accreditation. Where this document has been digitally signed, printed copies are uncontrolled.

Samp No	Origin / Location of Material	Material Type	Asbestos Type(s)	Comments
1	1/029 IB debris in chimney	Asbestos Insulation Board	Chrysotile	
2	0/015 Cinema Corridor	Floor Tile & Adhesive	Chrysotile	Floor tile and Adhesive