



Client: Ms. Alison Waller
Transport for London
HMPS
7th Floor
Endeavour Square
London, E20 1JN

Head Office: Unit 3, Metro Centre,
Britannia Way, London, NW10 7PA
Phone: 020 8955 9680 Fax: 020 8955 9689
Laboratory: Unit 11, Ironbridge Close,
Great Central Way, London, NW10 0UF
Phone: 020 8955 1700 Fax: 020 8830 1003
Email: enquiries@4-rail.com
Web: www.4-rail.com

Results of Bulk Sampling & Asbestos Identification Stratford Market Depot - ES10893

Report Number: 4RS-JP-183130-R673926
Client's reference number(s): ES10893
4-RAIL Services (4RS) reference number(s): 183130/210818/01
Date of sampling: 21st August 2018
Date sample(s) received: 23rd August 2018
Date(s) of examination(s): 23rd August 2018
Issue date: 1st September 2018

Sampling Strategy

Sampling for asbestos containing materials was carried out in accordance with the procedures described in HSE Document HSG264 Asbestos, The Survey Guide and in-house inspection procedure 4R-E200.

Test Method

Samples were examined in accordance with the methods described in the HSE Document HSG 248 Asbestos: The analysts' guide for sampling, analysis and clearance procedures and in-house test procedure 4R-E220.

The results relate only to the items submitted for testing. Where samples have been taken by others, 4-RAIL Services do not accept any responsibility for the sampling.

4RS Sample No	Sample Description*	Asbestos Type(s) Detected
183130/210818/01	Corrugated cement debris, 12no x sheets, loose underneath blue porta cabin on concrete slab near recycling bins outside in Car Park area at Stratford Market Depot	None Detected

*The sample description is outside the scope of UKAS accreditation.

Samples examined will be retained by 4-RAIL Services for a period of 6 months, unless otherwise specified by the Client.

Analysed by: [Redacted], Technologist

Prepared by: [Redacted] Delivery Support Administrator

Certified by: [Redacted], Consultant

Additional comments

The opinions and interpretations expressed herein are outside the scope of the UKAS Accreditation

4-RAIL Services Limited were requested by Ms. Alison Waller, Transport for London, Hazardous Materials Professional Services, to attend site and undertake sampling of materials suspected to contain asbestos from Stratford Market Depot, ES10893.

Sampling was undertaken during traffic hours on 21st August 2018 by Mr. [REDACTED] of 4-RAIL Services Limited.

One sample was taken for analysis and it **was not found to contain asbestos.**

CONDITIONS OF ISSUE OF REPORTS.

THIS REPORT IS ISSUED TO THE CLIENT IN CONFIDENCE AND SHALL NOT BE REPRODUCED, EXCEPT IN FULL, WITHOUT THE WRITTEN APPROVAL OF 4-RAIL SERVICES.

QUERIES OR FURTHER INFORMATION.

ANY QUERIES OR REQUESTS FOR ADDITIONAL INFORMATION ON THE SUBJECT OF THIS REPORT SHOULD BE ADDRESSED TO THE AUTHOR WHO MAY BE CONTACTED AT THE ADDRESS GIVEN ON THE TITLE PAGE.