

Incident Recording System

Identifier

FRS Incident Number: 002768-22042018

Incident status: Published

Recording FRS: Grampian

Recording station: Inverurie

Recording Fire Officer: sg-leonwebster

'Over the border' incident: No

Call

Origin of call: Other

Incident type at call: Building

▶ Timings

Time of call: 22 April 2018 13:39:38

Late call: No

Date/time of stopped message: 23 April 2018 00:02:25

Date/time closed: 24 April 2018 12:53:03



Incident Recording System

Attendance

Incident category: Fire

Type of property: Building > Other Residential > Residential Home >

Nursing/Care

Property regulated: Yes

Number of appliances deployed: 15

Victims involved: No

Evacuation involved: No

Attack on firefighters: No

Derelict buildings involved: Yes

Chimney fire: No

▶ Location of incident

Building name: THE OLD BLYTHEWOOD HOUSE ABERDEENSHIRE

COUNCIL

Street: SCHOOL ROAD

Locality: PORT ELPHINSTONE

Town: INVERURIE

Postcode: AB51 3XD

Location description: THE OLD BLYTHEWOOD HOUSE, ABERDEENSHIRE

COUNCIL, SCHOOL ROAD, PORT

ELPHINSTONE, INVERURIE

X-coordinate: 0377537

Y-coordinate: 0820232



Incident Recording System

Other Details

Multiple seats: No

Time between ignition and discovery: Under 5 minutes

Time between discovery and call: Immediately

How the fire was discovered: Person

Cause/motive: Deliberate - others property

Occupied at time of incident: No

Building normally occupied: No - unoccupied permanently (vacant)

State of building's means of escape: Exits locked

State of building's compartmentation found: Fire spread through gaps or voids in construction

Were hazardous materials involved: No



Incident Recording System

Resources

Number of non-rider officers: 1

Vehicles

Type: Pumping - Water tender ladder

Time mobilised: 22 April 2018 13:42:19

Deployed from Home Station: Grampian > Inverurie

Time mobile: 22 April 2018 13:50:24

Time at scene: 22 April 2018 13:53:12

Time available: 22 April 2018 18:57:14

Demounted resource: No

Number of crew: 5

FRS Callsign R31P7

Type: Pumping - Water tender ladder

Time mobilised: 22 April 2018 13:42:19

Deployed from Home Station: Grampian > Inverurie

Time mobile: 22 April 2018 13:46:32

Time at scene: 22 April 2018 13:48:36

Time available: 22 April 2018 20:23:38

Demounted resource: No

Number of crew: 4

FRS Callsign R31P6

Type: Transport - Officer's car

Time mobilised: 22 April 2018 13:45:42

Deployed from Home Station: Grampian > Peterhead

Time mobile: 22 April 2018 13:46:42

Time at scene: 22 April 2018 14:13:17

Time available: 22 April 2018 19:45:15

Demounted resource: No

Number of crew: 1

FRS Callsign D11



Incident Recording System

Type: Pumping - Water tender ladder

Time mobilised: 22 April 2018 13:52:54

Deployed from Other Station: Grampian > North Anderson Drive

Time mobile: 22 April 2018 13:54:59

Time at scene: 22 April 2018 15:16:21

Time available: 22 April 2018 18:36:24

Demounted resource: No

Number of crew: 4

FRS Callsign P03P2

Type: Pumping - Water tender ladder

Time mobilised: 22 April 2018 13:53:00

Deployed from Home Station: Grampian > Oldmeldrum

Time mobile: 22 April 2018 14:05:26

Time at scene: 22 April 2018 14:15:00

Time available: 22 April 2018 19:43:10

Demounted resource: No

Number of crew: 4

FRS Callsign R30P6

Type: Aerial - Aerial ladder platform

Time mobilised: 22 April 2018 13:53:19

Deployed from Home Station: Grampian > Station 1Blackness Road

Time mobile: 22 April 2018 13:56:36

Time at scene: 22 April 2018 15:43:54

Time available: 22 April 2018 19:16:44

Demounted resource: No

Number of crew: 2

FRS Callsign P03A1



Incident Recording System

Type: Transport - Officer's car

Time mobilised: 22 April 2018 14:02:32

Deployed from Home Station: Grampian > Central

Time mobile: 22 April 2018 14:04:50

Time at scene: 22 April 2018 14:26:27

Time available: 22 April 2018 20:01:17

Demounted resource: No

Number of crew: 1

FRS Callsign D7

Type: Pumping - Water tender ladder

Time mobilised: 22 April 2018 14:03:40

Deployed from Home Station: Grampian > Central

Time mobile: 22 April 2018 14:04:34

Time at scene: 22 April 2018 14:26:08

Time available: 22 April 2018 18:31:56

Demounted resource: No

Number of crew: 4

FRS Callsign Q02P2

Type: Pumping - Water tender ladder

Time mobilised: 22 April 2018 14:03:40

Deployed from Home Station: Grampian > Central

Time mobile: 22 April 2018 14:04:52

Time at scene: 22 April 2018 14:26:03

Time available: 22 April 2018 18:27:57

Demounted resource: No

Number of crew: 5

FRS Callsign Q02P1



Incident Recording System

Type: Pumping - Water tender ladder

Time mobilised: 22 April 2018 14:03:40

Deployed from Home Station: Grampian > Ellon

Time mobile: 22 April 2018 14:08:37

Time at scene: 22 April 2018 14:33:02

Time available: 22 April 2018 19:49:42

Demounted resource: No

Number of crew: 6

FRS Callsign R29P6

Type: Pumping - Water tender ladder

Time mobilised: 22 April 2018 14:03:40

Deployed from Home Station: Grampian > North Anderson Drive

Time mobile: 22 April 2018 14:05:14

Time at scene: 22 April 2018 14:26:24

Time available: 22 April 2018 23:26:29

Demounted resource: No

Number of crew: 6

FRS Callsign Q01P1

Type: Pumping - Water tender ladder

Time mobilised: 22 April 2018 14:03:41

Deployed from Home Station: Grampian > Altens

Time mobile: 22 April 2018 14:05:34

Time at scene: 22 April 2018 14:38:49

Time available: 22 April 2018 21:21:20

Demounted resource: No

Number of crew: 6

FRS Callsign Q03P1



Incident Recording System

Type: Command - Command support

Time mobilised: 22 April 2018 14:03:41

Deployed from Home Station: Grampian > Altens

Time mobile: 22 April 2018 14:07:32

Time at scene: 22 April 2018 14:41:23

Time available: 22 April 2018 21:21:57

Demounted resource: No

Number of crew: 0

FRS Callsign Q03C2

Type: Transport - General purpose lorry

Time mobilised: 22 April 2018 14:03:41

Deployed from Home Station: Grampian > Altens

Time mobile: 22 April 2018 14:07:32

Time at scene: 22 April 2018 14:41:23

Time available: 22 April 2018 21:21:57

Demounted resource: No

Number of crew: 0

FRS Callsign Q03C1

Type: Pumping - Water tender ladder

Time mobilised: 22 April 2018 14:04:28

Deployed from Home Station: Grampian > Alford

Time mobile: 22 April 2018 14:10:19

Time at scene: 22 April 2018 14:31:21

Time available: 22 April 2018 21:00:38

Demounted resource: No

Number of crew: 6

FRS Callsign R51P6



Incident Recording System

Type: Transport - Officer's car

Time mobilised: 22 April 2018 14:04:48

Deployed from Home Station: Grampian > Elgin

Time mobile: 22 April 2018 14:07:02

Time at scene: 22 April 2018 14:17:14

Time available: 22 April 2018 21:09:03

Demounted resource: No

Number of crew:

FRS Callsign SA1

Type: Transport - Officer's car

Time mobilised: 22 April 2018 14:06:58

Deployed from Home Station: Grampian > Laurencekirk

Time mobile: 22 April 2018 14:10:26

Time at scene: 22 April 2018 14:50:28

Time available: 22 April 2018 19:47:03

Demounted resource: No

Number of crew: 1

FRS Callsign D1

Type: Transport - Officer's car

Time mobilised: 22 April 2018 14:08:56

Deployed from Home Station: Grampian > Inverurie

Time mobile: 22 April 2018 14:14:38

Time at scene: 22 April 2018 14:42:01

Time available: 22 April 2018 21:50:29

Demounted resource: No

Number of crew: 1

FRS Callsign C6



Incident Recording System

Type: Transport - Officer's car

Time mobilised: 22 April 2018 14:11:52

Deployed from Home Station: Grampian > Station 21Perth

Time mobile: 22 April 2018 14:15:17

Time at scene: 22 April 2018 15:38:54

Time available: 22 April 2018 23:29:45

Demounted resource: No

Number of crew:

FRS Callsign D16

Type: Transport - Officer's car

Time mobilised: 22 April 2018 14:13:54

Grampian >

Time mobile: 22 April 2018 14:20:16

Time at scene: 22 April 2018 15:29:28

Time available: 22 April 2018 19:29:15

Demounted resource: No

Number of crew: 1

FRS Callsign SD6

Type: Pumping - Water tender ladder

Time mobilised: 22 April 2018 14:32:24

Deployed from Home Station: Grampian > Huntly

Time mobile: 22 April 2018 14:36:00

Time at scene: 22 April 2018 15:02:45

Time available: 22 April 2018 20:16:41

Demounted resource: No

Number of crew: 4

FRS Callsign R47P6



Incident Recording System

Type: Water Management - Water carrier / Tanker

Time mobilised: 22 April 2018 14:41:58

Deployed from Home Station: Grampian > Turriff

Time mobile: 22 April 2018 14:46:20

Time at scene: 22 April 2018 15:17:38

Time available: 22 April 2018 18:57:50

Demounted resource: No

Number of crew: 2

FRS Callsign R49W6

Type: Transport - Officer's car

Time mobilised: 22 April 2018 14:48:39

Deployed from Home Station: Grampian > Dyce

Time mobile: 22 April 2018 14:49:15

Time at scene: 22 April 2018 15:57:14

Time available: 22 April 2018 19:39:41

Demounted resource: No

Number of crew: 1

FRS Callsign SFE09

Type: Transport - General purpose lorry

Time mobilised: 22 April 2018 15:36:06

Deployed from Home Station: Grampian > Peterhead

Time mobile: 22 April 2018 15:43:22

Time at scene: 22 April 2018 16:22:42

Time available: 22 April 2018 19:48:26

Demounted resource: No

Number of crew: 2

FRS Callsign R02S1



Incident Recording System

Type: Transport - General purpose lorry

Time mobilised: 22 April 2018 15:36:46

Deployed from Home Station: Grampian > Dyce

Time mobile: 22 April 2018 15:57:52

Time at scene: 22 April 2018 16:15:46

Time available: 22 April 2018 18:06:20

Demounted resource: No

Number of crew: 2

FRS Callsign Q20S6

Type: Transport - General purpose lorry

Time mobilised: 22 April 2018 16:23:56

Deployed from Home Station: Grampian > Huntly

Time mobile: 22 April 2018 16:29:53

Time at scene: 22 April 2018 17:55:03

Time available: 22 April 2018 19:49:52

Demounted resource: No

Number of crew: 2

FRS Callsign R47T6

Type: Aerial - Aerial ladder platform

Time mobilised: 22 April 2018 18:06:46

Deployed from Home Station: Grampian > Central

Time mobile: 22 April 2018 18:10:05

Time at scene: 22 April 2018 18:58:55

Time available: 23 April 2018 00:20:04

Demounted resource: No

Number of crew: 2

FRS Callsign Q02A2



Incident Recording System

Type: Pumping - Water tender ladder

Time mobilised: 22 April 2018 19:34:42

Deployed from Home Station: Grampian > Dyce

Time mobile: 22 April 2018 19:43:21

Time at scene: 22 April 2018 19:59:26

Time available: 22 April 2018 22:54:37

Demounted resource: No

Number of crew: 4

FRS Callsign Q20P6

Type: Pumping - Water tender ladder

Time mobilised: 22 April 2018 19:41:42

Deployed from Home Station: Grampian > Peterhead

Time mobile: 22 April 2018 19:41:57

Time at scene: 22 April 2018 20:49:59

Time available: 22 April 2018 22:41:58

Demounted resource: No

Number of crew: 5

FRS Callsign R02P1

Type: Pumping - Water tender ladder

Time mobilised: 22 April 2018 22:35:42

Deployed from Home Station: Grampian > Central

Time mobile: 22 April 2018 22:37:21

Time at scene: 22 April 2018 23:12:41

Time available: 23 April 2018 00:15:45

Demounted resource: No

Number of crew: 5

FRS Callsign Q02P1



Incident Recording System

Type: Pumping - Water tender ladder

Time mobilised: 22 April 2018 23:02:12

Deployed from Home Station: Grampian > Central

Time mobile: 22 April 2018 23:03:34

Time at scene: 22 April 2018 23:34:33

Time available: 23 April 2018 01:01:30

Demounted resource: No

Number of crew: 4

FRS Callsign Q02P2

Type: Fire Investigation - Fire investigation unit

Time mobilised: 24 April 2018 09:17:11

Deployed from Home Station: Grampian > Dyce

Time mobile: 24 April 2018 09:17:31

Time at scene: 24 April 2018 09:41:28

Time available: 24 April 2018 12:53:03

Demounted resource: No

Number of crew: 2

FRS Callsign Q01F1

Type: Aerial - Aerial ladder platform

Time mobilised: 24 April 2018 11:00:42

Deployed from Home Station: Grampian > Central

Time mobile: 24 April 2018 11:01:36

Time at scene: 24 April 2018 11:32:55

Time available: 24 April 2018 11:33:06

Demounted resource: No

Number of crew: 2

FRS Callsign Q02A2



Incident Recording System

▶ Equipment	
Туре	Number Used
Water Delivery - Hosereel - high pressure	4
Water Delivery - Main line/jet	4
RPE - CABA - standard duration	20
Pumping Equipment - Portable pump	2
Pumping Equipment - Vacuum, suction hose	6
Forcible Entry Tools - Axes/Hammers/Crowbars/Croppers	4
Small Tools - Shovels/Forks/Brooms/Chimney Rods	4
▶ Fire officers	
RCC Callsign	FRS Callsign
	D1

Action

Delay in commencing firefighting action: No delay

Main action taken by the general public

prior to arrival:

None

Main action taken by FRS personnel: Hosereel (high pressure) (HRJ) - augmented supply

Damage - How the fire started

Main cause of fire: Heat source and combustibles brought together

deliberately

Person or action that caused the fire: Not known

Source of ignition:

Not known

Powered the ignition:

Unknown

Item that ignited first:

Structural/Fixtures/Fittings - Internal - Internal

Fittings

Item mainly responsible for spreading fire: Structural/Fixtures/Fittings - Internal - Internal

Fittings

Rapid fire growth caused by:

No rapid fire growth



Incident Recording System

Damage - Substances/explosions involved

Dangerous substances involved: None Explosion: No

Damage - Property information

Type of room/compartment fire started in: Not known

Factors contributing to start of fire: None

Impairment due to suspected drugs/alcohol: Don't Know

Special method of building construction: None

Heat and smoke damage only: No

Size of fire when fire service arrived: Limited to floor of origin (not whole building)

Distance from adjacent properties (m):No other property affected

Distance from adjacent properties at stop (m): No other property affected

Damage restricted to: Affecting more than 2 floors (not whole building)

201 - 500

201 - 500

Extent of the fire damage at stop: 101 - 200

Extent of the total area damaged (sq. m at

stop):

Approximate size of room/compartment of 11 - 20

fire's origin(sq. m):

Approximate size of floor at fire's origin (sq.

m):

Number of floors above ground: 2

Number of floors below ground: 1

Floor fire originated: 1

Persons

Number of casualties: 0

Number of casualties aged 0 to 15: 0

Number of casualties aged 16 and over: 0