Site	Downham Way		2200	22003273		
Asset Id	0123/0367		Locn		The second second second	
Asset Number	54.00	LMARK Ldn Ad 3	3 Bay Mk1A		RING ROAD , 89 M E	AST
Measurement	1.00	Number of				
Officer				***		
nspected	15/10/2019 09:54:12		Ехр	iry Date	00/00/0000 00:00	0:00
Due Date	25/02/2020 10:	32:59				
	_					

Conditions		Defects			
Observation Type	Grade	Score	Defects		
Able to Audit?	Yes	.0000	0		
Confirm data Correct?	Yes	.0000	0		
Is Asset Number Displayed?	Yes	.0000	0		
Structure / Foundation	Fair	.0000	0		
Roof	Fair	.0000	0		
Infill panels	Fair	.0000	0		
Publicity Information	Fair	.0000	0		
ublicity Present & Correct? Yes		.0000	0		
Lighting	Fair	.0000	0		
ectrical Box Fair		.0000	0		
Seating	Fair	.0000	0		
Ad Box	Fair	.0000	0		
Countdown Sign Working?	Not Applicable	.0000	0		
Countdown Unit Secure?	No (Give Details)	.0000	0		
Contacted Highway Authority?	No	.0000	0		
State of cleanliness	Fair	.0000	0		

Site	Downham Way				2200	13273	***
Asset Id	0123/0367		***	Locn		W 644/644A.	
Asset Number	54.00	LMARK Ldn A	d 3 Bay N	lk1A		RING ROAD , 8	89 M EAST
Measurement	1.00	Number of					
Officer	8				***		
nspected	25/02/2019 10	:32:59		Expi	ry Date	00/00/000	00:00:00
Due Date	25/02/2019 10	:32:59					

Conditions		Defects	
Observation Type	Grade	Score	Defects
Able to Audit?	Yes	.0000	0
Confirm data Correct?	Yes	.0000	0
Is Asset Number Displayed?	Yes	.0000	0
Structure / Foundation	Fair	.0000	0
Roof	Fair	.0000	0
Infill panels	Fair	.0000	0
Publicity Information	Fair	.0000	0
Publicity Present & Correct?	Yes	.0000	0
Lighting	Fair	.0000	0
RCD Tested?	No (Give Details)	.0000	0
Electrical Box	Fair	.0000	0
Seating	Fair	.0000	0
Ad Box	Fair	.0000	0
Countdown Sign Working?	Not Applicable	.0000	0
Countdown Unit Secure?	No (Give Details)	.0000	0
Contacted Highway Authority?	No	.0000	0
State of cleanliness	Fair	.0000	0