

HIGHWAYS AND TRANSPORTATION SERVICE REQUEST

Request No: ERG503376

Received: 06/07/2018

Taken By: [REDACTED]

Current State: Completed

Target: 26/09/2018

Handling Officer: [REDACTED]

From: [REDACTED]

Cust Ref: None

Address: None None,

Tel No(s):

Mobile:

Email Address: [REDACTED]

Request Name: PROW, PROW - other

Street Name: YCV144, Slaithwaite, Huddersfield

Location:

as per doc in images, col 144 builders waste

Reply Required: YES

Preferred Method of Contact:

Dealt With By: [REDACTED]

Date: [REDACTED]

How Replied: Phone ☐

Site Meeting ☐

Message ☐

Email/Letter ☐

Summary Of Reply:

Mayrise Works Orders Issued: Yes/No If Yes Enter Order No: [REDACTED]

Do You Want To Close The Request : Yes/No

If Yes Enter The Completed Date: [REDACTED]

Please Give Details:

HIGHWAYS AND TRANSPORTATION SERVICE REQUEST

Request No: ERG503376

Received: 06/07/2018

Taken By: [REDACTED]

Current State: Completed

Target: 26/09/2018

Handling Officer: [REDACTED]

Handlers

Issued	State	To	Handled	Status
06/07/2018	Received			
06/07/2018	New Request Add	PROW Strategic	[REDACTED]	Pass Forward
06/07/2018	Pass the request			
06/07/2018	Allocated			
06/07/2018		Environmental Ra	06/07/2018	Pass Forward
06/07/2018	Pass the request			
06/07/2018	Allocated			
06/07/2018		Environmental Ra	12/07/2018	Pass Forward
06/07/2018	Pass the request			
09/07/2018	Allocated			
12/07/2018		Environmental Ra	21/09/2018	Completed
12/07/2018	Pass the request			
12/07/2018	Allocated			
21/09/2018	Completed			

Images

Recorded	By	Type	Format
06/07/18	[REDACTED]	Correspondenc	Corresponde doc
21/09/18	[REDACTED]	Photograph	Photograph Rubble Moved

Contact Notes

Recorded	By	Type
21/09/18	[REDACTED]	OUT

Rubble moved

[REDACTED] has updated complainant