



Report Number: 8A57B41046 Date Submitted: 12/12/2016 Current
Authority / HSE Office: East and South East - 02 Basingstoke

Stored Licence expiry date does NOT match supplied Licence Expiry Date.

About you, the licence holder:

Licence Number: [REDACTED]

Licence Expiry
Date: [REDACTED]

Name: [REDACTED]

Position / Job Title: [REDACTED]

Licence Holder
Name: R H Insulation Services LimitedAddress: Unit D7, Segensworth Busines Centre
Segensworth Road

Town: FAREHAM

County: Hants

Post Code: PO15 5RQ

Phone Number: [REDACTED]

E-Mail: [REDACTED]

PVC Status: Notifications
↓ in Yr: 61

Visits in Yr: 2

☐ Visit☐ Visit

Desirable?

Completed?

[Update Visit Info](#)**Who are you Contracted to?**

Name: [REDACTED]

Phone Number: [REDACTED]

Contact: [REDACTED]

Address where asbestos work is to be carried outAddress: HMS Daedalus
Building 165
Broom Way

Town: LEE ON SOLENT

County: Hants

Post Code: PO13 9YA

Multiple Sites

No

Involved:

Enforcing Authority Details

Who is the enforcing authority? HSE

Local Authority Area

Country:

England

Geographic Area: Local Authority:

Hampshire

Gosport

Exact work location Building 165 - Boiler Room

or description of
where on premiseswork is to be
carried out:**Person preparing plan of work**

Name: [REDACTED]
Mobile Number: [REDACTED]

Site Supervisor

Name: [REDACTED]
Mobile Number: [REDACTED]

Timing and duration of work

Waiver Requested: No
Actual start date of setup on site: 02/01/2017 Expected finish date of work: 11/01/2017
Duration: 8 Start and finish times: 8am - 4pm
Will there be night working? No Will there be weekend working? No
Will there be a significant cessation / pause in the asbestos work? No

Cessation details:

About the work

ACM Type: Asbestos Insulation
Work to be undertaken: Environmental work
Removal work

General condition of asbestos: Poor

Main type of asbestos: Amosite
Chrysotile

Details of type of work to be undertaken, general condition and main type of asbestos: To remove and dispose of the asbestos residue to the walls of the Boiler Room and the dust and debris to the floor area.

Size of job (area or volume): 3 bags/max. 1m/sq

Number of persons employed per shift: 2 Minimum 3 Maximum

Control measures and risks

What control measures will be used to reduce exposure as low as reasonably practicable? Decontamination procedures using an asbestos decontamination unit
Enclosure of work under negative pressure
RPE

How will work be supervised and monitored? CCTV

Are there non-asbestos risks? Yes

Risk details: Working at height - steps/hop-ups will be required, these will be checked prior to, during and after use and will be used to the correct guidelines at all times.

Is asbestos removal
on special premises? No

Other licenced asbestos holders

Are other licenced
asbestos holders
involved in the work? No

List of Other Licence
Holder(s):

Audited Changes to form resubmission by notifier

Dates, Notifier and ACM Types:

Change Date	Start Date	Finish Date	Notifier Name	Job Title	ACM Types
12/12/2016	02/01/2017	11/01/2017	[REDACTED]	[REDACTED]	Asbestos Insulation

Cessation Details:

Change Date	Cessation	Cessation Details
12/12/2016	No	

Notes recorded for the report

Division	Location	Event Date	Event Type	Event Reason	Event No	User Name	Reason Note
FOD	East and South East - 02 Basingstoke	12/12/2016	Create		1	system	

