



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 25/08/2019
Until Less Than: 19/09/2019

Section:
7065U7105_39 PARKDALE ACCESS RD1: BALLYBOG RD1 TO END AT PARKDALE FLATS

Commencement date of inspection: 04 Sep 2019
Inspect History ID & Description: 3077107 - 6 Monthly - Safety Inspection of W12L-CASTLEREAGH / LISBURN
Inspector Name: James Wright
Class: Unclassified
Environment: URBAN
Traffic Level: Low Traffic

Ref: DCDS8-3077107-67
Defect Type: DEFECT
Defect Category: BITMAC POTHOLE (CBPH)
Location Description: opp sl 19 near garage no 15
Priority: R2 - 5 Working days
Defect Dimensions: Length (m): 0.20 Width (m): 0.20 Depth (mm): 56.00

①

Repair Lost Code:	Repair Item Name:	Quantity	Units	Repair Measures
D24022A	^ 70mm bit. patch w/c 1-3 m2	1.12	SQ.M	L 1.40 W 0.80 D 0.00
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No

Ref: DCDS8-3077107-68
Defect Type: DEFECT
Defect Category: BITMAC POTHOLE (CBPH)
Location Description: at garage no 22
Priority: R2 - 5 Working days
Defect Dimensions: Length (m): 0.70 Width (m): 0.20 Depth (mm): 70.00

②

Repair Lost Code:	Repair Item Name:	Quantity	Units	Repair Measures
D24021A	^ 70mm bit. patch w/c <1 m2	1.00	no	L 0.00 W 0.00 D 0.00

Photographs or Documents attached: No



Defect Inspections (By Road Section) Report

Selection Criteria:

Dates:
From: 25/08/2019
Until Less Than: 19/09/2019

Section:
7065U7105_39 PARKDALE ACCESS RD1: BALLYBOG RD1 TO END AT PARKDALE FLATS

Comencement date of inspection: 04 Sep 2019
Inspect History ID & Description: 3077107 - 6 Monthly - Safety Inspection of W12L-CASTLEREAGH / LISBURN
Inspector Name: James Wright
Class: Unclassified
Environment: URBAN
Traffic Level: Low Traffic

Ref: DCD58-3077107-69
Defect Type: DEFECT
Defect Category: BITMAC POTHOLE (CBPH)
Comments: CW phs
Location Description: at sl 2
Priority: R2 - 5 Working days
Defect Dimensions: Length (m): 0.30 Width (m): 0.10 Depth (mm): 53.00

Defect Date: 04-September-2019

3

Repair Lost Code: D24021A
Repair Item Name: ^ 70mm bit. patch w/c <1 m2
Photographs or Documents attached: No

Quantity: 2.00
Units: no
Repair Measures: L 0.00 W 0.00 D 0.00